

This is a digital copy of a book that was preserved for generations on library shelves before it was carefully scanned by Google as part of a project to make the world's books discoverable online.

It has survived long enough for the copyright to expire and the book to enter the public domain. A public domain book is one that was never subject to copyright or whose legal copyright term has expired. Whether a book is in the public domain may vary country to country. Public domain books are our gateways to the past, representing a wealth of history, culture and knowledge that's often difficult to discover.

Marks, notations and other marginalia present in the original volume will appear in this file - a reminder of this book's long journey from the publisher to a library and finally to you.

Usage guidelines

Google is proud to partner with libraries to digitize public domain materials and make them widely accessible. Public domain books belong to the public and we are merely their custodians. Nevertheless, this work is expensive, so in order to keep providing this resource, we have taken steps to prevent abuse by commercial parties, including placing technical restrictions on automated querying.

We also ask that you:

- + *Make non-commercial use of the files* We designed Google Book Search for use by individuals, and we request that you use these files for personal, non-commercial purposes.
- + Refrain from automated querying Do not send automated queries of any sort to Google's system: If you are conducting research on machine translation, optical character recognition or other areas where access to a large amount of text is helpful, please contact us. We encourage the use of public domain materials for these purposes and may be able to help.
- + *Maintain attribution* The Google "watermark" you see on each file is essential for informing people about this project and helping them find additional materials through Google Book Search. Please do not remove it.
- + *Keep it legal* Whatever your use, remember that you are responsible for ensuring that what you are doing is legal. Do not assume that just because we believe a book is in the public domain for users in the United States, that the work is also in the public domain for users in other countries. Whether a book is still in copyright varies from country to country, and we can't offer guidance on whether any specific use of any specific book is allowed. Please do not assume that a book's appearance in Google Book Search means it can be used in any manner anywhere in the world. Copyright infringement liability can be quite severe.

About Google Book Search

Google's mission is to organize the world's information and to make it universally accessible and useful. Google Book Search helps readers discover the world's books while helping authors and publishers reach new audiences. You can search through the full text of this book on the web at http://books.google.com/









. .

OPERATIVE MECHANIC'S

DRKSHOP COMPANION,

AND

HE SCIENTIFIC GENTLEMAN'S

Practical Assistant:

COMPRISING

REAT VARIETY OF THE MOST USEFUL RULES IN MECHANICAL SCIENCE,

DIVESTED OF MATHEMATICAL COMPLEXITY; umerous Tables of Practical Data and Calculated Results, facilitating Mechanical and Commercial Transactions.

BY W. TEMPLETON,
AUTHOR OF SEVERAL SCIENTIFIC WORKS.

THIRD EDITION, WITH THE ADDITION OF

CHANICAL TABLES FOR THE USE OF OPERATIVE
SMITHS, MILLWRIGHTS, AND ENGINEERS;
AND

CAL DIRECTIONS FOR THE SMELTING OF METALLIC ORES.

Mondon: JOHN WEALE, HIGH HOLBORN. 1853.

107. c. 31.

HUGHES, PRINTER,
KING'S HEAD COURT, GOUGH SQUARE.

TO THE PUBLIC.

The subjects of the following pages are chiefly compiled at the instigation of pressing solicitations by numerous individuals, no few of whom complain of the want of a convenient Text Book of Reference in which Mechanical and Commercial demands are judiciously combined. Others, with apparently equal reasons, for the sake of instruction, complain of the want of a compendium in which tuition and practical reference are discriminately arranged; and generally, that for purposes of estimation, no properly portable work is yet in existence: hence it is with a wish to diminish those wants in some degree that the present attempt has been made to supply the necessary information.

In regard to the selection, great care has been taken that the subjects be not only intimately interwoven, but also of such a nature as business transactions call most frequently into requisition. The elementary or educational portion will be found exceedingly plain, simple, and aptly adapted; also the practical rules much abbreviated through the application of decimal approximates, by which results are obtained sufficiently exact, and the means of calculation considerably facilitated.

That the production might be rendered still moworthy of public patronage, numerous diagrams, a several engravings, are annexed, which add much its value in regard to practical utility; and it or remains to add the hope, that the Operative, t Man of Science, and an interested Public, may gidue appreciation to the work, in proportion to merits.

W. T

The present edition has been much extended the insertion of numerous Tables for the use Operative Smiths, Millwrights, and Engineers, a by a further addition of Practical Observations the Smelting of Metallic Ores.

Nov. 16, 1852.

749	38 /	24	G E
GEOMETRY.	- 1	To draw a spiral with uniform spaces .	15
	. 1	To draw a volute for the lonic column .	16
To erect a perpendicular on a right line	1	To draw a scroll for hand-rails	16
To erect a perpendicular at the end of	. 1	To find the angles and lengths of ma-	
a line	1	terials for pyramidal frustums .	17
To bisect a given angle	2	To describe the proper form of material	
To describe a circle through three given	- 1	by which to form a cone	18
points out of a right line	2 3	Sector by which to obtain angles	18
To find the centre of a given circle	3		
To find the length of any given arc of a			
circle	8		
To draw a tangent to a circle	•	GEOMETRY APPLIED TO	
To draw lines towards the centre of a	3	MECHANICS.	
circle, the centre being inaccessible	4		• •
To describe an arc of a circle	5	To delineate a vee-threaded screw	18
To describe an ellipse or oval To describe an elliptic arch	5	To delineate a square-threaded screw	19
	6	To determine the proper forms for a	•
To describe a parabola	6	pair of bevel wheels .	20
To measure an intercepted line To obtain the distance of an inaccessible	•	Proportions for the construction of	٠.
object	7	toothed wheels	21
To find the distance between two inac-	•	To delineate wheels by orthographic	21
cessible objects	8	projection	21
To design a beam of strongest section .	8		22
To find the proper position for the	- 1	wheel	
eccentric in a steam engine	8		
To determine the proper length of valve			
levers	9	DECIMAL ARITHMETIC.	
	10	DECIMAL ARITHMETIC.	
To construct a square upon a right line	10	Definitions	23
To form a square equal to a given tri-	- t	Reduction	23
	10	Applied examples	24
To form a square equal to a given	- 1	Definitions of Arithmetical Signs .	27
	11	British Standard Measures	28
To form a rectangle equal to a given	- 1	British Special Measures	29
square	11	Decimal Approximations	30
To bisect any given triangle	11	Decimal Equivalents	31
To describe a circle in a given triangle.	12	Decimal Equivalents	••
	12		
To make a rectangle equal to a given	1		
	12	MENSURATION.	
To make a triangle equal to a given	1		
	13	To measure the surface of a square,	32
	13	rectangle, rhomboid, &c	32
To form an octagon from a given	I	Two sides of a triangle given, to find	33
	13	the third side	34
To form a square equal to two given		To find the area of a triangle	34
squares, or a circle equal to two	14	Table of Polygons	36
	•••	Definitions of the circle	37
To draw a line equal to any portion of a circle's circumference	14	Rules in relation to the circle	38
circle's circumference	**	terrica til terminom to pric critica	

	res		PAG
To find the diameter of a circle when		for Angled Iron Hoops, from 6 inches	
any chord and versed sine are given	39	to 6 feet in diameter; advancing by	
To find the length of any given arc of a		an eighth of an inch.—Angle outside	9
circle	40	Table containing the Circumferences	
To find the area of the sector of a circle	40	for Angled Iron Hoops, from 6 inches	
		to trugica from from o inches	
To find the area of a circular ring .	41	to 6 feet in diameter; advancing by	
To find the area of an ellipse	41	an eighth of an inch.—Angle inside	10
To find the area of a parabola	42	Proportional breadths for six-sided nuts	10
	74		10
To find the solidity or capacity of any	ĺ	Table of the Weight of Sheet Iron,	
cubical figure	42	Copper, and Brass	10
	1	Comparative weights of different bodies	ii
To find the convex surface and solidity			11
of a cylinder	43	Table of the Weights of Cast-Iron	
To find the length of any cylindrical		Pipes	11
	44		
_ helix .	44	Weights of leaden pipes	11
To find the convex surface and solidity		To find the weights of pipes of various	
of a cone	45	metals	11
	30		• •
To find the solidity or capacity of any	- 1	Weight of a cubic inch of various	
frustum of a cone or pyramid .	46	metals	11
		Table of the Weights of Cast-Iron Balls	īī
To find the solid contents of a wedge .	47		11
To find the convex surface and solidity		Table to facilitate the Measure of	
of a sphere or globe	48	Timber	11
		Table of Cubic or Solid Measure	
To find the convex surface and solidity			11
of the segment of a globe	49	To measure battens, deals, and planks	11
To find the convex surface and solidity		Table of Scantling Timber	11
		zabic of comming rimber	**
of a cylindrical ring	49		
To determine the proper length of iron			
for a ring of given diameter	50	**************************************	_
for a ring of given diameter	90	INSTRUMENTAL ARITHMETIC	;.
To determine the length of angle iron			
to form a ring of given diameter .	51	Explanation of the slide rule	11
		Numeration	11
To measure the capacity of a loco-			
motive tender tank	52	To multiply by the slide rule	11
		Proportion	12
		Rule of Three Inverse	12
Table of Specific Gravities and Pro-			
	53	Square and cube roots	12
perties of Metals	00	Measure of squares, rectangles, &c	12
Table of Specific Gravities and Pro-			12
perties of Timber	54	Measure of circles and polygons	12
	1	Tables of Gauge-Points for the Slide	
Table of Specific Gravities of Liquids,	1	Rule	12
Gases, &c	55	Mensuration of solidity and capacity .	12
Weights of various measures of water .	55		
		To compute the power of steam engines	12
Table of the Weight of Square and		Of steam engine boilers	12
Round Bar Iron	56 (or around on Bring popular	
Table of the Weight of Flat Bar Iron .	57		
	٠,		
Table of the Circumferences of Circles,	- 1	COMMERCIAL TABLES.	
from 1 inch to 20 feet 7-8ths of an	- 1		
inch; advancing by an eighth	60	Tables by which to facilitate the Calcu-	
Table showing the Weight of - 1:1	٦ ا	lation of British Money	12
Table showing the Weight of a lineal	- 1		
foot of Malleable Rectangular or	- 1	Table of Equivalent Prices	13
Flat Iron, from 1-8th of an inch to			
	- 1		
3 inches thick; advancing by an	- 1	STRENGTH OF MATERIALS.	
eighth, and quarter of an inch, in	- 1		
breadth	80	Definitions	13
	ا ت		10
Table showing the Weight of a lineal	- 1	Table of Tenacities, Resistance to Com-	
foot of Round Bar Iron, in avoirdu-	1	pression, &c. of Various Bodies .	13
	1	Table of Comparative Strength of Ropes	
pois qrs. lbs. oz., from 1-8th of an	- 1		
inch to 12 inches in diameter; ad-		and Chains	13
vancing by an eighth of an inch .	94	Table of Metallic Alloys	13
	[Resistance of bodies to lateral pressure	13
Table showing the Weight of a lineal	- 1		
foot of Square Bar Iron, in avoirdu-	- 1	Table of Practical Data	13
pois qrs. lbs. oz., from 1-8th of an	1	To find the dimensions of a beam of	
	- 1	timber to sustain a given weight .	13
inch to 12 inches; advancing by an	1		10
eighth	95	To determine the absolute strength of	
Table containing the Circumferences	- 1	a rectangular beam of timber	14
	- 1		

PAGE	. PAGE
mine the dimensions of a beam	PROPERTIES OF WATER AND
a given degree of deflection . 141	AIR
a beams of strongest section . 142	Personal and the second of the second
en beams, trussed 143	Rifects produced by water in its natural state
strength of cast-iron beams . 143	The pressure of fluids
of Dimensions for Cast-Iron	The hydraulic press
u 144	The weights of bodies obtained by dis-
he weight of a cast-iron beam 145	placement of fluids
ce to flexure by vertical pres-	The resistance of water to bodies
145	passing through it 233
rmine the dimensions for a	Of water flowing through orifices . 233
an of timber 146	Discharging of water by rectangular
which to determine the Dimen-	apertures
of Cast-Iron Columns 147	Flowing of water through pipes 236
	Table of the Diameters of Pipes for the
strength of metals to resist	Discharging of Water 237
Smelting of Metallic Ores 149	Laws of the gravity of water 237
Squares, Cubes, &c. of Numbers 203	Rules relating to water-wheels 238
pdamed crossing actor transports 200	Turbines, their effects, &c 239
	Rule to calculate the powers of turbines 240
MECHANIC POWERS.	Overshot water-wheels, notice of 241
MECHANIC FOWERS.	l
жа, &с 204	Effects produced by steam 241
First kind of lever 205	Table of the Elastic Force of Steam . 242
Second , 206	Of the latent heat in steam 244
Third ,, 206	Steam as a motive power 245
ı a safety-valve, &c 206	Temperature of steam 245
nd pinion, or crane 207	Expansive force of steam
c 207	Table of Hyperbolic Logarithms 247
ley, with applications 208	Condensation of steam 247
plane 210	Boiling points of impure water 248
f Inclinations and Amount of	
sing Resistance 211	Effects produced by air 248
Inclined Planes 213	Table of the Expansion of Air by Heat 249
lge	Table relating to Pumps
1W	Oxygen of the atmosphere
tless screw, or screw applied to	Resistance of the atmosphere 251
eel 215	Table of Atmospheric Force
	Effect of wind-mills 252
INTIONS CONCULAR MOREON	
INUOUS CIRCULAR MOTION.	
ons, &c 216	1
ional diameters of wheels to the	STEAM ENGINE BOILERS 253
ber of revolutions 216	To determine the amount of heating
in of wheels and pinions 217	surface in a boiler
rs or number of teeth in wheels	Of waggon-shaped boilers 254
oportion to their velocities . 217	Of cylindrical boilers
rmine the proper diameters of	Marine boilers
ils to given peculiarities	Locomotive boilers
the proportional wheels for	Heating powers of combustibles 257
v cutting by a lathe 219	Observations on the giving an order for
of Change Wheels for Screw	a steam engine 257
ing	Table of Dimensions for Steam Engine
	Cylinders
the Strength of Wheels of Cast	Units of nominal power 258
f the Diameters of Wheels to	To estimate the power of an engine . 259
tin a given number of Teeth . 223	To determine the velocity for the piston
ma a Brion number of Teeth . 220	of a steam engine
	Table of Approximate Velocities for
ION	Pistons
ION 227	Table for Parallel Motions 261

LOGARITHMS		Table of Square and Cube Roots Numbers Table of Per-Centage and Discount	. 27

LIST OF PLATES.

	Delineation of Screws						to f	ace pa	ge	1
	Illustration to the Drawing of Bevel Wheels	٠.						•	٠.	2
	Orthographic Projection									2
	Applications of Mechanic Powers .			•						20
	and F. Parallel Motions									26
G.	Elevation and Section of an Overshot \	Water-	Wheel	, con	struc	ted	by	Mess	rs.	
	Donkin and Co									24
	Details			•						24
K.	Boilers of the 'Braganza' steam vessel, by M	desars	. Bury,	Curti	s, an	d Ke	mne	dy.		25
L.	Locomotive Boiler				•			٠.		25


THE WORKSHOP COMPANION.

PRACTICAL GEOMETRY.

GEOMETRY is the science which investigates and demonstrates the properties of lines on surfaces and solids: hence, PRACTICAL GEOMETRY is the method of applying the rules of the science to practical purposes.

1. From any given point, in a straight line, to erect a perpendicular; or, to make a line at right angles with a given line.

On each side of the point A from which the line is to be made, take equal distances, as Ab, Ac; and from b and c as centres, with any distance greater than b A, or c A, describe arcs cutting each other at d; join Ad, which will be the perpendicular required.




 When a perpendicular is to be made at or near the end of a given line.

Take any point n above ab, and with centre n and distance na, describe a circle, cutting the given line at b; through b and the centre n, draw the diameter bnc, and join ca, which will be the perpendicular required.



3. To do the same otherwise.


From the given point A, with any convenient radius, describe the arc d c b; with the same radius from d, cut the arc in d, and from d, cut the arc in d; also from d and d as centres, with the same or any other radius, describe arcs cutting each other in d; then will the line d d be the perpendicular required.



Note.—When the three sides of a triangle are in the proportion of 3, 4, and 5 equal parts respectively, two of the sides form a right angle; and observe that in each of the preceding problems, the perpendiculars may be continued below the given lines, if necessarily required.


4. To bisect any given angle.

From the point Δ as a centre, with any radius less than the extent of the angle, describe an arc, as cd; and from c and d as centres, describe arcs cutting each other at b; then will the line Δb bisect the angle as required.



5. To find the centre of a circle that shall cut any three given points, not in a direct line.


From the middle point b as a centre, with any radius, as bc, bd, describe a portion of a circle, as csd; and from r and t as centres, with an equal radius, cut the portion of the circle in c, s and d, v; draw lines through where the arcs cut each other, and the



intersection of the lines at o is the centre of the circle required.

6. To find the centre of a given circle.

Bisect any chord in the circle, as AB, by a perpendicular CD; bisect also the diameter ED in f, and the intersection of the lines at f is the centre of the circle required.



7. To find the length of any given arc of a circle.


With the radius AC, equal to $\frac{1}{4}$ th the length of the chord of the arc AB, and from A as a



centre, cut the arc in c; also from B as a centre, with equal radius, cut the chord in b; draw the line c b, and twice the length of the line is the length of the arc nearly.

8. Through any given point, to draw a tangent to a circle.

Let the given point be at A; draw the line A C, on which describe the semicircle A D C; join A D, which, produced if necessary, is the tangent required.




9. To draw from, or to the circumference of a circle,

lines tending towards the centre, when the centre is inaccessible.

Divide the whole or any given portion of the circumference into the desired number of equal parts;

then with any radius less than the distance of two divisions, describe arcs cutting each other, as Al, Bl, C2, D2, &c.; draw the lines




c1, B2, D3, &c., which lead to the centre as required.

To draw the end lines,

As Ar, Fr, from c describe the arc r, and with the radius cl, from A or F as centres, cut the former arcs at r, or r, and the lines Ar, Fr, will tend to the centre as required.

10. On a given straight line, to describe an arc of a circle, the altitude being given.

Let DE be the given straight line, Bb the given altitude: join DB, BE, and of any suitable material




construct a triangle, as ABC, making each of the sides AB, BC, equal at least to the chord DE, and the angle contained by them equal to DBE; at each end of the chord DE, fix a pin, and at B a tracer, as a pencil; move the triangle along the pins as guides, and the tracer will describe the arc required.

11. To describe an ellipse, having the two diameters

given.


On the intersection of the two diameters as a centre, with a radius equal to the difference of the semi-diameters, describe the arc ab, and from b as a centre, with half the chord bca, describe the arc cd; from o,



as a centre, with the distance od, cut the diameters in d, r, d, t; draw the lines rs, rs, ts, ts, then from r and t describe the arcs ss, ss; also from d and d describe the smaller arcs ss, ss, which will complete the ellipse as required.

12. To describe an elliptic arch, the width and rise of span being given.


Bisect with a line at right angles the chord or span AB, erect the perpendicular Aq, and draw the line qD equal and parallel to AC; bisect AC and Aq in r and n, make Cl equal to CD, and draw the line lrq;



draw also the line $n \cdot s \cdot D$; bisect $s \cdot D$ with a line at right angles, and meeting the line $c \cdot D$ produced in g; draw the line $g \cdot q$, make $c \cdot P$ equal to $c \cdot k$, and draw the line $g \cdot P \cdot i$; then from g as a centre, with the radius $g \cdot D$, describe the arc $s \cdot D \cdot i$, and from k and P as centres, with the radius $A \cdot k$, describe the arcs $A \cdot S$ and $B \cdot i$, which completes the arch as required. Or,

13. Bisect the chord AB, and fix at right angles any straight guide, as bc; prepare of any suitable


material a rod or staff, equal to half the chord's length, as def; from the end of the staff, equal to the height of the arch, fix a pin e, and at the extremity a tracer f; move the staff, keeping its end



to the guide and the fixed pin to the chord, and the tracer will describe one-half the arch required.

14. To describe a parabola, the dimensions being given.


Let AB equal the length, and CD the breadth of the required parabola: divide CA, CB into any



number of equal parts, also divide the perpendiculars Aa and Bb into the same number of equal parts; then from a and b draw lines meeting each division on the line ACB, and a curve line drawn through each intersection will form the parabola required.

15. To obtain by measurement the length of any direct line, though intercepted by some material object.


Suppose the distance between A and B is required, but the right line is intercepted by the object c. On the point d, with any



convenient radius, describe the arc cc, make the arc twice the radius in length, through which draw the line dcc, and on e describe another arc equal in length to once the radius, as eff; draw the line efr equal to efd; on r describe the arc jj, in length twice the radius; continue the line through r, j, which will be a right line, and dc, or cc, will equal the distance between dc, dc, by which the distance between dc and dc is obtained as required.


16. To ascertain the distance geometrically, of any inaccessible object on an equal plane.

Let it be required to find the distance between A and B, A being inaccessible: produce the line in the direction of AB to any point, as D; draw the line Dd at any angle to the line AB; bisect the line Dd in c, through which draw the line Bb, making cb equal to Bc; join Ac, and draw dba meeting Ac, produced in a. Then ba, equal to AB, is the distance required.



17. Or otherwise,


Produce A B to any point D, and bisect BD in C; through D draw Da, making any angle with DA, and take Dc, Db, equal to DC and DB respectively; join Bc, Cb, and Ab. Through E, the intersection of Bc, Cb, draw DEF meeting Ab in



F; join BF, which being produced will meet D a in a. Then a b is equal to A B, the distance required.

18. To measure the distance between two objects, both being inaccessible.


From any point c draw any line cc, and bisect it in D; take any point E in the prolongation of AC, and draw the line Ee, making De equal to DE; in like manner take any point F in the prolongation of BC, and make Df equal to FD. Produce AD and ec till they meet in a, and also BD and fc till they meet in b; then ab is



equal to AB, or the distance between the objects as required.

19. A round piece of timber being given, out of which to cut a beam of strongest section.


Divide into three equal parts any diameter in the circle, as Ad, eC; from d or e, erect a perpendicular meeting the circumference of the circle, as dB; draw AB and BC, also AD equal to BC, and DC equal to AB, and the rectangle will be a section of the beam as required.



20. To find the proper position for an eccentric, in relation to the crank in a steam engine, the angle

of eccentric rod and travel of the valve being given.


Draw the right line A B, as the situation of the crank at commencement of the stroke; draw also the line c d, as the proper given angle of eccentric rod with the crank; then from c as centre, describe a circle



equal to the travel of the valve; draw the line ef at right angles to the line cd; draw also the lines 1 1, and 2 2, parallel to the line ef; and at a distance from ef on each side, equal to the lap and lead of the valve, draw the angular lines c1, c2, which are the angles of eccentric with the crank, for forward or backward motion, as may be required.

21. The throw of an eccentric, and the travel of the valve in a steam engine, also the length of one lever for communicating motion to the valve, being given, to determine the proper length for the other.

On any right line, as AB, describe a circle A D, equal to the throwofeccentric & travel of valve; then from C as a



centre, with a radius equal to the length of lever given, cut the line AB, as at d, on which describe a circle, equal to the throw of eccentric or travel of valve, as may be required; draw the tangents Ba, Ba, cutting each other in the line AB, and dB is the length of the lever as required.


Note.—The throw of an eccentric is equal to the sum of twice the distance between the centres of formation and revolution, as a b, or to the degree of eccentricity it is made to describe, as c d. And

The travel of a valve is equal to the sum of the widths of the two steam openings, and the valve's excess of length more than just sufficient to cover

the openings.

22. To inscribe any regular polygon in a given circle.


Divide any diameter, as A B, into so many equal parts as the polygon is required to have sides; from A and B as centres, with a radius equal to the diameter, describe arcs cutting each other in C; draw the line C D through e, the second point of division on the diameter, and the line D B is one side of the polygon required.



a b


23. To construct a square upon a given right line.

From A and B as centres, with the radius AB, describe the arcs Acb, Bcd, and from c with an equal radius describe the circle or portion of a circle edABbc; from b, d, cut the circle at e and c; draw the lines Ae, Bc, also the line st, which completes the square as required.



24. To form a square equal in area to a given triangle.


Let ABC be the given triangle: let fall the perpendicular Bd, and make Ae half the height dB; bisect eC,



and describe the semicircle enc; erect the perpendicular As, or side of the square, then Asts is the square of equal area as required.

25. To form a square equal in area to a given rectangle.

Let the line AB equal the length and breadth of the given rectangle: bisect the line in e, and describe the semicircle ADB; then from




A with the breadth, or from B with the length of the rectangle, cut the line AB at c, and erect the perpendicular cD, meeting the curve at D, and CD is equal to a side of the square required.

26. To find the length for a rectangle whose area shall be equal to that of a given square, the breadth of the rectangle being also given.

Let ABCD be referenced by the given square, and DE the given breadth pofrectangle. Through E draw EF parallel to AB or DC; produce BC to F, and join DF.

Through A draw Ag




parallel to $\hat{\mathbf{D}} \mathbf{F}$, cutting $\mathbf{D} \mathbf{C}$ produced in g, through which draw g d parallel to $\mathbf{D} \mathbf{E}$, meeting $\mathbf{E} \mathbf{F}$ produced in d. $\mathbf{E} \mathbf{D} g d$ is the rectangle required.

27. To bisect any given triangle.


Suppose ABC the given triangle: bisect one of

its sides, as AB in e, from which describe the semicircle ArB; bisect the same in r, and from B, with the distance Br, cut the diameter AB in v; draw the line vy parallel to AC, which will bisect the triangle as required.



28. To describe a circle of greatest diameter in a given triangle.


Bisect the angles A and B, and draw the intersecting lines A D, B D, cutting each other in D; then from D as centre, with the distance D C,



which is drawn perpendicular to AB, describe the circle cef, as required.


29. To form a rectangle of greatest surface, in a given triangle.

Let ABC be the given triangle: bisect any two of its sides, as AB, BC, in e and d; draw the line ed; also at right angles with the line ed, draw the lines ep, dp, and eppd is the rectangle required.



30. To make a rectangle equal to a given triangle


Suppose A B C the given triangle: bisect A B in d, and erect the perpendicular de; erect also the perpendicular Bn; through C draw the line e C n parallel to A B, meeting the above in e and n respec-



tively; then ed B n is the rectangle as required.


31. To make a triangle equal to a given quadrilateral, as ABCD.

Prolong the line BA, and draw the line AC; draw also the line DE parallel to AC, and cutting the line BA in E; then draw the line EC, and CEB is the triangle required.




32. To form a square nearly equal in area to a given circle.

Let ACBD be the given circle: draw the diameters AB and CD at right angles to each other, bisect the radius dB in e, and draw the line Cef; draw also at right angles the lines Cn and fr, making each equal to Cf; join nr, and n Cfr is the square as required.



Note.—The line of is equal to one-fourth the circumference of the circle.

- 33. To inscribe or describe a square within or without a given circle: also to form an octagon from a given square.
- 1. Let ABCD be the given circle: draw the diameters AC, BD, at right angles to each other, and join AB, BC, CD, DA, which will complete the inscribed square: through the extremities of the same diameters draw ab, cd, parallel



to BD, and ad, bc, parallel to AC, which will complete the square equal in breadth to the diameter of the circle.

2. Let ABCD be the given square. Draw the two diagonal lines AC and BD


two diagonal lines AC and BD intersecting in 0; then with a radius equal to AO, or half the diagonal, and with A as a centre, describe the arc EF, cutting the sides of the square in E and F; then from B as a centre, describe the arc GH, and in the same



manner from c and D describe the arcs I K and L M. Draw the lines L G, F I, H M, and K E, which, with the parts G F, I H, M K, and E L, form the octagon required.

34. To form a square equal to two given squares, or, a circle equal to two given circles.

Let AB, AC, equal the sides of the given squares, or diameters of the given circles: make the angle at A a right angle, and draw the line CB, which is the side of a square equal to both the given squares; or bisect the line CB as a diameter, on which describe the circle CBA, which is equal to the




circle CBA, which is equal to the two given circles as required.

35. To draw a right line equal to any given portion of the circumference of a circle.

Let ABCD be a given circle, the whole circum-


ference of which is required:
draw at right angles the diameters AC, BD, divide the radius aC into four equal parts, and make Cb equal to three of them; draw the tangent Ad parallel to BD, draw the line bDd, then will Ad equal one-fourth of the



whole circumference; and if lines be drawn from b, through points in the circumference, meeting the line Ad, as gg, hh, &c., the corresponding parts will be equal to each other.

36. To draw a spiral with spaces of uniform distance.


Bisect the height of the spiral, as AB, and divide either half into the number of spaces or revolutions required; then again subdivide any one space into four equal parts, one of which add to half the height of the spiral, and through which draw the line CD at right angles to AB, thus form-



ing the centre of the spiral, around which and equal to one of the subdivisions form a square, its sides being parallel with the lines AB and CD, the angles of which are the centres from whence to describe the various curves; as from 1, with the distance 1B, describe the curve BD; from 2, with the distance 2D, describe DA; from 3, with the distance 3A, describe AC, &C., &C., and from the same centres the spiral may be continued to any extent required.

37. To draw a volute for the capital of the Ionic column.


Draw at right angles CA, CB, and on the centre C describe a circle equal to one-fourth of the height CB; form a square in the circle, the diagonals of which correspond with or cut the diameters AD, EB; bisect the square with lines crossing each other in the centre C, and parallel with the sides of the square; di-



vide each into six equal parts, which are the centres from which the volute is to be described: thus, from 1, with the distance 1 B, describe the curve BD; from 2, with 2 D, describe DE; from 3, with 3 E, describe EA, &c., approaching the centre by degrees until the volute is completed as required.

38. To draw a scroll for the termination of a handrail, &c.

Let AB equal the given breadth: draw AE perpendicular to AB, which divide into eleven equal parts, and AE equal to one of them; join BE, bisect AB in c and BE in F, make CD equal to CF, and draw DG perpendicular to AB; from F, with the radius FE, or FB, describe an arc cutting




DG at G; draw GH perpendicular to BE, cutting BE at O (or centre of the scroll); draw the diagonals

DOK, IOL, perpendicular to DOK; draw IK parallel to BA, KL parallel to ID, &c., meeting the diagonals; from D as a centre, with the distance DB, describe the arc BG; from I as a centre, with the distance IG, describe GE; from K, with the distance KE, describe KH, &c., proceeding in the same manner until the outside of the scroll is completed; make BR equal to the breadth of the rail; then from D, with the distance DR, describe the arc RS; from I, and distance IS, describe ST; and from T, with KT, describe TU, which completes the scroll as required.

39. To find the various angles and proper dimensions of materials whereby to construct any figure whose form is the frustum of a proper or inverted pyramid, as hipped roofs, mill hoppers, &c., &c.


Let A B C D be the given dimensions of plan for a roof, the height R T also being given; draw the diagonal A R, meeting the top or ridge R s on plan; from R, at right angles with A R and equal to the required




height, draw the line RT, then TA, equal the length of the struts or corners of the roof; from A, with the distance AT, describe an arc T, continue the diagonal AR until it cuts the arc T, through which, and parallel with the ridge Rs, draw the line mn, which determines the required breadth for each side of the roof: from A, meeting the line mn, draw the line n, or proper angle for the end of each board by which the roof might require to be covered; and the angle at T is what the boards require to be made in the direction of their thickness, when the corners or angles require to be mitred.

40. To describe the proper form of flat plate by which to construct any given frustum of a cone.

Let ABCD represent the required frustum: continue the lines AD and BC until they meet at E; then from E as centre, with the radius EC, describe the arc CH; also from E, with the radius EB, describe the arc BI; make BI equal in length to twice AGB, draw the line EI, and BCIH is the form of plate as required.






Sector from which angles may be obtained.

GEOMETRY APPLIED TO MECHANICS.

41. To delineate a vee-threaded screw, the pitch and diameter of the screw being given. (See Plate A, fig. 1.)

Upon the end of the line, or vertical centre of the screw AB, describe the semicircles CD, cd, the one being equal to the greatest diameter of the screw, and the other to the lesser diameter, or diameter at the bottom of the threads; divide each semi-circumference





into any number of equal parts, as c, e, f, g, h, i, D, from which draw lines parallel to the line AB; divide the lines CF, DF, into equal divisions of half the required pitch or consecutive threads, as t, r, v, &c.; draw the lines tt, rr, vv, &c., parallel with the diameter cD, and subdivide any two connected divisions into the same number of equal parts contained in both semicircles, from which draw lines meeting the vertical lines; then by hand, or otherwise, and through the intersections, draw the waved lines, m, n, p, q, &c., and a thread of the screw is delineated as required.

Note.—The same process might be continued throughout the whole length of the screw, but it is much more convenient, when the proper curves are obtained, to form a suitable ruler: lay it in its proper situation upon each division, and draw the lines as required.

42. To delineate a square-threaded screw, the pitch and diameter of screw being given. (See Plate A, fig. 2.)


of the thread; describe also the curves k and b, which terminates the returning thread, and completes the delineation as required.

Fig. 3, as to mode of construction, is exactly similar to that of fig. 2, but intended, by displacement of the cylinder, to delineate a continuous vein of the spiral in its proper form around the whole circumference: hence, being deemed by the preceding figure already sufficiently described, further elucidation must be considered unnecessary.


43. To determine the proper forms for a pair of bevel wheels, the required angle of the shafts and diameters of the wheels being given.

Draw at the given angles lines representing the shafts on which the wheels are to be fixed, as A B,

A C; make the lines ab, ac, parallel with and at a distance from AB, AC, equal to the radius of each respective wheel at the greatest pitch circle; draw the line Aa through the intersection at d; then from a at right angles



with AB, AC, draw the lines ae, af, making each in length equal to the wheel's diameter; draw the lines Ae, Af, and from a, with the intended breadth of the wheels on the face, cut the line Aa in d; draw the lines di, dg, parallel to ae, af, (hence the proper conical forms of the wheels and the pitch circles;) draw at right angles with Aa, and through the intersection of the lines ae, af, the line CB, also the lines ae, af, the line CB, also the lines ae, af, af



Builished by Alm Raise is thinh living 1833.



the radius Ba, Ca, describe portions of circles, as aG, aH, on which describe the greatest dimensions of, and proper form of the teeth; then from d, and parallel with AB, AC, draw the lines av, ax, cutting the line CB in v and x; from B and C, with the distances c v, B x, describe the portions of circles, which determines the dimensions of the teeth on the interior pitch circle, and completes the proper forms of the wheels as required.

Proportions for the construction of toothed wheels.

Length of the teeth $= \frac{\pi}{4}$ of the pitch.

Thickness

Breadth on face $= 2\frac{1}{4}$ times the pitch.

Edge of the rim

Projecting rib inside do. > each 4 of the pitch.

Thickness of flat arms

Breadth of arms at rim = 2 teeth and \(\frac{1}{2} \) the pitch, increasing in breadth towards the centre of the wheel, in the proportion of 1 an inch for every foot in length.

Thickness of the ribs or feathers on the arms = 1

of the pitch.

Thickness of metal around the eye, or centre, $= \frac{7}{4}$ of the pitch.


Wheels and other circular bodies are very conveniently transferred from plan to that of a projected perspective by means of a peculiar appropriation of straight lines, commonly called orthographic projection, the principle of which will be readily understood by reference to the diagrams and illustrations given for the purpose in Plate C.

Fig. 1 is a circle divided into equal parts, and its form in projection is required, vn being supposed the line of intersection: parallel with the diameter of the


circle bf, draw at right angles, and through the centre, the line ce; draw also the line or chord fg, cutting the line vn in g; then, with the distance vg, describe the quadrant irs; bisect the arc in r, from which and parallel with vn, draw the line rt; draw also the lines ft, gt, which determines the breadth of the ellipsis or projected form of the circle, and which may be drawn as described (page 5, fig. 12): hence all the other lines being so distinctly described, by mere inspection of the diagrams, further explanation is unnecessary.

Fig. 2 is a projected representation of an undershot water-wheel, of which n is the plan, vn the line of intersection, and n the diameter and breadth, laid at a proper angle or inclination, as determined by the principles of the diagrams: the breadth of the ellipsis is found and formed as there described, and the lines in the illustration, or fig. 2, whereby to obtain the proper angles for projection, render sufficiently explicit the proper mode by which the representation is effected.

ORTHOGRAPHIC PROJECTION.



Rublished by John Weale St. High Helbern 1863.



DECIMAL ARITHMETIC.

DECIMAL ARITHMETIC is the most simple and explicit mode of performing practical calculations; on account of its doing away with the necessity of fractional parts in the fractional form, thereby reducing long and tedious operations to a few figures, arranged and worked in all respects according to the usual rules of common arithmetic.

Decimals simply signify tenths: thus, the decimal of a foot is the tenth part of a foot, the decimal of that tenth is the hundredth of a foot, the decimal of that hundredth is the thousandth of a foot, and so might the divisions be carried on and lessened to infinity; but in practice it is seldom necessary to take into account any degree of less measure than a onehundredth part of the integer or whole number. And, as the entire system consists in supposing the whole number divided into tenths, hundredths, thousandths, &c., no peculiarity of notation is required, otherwise than placing a mark or dot, to distinguish between the whole and any part of the whole: thus 34.25 gallons signify 34 gallons 2 tenths and 5 hundredths of a gallon; 11.04 yards signify 11 yards and 4 hundredths of a yard; 16.008 shillings signify 16 shillings and 8 thousandth parts of a shilling: from which it must appear plain, that ciphers on the right hand of decimals are of no value whatever; but placed on the left hand, they diminish the decimal value in a tenfold proportion,—for 6 signifies 6 tenths; 06 signifies 6 hundredths; and 006 signifies 6 thousandths, of the integer or whole number.

REDUCTION.

Reduction means the construing or changing of

vulgar fractions to decimals of equal value; also finding the fractional value of any decimal given.

Rule 1. Add to the numerator of the fraction any number of ciphers at pleasure, divide the sum by the denominator, and the quotient is the decimal of equivalent value.

Rule 2. Multiply the given decimal by the various fractional denominations of the integer or whole number, cutting off from the right hand of each product for decimals a number of figures equal to the given number of decimals, and thus proceed until the lowest degree, or required value, is obtained.

Ex. 1. Required the decimal equivalent, or decimal

of equal value, to 3 of a foot.

$$\frac{3.00}{12}$$
 = .25, the decimal required.

Ex. 2. Reduce the fraction $\frac{1}{8}$ of an inch to a decimal of equal value.

$$\frac{1.000}{8}$$
 = .125, the decimal required.

Ex. 3. What is the decimal equivalent to $\frac{7}{6}$ of a gallon?

$$\frac{7.000}{8}$$
 = .875, the decimal equivalent.

Ex. 4. Required the value of the decimal '40625 of an inch.

 $1.000000 \frac{s}{8}$ and $\frac{1}{89}$ of an inch, the value required.

Ex. 5. What is the value of .625 of a cwt.?

Ex. 6. Ascertain the value of 875 of an imperial gallon.

Ex. 7. What is the value of .525 of a £. sterling?

Multiply by 20 sh. 20 10.500× 12 pence 12 6.000 = 10 shillings and 6 pence, the value

Independent of the mark or dot which distinguishes between integers and decimals, the fundamental rules, viz., Addition, Subtraction, Multiplication, and Division, are in all respects the same as in Simple Arithmetic; and an example in each, illustrative of placing the separating point, will no doubt render the whole system sufficiently intelligible, even to the dullest capacity.

required.

Ex. 1. Add into one sum the following integers and decimals.

16.625; 11.4; 20.7831; 12.125; 8.04; and 7.002.

16.625
11.4
20.7831
12.125
8.04
7.002
75.9751 = the sum required.

Ex. 2. Subtract 119.80764 from 234.98276.

234·98276 119·80764 115·17512 = the remainder required.

Ex. 3. Multiply 62·10372 by 16·732.

1039.11944304 = the product required.

Observe that the number of figures in the product from the right hand, accounted as decimals, are equal to the number of decimals in the multiplier and multiplicand taken together.

Ex. 4. Divide 39:375 by 9:25.

9.25)39.375(4.256 =the quotient required.

3/00	
2375	Observe that the number of deci-
1850	mals in the divisor and quotient
5250	together, must be equal to the
4625	number in the dividend.
6250	
5550	
700	

Note.—The operation might be still continued, so as to reduce the quotient to a degree of greater exactitude, but in practice it is quite unnecessary, being even now reduced to a measure of greater nicety than is commonly required.

Definitions of Arithmetical signs employed in the following calculations, which ought to be particularly attended to.

```
= sign of equality, and signifies equal to, as 3 added 4=7.
           addition
                                    plus or more, as 5+3=8.
           subtraction
                                    minus or less, as 8-3=5.
           multiplication
                                    multiplied by, as 8 \times 3 = 24.
                              ,,
     ,,
         division
                                    divided by, 24 + 4 = 6 or \frac{24}{3} = 6.
                             ,, that 2 is to 3 as 4 is to 6, &c. evolution, or the extr<sup>n</sup>. of roots;
           proportion
           square root ]
           cube root
                                    thus, \sqrt{64} = 8 and \sqrt[3]{64} = 4.
      ,,
           to be squared
                                    involution, or the raising of
                                      powers;
           to be cubed
                                    thus, 4^2 = 16, and 4^3 = 64.
                                   f that, 3 plus 5, or 8 multiplied
3+5 \times 4 = 32
                                      by 4 = 32.
\sqrt{5^2-3^2=4}
                  5 squared, minus 3 squared, the square root of
                                       the remainder = 4.
                 = 2, 20 multiplied by 12, and divided by 30, the
                         cube root of the quotient = 2.
```

2 stones

4 quarters, or 112 lbs.

20 cwt.

BRITISH STANDARD MEASURES. 1. Measures of length. 12 inches . = 1 foot. 3 feet . = 1 vard. 54 yards = 1 pole or rod. 40 poles = 1 furlong. 8 furlongs, 1760 yards, or 5280 feet . = 1 mile. 2. Measures of surface, or square measure. 144 square inches = 1 square foot. 9 square feet . . =1 square yard. 301 square yards . =1 square pole. = 1 rood. 40 square poles . 4 roods, or 4840 square yards = 1 acre. 3. Measures of solidity, or cubic measure. 1728 cubic inches = 1 cubic foot. 27 cubic feet . . = 1 cubic yard. 4. Measures of capacity. LIQUIDS. 8.665 cubic inches =1 gill. 4 gills = 1 pint. =1 quart. 2 pints . 4 quarts, or 2771 cubic inches = 1 gallon. GRAIN, FRUITS, &c. 2 gallons =1 peck. 4 pecks, or 2218·192 cubic inches = 1 bushel. 8 bushels = 1 quarter. = 1 load. 5 quarters . 5. Measures of weight. TROY. 24 grains = 1 pennyweight. 20 pennyweights . = 1 ounce. 12 ounces . . . = 1 pound. 27.34375 troy grains = 1 dram. 16 drams = 1 ounce. 16 ounces . = 1 pound. 14 pounds . = 1 stone.

=1 quarter.

=1 cwt.

=1 ton.

BRITISH SPECIAL MEASURES.

						***	ACCED.
1. Lineal measur	es :	for	·lo	nd			
7:92 inches							= 1 link.
7.92 inches 100 links or 22 ys	ırds					-	=1 chain.
80 chains						•	= 1 mile.
80 chains 69.121 miles	•	•	•	•	•	•	= 1 geog. degree.
	•					•	- 1 goog. degree.
2. Square measur	res	fo	r l	anc	l.		
62·7264 square in	che	8 .				•	= 1 square link.
10,000 square link							
10 square chains							= 1 acre.
3. Nautical meas							
6082:66 feet			_		_		= 1 nautical mile.
3 miles	• •	•	•	•	•	•	-1 league
3 miles 20 leagues 360 degrees	• •	•	•	• •	•	•	-1 degree
260 domes	•	•	•	•	•	•	= the earth's cir-
soo degrees .	•	•	•	•	•	•	cumference.
						_	
Miscel	lan	eo	u8	spe	cio?	ıl n	reasures.
6 lineal feet .						=1	fathom.
100 square feet		•				=1	fathom. square of flooring.
	1	-	·	-		_	
272 so, feet, at 14	in.	in	thi	ckn	ess	= 1	rod of brick-work.
272 sq. feet, at 14 600 square feet of	in.	in h l	thi	ckn rds	e88 -		
600 square feet of	inc	h t	oa	rds	•	= 1	load.
600 square feet of 40 cubic feet of ro	inc und	h t l tir	ooa nbe	rds er (•	= 1	
600 square feet of 40 cubic feet of ro 50 cubic feet of he	inc und wn	h t l tir tin	ooa: nbe	rds er } er }	•	= 1 = 1	load. ton or load.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet	inc und wn	h t l tir tin	nbe	rds er } er }	•	=1 =1 =1	load. ton or load. ton of shipping.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals	inc und wn	h t l tir tin	nbe	rds er } er }	•	=1 =1 =1 =1	load. ton or load. ton of shipping. hundred.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals 120 nails	inc und wn	h t l tir tin	nbe	rds er } er }	•	=1 =1 =1 =1	load. ton or load. ton of shipping. hundred. hundred.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet . 120 deals . 120 nails .	inc und wn	h t l tir tin	nbe	rds er } er }	•	=1 =1 =1 =1 =1	ton or load. ton of shipping. hundred. hundred. thousand.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals 120 nails 1200 do.	inc und wn	h tin tin	nbe	rds er } er }		=1 =1 =1 =1 =1	ton or load. ton of shipping. hundred. thousand. load.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals 120 nails 1200 do.	inc und wn	h tin tin	nbe	rds er } er }		=1 =1 =1 =1 =1 =1	ton or load. ton of shipping. hundred. hundred. thousand. load. do.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals 120 nails 1200 do.	inc und wn	h tin tin	nbe	rds er } er }		=1 =1 =1 =1 =1 =1	ton or load. ton of shipping. hundred. hundred. thousand. load. do. do.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals 120 nails 1200 do.	inc und wn	h tin tin	nbe	rds er } er }		=1 =1 =1 =1 =1 =1	ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet . 120 deals . 120 nails . 1200 do 500 bricks . 32 bushels of lime 36 do. sand 19½ cwt 108 cubic feet .	inc und wn	h l l tir tim	nbe	rds er }		=1 =1 =1 =1 =1 =1	load. ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood.
600 square feet of 40 cubic feet of ro 50 cubic feet of ne 40 cubic feet. 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. sand 19½ cwt. 108 cubic feet. 42 gallons	inc und wn	h l tir tim	ooan nbe	rds er }			ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet. 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. sand 19½ cwt. 108 cubic feet 42 gallons 63 do	inc und wn	h l l tir tin	nbe	rds er }		=1 =1 =1 =1 =1 =1 =1 =1	ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce. hogshead old
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet. 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. sand 19½ cwt. 108 cubic feet 42 gallons 63 do	inc und wn	h l l tir tin	nbe	rds er }			ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce. hogshead old puncheon wine
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. 19½ cwt. 108 cubic feet 42 gallons 63 do. 126 do. 126 do.	inc und wn	h l l tir tin	nbe	rds er }			ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce. hogshead puncheon wine pipe measure.
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. 19½ cwt. 108 cubic feet 42 gallons 63 do. 126 do. 126 do.	inc und wn	h l l tir tim	nbe	rds er }			ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce. hogshead puncheon pipe tun
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet. 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. sand 19½ cwt. 108 cubic feet 42 gallons 63 do. 126 do. 126 do. 36 do. 36 do.	inc und wn	h l l tir tin	ooanbee	rds er }			ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce. hogshead puncheon pipe tun barrel
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet. 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. sand 19½ cwt. 108 cubic feet 42 gallons 63 do. 126 do. 126 do. 36 do. 36 do.	inc und wn	h l l tir tin	ooanbee	rds er }			ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce. hogshead puncheon pipe tun barrel
600 square feet of 40 cubic feet of ro 50 cubic feet of he 40 cubic feet. 120 deals 120 nails 1200 do. 500 bricks 32 bushels of lime 36 do. sand 19½ cwt. 108 cubic feet 42 gallons 63 do. 126 do. 126 do. 36 do. 36 do.	inc und wn	h l l tir tin	ooanbee	rds er }			ton or load. ton of shipping. hundred. hundred. thousand. load. do. do. fother of lead. stack of wood. tierce. hogshead puncheon pipe tun

DECIMAL APPROXIMATIONS FOR FACILIT CALCULATIONS IN MENSURATION.

Lineal feet multipl	lied by	.00019	= miles.
,, yards	,,	·0005 6 8	= ,,
Square inches	"	.007	=square feet.
,, yards	,,	.0002067	=acres.
Circular inches	"	·00546	= square feet.
Cylindrical inches	"	.0004546	= cubic feet.
,, feet	"	· 0 2909	=cubic yards.
Cubic inches	"	.00058	= cubic feet.
" feet	"	.03704	= cubic yards.
" "	,,	6.232	=imperial gall
,, inches	"	.003607	= ',, ',
Cylindrical feet	"	4.895	= ", ",
inches	"	·002832	= ", ",
Cubic inches	"	.263	=tbs. avs. of ca
,, ,,	"	.281	= ,, wroug
" "	"	·283	= ,, steel.
" "	,,	.3225	= " copper
""	"	·3037	= ,, brass.
" "	,,	·26	= ,, zinc.
,, ,,	"	·4103	= ,, lead.
" "	,,	.2636	= ,, tin.
" " "	"	·4908	= " mercu
Cylindrical inches	"	.2065	= ,, cast in
,,	"	·2168	= ,, wrougl
"	,,	.2223	= ,, steel.
"	"	·2533	= ,, copper
"	,,	.2385	= ,, brass.
"	"	.2042	= ,, zinc.
"	"	.3223	= ,, lead.
" "	"	.207	= ,, tin.
"	"	.3854	= ,, mercu
Avoirdupois lbs.	"	.009	= cwts.
	"	.00045	=tons.

DECIMAL EQUIVALENTS TO FRACTIONAL PARTS OF LINEAL MEASURES.

One inch,	the integer or who	e number.
96875	-625 -59375 -5625 -53125 -53125 -46875 -46875 -4375 -40625 -375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34375 -34468 -34468 -34468 -34468 -34468 -34468 -34468 -34468 -34468 -34468 -34468 -34468 -34468 -34688 -346	-28125 -25 -21875 -1875 -18625 -125 -09375 -0625 -03125
	t, or 12 inches, the	integer.
9166 9 11 inches. -6338 9 10 ", -75 18 9 ", -6666 9 8 ", -5833 p 7 ", -5 6 ",	·4166	·0625
One yaı	d, or 36 inches, the	integer.
9722 35inches. 9444 34 " 9167 33 " 8889 23 " 8611 31 " 8333 30 " 8056 229 " 7778 228 " 7522 26 " 6944 25 "	6389 23inches. 6111 22 " 5833 21 " 55556 20 " 5278 219 " 54722 2717 " 4444 216 " 4167 215 " 3889 14 " 3611 13 " 3333 12 "	-3055 11inches -2778 10 " -25 9 " -2222 S 8 " -1944 7 7 " -1667 5 6 " -1389 5 5 " -1111 2 4 " -0833 3 " -0555 2 " -0278 1 "

MENSURATION.

MENSURATION is that branch of Mathematics which is employed in ascertaining the extension, solidities, and capacities of bodies, capable of being measured.

1. MENSURATION OF SURFACE.

To measure or ascertain the quantity of surface in any right-lined figure whose opposite sides are parallel to each other, as a

Square,	Rectangle,	Rhomboid,	
			/kc.

Rule.—Multiply the length by the breadth; the product is the area or superficial contents.

Application of the rule to practical purposes.

1. The side of a square piece of board is $8\frac{3}{16}$ inches in length; required the area or superficies.

Decimal equivalent to the fraction $\frac{1}{16}$ = 1875 (see page 31); and $8\cdot1875 \times 8\cdot1875 = 67\cdot03515625$ square inches, the area.

2. The length of the fire-grate under the boiler of a steam engine is 4 feet 7 inches, and its width 3 feet 6 inches; required the area of the fire-grate.

7 in. = $\cdot 5833$ and 6 in. = $\cdot 5$ (see Table of Equivalents, p. 31): hence $4 \cdot 5833 \times 3 \cdot 5 = 16 \cdot 04155$ square feet, the area.

3. Required the number of square yards in a floor whose length is 13½, and breadth 9½ feet.

 $13.5 \times 9.75 = 131.625 + 9 = 14.625$ square yards.

- Note 1.—The above rule is rendered equally applicable to figures whose sides are not parallel to each other, by taking the mean breadth as that by which the contents are to be estimated.
- 2. The square root of any given sum equals the side of a square of equal area.

3. Any square whose side is equal to the diagonal of another

square, contains double the area of that square.

4. Any sum or area (of which to form a rectangle) divided by the breadth, the quotient equals the length; or divided by the length, the quotient equals the breadth of the rectangle required.

TRIANGLES.

Any two sides of a right-angled triangle being given, to find the third side.

Rule 1.—Add together the squares of the base and perpendicular, and the square root of the sum is the

hypotenuse or longest side.

Rule 2.—Add together the hypotenuse and any one side, multiply the sum by their difference, and the square root of the product equals the other side.

Application to practical purposes.


- 1. Wanting to prop a building with raking shores, the top ends of which to be 25 feet from the ground, and the bottom ends, 16 feet from the base of the building; what must be their length, independent of any extra length allowed below the surface of the ground?
- $25^{2}+16^{2}=\sqrt{881}=29.6816$ feet, or $.6816 \times 12=8$ inches; consequently, 29 feet 8 inches nearly.
- From the top of a wall 18 feet in height, a line was stretched across a canal for the purpose of ascer-

taining its breadth; the length of the line, when measured, was found to be 40 feet; required the breadth from the opposite embankment to the base of the wall.

40-18=22, and $40+18\times 22=\sqrt{1276}=35.72$, or 35 feet 9 inches nearly, the width of the canal.

Triangles similar to each other are proportional to each other; hence their utility in ascertaining the heights and distances of inaccessible objects.


Thus, suppose the height of an inaccessible object D is required, I find by means of two staffs or otherwise, the height of the perpendicular B C and the length of the



base line AB; also the distance from A to the base of the object GD;

then AB: BC:: AG: GD. And suppose AB=6 feet, BC=2 feet, and AG=150; 6:2::150:50 feet, the height of D from G.

Again, suppose the inaccessible distance A be required, make the line BA, BC, at right angles, and BC of three or four equal parts of any convenient distance, through one of which and in a line with the object A, determine the triangle CDF, then the proportion will be as




CF:CD::BF:BA. Let CF=10 yards, CD=53, and BF=30, 10:53::30:159 yards, the distance from B.

To find the area of a triangle when the base and perpendicular are given.

Rule.—Multiply the base by the perpendicular height, and half the product is the area.

1. The base of the triangle ADB is $11\frac{3}{32}$ inches in length, and the height DC, $3\frac{3}{3}$ inches; required the area.



$$\frac{3}{39}$$
 = .09375 and $\frac{3}{8}$ = .375 (see page 31):
hence $\frac{11.09375 \times 3.375}{2}$ = 18.72075 square inches, the area.

2. The base of a triangle is 53 feet 3 inches, and the perpendicular 7 feet 9 inches; required the area or superficies.

$$\frac{53.25 \times 7.75}{2}$$
 = 206.34375 square feet, the area.

When only the three sides of a triangle can be given, to find the area.

Rule.—From half the sum of the three sides, subtract each side severally; multiply the half sum and the three remainders together, and the square root of the product is equal to the area required.

Required the area of a triangle whose three sides are respectively 50, 40, and 30 feet.


$$\frac{50+40+30}{2} = 60$$
, or half the sum of the three sides.

$$60-30=30$$
, first difference,

$$60-40=20$$
, second difference,

60-50=10, third difference; then $30 \times 20 \times 10 \times 60 = \sqrt{360000} = 600$, the area required.

Triangles are employed to great advantage in determining the area of any rectilineal figure, as the annexed, and by which the measurement is rendered comparatively simple.



POLYGONS.

Polygons being composed of triangles, may of course be similarly measured: hence in regular polygons, multiply the length of a side by the perpendicular height to the centre, and by the number of sides, and half the product is the area.

	Š.	Angle	Angle	Perpen.	Length of side, radius	H .2	Radius of circle, per.	Area, side
Name.	sides.	centre.	circum.	being 1.	being 1.	being 1.	being 1.	being 1.
Triangle .	ဗ	120°	.09	0.2886	1.73	.579	2	0.4330
Square	4	06	96	0.2	1.412	.705	1-41	_
Pentagon.	2	72	108	0.6882	1.174	.825	1.238	1.7204
Hexagon .	9	09	120	0998-0	_	-	1.156	2.5980
Heptagon.	1	513	128	1.0382	498.	1.16	1:11	3.6339
Octagon .	80	45	135	1.2071	.765	1.307	1.08	4.8284
Nonagon .	6	40	140	1.3737	.681	1.47	1.062	6.1818
Decagon .	10	36	144	1.5388	.616	1.625	1.05	7.6942
Undecagon	11	324		147 th 1.7028	.561	1.777	1.04	9.3656
Dodecagon	12	30	150	1.8660	.516	1.94	1.037	11-1961

Application of the Table.

1. The radius of a circle being 6½ feet, required the side of the greatest heptagon that may be inscribed therein.

 $\cdot 867 \times 6 \cdot 5 = 5 \cdot 6355$, or 5 feet $7\frac{1}{4}$ inches nearly.

2. Each side of a pentagon is required to be 9 feet; required the radius of circumscribing circle.

 $852 \times 9 = 7.668$, or 7 feet 8 inches.

3. A perpendicular from the centre to either side of an octagon is required to be 12 feet; what must be the radius of circumscribing circle?

 $1.08 \times 12 = 12.96$, or 12 feet $11\frac{1}{4}$ inches.

4. Each side of a hexagon is 4½ yards; required its superficial contents.

 $4\frac{1}{2} \times 2.598 = 52.6095$ square yards.

THE CIRCLE AND ITS SECTIONS.

Observations and definitions.

- 1. The circle contains a greater area than any other plane figure bounded by the same perimeter or outline.
- 2. The areas of circles are to each other as the squares of their diameters; any circle twice the diameter of another contains four times the area of the other.
- 3. The radius of a circle is a straight line drawn from the centre to the circumference, as OB.
- 4. The diameter of a circle is a straight line drawn through the centre, and terminated both ways at the circumference, as COA.



- 5. A chord is a straight line joining any two points of the circumference, as D F.
- 6. The versed sine is a straight line joining the chord and circumference, as E G.
 - 7. An arc is any part of the circumference, as CDE.
- 8. A semicircle is half the circumference cut off by a diameter, as C E A.
- 9. A segment is any portion of a circle cut off by a chord, as D E F.
- 10. A sector is a part of a circle cut off by two radii, as A O B.

General rules in relation to the circle.

- 1. Multiply the diameter by 3.1416, the product is the circumference.
- 2. Multiply the circumference by '31831, the product is the diameter.
- 3. Multiply the square of the diameter by .7854, the product is the area.
- 4. Multiply the square root of the area by 1.12837, the product is the diameter.
- 5. Multiply the diameter by 8862, the product is the side of a square of equal area.
- 6. Multiply the side of a square by 1.128, the product is the diameter of a circle of equal area.

Application of the rules as to purposes of practice.

1. The diameter of a circle being $7\frac{3}{16}$ inches, required its circumference.

 $7.1875 \times 3.1416 = 22.58025$ inches, the circumference.

Or, the diameter being 30½ feet, required the circumference.

 $3.1416 \times 30.5 = 95.8188$ feet the circumference.

2. A straight line or the circumference of a circle

being 274.89 inches, required the circle's diameter corresponding thereto.

 $274.89 \times .31831 = 87.5$ inches diameter.

Or, what is the diameter of a circle when the circumference is 39 feet?

- $31831 \times 39 = 12.41409$ feet, and $.41409 \times 12 = 4.96908$ inches, or 12 feet 5 inches, very nearly the diameter.
- 3. The diameter of a circle is 3½ inches; what is its area in square inches?

 $3.75^2 = 14.0625 \times .7854 = 11.044$, &c. inches area.

Or, suppose the diameter of a circle 25 feet 6 inches, required the area.

 $25.5^2 = 650.25 \times .7854 = 510.706$, &c. feet, the area.

- 4. What must the diameter of a circle be, to contain an area equal to 706.86 square inches?
 - $\sqrt{706.86} = 26.586 \times 1.12837 = 29.998$ or 30 inches, the diameter required.
- 5. The diameter of a circle is $14\frac{1}{4}$ inches; what must I make each side of a square, to be equal in area to the given circle?

 $14.25 \times .8862 = 12.62835$ inches, length of side required.

Any chord and versed sine of a circle being given, to find the diameter.

Rule.—Divide the sum of the squares of the chord and versed sine by the versed psine; the quotient is the diameter

of corresponding circle.

1. The chord of a circle AB equal 6½ feet, and the versed sine CD equal 2 feet; required the circle's diameter.



 $6.5^2 + 2^2 = 46.25 + 2 = 23.125$ feet, the diameter.


2. In a curve of a railway, I stretched a line 72 feet in length, and the distance from the line to the curve I found to be 11 ft.; required the radius of the curve.

$$72^{2}+1\cdot25^{2}=5185\cdot5625$$
, and $\frac{5185\cdot5625}{1\cdot25\times2}=2074\cdot225$ ft. the radius.

To find the length of any given arc of a circle.

Rule.—From eight times the chord of half the arc, subtract the chord of the whole arc, and onethird of the remainder is equal the length of the arc.

Required the length of the arc ABC, the chord AB of half the arc being 4 feet 3 inches. and chord A c of the whole arc 8 feet 4 inches.



$$4.25 \times 8 = 34$$
, and $34 - 8.333 = \frac{25.667}{3} = 8.555$ feet, the length of the arc.

To find the area of the sector of a circle.

Rule.—Multiply the length of the arc by its radius, and half the product is the area.

The length of the arc ACB equal 91 feet, and the radii FA, FB, equal each 7 feet; required the area.

$$9.5 \times 7 = 65.5 + 2 = 32.75$$
, the area.

Note.—The most simple means whereby to find the area of the segment of a circle. is, to first find the area of a sector whose



arc is equal to that of the given segment; and if it be less than a semicircle, subtract the area of the triangle formed by the chord of the segment and radii of its extremities; but if more than a semicircle, add the area of the triangle to the area of the sector, and the remainder or sum is the area of the segment.

Thus, suppose the area of the segment ACBe is required, and that the length of the arc ACB equal 9\frac{2}{3} feet, FA and FB each equal 7 feet, and the chord AB equal 8 feet 4 inches, also the perpendicular eF equal 3\frac{2}{3} feet.

$$\frac{9.75 \times 7}{2} = 34.125$$
 feet, the area of the sector.


$$\frac{8.833 \times 3.75}{2} = 15.624$$
 feet, area of the triangle.

And $34 \cdot 125 - 15 \cdot 624 = 18 \cdot 501$ feet, the area of the segment.

To find the area of the space contained between two concentric circles.

Rule.—Multiply the sum of the inside and outside diameters by their difference, and by '7854; the product is the area.

1. Suppose the external circle AB equal 32 inches, and internal circle CD equal 28 inches; required the area of the space contained between them.



$$32+28=60$$
, and $32-28=4$; hence $60 \times 4 \times 7854 = 188.496$ in. the area.

2. The exterior diameter of the fly-wheel of a steam engine is 20 feet, and the interior diameter 18½ feet; required the area of the surface or rim of the wheel.

20+18.5=38.5, and 20-18.5=1.5; hence $38.5 \times 1.5 \times .7854$ = 45.35, &c. feet, the area.

To find the area of an ellipse or oval.

Rule. — Multiply the longest diameter by the shortest, and the product by 7854; the result is the area.

An oval is 25 inches by 16.5; what are its superficial contents?

 $25 \times 16.5 = 412.5 \times .7854 = 323.9775$ inches, the area.

Note.—Multiply half the sum of the two diameters by 3-1416, and the product is the circumference of the oval or ellipse.

To find the area of a parabola, or its segment.

Rule.—Multiply the base by the perpendicular height, and two-thirds of the product is the area.

What is the area of a parabola whose base is 20 feet and height 12?

$$20 \times 12 = \frac{240 \times 2}{3} = 160$$
 feet, the area.

Note.—Although the whole of the preceding practical applications or examples are given in measures of feet or inches, these being considered as the most generally familiar, yet the rules are equally applicable to any other unit of measurement whatever, as yards, chains, acres, &c., &c., &c.

2. MENSURATION OF THE SUPERFICIES, SOLI-DITIES, AND CAPACITIES OF BODIES.

To find the solidity or capacity of any figure in the cubical form.

Rule.—Multiply the length of any one side by its breadth and by the depth or distance to its opposite side; the product is the solidity or capacity, in equal terms of measurement.

Application of the rule to practical purposes.

1. Required the number of cubic inches in a piece of timber 23½ inches long, 7½ inches broad, and 3½ inches in thickness.

$$23.5 \times 7.75 \times 3.625 = 660.203$$
 cubic inches.

 A rectangular cistern is in length 8½ feet, in breadth 5¼ feet, and in depth 4 feet; required its capacity in cubic feet, also its capacity in British imperial gallons.

- $8.5 \times 5.25 \times 4 = 178.5$ cubic feet, and 178.5×6.232 (see Table of Decimal Approximations, p. 30) = 1112.412 gallons.
- 3. A rectangular cistern capable of containing 520 imperial gallons is to be 7½ feet in length, and 4½ feet in width; it is required to ascertain the necessary depth.
 - $7.25 \times 4.5 \times 6.232 = 203.318$, and $\frac{520.000}{203.318} = 2.557$ feet, or 2 feet 6\frac{2}{8} inches nearly.
- 4. A rectangular piece of cast iron, 20 inches long and 6 inches broad, is to be formed of sufficient dimensions to weigh 150 lbs.; what will be the depth required?

 $20 \times 6 \times 263$ (see Table of Decimal Approximations, Cast Iron, p. 30)=31.96, and $\frac{150}{31.96}$ = 4.69 in., or 4 and $\frac{11}{16}$ in., the thickness required.

To find the convex surface, and solidity or capacity, of a cylinder.

Rule 1.— Multiply the circumference of the cylinder by its length or height; the product is the convex surface.

Rule 2.—Multiply the area of the diameter by the length or height, and the product is the cylinder's solidity or capacity, as may be required.

Application of the rules.

- 1. The circumference of a cylinder is 37\frac{1}{4} inches, and its length 54\frac{3}{4} inches; required the convex surface in square feet.
 - $54.75 \times 37.5 \times .007$ (see Table of Approximations) = 14.371 square feet.
 - 2. A cylindrical piece of timber is 9 inches dia-

meter, and 3 feet 4 inches in length; required its solidity in cubic inches, and also in cubic feet.

- 3 feet 4 inches = 40 inches, and $9^2 \times .7854 \times 40 = 2544.696$ cubic inches; then $2544.696 \times .00058 = 1.4759$ cubic feet.
- 3. Suppose a well to be 4 feet 9 inches diameter, and 161 feet from the bottom to the surface of the water; how many imperial gallons are therein contained?

$$4.75^2 \times 16.5 \times 4.895 = 1822.162$$
 gallons.

4. Again, suppose the well's diameter the same, and its entire depth 35 feet; required the quantity in cubic yards of material excavated in its formation.

$$4.75^2 \times 35 \times .02909 = 22.973$$
 cubic yards.

5. I have a cylindrical cistern capable of holding 7068 gallons, and its depth is 10 feet; now I want to replace it with one of an equal depth, but capable of holding 12,500 gallons; what must be its diameter?

$$4.895 \times 10 = 48.95$$
, and $\frac{12500}{48.95} = \sqrt{255.3} = 15.9687$ feet, or 15 feet $11\frac{3}{8}$ inches.

6. A cylindrical piece of lead is required 7½ inches diameter, and 168 ibs. in weight; what must be its length in inches?

$$7.5^2 \times .3223 = 18$$
, and $\frac{168}{18} = 9.3$ inches.

To find the length of a cylindrical helix, or spiral, wound round a cylinder.

Rule.—Multiply the circumference of the base by the number of revolutions of the spiral, and to the square of the product add the square of the height; the square root of the sum is the length of the spiral.

Application of the rule.

- 1. Required the length of the thread or screw twisting round a cylinder 22 inches in circumference 3½ times, and extending along the axis 16 inches.
- $22 \times 3.5 = 77^2 = 5929$, and $16^2 = 256$; then $\sqrt{5929 + 256} = 78.64$ inches.
- The well of a winding staircase is 5 feet diameter, and height to the top landing 25 feet, the hand-rail is to make 2½ revolutions; required its length.

5 feet diameter = 15.7 feet circumference. 15.7 × 2.5 = 39.25^2 = 1540.5625, and 25² = 625; then $\sqrt{1540 + 625}$ = 46.5 feet, the length required.

To find the convex surface, solidity, or capacity of a cone or pyramid.

- Rule 1.—Multiply the circumference of the base by the slant height, and half the product is the slant surface.
- Rule 2.—Multiply the area of the base by the perpendicular height, and one-third of the product is the solidity or capacity, as may be required.

Application of the rules.

1. Required the area in square inches of the slant surface of a cone whose slant height equals 183 inches, and diameter at the base 61 inches.

 $6.25 \times 3.1416 = 19.635$, circumference of the base; and $\frac{19.635 \times 18.75}{2} = 184.078125$ square inches.

2. Required the quantity of lead, in square feet, sufficient to cover the slant surface of a hexagonal pyramid whose slant height is 42 feet, and the breadth of each side at the base 4 feet 9 inches.

 $\frac{4.75 \times 42 \times 6 \text{ sides}}{2} = 598.5 \text{ square feet.}$

3. What is the solidity of a cone in cubic inches, the diameter at the base being 15 inches, and perpendicular height 324 inches?

$$\frac{15^2 \times .7854 \times 32.5}{3} = 1914.4125$$
 cubic inches.

4. In a square solid pyramid of stone 67 feet in height, and 16½ feet at the base, how many cubic feet?

$$\frac{16.5 \times 16.5 \times 67}{3}$$
 = 6080.25 cubic feet.


To find the solidity or capacity of any frustum of a cone or pyramid.

Rule.—If the base be a circle, add into one sum the two diameters, or, if a regular polygon, the breadth of one side at the top and at the base; then from the square of the sum subtract the product of these diameters or breadths; multiply the remainder by 7854, if a circle, or by the tabular area (see Table of Polygons, p. 36) and by one-third of the height, and the product is the content in equal terms of unity.

Note.—Where the whole height of the cone or pyramid can be obtained, of which the given frustum forms a part, the most simple method is first to find the whole contents, then the contents extending beyond the frustum, and subtracting the less from the greater, leaves the contents of the frustum required.

Application of the rules.

1. The perpendicular height A B of the frustum of a hexagonal pyramid CDE, is $7\frac{1}{2}$ feet, and the breadth of each side at top and base equal $3\frac{3}{4}$ and $2\frac{1}{2}$ feet; required the solid contents of the frustum in cubic feet.



- .75 + 2.5 = 6.25, and $6.25 \times 6.25 = 39.0625$; then $3.75 \times 2.5 = 9.375$, and $39.0625 9.375 = 29.6875 \times 2.598$ (tabular area, p. 36) = 77.138×2.5 or $\frac{1}{8}$ of the height = 192.845 cubic feet.
- 2. Required the solidity of the frustum of a cone, he top diameter of which is 7 inches, the base diameter 9½, and the perpendicular height 12.
- $+9.5^{2} = 272.25$, and $7 \times 9.5 = 66.5$; then 272.25 66.5= $205.75 \times .7854 = 161.576 \times 4$ or $\frac{1}{2}$ of the height = 646.3 cubic inches.
- 3. A vessel in the form of an inerted cone, as ABCD, is 5 feet in immeter at the top, 4 feet at the ottom, and 6 feet in depth; reuired its capacity in imperial galms.




 $+4=9^2=81$, and $5\times 4=20$; hence $81-20=61\times .7854$, and by 2 or $\frac{1}{3}$ of the depth=95.8188 cubic feet, and $\times 6.232$ = 597.1427 gallons.

To find the solid contents of a wedge.

Rule.—To twice the length of the base add the ength of the edge; multiply the sum by the breadth f the base, and by the perpendicular height from he base, and one-sixth of the product is the solid ontents.

Application of the rule.

Required the solidity of a wedge in ubic inches, the base ABCD being inches by 3½, the edge EF, 7 inches, and the perpendicular height GE, 15.





To find the convex surface, the solidity, or the capacity of a sphere or globe.

Rule 1.—Multiply the square of the diameter by

3.1416, the product is the convex surface.

Rule 2.—Multiply the cube of the diameter by

'5236, the product is the solid contents.

Rule 3.—Multiply the cube of the diameter in feet by 3.263, or in inches by .001888, the product is the capacity in imperial gallons.

Application of the rules.

- 1. Required the convex surface, the solidity, and the weight in cast iron, of a sphere or ball 101 inches in diameter.
- $10.5^2 \times 3.1416 = 346.3614$ square inches.

 $10.5^3 \times .5236 = 606.132$, &c. cubic inches; and

 $606\cdot132 \times \cdot 263$ (see Table of Approximations, p. 30) = 159.4 lbs.

2. A hollow or concave copper ball is required 8 inches diameter, and in weight just sufficient to sink to its centre in common water; what is the proper thickness of copper of which it must be made?

Weight of a cubic inch of water = 03617 fbs. copper = 3225 , see p. 113.

 $8^3 \times \cdot 5236 \times \cdot 03617 = 4.84828$ cub. in. of water to be displaced.

=15.0334 cubic inches of copper in the ball.

Then $8^2 \times 3.1416 = 201.0624$, and $\frac{15.0334}{201.0624}$ thickness of copper required.

 $0.0747 \times 16 = \frac{1}{16}$ of an inch full, or 3 ths. copper to a square foot.

- 3. What diameter must I make a leaden ball, so as to weigh 72 lbs.?
 - $\cdot 5236 \times \cdot 4103 = \cdot 21483308$, and $\frac{72}{\cdot 21483308} = \sqrt[3]{340} = 6.97$ inches diameter.

To ascertain the amount of convex surface, also the solid contents, of the segment of a globe.

Rule 1.—Multiply the circumference of the globe or sphere by the height of the segment, and the product is the convex surface.

Rule 2.—To three times the square of the segment's radius add the square of its height, multiply the sum by the height, and by 5236; the product is the solid contents.


Application of the Rules.

1. Required the number of square feet in the convex surface of a sphere, the height of which is 9½ feet, and the circumference of the sphere of which it is a part equal 70½ feet.

 $70.5 \times 9.5 = 669.75$ square feet.

2. The radius AC or BC of the spherical segment ADB equal 48 inches, and the height DC equal 12 inches; required its solidity in cubic inches.

48² × 3 = 6912, and 12² = 144; then 6912 + 144 × 12 × ·5236 = 44334·75 cubic inches.



To find the convex surface and solidity of a cylindrical ring.


Rule 1.—To the sectional diameter of the ring add the inner diameter of the circle, multiply the sum by the sectional diameter, and by 9.8696; the product is the convex surface.

Rule 2.—To the sectional diameter of the ring add the inner diameter of the circle, multiply the sum by the square of the sectional diameter, and by 2.4674; the product is the solid contents.

Application of the Rules.

The inner diameter AB of the cylindric ring cdef equal 18 feet, and the sectional diameter cA or Be equal 9 inches; required the convex surface and solidity of the ring.

 $\frac{18 \text{ feet} \times 12 = 216 \text{ inches, and}}{216 + 9 \times 9 \times 9 \cdot 8696 = 19985 \cdot 94}$ square inches.



 $2\overline{16+9} \times 9^2 \times 2.4674 = 44968.365$ cubic inches.

In the formation of a hoop or ring of wrought iron, it is found in practice, that in bending the iron the side or edge which forms the interior diameter of the hoop is upset or shortened, while at the same time the exterior diameter is drawn or lengthened; therefore, the proper diameter by which to determine the length of the iron in an unbent state, is the distance from centre to centre of the iron of which the hoop is composed: hence the rule to determine the length of the iron. If it is the interior diameter of the hoop that is given, add the thickness of the iron; but if the exterior diameter, subtract from the given diameter the thickness of the iron, multiply the sum or remainder by 3:1416, and the product is the length of the iron, in equal terms of unity.

Supposing the interior diameter of a hoop to be 32 inches, and the thickness of the iron $1\frac{1}{4}$, what must be the proper length of the iron, independent of any allowance for shutting?

 $32+1.25=33.25\times3.1416=104.458$ inches.

But the same is obtained simply by inspection in the Table of Circumferences.

Thus, 33.25 = 2 feet 91 in., opposite to which is 8 feet 81 inches.

Again, let it be required to form a hoop of iron 7 inch in thickness, and 161 inches outside diameter.


16.5 - .875 = 15.625, or 1 foot 3 inches;

opposite to which, in the Table of Circumferences, is 4 feet 1 inch, independent of any allowance for

shutting.


The length for angle iron, of which to form a ring of a given diameter, varies according to the strength of the iron at the root; and the rule is, for a ring with the flange outside, add to its required interior diameter, twice the extreme strength of the iron at the root; or, for a ring with the flange inside, subtract twice the extreme strength; and the sum or remainder is the diameter by which to determine the

length of the angle iron. Thus, suppose two angle iron rings similar to the following be required, the exterior diameter A B, and interior diameter C D, each to be 1 foot 10½ inches, and the extreme strength of the ron at the root c d, c d, &c. 3 of an inch:



wice $\frac{2}{8} = 1\frac{8}{4}$, and 1 ft. $10\frac{1}{2}$ in. $+1\frac{9}{4} = 2$ ft. $\frac{1}{4}$ in., opposite to which, in the Table of Circumferences, is 6 ft. $4\frac{1}{4}$ in., the length of the iron for c D; and 1 ft. $10\frac{1}{4}$ in. $-1\frac{8}{4} = 1$ ft. $8\frac{9}{4}$ in., opposite to which is 5 ft. $5\frac{1}{4}$ in., the length of the iron for A B.

it observe as before, that the necessary allowance shutting must be added to the length of the iron, addition to the length as expressed by the Table. Required the capacity in imperial gallons of a Locomotive Engine Tender tank, 2 feet 8 inches in depth, and its superficial dimensions the following, with reference to the annexed plan.



Length, or dist. between A and B=10 ft. 24 in. or, 122.75 in. Breadth C p = 6 , 7Length g = 3 , 10446.75 " Mean breadth of coke space or Diameter of circle 81 32.25 1 " 6¥ 18.5 Radius of back corners v x Then. $122.75 \times 79.5 = 9758.525$ square inches, as a rectangle. And $18.5^2 \times .7854 = 268.8$ area of circle formed by the two ends.

Total 10027:325 ,, ,, from which deduct the area of the coke space, and the difference of area between the semicircle formed by the two back corners, and that of a rectangle of equal length and breadth;

Then $46.75 \times 37.25 = 1731.4375$ area of r, n, s, t, in sq. ins. $\frac{32.25^2 \times .7854}{2} = 408.4$ area of half the circle r m.

Radius of back corners = 4 inches;

consequently $8^2 \times .7854 = 25 \cdot 13$, the semicircle's area; and $8 \times 4 = 32 - 25 \cdot 13 = 6 \cdot 87$ inches taken off by rounding the corners.

Hence, 1731:4375 + 408:4 + 6:87 = 2146:707, and 10027:325 - 2146:707 = 7880:618 square inches, or whole area in plan,

7880·618 × 32 the depth = 252179·776 cubic inches, and 252179·776 × 003607 (see Table of Approximations, page 30) = 909·61245 gallons.

Tables combining the Specific Gravities and other Properties of Bodies. Water the standard of comparison, or 1000.

				M	METALS.						STONES,	ES, EA	EARTHS,	, &c.
Names.	Specific gravity.	Melting points in de- grees of Fahrenheit.	Contraction in parts of an in, per lineal it, from the fluid to the average temperature in solid state,	Ultimate cohesive strength of an inch sq. prism in tons.	Scale of wire-drawing ductility.	Scale of laminable ductility,	Ratio of hardness.	Scale as conductors of electricity.	Ratio of power in the conduction of heat.	Names.	Specific gravity.	Weight of a cubic foot in fbs.	Cubic feet in a ton.	Tons required to crush 14-inch cubes.
Matinum	19500	3280	1	1	00	2	1	1	8.8	Marble, average	2720	170.00	13	9.52
oure Gold	19258	2016	1	1	-	-	1.8	m	10.0		2651	165.68	134	6.9
Mercury	13500	Ī	1	1	1	1	ı	1	1	Purbeck stone .	2601	162.56	133	0.6
pa-	11352	613	.319	18.	00	7	1.0	9	1.8	Portland do	2570	160-62	1	4.9
vare Silver	10474	1873	1	1	69	01	5.4	G4	2.6	Bristol do	2554	159-62	14	1
Bismuth	9823	476	.156	1.45	1	1	5.0	1	1	Millstone	2484	155-25	144	ı
Copper, cast	8288	1006	.193	8.21	1	١	1	1	Į	Paving stone.	2415	150.93	143	2.2
wrought	8910	1	1	15.08	10	00	3.8	-	6.8	Craigleith do	2369	147-69	15	2.0
Brass, cast	7824	1900	.210	8.01	1	1	toany	1	1	Grindstone	2143	133-93	162	9.9
sheet	8306	1	1	12.23	9	9	angan,	1	9.6	Brick.	2000	125.00	174	8.0
ron. cast	7964	9786	.125	7.87	1	1	(to any	1	1	Coal, Scotch	1300	81.15	274	1
hor	1700		191.	95.00		0	degree	•	6.4	" Newcastle	1270	79.37	2/4	1
soft	7833	I	133	58.01	• 1	0	. 1	- 1	1	Cannel	1238	77.37	30	1
hard	7816	1	. 1	1	1	1	(to any	1	1					Ī
cast	7291	442	.278	2.11	80	4	1.5	40	3.0					
cast	2100	279	.350	2.06	1	α	9-1	*	3.6					

		W	oods.				
	3	ofa lbs.		900	Co	mpara	tive
Names.	Specific gravity, water, 1000.	Average wt. o	Cubic feet in a ton.	Ultimate cohesive sive strength of an inch square prism in lbs.	Stiffness.	Strength.	Resilience.
English oak	934	58	381	11880	100	100	100
Riga do	872	54	414	12888	93	108	12
Dantzic do	756	47	48	12780	117	107	99
American do	672	42	53	10253	114	86	6
Beech	852	48	45	12225	77	103	138
Alder	800	46	481	9540	63	80	101
Plane	640	40	55	10935	78	92	108
Sycamore	604	38	59	9630	59	81	111
Chestnut	610	38	59	10656	67	89	118
Ash	845	52	43	14130	89	119	160
Elm	673	42	53	9720	78	82	86
Mahog. Spanish	800	50	45	7560	73	67	61
, Honduras	637	40	55	11475	93	96	99
Walnut	671	42	53	8800	49	74	111
Teak	750	46	481	12915	126	109	94
Poona	640	40	55	12350	99	104	82
African oak	944	59	38	17200	101	144	138
Poplar	383	34	66	5928	44	50	57
Cedar	561	33	68	7420	28	62	106
Riga fir	753	47	48	9540	98	80	64
Memel do	546	34	66	9540	114	80	56
Scotch do	528	33	68	7110	55	60	65
Christ. whte. deal .	590	37	60	12346	104	104	104
Amn. white spruce	551	34	66	10296	72	86	102
Yellow pine	461	28	80	11853	95	99	103
Pitch pine	660	41	541	9796	73	82	92
Larch	530	31	72	12240	79	103	134
Cork	240	15	149	_	-	-	_

LIQUID	١.		GASES.	
	Specific grav., water, 1000.	nt of an ial gall.	Atmospheric air being the of comparison, or 1	e standard 000.
Names.	Specif water,	Weight o imperial in the.	Names.	Specific gravity.
Acid, sulphuric	1850		Hydriodic acid gas	4340
" nitric	1271		Chlorine acid ,,	25 00
" muriatic	1200		Carbonic acid	1527
" fluoric	1060	10.6	Nitrous oxide "	1527
" citric	1034	10.3	Cyanogen "	1805
" acetic	1062	10.6	Oxygen "	1111
Water from the		i I	Carbonic oxide "	972
Baltic	1015	10.2	Carburetted hydrogen	
Water from the		1 1	gas	972
Dead Sea	1240	12.4	Prussic acid ,,	937
Water from the			Ammoniacal do. ,,	590
Mediterranean .	1029	10.3	Steam of water ,,	623
Water, distilled	1000	10.0	Hydrogen "	69
Oils, expressed:		1		
" linseed	940	9.4	Weight of water at	the com-
" sweet almond		9.3	mon temperature:	Į
" whale	923	9.2		17 fb.
" hempseed	926	9.3	1 ,, foot = 62.5	,,
" olive	915	9.2	1 ,, , = 6.25 im	p. galls.
Oils, essential:		ا ا	1.8 ,, ,, =1 cwt.	
" cinnamon		10.4	1 cylindrical inch = 0	
" lavender	894	8.9	1 ,, foot $=49$	- ,,
" turpentine	870	8.7		imp. galls.
" amber	868	8.7	2.282 feet = 1 cwt.	
Alcohol	825	8.2	11.2 imp. gallons = 1 c	
Ether, nitric	908	9.1	224 ,, ,, =11	on.
Proof spirit	922	9.2		
Vinegar	1009	10.1		i
			l 	

WEIGHT OF A LINEAL FOOT OF SQUARE AND ROUND BAR IRON IN POUNDS.

		UND	DAR IA	UN IN	FOUN		
	Squar	e iron.			Round	l iron.	
Inches square.	ībs.	Inches square.	lbs.	Inches diam.	ibs.	Inches diam.	ībs.
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	-208 -325 -468 -638 -638 1-05 1-30 1-57 1-87 2-20 2-55 2-92 3-33 3-76	2 2 2 4 4 5 1 5 5 4 5 1 5 1 5 5 5 5 5 5 5 5 5	13·33 15·05 16·87 18·80 20·81 22·96 25·20 27·55 30·00 32·55 35·20 37·96 40·80 43·81		·163 ·255 ·368 ·501 ·654 ·828 1·02 1·23 1·47 1·72 2·00 2·30 2·61 2·95	2 2 2 2 2 2 2 2 3 3 3 3 3 3 3 3 3 3 3 3	10-47 11-82 13-25 14-76 16-36 18-03 19-79 21-63 23-56 25-56 27-65 29-82 32-07 34-40
1 1 8	4·21 4·70 5·20 5·74 6·30 6·88 7·50 8·15 8·80 9·50 10·20 10·69 11·71 12·52	334 444 555 667 8	46.87 50.05 53.33 60.20 67.50 75.20 83.33 92.43 101.03 110.40 120.21 130.20 151.81 213.29	1 18 1 18 1 1 18 1 1 18 1 1 18 1 1 18 1 1 18 1 1 1 18 1	3·31 3·69 4·09 4·51 4·95 5·40 6·40 6·91 7·46 8·60 9·20 9·33	334 4 4 4 5 5 5 5 6 6 7 8	36·81 39·31 41·88 47·28 53·01 59·06 65·45 72·61 79·36 86·73 94·60 110·60 128·28 167·51

Note.—The elastic power or direct tension of bar iron medium quality per square inch of cross section equals 10 tons; and a bar is extended '000096, or nearly one ten-thousandth part of its length for every ton of direct strain per square inch of its sectional area: note, also, that either of the metals,—iron, tin, or zinc,—at a red heat, possesses the property of decomposing water when in an aëriform state.

WEIGHT OF A LINEAL FOOT OF FLAT BAR IRON IN POUNDS.

lth these.		Thi	ckness i	in parts	of an ir	ich.	
Breadth in inches.	‡	18 18	ŧ	78	}	18	ŧ
1	.417	•52	-	_	_	_	_
ŧ	•52	•65	•78	·91			—
* *	•625	·785	•93	1.09	1.25	1.40	
	•725	·91	1.09	1.27	1.46	1.64	1.82
1	•834	1.04	1.25	1.45	1.67	1.87	2.08
11	•937	1.17	1.40	1.64	1.87	2.10	2.34
1‡	1.04	1.30	1.26	1.85	2.08	2.34	2.60
18	1.14	1.43	1.71	2.00	2.29	2.57	2.86
11	1.25	1.26	1.87	2.18	2.50	2.81	3.13
1	1.35	1.69	2.03	2.36	2.70	3.04	3.38
14	1.45	1.82	2.18	2.55	2.91	3.28	3.64
17	1.56	1.95	2.34	2.73	3.12	3.21	3.90
2	1.66	2.08	2.50	2.91	3.33	3.75	4.16
21	1.77	2.21	2.65	3.09	3.54	3.98	4.42
21	1.87	2.34	2.81	3.28	3.75	4.21	4.68
2흏	1.97	2.47	2.96	3.46	3.95	4.45	4.94
21	2.08	2.60	3.12	3.64	4.16	4.68	5.20
2	2.18	2.73	3.28	3.82	4.37	4.92	5.46
24	2.29	2.86	3.43	4.01	4.58	5.15	5.72
2 7	2.39	2.99	3.59	4.19	4.79	5.39	5.98
3	2.50	3.12	3.75	4.37	5.00	5.62	6.25
3 1	2.70	3.38	4.06	4.73	5.41	6.09	6.77
31	2.91	3.64	4.37	5.10	5.83	6.26	7.29
34	3.12	3.90	4.68	5.46	6.25	7.03	7.81
4	3.33	4.16	5.00	5.83	6.66	7.50	8.33
41	3.54	4.42	5.31	6.19	7.08	7.96	8.85
4	3.75	4.68	5.62	6.56	7.50	8.43	9'37
44	3.95	4.94	5.93	6.92	7.91	8.90	9.89
5	4.17	5.20	6.25	7.29	8.33	9.37	10.41
51	4.37	5.46	6.56	7.65	8.75	9.84	10.93
51	4.58	5.72	6.87	8.02	9.16		11.45
5‡	4.79	5.98	7.18	8.38	9.58	10.78	11.97
6	5.	6.26	7.50	8.75	10.00	11.52	15.20

WEIGHTS OF IRON.

WEIGHT OF FLAT BAR IRON-continued.

Breadth in inches.		Th	ickness	in parts	of an i	nch.	
Bread in inc	18	4	13	3	15	1	11
1	2.29	-	-	-	-	-	-
11	2.57	2.81	3.04	-	-	-	=
11	2.86	3.12	3.38	3.64	3.90	-	-
14	3.15	3.43	3.72	4.01	4.29	4.58	-
14	3.43	3.75	4.06	4.37	4.68	5.00	5.62
14	3.72	4.06	4.40	4.73	5.07	5.41	6.08
14	4.01	4.37	4.73	5.10	5.46	5.83	6.56
12	4.29	4.68	5.07	5.46	5.85	6.25	7.02
2	4.58	5.00	5.41	5.83	6.25	6.66	7.50
21	4.86	5.31	5.75	6.19	6.64	7.08	7.96
24	5.15	5.62	6.09	6.56	7.03	7.50	8.43
23	5.44	5.93	6.43	6.92	7.42	7.91	8-90
21	5.72	6.25	6.77	7.29	7.81	8.33	9.36
25	6.01	6.56	7.10	7.65	8.20	8.75	9.84
23	6.30	6.87	7.44	8.02	8.59	9.16	10.30
27	6.58	7.18	7.78	8.38	8.98	9.58	10.78
3	6.87	7.50	8.12	8.75	9.37	10.00	11.25
31	7.44	8.12	8.80	9.47	10.15	10.83	12-18
31	8.02	8.75	9.47	10.20	10.93	11.66	13-12
34	8.59	9.37	10.15	10.93	11.71	12.50.	14.06
4	9.16	10.00	10.83	11.66	12.50	13.33	15-00
41	9.73	10.62	11.51	12:39	13.28	14.16	15.92
41	10-31	11.25	12.18	13.12	14.06	15.00	16.86
44	10.88	11.87	12.86	13.85	14.84	15.83	17.80
5	11.45	12.50	13.54	14.58	15.62	16.66	18.75
51	12.03	13.12	14.21	15.31	16.40	17.50	19.68
51	12.60	13.75	14.89	16.04	17.18	18.33	20.62
54	13.17	14.37	15.57	16.77	17.96	19.16	21.56
6	13.75	15.00	16.25	17.50	18.75	20.00	22.50
$6\frac{1}{2}$	14.88	16.24	17.60	18.95	20.30	21.66	24.36
7	16.04	17.50	18.94	20.41	21.86	23.33	26.24
71	17.18	18.74	20.30	21.86	23.42	25.00	28-12
8	18.32	20.00	21.76	23.32	25.00	26.66	30-00

WEIGHT OF FLAT BAR IRON-continued.

eadth inches.		T	hickness	in inch	es.	
Breadth in inches	11	13	11	18	2	21
11	6.24	6.86	-	-	-	-
14	7.28	8.02	8.74		-	-
2	8.32	9.16	10.00	11.66	-	-
21	9.36	10.30	11.24	13.12	15.00	-
21	10.40	11.44	12.50	14.58	16.66	-
23	11.44	12.60	13.74	16.04	18.32	22.88
3	12.50	13.74	15.00	17.50	20.00	25.00
31	13.54	14.88	16.24	18.94	21.66	27.08
31	14.58	16.04	17.50	20.40	23.32	29.16
34	15.62	17.18	18.74	21.86	25.00	31.24
4	16.66	18.32	20.00	23.32	26.66	33-32
41	17.70	19.46	21.24	25.78	28.32	35.40
41	18.74	20.62	22.50	26.24	30.00	37.48
43	19.78	21.76	23.74	27.70	31.67	39.56
5	20.82	22.90	25.00	29.16	33.32	41.64
51	21.86	24.06	26.24	30.62	35.00	43.72
51	22.90	25.20	27.50	32.08	36.66	45.80
58	23.94	26.34	28.74	33.54	38.32	47.88
6	25.00	27.50	30.00	35.00	40.00	50.00
61	27.08	29.76	32.48	37.88	43.32	54.16
7	29.16	32.08	35.00	40.80	46.64	58.32
71	31.24	34.36	37.48	43.72	50.00	62.48
8	33.32	36.64	40.00	46.64	53.32	66-64
81	35.40	38.92	42.48	51.56	56.64	70.80
9	37.48	41.24	45.00	52.48	60.00	74.96

MECHANICAL TABLES

FOR THE USE OF OPERATIVE SMITHS, MILLWRIGHTS, AND ENGINEERS.

The following Tables, originally dedicated to 'the National Association of the Forgers of Iron-Work,' are, with permission, added to the present edition: they will be found extremely useful to Smiths generally, and are accompanied by Observations and Practical Examples.

TABLE I.*

DIAMETERS AND CIRCUMFERENCES OF CIRCLES from One Inch to upwards of Twenty Feet, advancing by an Ei

Dia- meter.	Circum- ference.	Dia- meter.	Circum- ference.	Dia- meter.	Circum- ference.	Dia- meter.	f
In. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Ft. In. 0 3½ 0 3½ 0 3½ 0 4½ 0 4½ 0 5 0 5½ 0 6½	In. 5 5 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Ft. In. 1 3	Ft. In. 0 9 0 9½ 0 9½ 0 9½ 0 9½ 0 9½ 0 9½ 0 9½	Ft. In. 2 44 2 45 2 5 5 5 5 6 5 2 6 5 5 7 2 7 5 8	Ft. In. 1 1 1 1½ 1 1½ 1 1½ 1 1½ 1 1½ 1 1½ 1 1½	E 00 00 00 00 00 00 00 00
218 214 288 219 24 258 228 238 238 238 238 238 238 238 238 23	0 65 0 7 0 75 0 75 0 85 0 85 0 85 0 9	618 64 68 619 68 68 68 68 68 68 68 68 68 68 68 68 68	1 7± 1 75 1 8 1 85 1 85 1 95 1 95 1 97	0 10½ 0 10¼ 0 10¾ 0 10½ 0 10½ 0 10¾ 0 10¾ 0 10¾	2 7 ⁵ / ₄ 2 8 ¹ / ₈ 2 8 ¹ / ₂ 2 8 ² / ₅ 2 9 ³ / ₈ 2 9 ³ / ₄ 2 10 ¹ / ₈ 2 10 ¹ / ₂	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	3 3 3 3 3 3 3
3 3 3 3 5 5 5 5 4	0 9 ⁴ / ₄ 0 10 ¹ / ₆ 0 10 ¹ / ₆ 0 10 ² / ₆ 0 11 ² / ₆ 1 0 ¹ / ₆ 1 0 ¹ / ₆	7 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1 10\$ 1 10\$ 1 11\$ 1 11\$ 1 11\$ 2 0\$ 2 0\$	0 11½ 0 11¼ 0 11½ 0 11½ 0 11½ 0 11½ 0 11½ 1 0	2 10½ 2 11½ 2 11½ 2 11½ 3 0 3 0½ 3 0½ 3 1½ 3 1½	1 3½ 1 3½ 1 3½ 1 3½ 1 3½ 1 3½ 1 3½ 1 3½	3 3 4 4 4 4 4 4 4
4 1 1 1 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1 05 1 11 1 15 1 25 1 21 1 25 1 25 1 31	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	2 1½ 2 1½ 2 2½ 2 2½ 2 3 2 3½ 2 3½	1 0	3 2 3 25 3 25 3 34 3 35 3 4 3 45	1 4	4 4 4 4 4 4 4

^{*} James Foden.

Diam.	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.	Circum.
Ft. In. 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5	Ft. In. 4 5	Ft. In. 1 9 1 1 9 1 1 9 1 1 9 1 1 9 1 1 10 1	Ft. In. 5 7½ 5 7½ 5 8 5 8½ 5 9	Ft. In. 2 13 2 15 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Ft. In. F 6 8 2 2 6 9 2 2 6 9 8 2 6 10 2 6 10 2 6 10 2 6 11 2 2	2 6 d d d d d d d d d d d d d d d d d d	Ft. In. 7 10\$ 7 11 7 11\$ 7 11\$ 8 0\$ 8 0\$ 8 0\$ 8 1\$
1 6 1 6 1 6 1 6 1 6 1 6 1 6	4 8 4 9 4 4 9 6 4 10 4 10 8 4 10 7	1 10± 1 10± 1 10± 1 10± 1 10± 1 10± 1 11±	5 97 5 104 5 105 5 11 5 118 5 114 6 04	2 2 2 2 2 2 2 2 3 2 3 2 3 2 3 2 3 2 3 2	6 11 ± 7 0 5 7 0 ± 5 7 0 ± 5 7 1 ± 7 1 ± 7 2 5 5	74 74 74 74 74 74	8 1½ 8 2½ 8 2½ 8 2½ 8 3½ 8 3½ 8 3½ 8 4½
1 6 1 7 1 7 1 7 1 7 1 7 1 7 1 7 1 7 1 7	4 11½ 4 11½ 5 0 5 0¾ 5 0¾	1 11	6 05 6 1 6 13 6 13 6 14 6 21 6 21	2 3½ 2 3½ 2 3¾ 2 3½ 2 4	7 2	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	8 4½ 8 4½ 8 5½ 8 5½ 8 6
1 7½ 1 7½ 1 7½ 1 7½ 1 8½	5 1½ 5 1½ 5 2 5 2¾ 5 2¾ 5 3½	1 11½ 2 0 2 0½ 2 0½ 2 0½ 2 0½ 2 0½	6 3 6 3 8 6 4 1 6 4 1 6 4 7	2 4½ 2 4½ 2 4½ 2 4½ 2 4½ 2 4½ 2 4½	7 4½ 2 7 4½ 2 7 5½ 2 7 5½ 2 7 5½ —	2 8 1 2 8 1 2 9	8 6½ 8 6½ 8 7½ 8 7½ 8 8
1 8 1 8 1 8 1 8 1 8 1 8 1 8 1 8 1 8 1 8	5 38 5 4 5 48 5 48 5 58 5 58	2 0	6 5½ 6 5½ 6 6½ 6 6½	2 5 2 5 2 5 2 5 3 2 5 3 2 5 3 4 2 5 3 4 2 5 3 4 2 5 3 4 2 5 3 4 2 5 4 2	7 7 2 2 7 7 8 2 7 7 8 3 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	8 8 9 1 8 9 1 8 10 8 10 8 10 8 10 8 10 8
l 9 l 91 l 91	5 6± 5 6±	2 12 2 12 2 13 2 14 2 14	6 7½ 6 7½ 6 8 6 8½	2 5 1 2 5 1 2 5 1 2 6	7 9 7 9 7 9 7 9 7 9 7 9 7 9 7 9 7 9 7 9	101	8 11½ 8 11½ 8 11¾

Diam.	Circum.	Diam.	Circum.	Diam.	Circum.
Pt. In. 2 10 1 2 10 2 2 10 2 2 10 2 2 10 2 2 10 2 2 10 2 2 2 2	Ft. In. 9 03 9 03 9 11	Ft. In. 3 27 3 3	Ft. In. 10 2½ 10 2½	Ft. In. 3 7\frac{1}{3} 3 7\frac{1}{4} 3 7\frac{2}{3}	Ft. In. 11 3
2 10 ² / ₈ 2 11	9 1½ 9 1½	3 3½ 3 3½ 3 3¾	10 27 10 31 10 31	3 7½ 3 7½ 3 7½	11 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2 11½ 2 11½ 2 11½ 2 11½ 2 11½	9 2½ 9 2½ 9 3 9 3½	3 3½ 3 3½ 3 3½	10 4 10 4 ¹ / ₈ 10 4 ⁷ / ₈	3 8	11 5 1 11 6 1
2 11 § 2 11 § 2 11 §	9 3 8 9 4 1 9 4 8	3 4	10 5 1 10 5 1 10 6	3 8 4 3 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	11 7 11 78 11 78
3 0 3 0 3 0 3 0 3 0 3 0 3 0 3 0 3 0 3 0	9 5 9 5 ⁸ / ₈ 9 5 ⁷ / ₈	3 4 1 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3	10 68 10 62 10 71	3 8 4 3 8 7 3 9 9	11 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
3 0 1 3 0 1 3 0 1 3 0 1 1 1 1 1 1 1 1 1	9 6 1 9 6 1 9 7	3 4\frac{5}{8} 3 4\frac{3}{4} 3 4\frac{7}{8} 3 5	10 7 8 10 8 10 8 10 8 10 8 10 8 10 8 10	3 9½ 3 9½	11 9 2 11 10 1
3 0 ³ / ₄ 3 0 ⁷ / ₈ 3 1	9 78 9 73 9 88	3 5 1 3 5 1	10 9½ 10 9½	3 9\frac{3}{3} 9\frac{1}{3} 9\frac{1}{3} 9\frac{1}{3} 9\frac{1}{3}	11 101 11 102 11 111 11 114
3 1½ 3 1½ 3 1¾ 3 1¾	9 8 § 9 9 9 9 §	3 5 g 3 5 g	10 97 10 108 10 108	3 9 1 3 10	12 0° 12 0½
3 1½ 3 1½	9 9 1 9 10 1 9 10 1	3 5 8 3 5 8 3 5 8 3 6	10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3 10½ 3 10½ 3 10¾ 3 10¾	12 0 8 12 1 1 12 1 8
3 1 ⁷ / ₃ 3 2 ¹ / ₄	9 10 1 9 11 1 9 11 1 9 11 4	3 6½ 3 6½ 3 6¾	11 0½ 11 0½ 11 1½	3 10 1 3 10 1 3 10 1	12 2 12 28 12 28 12 24 12 34
3 2½ 3 2½ 3 2½	10 01 10 01 10 07	3 6½ 3 6½ 3 6¾	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	3 11	12 3 4
3 2 1 3 2 1	10 1 1 10 1 1	3 6 7 3 7	11 2 1 11 3	3 11 1 3 11 8	12 4 8 12 4 2

_							
_	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.	Circum.
ı.	Pt. In.	Pt. In.	Pt. In.	Ft. In.	Pt. In.	Pt. In.	Ft. In.
ŧ	13 64	4 8	14 81	5 01	15 10	5 47	16 114
	13 74	4 81	14 8	5 0 8	15 10#	5 5	17 0
_		4 8	14 9	5 04	15 10 1		
ļ	13 74	4 81	14 91	5 0	15 11 1	5 5 A	17 04
ŧ	13 8	4 8	14 94	5 1	15 114	5 51	17 1
ŧ	13 8	4 84	14 101			5 5	17 12
ł	13 8 7	4 87	14 10	5 11	16 0	5 51	17 14
ł	13 94	4 9	14 11	5 14	16 0g	5 5	17 2
ŧ.	13 9			5 1	16 04	5 5	17 24
ł	13 10	4 9	14 11	5 11	16 1	5 5 1	17 24
	13 101	4 91	14 114	5 14	16 14	5 6	17 31
_		4 9	15 01	5 14	16 17		
Εİ	13 10#	4 91	15 0	5 17	16 2	5 61	17 34
1		4 9	15 1	5 2	16 24	5 61	17 4
1	13 114	4 94	15 18			5 6	17 4
	14 0	4 97	15 14	5 21	16 31	5 61	17 47
Ţ	14 0#	4 10	15 21	5 21	16 34	5 64	
	14 04	II	·	5 2	16 37	5 61	17 54 17 54
	14 11	4 101	15 21	5 21	16 41	5 64	17 6
7	14 14	4 101	15 24	5 24	16 4	5 7	
	12 18	4 10	15 3	5 24	16 51	3 /	17 6
_		4 10	15 34	5 27	16 51		1
:	14 2	4 10	15 4	5 3	16 57	5 7g	17 6 7
7	14 2	4 10	15 44			5 71	17 7 }
•	14 24	4 107	15 47	5 34	16 6 1	5 7	17 7
t	14 3}	4 11	15 4 8 15 5 1	5 31	16 64	5 71	17 8
•	14 3			5 34	16 7	5 7	17 88
Ļ	14 4	4 111	15 54	5 31	16 7 8 16 7 8	5 73	17 84
÷	14 4	4 111	15 61	5 34	16 77	5 77	17 91
i	14 44	4 114	15 64	5 3 1	16 81	5 8	17 9
_		4 11	15 67	5 37	16 84		
F	14 51	4 114	15 71	5 4	16 9	5 8 1	17 10
ŀ	14 5	4 11	15 74			5 81	17 104
į	14 57	4 117	15 8	5 41	16 94	5 8	17 10
	14 61	5 0	15 8#	5 41	16 91	5 84	17 114
i:	14 64			5 4	16 10	5 8	17 114
1:	14 71	5 01	15 87	5 41	16 104	5 84	17 114
:	14 7	5 01	15 91	5 44	16 11	5 84	18 0
	14 77	5 0	15 94	5 44	16 118	5 9	18 0

D	iam.	Cir	cum.	Di	am.	Cir	cum.	D	iam.	Cir	cum.	D	iam.	Circ	4
Ft.	Įn.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.		Pt.	1
5	91	18	14	6	11	19	27	6	57	20	48	6	101	21	1
5	94	18	14	6	1#	19	31	6	6	20	5	6	10}	21	1
5	98	18	17	6	14	19	3	<u> </u>				6	10	21	1
5	9 🛔	18	21	6	17	19	4	6	6 1	20	51	6	10 <u>1</u>	21	1
5	9 §	18	25	6	2	19	48	6	6 1	20	54	6	10	21	1
5	93	18	3					6	6	20	61	6	10	21	1
5	9 7	18	31	6	21	19	44	6	61	20	64	6	10	21	1
5	10	18	37	6	2 1	19	54	6	6	20	7	6	11	21	1
				6	2	19	54	6	64	20	72				إ
5	101	18	41	6	2	19	6	6	64	20	71	6	111	21	1
5	101	18	48	6	2	19	68	6	7	20	81	6	11‡	21	1
5	103	18	5	6	2	19	64					6	11#	21	1
5	10½	18	58	6	27	19	71	6	7 <u>1</u>	20	81	6	111		Ą
5	10	18	57	6	3	19	71	6	71	20	87	6	11#		I
5	104	18	64	_				6	7	20	91	6	11‡		ų
5	10%	18	6	6	31	19	8	6	71	20	94	6	114		Ц
5	11	18	7	6	3∤	19	8홍	6	7	20	101	7	0	21 1	l,
				6	3	19	84	6	7	20	101	-		-	
5	111	18	78	6	31	19	94	6	7 1	20	107	7	0	22	Ţ
5	11‡	18	74	6	3	19	91	6	8	20	111	7	0 1	22	
5	118	18	81	6	34	19	97	_				7	0	22	ļ
5	114	18	81	6	37	19	101	e	01	20	114	7 7	01	22	H
5	11#	18	9	6	4	19	104	6	81	21	0		0#	22	1
5	114	18	98					6	8 1 81	21	01	7	0#	22	Į
5	117	18	94	6	41	19	114	6	8 1	21	07	7	01	22	Į
6	0	18	101	6	41	19	111	6	84	21	11	7	1	22	3
_		1.0		6	48	19	117	6	81	21	i	_			-
6	0 1	18	101	6	4	20	01	6	87	21	2	7	1	22	1
6	01	18	107	6	4	20	0#	6	9	21	24	7	11	22	4
6	08	18 18	111	6	44	20	1	0	7		-8	7	1	22	1
	0 1		114	6	47	20	14			03	-	7	11	22	1
6	0 1 01	19 19	01	6	5	20	17	6	91	21	23	7	14	22	3
6		19	01	6	£1	20	2 1	6	91	21	31	7	14	22	1
6	0 % 1	19	03		5	20	2‡ 2‡		9	21	31	7	14	22	2
0	1	19	1‡	6	5‡ 5#	20	3	6	91	21	4	7	2	22	4
6	11	19	14	6		20	3#	6	94	21		,	01	-	è
6		19	2	6	5 1	20	34	6	94	21	4	7	21	22	7
6	l‡ 1≩	19	21	6	5 § 5 §	20	41	6	9 7 10	21 21	5 1	7	2 <u>}</u>	22 22	2
	18	1 19	21	1 0	74	1 20	-37	. 0	10	121	34	1	21	Z.3	4

Di	ım.	Cir	cum.	D	iam.	Cir	cum.	מ	iam.	Cir	cum.	Di	am.	Cir	cum.
٠,	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.		Ft.	In.	Ft.	In.	Ft.	In.
F.	21	22	71	7	6 7	23	9	7	111	24	104	8	31	26	01
	2	22	81	7	7	23	9 7	7	11‡	24	111	8	3	26	07
K K	2	22	81	<u></u>				7	118	24	111	8	3#	26	18
Ė	2 <u>i</u>	22	87	7	7 k	23	10 1	7	111	25	0	8	37	26	14
ř	3	22	9 <u>1</u>	7	71	23	10#	7	114	25	0	8	4	26	$2\frac{1}{8}$
-				7	7	23	11	7	114	25	04			_	
ŧ	31	22	9#	7	71	23	11#	7	117	25	14	8	41	26	21
Z	3 1	22	10	7	7 🖁	23	113	8	0	25	11	8	41	26	27
7	3	22	108	7	71	24	01	-				8	48	26	31
ŗ	31	22	107	7	7	24	0	8	0 1	25	17	8	41	26	3
į	3	22	114	7	8	24	ı	8	0‡	25	2	8	45	26	41
7	3 1	22	114					8	0흏	25	24	8	44	26	41
7. 7. 7	31	23	0	7	81	24	18	8	01	25	31	8	48	26	44
7	4	23	08	7	8 <u>1</u>	24	12	8	0	25	31	8	5	26	54
-				7	8	24	2	8	0 3	25	37	<u> </u>			
77	41	23	04	7	81	24	21	8	07	25	41	8	51	26	58
	44	23	1į	7	84	24	27	8	1	25	48	8	51	26	6
.7	48	23	1	7	8	24	3	-				8	58	26	68
777	41	23	2	7	87	24	31	8	11	25	5 }	8	51	26	64
17	48	23	28	7	9	24	41	8	11	25	51	8	5	26	71
7	44	23	24	•	•		-8	8	18	25	57	8	5‡	26	78
7	47	23	31	7	01	24	44	8	11	25	61	8	57	26	8
7	5	23	31	7 7	9 1 91	24		8	1#	25	6	8	6	26	88
_		-			9 1	24	4 8 51	8	12	25	7	1	<u> </u>	00	0.8
,7	51	23	34	7 7	91 98	24	5 1	8	14	25	78	8	6	26	84
7	51	23	48	7		24		8	2	25	7 %	8	61	26	91
7	5	23	44	7	9‡ 9‡	24	61 61	_		-	-01	8	68	26 26	91 10
7	51	23	51	7	9 1	24	67	8	21	25	81	8	6 <u>1</u>	26	10
7777	54	23	51	7	10	24	71	8	21	25	88	8	6 §	26	101
7	54	23	54	•	10		14.	8	28	25	9	8	63	26	114
7	57	23	61		101	1		8	21	25	98	8	6 7 7	26	114
7	6	23	6 8	7	101	24	78	8	25	25 25	94	ľ	7	20	114
	<u></u>	00		7	101	24	8	8	24	25 25	101 101	8	71	26	114
?	61	23	78	7	10	24	87	8	2 1 3	25 25	105	8	7 1 1 7 1 2	27	01
!	61	23	71	7	101	24	87	8	3	23	11	8	7# 7#	27	01
!	6	23	74	7	10	24	91	•	21	OF.	118	8	7 1 1	27	11
[61	23	81	7	104	24	9#	8	31	25	118	8		27	
Ţ	6	23	84	7	104	24	10	8	31	25	113	8	7 8 7 2	27	1 } 1 }
Ŀ	6‡	23	9	7	11	24	10	8	38	26	0 §	1 8	/3	121	18

Diam.	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.	Cîr
Ft. In. 8 77 8 8	Ft. In. 27 21 27 25	Ft. In. 9 01 9 01 9 01	Ft. In. 28 3\frac{1}{8} 28 4 28 4\frac{3}{8}	Ft. In. 9 41 9 41 9 41	Ft. In. 29 5\frac{3}{2} 29 5\frac{3}{4} 29 6\frac{1}{4}	Ft. In. 9 8 9 9	Pt. 30 30
8 81 8 81 8 83	27 3 27 3½ 27 3½	9 01 9 01 9 02	28 4 1 28 5 1 28 5 1	9 4 1 9 5	29 61 29 7	9 9½ 9 9½ 9 9¾	30 30 30
8 8± 8 8± 8 8±	27 4½ 27 4½ 27 5	$9 0\frac{2}{8}$ $9 1$ $9 1\frac{1}{8}$	28 6 28 6 28 6	9 51 9 51 9 51 9 51	29 7 8 29 7 8 29 8 8 29 8 1	9 9 1 9 9 1	30 30 30
8 8 8 9	27 5 27 5 27 6 27 6 27 6 27 6 27 6 27 6	9 11 9 12 9 11	28 71 28 71 28 8	9 5± 9 5± 9 5± 9 5±	29 87 29 91 29 91	9 9 1 9 10 9 10 1	30 30 30
8 91 8 91 8 91	27 68 27 7	9 1 1 9 1 1	28 8 8 8 8 8 8 8 8 9 8 9 8 9 8 9 8 9 8 9	9 6	29 101 29 101	9 101 9 101 9 101 9 101	30 30 30 31
8 9 1 8 9 1 8 9 1	27 78 27 78 27 88 27 81	9 2 9 2 1 9 2 1 1 1 1 1 1 1 1 1 1 1 1 1	28 9½ 28 9½ 28 10½	9 61 9 61 9 61 9 61	29 10 2 11 2 1 2 1 1 1 2 1 1 1 2 1 1 1 2 1	9 10 1 9 10 1 9 10 1	31 31 31
8 10 8 10	27 9 27 9	9 28 9 28 9 28 9 28	28 104 28 114 28 114	9 6 1 9 6 1 9 7	30 01 30 07 30 11	9 11	31
8 101 8 103 8 101	27 93 27 103 27 104 27 104	9 2½ 9 2½ 9 3	28 11	9 7± 9 7±	30 1 1 30 2	9 111 9 112 9 111	31 31 31
8 10	27 102 27 112 27 112 28 02	9 3½ 9 3½ 9 3¾	29 1 29 1 29 1	9 7	30 23 30 23 30 33 30 34	9 118 9 118 9 118 10 0	31 31 31 31
8 11 1 8 11 1	28 01	9 3 8 9 3 8 9 3 8 9 3 8 9 3 8 9	29 1 8 29 2 8 29 3	9 71 9 8	30 3 4 30 4 30 4 3	10 01 10 01	31
8 11 8 8 11 8 8 11 8	28 1½ 28 1½ 28 2	9 37 9 4	29 3 8 29 3 8	9 81 9 81 9 83	30 4\\\ 30 5\\\\\ 30 5\\\\\\\\\\\\\\\\\\\\\\	10 0 1 10 0 10 0 10 0 10 0 10 0 10 1	31 31 31
8 11 1 8 11 1 9 0	28 2½ 28 2½ 28 3½	9 4½ 9 4½ 9 4¾	29 4½ 29 4½ 29 5	9 8 1 9 8 1 9 8 1 9 8 1	30 6 30 6 30 6	10 0 1 10 0 1 10 1	31 31 31

	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.	Circum.
a.	Ft. In. 31 8½ 31 8%	Ft. In. 10 54 10 58	32 105	Ft. In. 10 92 10 10	Ft. In. 34 0 34 0§	Ft. In. 11 2½ 11 2½	Ft. In. 35 14 35 14
10 10 00 00 00 00 00 00 00 00 00 00 00 0	31 9½ 31 9½ 31 10 31 10¾	10 54 10 54 10 6	32 11 32 113 32 113 32 113	10 10± 10 10±	34 04 34 11	$\begin{array}{cccc} 11 & 2\frac{3}{8} \\ 11 & 2\frac{1}{2} \\ 11 & 2\frac{5}{8} \\ 11 & 2\frac{3}{4} \end{array}$	35 2½ 35 2½ 35 2½ 35 3½
2	31 10g 31 11g	10 61 10 61 10 63	33 05	10 10 8 10 10 10 10 10 10 10 10 10 10 10 10 10	34 1½ 34 1½ 34 2¾ 34 2¾	11 2½ 11 3	35 3\\\\ 35 4
2½ 2½ 2¾ 2¾	31 115 32 0 32 03	10 65 10 65 10 65	33 13 33 13	10 10½ 10 10½ 10 11	34 3½ 34 3½	11 3½ 11 3½ 11 3¾	35 4½ 35 4½ 35 5¼
2½ 2½ 2½ 2¾	32 03 32 13 32 13	10 6g 10 7	33 27	10 11½ 10 11¼ 10 11¾	34 3½ 34 4½ 34 4½	11 3½ 11 3½ 11 3¾	35 5\\\\ 35 6\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
27 3	32 2 32 2§	10 75 10 75 10 75	33 34	10 11½ 10 11½	34 5 34 5 ¹ / ₂	11 3 2 11 4	35 6 3 35 74
31 31 32 33	32 2\frac{3}{3} 32 3\frac{1}{3} 32 3\frac{1}{2}	10 74 10 74 10 75	33 4½ 33 4½	10 113 10 117 11 0	34 5 3 34 6 1 34 6 8	11 4½ 11 4½ 11 4¾	35 7± 35 8 35 8₹
31 35 35 37	32 35 32 43 32 43	10 7 10 8		11 0½ 11 0¼	34 7 34 73	11 4½ 11 4½ 11 4½	35 84 35 91 35 91
37	32 5\\\\ 32 5\\\\\\\\\\\\\\\\\\\\\\\\\\\	10 81 10 82 10 81	33 67	11 05 11 01 11 01	34 74 34 84 34 84	11 4 7 11 5	35 10 35 10§
41 41 48	32 5 8 32 6 1 32 6 8	10 8 10 8 10 8	33 74 33 8 33 83	11 03 11 07 11 1	34 9 34 9 8 34 9 8 34 9 8	11 5½ 11 5½ 11 5¾	35 111
45 45 45	32 7	-	33 9‡	11 1½ 11 1¼	34 10½ 34 10½	11 5½ 11 5½ 11 5¾	36 04
5	32 8		33 10 33 10		34 11 34 11 34 11 34 11	11 5 ² / ₈	36 1
51 51 53	32 9		33 11	$\begin{array}{cccccccccccccccccccccccccccccccccccc$		11 6½ 11 6½ 11 6¾	36 2

Di	iam.	Cir	cum.	Di	am.	Cir	cum.	Dia	m.	Cir	cum.	Di
Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.
11	61	36	3	11	10%	37	44	12	31	38	61	12
11	64	36	31	11	11	37	51	12	3 <u>1</u>	38	61	12
11	61	36	37					12	34	38	6	12
11	6#	36	41	11	111	37	54	12	3 j	38	7	12
111	7	36	48	11	111	37	6	12	3	38	71	12
├-		—		ii	114	37	6#	12	34	38	81	
11	71	36	5	11	111	37	61	12	37	38	81	12
11	71	36	5#	ii	114	37	71	12	4	38	87	12
11	78	36	57	11	114	37	71			_		12
11	71	36	64	11	117	37	77	12	41	38	91	12
11	78	36	6 8	12	0	37	8	12	41	38	9	12
11	74	36	7					12	44	38	10	12
11	77	36	7 8	12	01	37	84	12	4	38	101	12
11	8	36	74	12	01	37	98	12	4 8	38	107	12
-				12	0#	37	91	12	44	38	111	
11	81	36	81	12	01	37	97	12	47	38	114	12
11	8‡	36	81	12	0 4	37	101	12	5	39	0	12
11	8	36	9	12	02	37	104					12
11	81	36	9흏	12	0 4	37	111	12	5 k	39	0#	12
11	88	36	94	12	1	37	111	12	51	39	07	12
111	84	36	10å		•	٠,	***	12	5	39	14	12
11	87	36	101		•	-		12	51	39	14	12
11	9	36	10%	12	11	37	114	12	54	39	2	12
_		_		12	11	38	01	12	54	39	2#	 -
11	9 g	36	114	12	18	38	08	12	57	39	24	12
11	91	36	114	12	11	38	1	12	6	39	31	12
11	98	37	0	12	15	38	18			 - 		12
11	91	37	01	12	14	38	17	12	6 1	39	38	12
11	98	37	07	12	17	38	2 1	12	61	39	4	12
111	94	37	14	12	2	38	25	12	68	39	4	12
11	97	37	1#					12	61	39	41	12
11	10	37	2	12	21	38	3	12	6	39	51	12
-		-		12	21	38	38	12	64	39	5 <u>1</u>	-
11	10	37	21	12	28	38	34	12	6 7	39	51	12
11	101	37	27	12	21	38	41	12	7	39	6∦	12
11	10	37	31	12	25	38	4#					12
11	104	37	34	12	24	38	5	12	74	39	64	12
111	104	37	4	12	27	38	58	12	71	39	73	12
11	104	37	4월	12	3	38	54	12	78	39	71	12

Cir	cum.	Di	am.	Cir	cum.	D	am.	Cir	eum.	Di	am.	Cir	eum.
Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.
40		13	44	41	11	13	81	43	03	14	07	44	21
	10	13	41	41	118	13	84	43	14	14	1"	44	2
-		13	44	41	114	13	84	43	11		(5)	-	-
	105	13	44	42	01	13	87	43	17	14	11	14	91
40	108	13	44	42	04	13	9	43	21	14	11	44	34
40	10%	13	42	42	1			40	-4	14	11	44	3
40	114	13	47	42	18	13	91	43	24	14	18	44	4
40	114	13	5	42	14	13	91	43	31	14	14	44	41
41	0	10		42	14	13	92	43		14	18	44	47
41	08	13	51	40	01	13		43	31	14	14	44	54
41	04			42	21		91		37	14	17	44	5
41	11	13	51	42	21	13	98	43	41	14	2	44	6
_	-	13	58	42	22	13	93	43	48	-	_	-	_
41	14	13	54	42	31	13	97	43	5	14	24	44	61
41	2	13	54	42	34	13	10	43	51	14	21	44	67
41	24	13	54	42	48	-				14	2	44	71
41	24	13	5%	42	41	13	101	43	57	14	21	44	74
41	34	13	6	42	47	13	101	43	61	14	24	44	8
41	31	-			_	13	108	43	64	14	24	44	81
41	34	13	61	42	51	13	101	43	7	14	27	44	84
41	44	13	61	42	58	13	105	43	78	14	3	44	91
**	44	13	68	42	6	13	104	45	74	1.4		**	2.8
	-	13	64	42	61	13	107	43	81			1.5	-
41	44	13	64	42	67	13	11	43	84	14	31	44	91
41	51	13	64	42	71	_		-	-	14	34	44	97
41	51	13	64	42	78	13	11#	43	9	14	35	44	10
41	54	13	7	42	8	13	111	43	93	14	31	44	104
41	61		_	-		13	114	43	94	14	34	44	111
41	68	13	71	42	88	13	114	43	101	14	34	44	114
41	7	13	71	42	87	13	114	43	101	14	37	44	117
41	74	13	78	42	91	13	114	43	11	14	4	45	01
_		13	74	42	94	13	114	43	118	-			_
41	78	13	78	42	10	14	0	43	114	14	41	45	04
41	81	13	74	42	104	**		10	***	14	41	45	11
41	84	13	74	42	104	14	01	44	01	14	48	45	18
41	9	13	8	42	111	14	01	44	04	14	44	45	17
41	94	10	0	7.0	118	14	04	44	07	14	44	45	21
41	94	13	81	42	111	14	04	44	11	14	44	45	24
-		13	81	43	0	14		44	14	14		45	3
41	104	13	88		04	14	0±	44	21	14	5	45	38
41	105	10	Oğ	43	UE	14	04	44	2 B	1.4	0	40	08

D	cum.	Cir	ım.	Dia	eum.	Cir	am.	Di	cum.	Cir	ım.	Dia
Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.
15	75	47	17	15	55	46	94	14	32	45	51	14
15	74	47	2	15	6	46	94	14	41	45	51	14
15		_	_		65	46	93	14	44	45	53	14
15	81	47	21	15	63	46	97	14	5	45	51	14
15	81	47	21	15	71	46	10	14	53	45	54	14
15	87	47	23	15		-		_	53	45	53	14
15	91	47	24	15	71	46	101	14	61	45	57	14
15	95	47	24	15	77	46	101	14	65	45	6	14
-	101	47	23	15	88	46	10%	14				
15	101	47	27	15	84	46	101	14	7	45	61	14
15	107	47	3	15	91	46	104	14	73	45	61	14
15		~*			91	46	103	14	74	45	63	14
15	111	47	31	15	97	46	104	14	81	45	61	14
15		47		15 15	101	46	11	14	81	45	64	14
15	115	48	31		-		2.50	_	9	45	63	14
15	03	48	33	15 15	105	46	11#	14	93	45	62	14
15		48	35	15	111	46	111	14	93	45	7	14
-	07	48	33	15	111	46	113	14	-	_	-	_
15	11				112	46	114	14	101	45	71	14
15	15	48	37	15	01	47	115	14	101	45	71	14
15	2	48	4	15	05	47	114		107	45	73	14
15			7.00		1	47	117	14	111	45	71	14
15	28	48	41	15	11	47	0	15	115	45	75	14
15	24	48	44	15	_			-	01	46	73	14
15	31	48	43	15	17	47	01	15	01	46	73	14
15	31	48	41	15	21	47	01	15	07	46	8	14
-	4	48	45	15	24	47	08	15	-	-		_
15	44	48	44	15	3	47	01	15	11	46	81	14
15	44	48	47	15	33	47	05	15	15	46	81	14
15	51	48	5	15	37	47	04	15	2	46	83	14
15		_	_	-	41	47	03	15	23	46	81	14
15	51	48	51	15	45	47	1	15	27	46	84	14
15	57	48	51	15			-	_	31	46	84	14
15	61	48	54	15	5	47	14	15	34	46	87	14
15	64	48	51	15	53	47	11	15	4	46	9	14
-	71	48	55	15	54	47	13	15	15.	-		_
15	71	48	54	15	61	47	11	15	43	46	91	14
15	77	48	57	15	61	47	15	15	47	46	91	14
15	81	48	6	15	67	47	13		51		94	14

	Cir	cum.	Di	am.	Cir	cum.	D	iam.	Cir	cum.	D	iam.	Cir	cum.
1. 19 50 34	Ft. 49 49	In. 10½ 10¾ 11¼	Ft. 16 16	In. 2½ 3	Ft. 51 51	In. 01 01 01	Ft. 16 16 16	In. 71 71 74 73	Ft. 52 52 52	In. 1½ 1½ 1½ 2½	Ft. 16 16 16	In. 115 115 115	Ft. 53 53 53	In. 31/3 / 31/8
3	49 50	114	16 16	3\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	51 51	1 13	16 16 16	7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	52 52 52	25 31 31 31	16 17	117	53 53	43
1814	50 50 50	01 07 11	16 16 16	38 31 35 38	51 51 51	13 21 21 21	16 16	77	52 52	37 41	17 17 17	01 01 01 01	53 53 53	54 58 6
क्षेत्र नेत्र क्षेत्र व	50 50	14 18 2	16 16 16	33 34 4	51 51 51	25 31 33 34	16 16	81 81	52 52	4 ½ 5	17 17	0½ 0å	53 53	68 68
2479	50 50 50	25 24 31	16 16	4½ 4½	51 51	41/2 41/2	16 16 16	84 84 84 84	52 52 52	58 54 64	17 17 17	05 05 1	53 53 53	7± 7± 8
诗	50 50	3½ 3½	16 16 16	43 45 45	51 51 51	47 54 55	16 16 16	84 84 9	52 52 52	65 7 73	17 17	1± 1±	53 53	88 88 84
)을 ()을 ()을	50 50 50	44 44 58	16 16 16	4 4 4 4 5	51 51 51	6 6 6	16 16	9½ 9¼	52 52	7 1 8 1	17 17 17	13 11 15 15	53 53	9± 9± 10
0육 0중 1	50 50 50	5½ 5½ 6¼	16	51	51	71	16 16 16	98 91 98	52 52 52	9 9 93	17 17 17	$\frac{1\frac{3}{4}}{1\frac{7}{8}}$	53 53 53	10 ³ / ₄ 10 ³ / ₄ 11 ¹ / ₈
1 1 1 1	50 50	6 <u>5</u> 7	16 16 16	51 51 51 51	51 51 51	78 8 88	16 16 16	9 4 9 8 10	52 52 52	9# 10# 10#	17 17	2½ 2¼	53 53	114
1음 1음 1음	50 50 50	7± 7₹ 8±	16 16 16	55 53 53	51 51 51	8# 9# 9#	16 16	10½ 10½	52 52	11 11a	17 17 17	25 21/2 25 25	54 54 54	01 01 11
13 13 2	50 50 50	85 9 93	16	6 61	51	10	16 16 16	10 ³ / ₂ 10 ¹ / ₂ 10 ⁵ / ₂	52 53 53	11# 0# 0#	17 17 17	24 24 3	54 54 54	1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1
2½ 2½	50 50	93 101	16 16 16	61 63 61	51 51 51	108 1118 1118	16 16 16	10 4 10 4 11	53 53 53	07 11 18	17	3½ 3½	54 54	25
21/2	50 50	10g 11	16 16	65 63	52 52	0 03 8	16	111	53	2	17 17	3 3 3 3	54 54	33
25	50	11章	16 16	6 1 7	52 52	03 1분	16 16	111 118	53 53	$\frac{2\frac{1}{2}}{2\frac{7}{8}}$	17 17	35	54 54	44

Di	In. Ft. In.		cum.	Diam.		Cir	cum.	Dia	am.	Cir	cum.	Dia	am.
Ft.	In	Fe.	In	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In.	Ft.	In
17	37	54	5	17	81	55	63	18	01	56	81	18	4
17	4	54	54	17	81	55	64	18	04	56	81	18	5
••			og	17	84	55	71	18	03	5€	87	10	.,
	100	50		17		55	71	18		56		-	
17	41	54	53		81				07		91	18	5
17	44	54	61	17	85	55	73	18	1	56	95	18	5
17	48	54	65	17	84	55	83					18	5
17	41	54	7	17	87	55	84	18	11	56	10	18	5
17	45	54	78	17	9	55	91	18	14	56	101	18	5
17	44	54	73			-		18	18	56	10%	18	5
17	47	54	81	17	91	55	91	18	11	56	114	18	5
17	5	54	81	17	91	55	97	18	15	56	114	18	6
			0 9	17	93	55	104	18	13	57	0		_
			0.	17	91	55	108	18	17	57	04	10	
17	51	54	87	17	94	55	111	18	2	57	03	18	6
17	51	54	98	17	93	55	111	-		7.5		18	6
17	5書	54	94	17	97	55	117	18	21	57	11	18	6
17	51	54	101	17	10	56	01	18	21	57	15	18	6
17	55	54	101	~	•	00	04	18	24	57	2	18	6
17	54	54	107	17	101	56	05	18	21	57	23	18	6
17	5%	54	111	17	101	56	1	18	24	57	23	18	6
17	6	54	115	17	104	56		18		57		18	7
			_				13		23		31		_
17	61	55	01	17	101	56	17	18	27	57	31	18	7
17	61	55	01	17	105	56	24	18	3	57	4	18	7
17	63	55	07	17	10章	56	25		-		-	18	7
17				17	10g	56	3	18	31	57	43	18	7
	61	55	11	17	11	56	33	18	31	57	43		7
17	65	55	14	-	-	-	_	18	33	57		18	
17	63	55	2	17	111	56	34	18	31	57	51	18	7
17	67	55	23	17	111	56	41	18	35	57		18	7
17	7	55	27	17	113	56	41	18	33	57	63	18	8
_	_	-	_	17	111	56	5	18	37	57	63	-	_
17	71	55	31	17	114	56	53	18	4	57		18	8
17	71	55	34	17	113	56	53	-	_	_	- 0	18	8
17	73	55	4	17	117	56		18	41	57	74	18	8
17	71	55	43	18	0	56		18	41	57		18	8
17	75	55	43	-3		-	- 2	18	43	57		18	8
17	74	55	51	18	01	56	67	18	41	57		18	8
17	77	55	51	18	01	56		18	44	57		18	8
17	8	55	6	18	03			18	43	57		18	9

Diam.	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.	Circum.
Pt. In. 18 9½ 18 9½ 18 9½ 18 9½ 18 9½ 18 9½ 18 9½ 18 9½	Ft. In. 58 114 58 118 59 0 59 08 59 08 59 14 59 14 59 2	Ft. In. 19 11/2 19 11/2 19 11/2 19 11/2 19 11/2 19 11/2 19 11/2 19 2	Ft. In. 59 113 60 01 60 1 60 13 60 21 60 21	Ft. In. 19 5½ 19 5½ 19 5½ 19 5½ 19 5½ 19 5½ 19 5½ 19 5½	Ft. In. 61 03 61 04 61 11 61 11 61 15 61 22 61 24 61 3	Ft. In. 19 9½ 19 9½ 19 9½ 19 9½ 19 9½ 19 9½ 19 9½ 19 10	Ft. In. 62 0\$\frac{1}{6}\$ 62 1\$\frac{1}{6}\$ 62 2\$\frac{1}{6}\$ 62 2\$\frac{1}{6}\$ 62 2\$\frac{1}{6}\$ 62 3\$\frac{1}{6}\$ 62 3\$\frac{1}{6}\$
18 10± 18 10± 18 10± 18 10± 18 10± 18 10± 18 11±	59 28 59 28 59 38 59 38 59 38 59 48 59 48 59 58	19 2½ 19 2½ 19 2½ 19 2½ 19 2½ 19 2½ 19 2½ 19 3	60 2	19 6± 19 6± 19 6± 19 6± 19 6± 19 6± 19 6± 19 6± 19 6± 19 7	61 3½ 61 3½ 61 4½ 61 4½ 61 5 61 5½ 61 5½ 61 6½	19 10± 19 10± 19 10± 19 10± 19 10± 19 10± 19 10± 19 10±	62 4 62 4 62 5 62 5 62 62 68 62 68
18 111 18 112 18 113 18 113 18 113 18 113 18 113 18 113 19 0	59 51 59 51 59 61 59 61 59 7 59 71 59 71 59 81	19 3½ 19 3½ 19 3½ 19 3½ 19 3½ 19 3½ 19 3½ 19 3½ 19 3½	60 6 60 6 60 6 60 7 60 7 60 8 60 8 60 8	19 7± 19 7± 19 7± 19 7± 19 7± 19 7± 19 7± 19 8	61 68 61 7 61 78 61 84 61 86 61 98	19 11± 19 11± 19 11± 19 11± 19 11± 19 11± 19 11± 20 0	62 71 62 71 62 8 62 83 62 83 62 91 62 91 62 91
19 01 19 02 19 03 19 03 19 04 19 05 19 05 19 05 19 1	59 8 5 59 9 59 9 59 9 59 10 5 59 10 5 59 11 59 1	19 4± 19 4± 19 4± 19 4± 19 4± 19 4± 19 5	60 91 60 91 60 10 60 103 60 104 60 111 60 111 60 111	19 8½ 19 8½ 19 8½ 19 8½ 19 8½ 19 8½ 19 8½ 19 8¾	61 94 61 103 61 104 61 11 61 114 61 114 62 03 62 04	20 01 20 01 20 03 20 01 20 05 20 01 20 01	62 10\$ 62 10\$ 62 11\$ 62 11\$ 62 11\$ 63 0\$ 63

OBSERVATIONS ON TABLE I.

I do not intend to enter into any laboured argument to prove the general utility of these Tables, as their simplicity and clearness are sufficient to stamp their value to the artist and mechanic. It will be clearly perceived, on inspection, that the Table commences with as small a diameter as is generally used in hoops and rings, viz. one inch, and increases by the regular gradation of one-eighth of an inch, to upwards of twenty feet; and in the column marked Circumference, against each Diameter stand the respective circumferences: hence all that is necessary on inspecting these Tables is to enter into them with any proposed diameter or circumference, and an answer to the inquiry is immediately obtained.

Example.—Required the circumference of a circle, the diameter being 11 feet 7% inches.

In the column of circumferences, opposite the given diameter, stands 36 feet 7 inches, the circumference required.

But it will be necessary to observe, that in the formation of hoops and rings a contraction of the metal takes place. Now, the just allowance for this contraction is the exact thickness of the metal, which must be added to the diameter.

Ex. In making a hoop whose diameter inside is 6 feet $9\frac{1}{8}$ inches, the thickness of the iron being $\frac{1}{2}$ inch, this $\frac{1}{4}$ inch must be added to the given diameter, which will make it 6 feet $9\frac{5}{8}$ inches; this will allow $1\frac{5}{8}$ inch for the contraction in bending in a hoop of the above diameter, giving the circumference or length of iron required for the hoop, 21 feet $4\frac{3}{8}$ inches.

The foregoing example appertains to the formation of hoops or iron bent on the flat; but in the formation of rings or iron bent on the edge, the same rule must also be followed, only taking care to add the breadth instead of the thickness. As for example:


To make a ring whose inside diameter is 8 feet 2½ inches, the *breadth* of the iron being 2½ inches; by adding the 2½ inches to the given diameter, will increase it to 8 feet 4½ inches; opposite to this diameter in the column of circumferences stands 26 feet 4½ inches, being the length of iron necessary

for the ring.

The foregoing observations relate more particularly to plain hoops and rings; but as respects the hoops that are on the wheels of railway carriages, a difference must be observed, which is as follows: These hoops having a flange projecting on the one edge of the surface, it will be necessary, in addition to the thickness of the metal, to add two-thirds of the thickness of the flange to the diameter, as the flange side would contract considerably more than the plain surface; this is supposing the tires are in a straight form, but, in general, they come from the iron-works in a curved state, as represented in the engraving, figure 3. In the latter case, it will be only necessary to add the thickness of the bare metal, as the aforesaid portion of the thickness of the flange is allowed for in the curve. By having had some experience in hoops of this nature, I have found that the curve may be exactly obtained, by using four times the circumference of the hoop as a radius.

In the engraving, fig. 1, is given a representation of a tire in its curved state, fixed to the blocks, and in the act of being bent; but if the tire has not been previously curved, it may easily be done in the

operation of bending: the smith must pay particula attention to this, or he will have his hoop bent in a angle.



The following is a description of the figures 1 and Figure 3. 2: A is a strong cast-iron ground-plate,

in which ffff are four slot-holes for the bolts a a a a to slide in, and are for the purpose of screwing down the two semicircular blocks, to prevent them from moving whilst the tire is in the act of being bent. BB is the block in two halves, opening at cc; the aperture is cut in a conical form, for the reception of the two conical wedges D D, on which the tire E is represented. hh are two holes in the ground-plate, into which the wedges are driven whilst blocking the r is a strong cramp for screwing the tire firm to the block whilst in the act of being bent round it: it is made with a joint at the top, and secures the tire to the block by means of a strong square-threaded screw, which screws into a boss on the innermost leg.

But the practical utility of this Table is not confined to smiths alone; to the millwright it will be found equally useful and expeditious, as on a bare inspection of the Table he may ascertain the diameter of any wheel that may be required to be made, the pitch and number of

teeth being given.

Ex. Suppose a wheel were ordered to be made to contain sixty teeth, the pitch of the teeth to be 3½ inches, the dimensions of the wheel may be ascertained simply as follows:

Multiply the pitch of the tooth by the

number of teeth the wheel is to contain, and the product will be the circumference of the wheel: thus

Inches. $3\frac{7}{8}$ the pitch of the tooth, $10 \times 6 = 60$, the number of teeth, 3 $2\frac{3}{4}$

Feet 19 41 the circumference of the wheel.

However, by inspecting the column marked Circumference, I find the nearest number to this is 19 feet $4\frac{\pi}{3}$ inches, which is the eighth of an inch less than the true circumference; but if this $\frac{\pi}{3}$ were divided into sixty equal parts, it would not make the difference of a single hair's-breadth in the size of each tooth; so that it is sufficiently near for any practical purpose. The diameter answering to this circumference is 6 feet 2 inches; consequently, with one half of this number as a radius, the circumference of the wheel will be described.

The manner in which the foregoing Table of Circumferences is found is as follows: Taking the diameter at unity, we have by decimal proportion

In. In. As 1:3.1416::1.:3.1416,

and the decimal 1416 multiplied by 8, gives the circumference for 1 inch of diameter 31 inches.

In these Tables the number 3.1416 is divided by 8, which gives .3927. This decimal proportion has been used as a constant, and the sum multiplied by 8 gives the excess above the decimal value in eighths of an inch.

EXAMPLE.

Diam.	in. 3	Circum. $1416 \times 8 = \frac{1}{4} \cdot 1328$
		+ ·3927
11		5343 × 8 = ½·2744 +·3927
`1‡		-9270 × 8 = \$.7160 + .3927
18		·3197 × 8 = ½·6576 +·3927
11		·7124 × 8= \$·6922 +·3927
15	5	·1051 × 8 = ·8408 +·3927
14	5	·4978 × 8=\frac{2}{8}.9824 +3927
13	5	$ \begin{array}{r} $
2	6	·2832 × 8 = ½·2656

^{.—}The nearest eighth of an inch is only given, as I : it quite unnecessary to add the first decimal figure in ble.

J. F.

TABLE II.*

SHOWING THE WEIGHT OF A LINEAL FOOT OF MALLEABLE RECTANGULAR OR FLAT IRON,

From an Eighth of an Inch to Three Inches thick; advancing by an Eighth and Quarter of an Inch in breadth.

Thick.	Broad.	ths.	oz.	Thick.	Broad.	ibs.	oz.	Thick.	Broad.	the	. oz.
in.	in.			in.	in.			in.	in.		
18	14 3 3 1 3 5 3 3 4 7 3	0	1.6	3	37	1	9.7	18	71/2	3	1.8
	용	0	2.4		4	1	10.5		7 8 7 4	3	2.6
	2	0	3.3		41	1	11.3		74	3	3.4
	8	0	4.1		44	1	12.2		73	.3	4.3
	幸	0	5.0	1	48	1	13.0		8	3	5.1
	- 8	0	5.8	1	41	1	13.8		81	3	5.9
	1	0	6.6	1	48	1	14.7		81	3	6.7
	13	0	7.5	1	44	1	15.5		83	3	7.6
	11	0	8.3		43	2	0.3		81	3	8.4
	13 11 11	0	9.1		5	2	1.2		88	3	9.2
	15	0	9.9		51	2	2.0		83	3	10.1
	15		0.8	1	51	2	2.8		87	3	11.0
	13		1.6	1 1	53	2	3.7		9	3	11.7
	178		2.4		51	2	4.5		91	3	12.6
	2		3.2	1	5 5 5 3 4	2	5.3		91	3	13.4
	21/8		4.1	1 1	54	2	6.1		98	3	14.2
	21		4.9	1 1	57	2	7.0		91	3	15.0
- 1	23		5.7		6	2	7.8		95	3	15.9
	21/2	1	0.6		61 61	2	8.6		94	4	0.7
	25	1	1.4	1	C3	2 2	9.5		97	4	1.5
	23		2.2	1 1	63	2	10.3		10	4	2.4
	278		3.0		61	2	11.1		101	4	3.2
- 1	3		3.9		65	2	12.0		101	4	4.0
- 1	31		4.7		63	2 2	12.8		103	4	4.9
- 1	34		5.5		67	2	13.6		101	4	5.7
- 1	33	1	6.4		7	2	14.4		105	4	6.5
	31	1	7.2		71	2	15.3		104	4	7.3
	35		8.9		7± 7=	3	1.0		10 2 11	4	9.0
	34	1	0.9	1	18	3	1.0		11	4	9.0

^{*} James Foden.

						1		
Thick.	Broad.	ibs. os.	Thick.	Broad.	ibs. os.	Thick.	Broad.	the. os.
in.	in. 111111111111111111111111111111111111	4 9.8 4 10.7 4 11.5 4 12.3 4 13.2 4 14.0 4 14.8 4 15.6	in.	in. 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	3 5·1 3 6·7 3 8·4 3 10·1 3 11·7 3 13·4 3 15·0 4 0·7 4 2·4	in.	in. 88478 9 16 19 16 19 16 19 16 19 16 19 16 19 16 16 16 16 16 16 16 16 16 16 16 16 16	7 2·5 7 4·2 7 5·8 7 7·5 7 9·1 7 10·8 7 12·5 7 14·1 7 15·8
+	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0 6.6 0 8.3 0 10.0 0 11.6 0 13.2 0 14.9 1 0.6 1 2.2 1 3.9 1 5.5 1 7.2 1 10.5 1 10.5 1 10.5 2 2.8 2 4.5 2 9.5 2 11.1		55555556666666777777777777777777777777	4 4·0 4 5·7 4 7·3 4 10·7 4 12·3 4 14·0 4 15·6 5 1·3 5 4·6 5 5·3 5 13·0 5 14·6 5 12·3 5 13·0 6 3·6 6 3·6 6 5·2 6 8·5 6 8·5	-	9% 9% 10 10% 10% 10% 10% 10% 11% 11% 11% 11%	8 1·4 8 3·1 8 6·4 8 8·1 8 9·7 8 11·4 8 13·1 9 0·4 9 2·0 9 3·7 9 10·3 9 12·0 9 13·7 9 15·3 0 14·9 1 1·3 1 3·8
	3	2 12·8 2 14·4 3 0·1 3 1·8 3 3·4		8 8 8 8 8 8 8 8	6 10·2 6 12·0 6 13·5 6 15·2 7 0·8		18 14 18 18 18	1 6·3 1 8·8 1 11·3 1 13·8 2 0·3

Thick.	Broad.	ibs. oz.	Thick.	Broad,	ths. oz.	Thick.	Broad.	ibs. oz.
in.	in. 14 1 2 1 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2	2 2·7 2 5·2 2 7·7 2 10·2 2 12·7 2 15·1 3 1·6 3 4·1 3 6·6	in. 3 8	in. 66 66 66 66 7 7 16 14 26 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	7 14·6 8 1·1 8 3·6 8 6·1 8 8·6 8 11·1 8 13·5 9 0·0 9 2·5	in. 38	in. 11 11 11 11 11 11 11 11 11 11 11 11 11	13 10·5 13 13·0 13 15·5 14 2·0 14 4·5 14 7·0 14 9·4 14 11·9 14 14·4
	2 3 3 3 3 3 3 3 3 4 4 4 4 4 4 4 4 4 4 4	3 9·1 3 11·6 3 11·1 4 0·5 4 3·0 4 5·5 4 8·0 4 10·5 4 13·0 4 15·4 5 1·9 5 4·4 5 6·9 5 9·4		7777 8 8 4 4 5 1 4 5 5 4 7 5 7 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 9 1 8 8 8 8 8	9 5·0 9 7·5 9 10·0 9 12·4 9 14·9 10 1·4 10 3·9 10 6·4 10 8·9 10 11·3 10 13·8 11 0·3 11 2·8 11 5·3	ż	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 10·4 1 13·8 2 1·1 2 4·4 2 7·7 2 11·0 2 14·3 3 1·6 3 4·9 3 8·3 3 11·6 3 14·9 4 2·2
	445555555666	5 11·9 5 14·3 6 0·8 6 3·3 6 5·8 6 8·3 6 10·8 6 13·2 6 15·7 7 2·2 7 4·7 7 7·2 7 9·7 7 12·2		94 95 95 95 95 95 10 105 105 105 105 105 105 105 105	11 7·8 11 10·3 11 12·7 11 15·2 12 1·7 12 4·2 12 6·7 12 9·2 12 11·6 12 14·1 13 0·6 13 3·1 13 5·6 13 8·1		2 2 2 3 3 3 3 3 3 3 3 3 4 4 4 4 4 4 4 4	4 5.5 4 8.8 4 12.1 4 15.4 5 2.8 5 6.1 5 9.4 5 12.7 6 0.0 6 3.3 6 6.6 6 9.9 6 13.3 7 0.6

Thick.	Broad.	ibs. oz.	Thick.	Broad,	ths. oz.	Thick.	Broad.	ths. oz.
in.	11.4444455555555556666666677777	7 3·9 7 7·2 7 10·5 7 13·8 8 1·1 8 4·4 8 7·7 8 11·1 8 14·4 9 1·7 9 5·0 9 8·3 9 11·6 9 14·9 10 2·2 10 5·6 10 8·9 10 12·2 10 15·5 11 2·8 11 6·1 11 9·4 11 12·7 12 0·0 12 3·4 12 6·7	in.	in. 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	14 14·4 15 1·7 15 5·0 15 8·4 15 11·7 15 15·0 16 2·3 16 5·6 16 8·9 16 12·2 16 15·5 17 2·8 17 6·2 17 9·5 17 12·8 18 0·1 18 6·7 18 10·0 18 13·3 19 0·7 19 10·6 19 13·9	in. §	11.26 22 23 3 3 3 3 3 3 3 3 3 4 4 4 4 4 4 4 4	5 6-9 5 11-0 5 15-2 6 3-3 6 7-5 6 11-6 6 15-7 7 8-0 7 12-2 8 0-3 8 4-4 8 8-6 8 12-7 9 0-9 9 5-0 9 13-3 10 1-4 10 5-6 10 9-7 10 13-8 11 2-0 11 6-1 11 10-3 11 11-1
	7555475 7778 8514451-1955447 8688 8684 8684	12 10-0 12 13-3 13 0-6 13 3-9 13 7-2 13 10-5 13 13-9 14 1-2 14 4-5 14 7-8 14 11-1	\$	14 15 15 15 15 15 15 15 15 15 15 15 15 15	2 9·4 2 13·5 3 1·6 3 5·8 3 9·9 3 14·1 4 2·2 4 6·3 4 10·5 4 14·6 5 2·8		556 664 56 66 66 66 67 7 7 18	12 2·5 12 6·7 12 10·8 12 15·0 13 3·1 13 7·2 13 11·4 13 15·5 14 3·7 14 7·8 14 11·9

Thick.	Broad.	lbs. oz.	Thick.	Broad.	ibs. oz.	Thick.	Broad.	lbs. oz.
in.	in. 74 78	15 0·1 15 4·2	in. 5	in. 11 2 12	24 9·3 24 13·4	in.	in. 53 53	14 4·5 14 9·5
	71	15 8.4		-			6	14 14.4
	75	15 12.5	3	11	3 11.6	9	61	15 3.4
W)	74	16 0.6	1	15	4 0.5		64	15 8.4
П	77	16 4.8	1	15	4 5.5		68	15 13.3
	8	16 8.9	1	17	4 10.5		61	16 2.3
118	81	16 13.1	1	2	4 15.4	ı	65	16 7.3
119	81	17 1.2	1	21	5 4.4	1	63	16 12-2
- 1	88	17 5.3	1	21	5 9.4		67	17 1.2
. 1	81	17 9.5		28	5 14.3	1	7	17 6.2
- 1	88	17 13.6	1	21	6 3.3		71	17 11-1
- 1	84	18 1.8	1	25	6 8.3		71	18 0·1 18 5·1
	8 1 9	18 5·9 18 10·0		23	6 13·2 7 2·2		78	18 5·1 18 10·0
- 1	91	18 14.2	1	27 3	7 7.2		7± 7±	18 15.0
- 17	91	19 2.3	1	31	7 12.2		73	19 4.0
ш	93	19 6.5	1	34	8 1.1		77	19 8.9
11)	91	19 10-6	1	33	8 6.1		8	19 13.9
	95	19 14.7	1	31	8 11.1		81	20 2.9
м	93	20 2.9	1	35	9 0.0		81	20 7.8
П	97	20 7.0	1	33	9 5.0		88	20 12.8
	10	20 11.2	1	37	9 10-0		81	21 1.8
ш	101	20 15.3	1	4	9 14.9		85	21 6.7
. 14	104	21 3.4		418	10 3.9		83	21 11.7
	108	21 7.6	N.	44	10 8-9		87	22 0.7
	101	21 11.7		48	10 13.8		9	22 5.7
Ш	10₫	21 15.9		41	11 2.8		91	22 10.6
	104	22 4.0	1	45	11 7.8		91	22 15.6
Ш	107	22 8.1		43	11 12.7		98	23 4.6
	11	22 12.3		47	12 1.7		91	23 9.5
1/2	111	23 0.4		5	12 6.7		95	23 14.5
	114	23 4.6		51	12 11.6		94	24 3.5
	118	23 8.7		51	13 0.6		97	24 8.4
	111	23 12.8		58	13 5.6		10	24 13.4
	115	24 1.0		53	13 10.6		104	25 2.4
	114	24 5.1	11	55	13 15.5		101	25 7.3

rs. Ths. oz.	Thick.	Broad.	the. oz.	Thick.	Broad,	qrs. fbs. oz.
0.05.10.0	in.	in.	10.00	in.	in.	
0 25 12.3	3	44	13 0.6	1 3	91	0 26 7.1
0 26 1·3 0 26 6·2		48	13 6.4		91	0 26 12-9
	110	47	13 12.2	1	98	0 27 2.7
0 26 11·2 0 27 0·2		47	14 2·0 14 7·8		91	0 27 8.5
0 27 5.1		5 51		1	95	0 27 14.3
0 27 10-1	11.8	51	14 13·6 15 3·4		94	1 0 9.8
0 27 15-1		58	15 9.2		10	1 0 15.6
1 0 4.0		54	15 15.0		101	1 1 5.4
1 0 9.0		54	16 4.8		101	1 1 11.2
1 0 14.0		5年	16 10.6		104	1 2 1.0
1 1 3.0			17 0.4		101	1 2 6.8
1 1 7.9	. 4	5 4	17 6.2		105	1 2 12.6
1 1 12.9		61	17 12.0		104	1 3 2.4
1 1 12 9		61	18 1.8		10%	1 3 8.2
0 5 1.1			18 7.6		11	1 3 14.0
0 5 6.9		6 8 6 1	18 13.4		111	1 4 3.8
0 5 12.7		65	19 3.1		114	1 4 9.6
0 6 2.5		64	19 8.9		113	1 4 15.4
0 6 8.3	1.3	67	19 14.7		113	1 5 5.2
0 6 14.1		7	20 4.5		115	1 5 11.0
0 7 3.9	- 1	71	20 10-3		113	1 6 0.8
0 7 9.7		71	21 0.1		117	1 6 6.6
7 15.5	- 1	74	21 5.9		12	1 6 12.4
0 8 5.3		71	21 11.7		12	1 0 124
8 11.1	- 1	74	22 1.5	1	2	0 6 10.0
9 0.9	- 1	74	22 7.3	*	21	0 7 0.6
9 6.7		77	22 13.1	1	21	0 7 7.2
9 12.4		8	23 2.9	- 1	23	0 7 13.8
10 2.2		81	23 8.7		21	0 8 4.4
10 8.0		81	23 14.5		25	0 8 11-1
10 13.8	- 1	84	24 4.3		23	0 9 1.7
11 3.6		81	24 10-1		27	0 9 8.3
11 9.4		85	24 15.9		3	0 9 14.7
11 15.2		83	25 5.7		31	0 10 5.6
12 5.0		87	25 11.5		31	0 10 12.2
12 10.8		9	26 1.3		33	0 10 12 2

Thick.	Broad.	lbs. oz.	Thick.	Broad.	qrs. Ibs. oz.	Thick.	Broad.	qrs. it
in.	in.	11 0.4	in.	in.	0.01.1.0	in.	in.	
ı	31	11 9.4	1	68	0 21 1.8	1	91	1 :
iU	35	12 0.1		61	0 21 8.4		98	1 3
Ш	34	12 6.7		65	0 21 15.0		91	1 3
	37	12 13·3 13 3·9		63	0 22 5.7		98	1 3
		13 10.6		67	0 22 12.3		94	1 4
ш	41 41	the second section of		7	0 23 2·9 0 23 9·5		97	1 1
				71	0 23 9.5		10	1 8
	48	14 7.8		71	0 24 6.6	63.	101	1 8
- 1	41	15 5.0		78	0 24 13.4		10‡ 10‡	1 6
	48 48	15 11.7		74	0 24 134	6.0	104	1 6
- 1		16 2.3		75	0 25 10.6		105	1 2
- 1	4 7 5	16 8.9		74	0 26 1.3		102	1 2
- 1	51 51	16 15.5		7 1 8	0 26 7.9	(a)	107	1 8
- 1	51	17 6.2		81	0 26 14.5		11	1 8
М	54	17 12-8		81	0 27 5.1		114	1 8
- 1	51	18 3.4		83	0 27 11.8		111	1 9
- 1	55	18 10.0		81	1 0 2.4		118	1 9
	54	19 0.7	1	85	1 0 9.0	TO	111	1 10
- 1	57	19 7.3	1	84	1 0 15.6	10	115	1 10
- 1	6	19 13-9		87	1 1 6.3	3.0	113	1 10
	61	20 4.5		9	1 1 12.9		117	1 11
- 1	61	20 11.2		91	1 2 3.5		12	1 11

Thick.	Broad.	qrs. lbs. oz.	Thick.	Broad.	qrs. lbs. oz.	Thick.	Broad.	qrs. tbs. oz.
in. 14	in. 24 22 23 23 3	0 8 6·1 0 9 5·0 0 10 3·9 0 11 2·8	in. 11	in. 11½ 11¾ 12	1 14 13·5 1 15 12·4 1 16 11·4	in. 11	in. 104 11 114 114	1 16 8·0 1 17 8·6 1 18 9·2 1 19 9·7
1	31 31 32 34	0 12 1·7 0 13 0·6 0 13 15·5	11	2½ 2¾ 3	0 10 5·6 0 11 6·1 0 12 6·7		114 12	1 20 10·3 1 21 10·8
	4 4 4 4 4 4 5 5 5 5 6 6 6 6 6 7 7 7 7 8 8 8 8 9 9 9 9 9	0 14 14·4 0 15 13·3 0 16 12·2 0 17 11·1 0 18 10·0 0 19 8·9 0 20 7·8 0 21 6·8 0 22 5·7 0 23 4·6 0 24 3·5 0 25 2·4 0 26 1·3 0 27 0·2 0 27 15·1 1 0 14·0 1 1 12·9 1 2 11·8 1 3 10·7 1 4 9·6 1 5 8·5 1 6 7·4 1 7 6·3 1 8 5·2		34 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	0 13 7·2 0 14 7·8 0 15 8·4 0 16 8·9 0 17 9·5 0 18 10·0 0 19 10·6 0 20 11·2 0 21 11·7 0 22 12·3 0 23 12·8 0 24 13·4 0 25 14·0 0 26 14·5 0 27 15·1 1 0 15·6 1 2 0·2 1 3 0·8 1 4 1·3 1 5 1·9 1 6 2·4 1 7 3·0 1 8 3·6 1 9 4·1	18	2 \$\frac{1}{3} \frac{1}{4} \fr	0 12 8·3 0 13 10·6 0 14 12·8 0 15 15·0 0 17 1·2 0 18 3·4 0 19 5·6 0 20 7·8 0 21 10·1 0 22 12·3 0 23 14·5 0 25 0·7 0 26 2·9 0 27 5·1 1 0 7·4 1 1 9·6 1 2 11·8 1 3 14·0 1 5 0·2 1 6 2·4 1 7 4·7 1 8 6·9 1 9 9·1 1 10 11·3
	10 10 10 10 10 10 11 11	1 9 4·1 1 10 3·0 1 11 1·9 1 12 0·8 1 12 15·7 1 13 14·6		91 91 92 10 101 104	1 10 4·7 1 11 5·2 1 12 5·8 1 13 6·4 1 14 6·9 1 15 7·5		84 9 94 94 10	1 11 13·5 1 12 15·7 1 14 2·0 1 15 4·2 1 16 6·4 1 17 8·6

Thick,	Broad.	qrs. ths. oz.	Thick.	Broad.	qrs. ibs. oz.	Thick,	Broad.	qr
in. 13	in. 101 101 103 103	1 18 10·8 1 19 13·0 1 20 15·2	in, 11/2	in. 10 10 10 10 10	1 21 10·8 1 22 14·7 1 24 2·6	in. 15	in. 10 101 101 101	1 1 2
	11 11‡ 11‡	1 22 1·5 1 23 3·7 1 24 5·9		104 11 114	1 25 6·5 1 26 10·3 1 27 14·2		103 11 114	2 2
1	115 12	1 25 8·1 1 26 10·3		11½ 11¾ 12	2 1 2·1 2 2 5·9 2 3 9·8		11½ 11¾ 12	2 2
11	3 3 3 3	0 14 14·4 0 16 2·3 0 17 6·2	15	31	0 17 7·8 0 18 13·4	13	3½ 3¾	0
	33 4	0 18 10·0 0 19 13·9		31 31 4	0 20 2·9 0 21 8·4		4	0
	44	0 21 1·8 0 22 5·7		41 41	0 22 13·9 0 24 3·5		41	0
	44 5 54	0 23 9·5 0 24 13·4 0 26 1·3		43 5 51	0 25 9·0 0 26 14·5 1 0 4·0		5 5 5 5	1 1 1
	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	0 27 5·1 1 0 9·0		5½ 5¾	1 1 9·6 1 2 15·1		53 6	1
	6 64 64	1 1 12·9 1 3 0·8 1 4 4·6		6	1 4 4·6 1 5 10·2 1 6 15·7		61 61 63	1 1 1
	64 7	1 5 8·5 1 6 12·4		6 ¹ / ₂ 6 ³ / ₄ 7	1 8 5.2		7 71	i
	7± 7±			7± 7±	1 11 0·3 1 12 5·8		7± 7±	1
	73 8 81	1 10 8·0 1 11 11·9 1 12 15·7		74 8 81	1 13 11·3 1 15 0·9 1 16 6·4		8 81 81	1 1
	81 83 83	1 14 3·6 1 15 7·5		81 83 84	1 17 11.9		84 9	i
	91	1 16 11·4 1 17 15·2		9 94	1 20 7·0 1 21 12·5		91	1
	9½ 9¾	1 19 3·1 1 20 7·0		9± 9±	1 23 2·0 1 24 7·6		9 1 10	2

Thick.	Broad.	qrs. ibs	02.	Thick.	Broad.	qrs.	lbs.	oz.	Thick.	Broad.	qrs.	ibs.	oz.
in. 13	in. 101 101 101 104 11	2 3 2 4 2 6 2 7	6·5 13·7 4·9 12·1	in. 1 ² / ₈	in. 103 11 114 114 114	2 2 2 2	10 12 13 15	12·1 4·9 13·8 6·6	in. 2	in. 11½ 11¾ 11¾ 12	2 2 2	20 21 23	2·8 13·3 7·8
	111 111 112	2 9 2 10 2 12	3·2 10·4 1·6		115 12	2 2	16 18	15·4 8·3	2½	41 41 42 43	1 1 1	1 3 5	14·5 10·7 6·8
	12	2 13	8.8	2	4 41	0	26 0	7·9 2·4		5	1	7 8	3·0 15·2
17	34 4	0 23 0 24	4·6 13·4		44	1	3	12·9 7·4		54 54	1	10 12	11·3 7·5
	44 44	0 26 0 27 1 1	6·2 15·1 7·9		5	1 1 1	6	1·9 12·4 .6·9		6	1	14	3·6 15·8
	5 5 54	1 3 1 4	0.8		5 1 5 3 6	1	8 10 11	1.4		6½ 6¾ 7	1 1 1	17 19 21	8·1 4·2
	5± 5±	1 6	2·4 11·3		61 61	1	13 15	6.4		7± 7±	î	23	0.4
	6	1 9 1 10	4·6 13·0		6 ‡	1	16 18	11·4 5·8		7ª 8	1 2	26 0	8·7 4·8
	6± 6± 6±	1 12 1 13 1 15	5·8 14·6 7·5		7± 7±	1	20 21	0·3 10·8		81 81	2	3	13.1
	7 7± 7±	1 15 1 17 1 18	0.3		73 8 81	1 1 1	23 24 26	5·3 15·8 10·3		83 9 91	2 2 2	5 7 9	9·3 5·4 1·6
	74 8	1 20	2.0		81 81 81	2 2	0	4·8 15·3		91 92	2 2	10 12	13.7
	81 81	1 23 1 24	3·7 12·5		9 94	2 2	3 5	9·0 4·3		10 101	2 2	14 16	6.0
	84	1 26 1 27	5·4 14·2		9 1 9 1	2 2	6	14·8 9·3		10± 10± 10±	2 2	17 19	14:3 10:5
	91 91 93	2 1 2 2	7·0 15·9		101	2	10	3·8 14·3		11	2	21 23	2.8
1	9 3 10 101	2 4 2 6 2 7	8·7 1·6 10·4		10½ 10¾ 11	2 2 2	13 15 16	8·8 3·3 13·8		11½ 11¾ 12	2 3	24 26 0	15·0 11·1 7·3
	101	2 9	3.5		111	2	18	8.3		10	0	U	1.0

Thick.	Broad.	qrs. lbs. oz.	Thick.	Broad.	qrs. fbs. oz.	Thick.	Broad.	qrs. 1
in. 2‡	in 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 5 8·5 1 7 6·3 1 9 4·1 1 11 1·9 1 12 15·7 1 14 13·5 1 16 11·4 1 18 9·2 1 20 7·0 1 22 4·8 1 24 2·6 1 26 0·4 1 27 14·2 2 1 12·0 2 3 9·8 2 5 7·6 2 7 5·4 2 9 3·2 2 11 1·0	in. 23	in. 6 64 64 7 74 74 8 84 84 9 94 94 94 10 10 10 10 10 10 10 10 10 10 10 10 10	1 19 3·1 1 21 2·6 1 23 2·0 1 25 1·5 1 27 1·0 2 1 0·4 2 2 15·9 2 4 15·3 2 6 14·8 2 8 14·3 2 10 13·7 2 12 13·2 2 14 12·7 2 16 12·1 2 18 11·6 2 20 11·1 2 22 10·5 2 24 10·0 2 26 9·4	in. 2½	in. 74 8 84 84 9 94 94 10 10 10 11 11 11 11 11 11 11 11 11 11	2 1 2 1 2 1 2 1 2 2 2 2 2 2 2 2 3 3 3 3
	9 94 95 95 10 104 105 108 11	2 12 14·9 2 14 12·7 2 16 10·5 2 18 8·3 2 20 6·1 2 22 3·9 2 24 1·7 2 25 15·5	21/2	10½ 10¾ 11 11½ 11½ 11¾ 12	3 0 8.9 3 2 8.4 3 4 7.8 3 6 7.3 3 8 6.8 3 10 6.2	25	54 54 54 54 64 64 64 64 7	1 1 1 1 1 1 2 1 2 1 2 2 2 2 2 2 2 2 2 2
23	114 115 117 12 47 5	2 27 13·3 3 1 11·1 3 3 8·9 3 5 6·7 1 9 5·8 1 11 5·2		54 54 54 64 64 64 64	1 15 7.5 1 17 8.6 1 19 9.7 1 21 10.8 1 23 12.0 1 25 13.1 1 27 14.2		74 74 74 8 84 84 84 84	2 2 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1
	5½ 5½ 5¾	1 13 4·7 1 15 4·2 1 17 3·6		7 71 71 71	2 1 15·3 2 4 0·4 2 6 1·6		9 [*] 9 [‡] 9 [‡]	2 2 2 2 2 2

rs. Ibs. oz.	Thick.	Broad.	qrs. lbs. oz.	Thick.	Broad.	qrs. ibs. oz.
3 0 12·2 3 2 15·0 3 5 1·8 3 7 4·6 3 9 7·3	in. 2 ^a / ₄	in. 10½ 10¾ 11 11¼ 11¼	3 11 10·1 3 13 14·5 3 16 3·0 3 18 7·4 3 20 11·8	in. 27	in. 11‡ 11½ 11¾ 12	3 23 1·9 3 25 8·0 3 27 14·1 4 2 4·2
3 11 10·1 3 13 12·9 3 15 15·7		11 3 12	3 23 0·3 3 25 4·7	3	6 61 61	2 3 9:8 2 6 1:6 2 8 9:3
3 18 2·4 3 20 5·2	27	5 3 6 61	1 26 12·0 2 1 2·1 2 3 8·2		64 7 71	2 11 1·0 2 13 8·8 2 16 0·5
1 22 1·5 1 24 5·9 1 26 10·3		61 61 7	2 5 14·2 2 8 4·3 2 10 10·4		7± 7± 8	2 18 8·3 2 21 0·0 2 23 7·8
2 0 14·8 2 3 3·2		74 74	2 13 0·5 2 15 6·6		81 81	2 25 15·5 3 0 7·3
2 5 7·6 2 7 12·1 2 10 0·5		74 8 81	2 17 12·7 2 20 2·8 2 22 8·9		84 9 94	3 2 15·0 3 5 6·7 3 7 14·5
2 12 4·9 2 14 9·4 2 16 13·8		81 82 9	2 24 15·0 2 27 5·0 3 1 11·1		9½ 9¾ 10	3 10 6·2 3 12 14·0 3 15 5·7
2 19 2·2 2 21 6·6 2 23 11·1		91 91	3 4 1·2 3 6 7·3 3 8 13·4		10½ 10½ 10¾	3 17 13·5 3 20 5·2 3 22 13·0
2 25 15·5 3 0 3·9		9# 10 104	3 11 3·5 3 13 9·6		11	3 25 4·7 3 27 12·4
3 2 8·4 3 4 12·8 3 7 1·2 3 9 5·7		10½ 10¾ 11	3 15 15·7 3 18 5·7 3 20 11·8		115 115 12	4 2 4·2 4 4 11·9 4 7 3·7

OBSERVATIONS ON TABLE II.

The weights here given are in pounds, ounces, a decimal parts, avoirdupois; and it will be seen, inspecting the Table, that the first numbers in expage are those which apply to nut iron, and that breadth increases by \$\frac{1}{2}\$th of an inch as far page 86, after which they rise by \$\frac{1}{2}\$th of an inch breadth to the end. The last numbers in each p show the weight of a square foot, according to respective thickness of each bar. Hence the weight of any length of a bar of rectangular iron may ascertained simply, as follows:

Rule.—Multiply the tabular weight, according the thickness and breadth, by the number of feet the bar, the product will be the weight required.

Example.—In a bar of iron whose thickness is inches, the breadth 6\frac{3}{4} inches, and the length 18 for what is the weight thereof?

In the Table for $2\frac{5}{6}$ inches thick, and opposite inches, stand 2 qrs. 2 fbs. 10.9 oz., being the weig of one lineal foot. Multiply this number by 18 fc and we have as follows:

9 1 20 4.2 Answer.

The foregoing Table of weights is obtained by

following approximate rule:

Multiply the area of the end of the bar by t length of one foot, and multiply that product by 3:5 the product will be the weight in pounds avoirdupe nearly.*

* By this rule the weight of any length of malleable recti gular iron may be ascertained nearly. —Required the weight of one lineal foot of ble iron, $\frac{1}{2}$ inch thick, and $2\frac{1}{4}$ inches broad. $i=1\cdot125\times1\times1\cdot125\times3\cdot32=3\cdot735$ is or 3 is $11\cdot76$ oz. r the sake of expedition these Tables have been acted as follows. Having found, by the above weight of one lineal foot for $\frac{1}{2}$ th of an inching to the thickness, it has been constantly until the breadth has attained to one foot.

Example.

, then

6:64=1 inch broad.

The Tables advancing by $\frac{1}{4}$ of an inch in breadth are cted in the same manner as the above.

TABLE III.*

SHOWING THE WEIGHT OF A LINEAL FOOT OF ROUND BAR IRON,

in Avoirdupois qrs. tbs. oz., from 1th of an Inch to 12 Inch Diameter, advancing by 1th of an Inch.

				_
Inches.	qrs. ibs. os.	g drs. Ibs. os.	다 qrs. fbs. os.	
ł	0 0 0.4	4 1 16 4.1	81 6 3 10.1	٦
ı	0 0 2.6	41 1 18 15.8	81 6 8 15.4	
Į į	0 0 5.8	4 1 21 12 6	8 6 14 5.8	1
4 58 4 48 84 78	0 0 10.4	4 1 24 10.8	8½ 6 19 13·6	, [
Ā	0 1 0.1	4 1 27 10.2	84 6 25 6.7	1
4	0 1 7.3	44 2 2 11.0	8 3 7 3 1·0	
큠	0 1 15.8	$ 4\frac{7}{8} 2513\cdot1$	8 1 7 8 12.7	
1	0 2 9.4	5 2 9 0.6	9 7 14 9.6	
11	0 3 4.8	5 2 12 5.2	98 7 20 7.8	
14	0 4 1.1	51 2 15 11.0	91 7 26 7.4	
18	0 4 14.7	5 2 19 2.4	98 8 4 8.2	1
14	0 5 13.7	51 2 22 11.0	9 8 10 10.4	١
15	0 6 13.9	5 2 26 4.8	9 8 16 13.8	ı
14	0 7 15.5	5 3 2 0.1	94 8 23 2.6	ı
17	0 9 2.4	5 3 5 12·6	9 9 1 8.6	1
2	0 10 6.5	6 3 9 10.4	10 9 8 0.0	١
21	0 11 12.0	61 3 13 8.6	101 9 14 8·6	1
21	0 13 1.7	61 3 17 9·0 61 3 21 10·6		1
28	0 14 10·7 0 16 4·1		108 9 27 13·8 101 10 6 10·4	1
21	0 16 4·1 0 17 14·8		10 10 13 8.2	1
25	0 17 14 8	6 4 2 1.8 6 7.4	102 10 20 7.4	١
24	0 21 8.0		10 10 27 7.8	1
2 7 3	0 23 6.5	67 4 11 1·4 7 4 15 6·4	11 11 6 9.6	1
31	0 25 6.4	78 4 19 15.5	111 11 13 12.6	1
31	0 27 7.6	71 4 24 10.6	114 11 21 1.0	ı
38	1 1 10.0	78 5 1 6.7	118 12 0 56	1
31	1 3 13.9	71 5 6 4.0	111 12 7 13.6	1
3	1 6 2.8	7 5 11 2.6	114 12 15 5.8	l
32	1 8 9.2	74 5 16 2.7	114 12 22 15.4	1
37	1 11 0.9	7 5 21 3.7	117 13 2 10.2	1
4	1 13 9.9		12 13 10 6.4	1

^{*} James Foden.

TABLE IV.*

WING THE WEIGHT OF A LINEAL FOOT OF SQUARE BAR IRON,

pirdupois qrs. its. oz., from hth of an Inch to 12 Inches, advancing by hth of an Inch.

į		Inches.		8	
THERES.	qrs. ibs. os.	Incl	qrs. ibs. os.	Inches.	qrs. ibs. os.
1	0 0 0.8	41	2 0 7.8	81	7 23 2.7
ļ	0 0 3.3	44	2 3 14.1	8₺	8 1 15.4
ŧ	0 0 7.4	48	2 7 6.4	8	8 8 13.8
1	0 0 13.2	41	2 11 3.7	81	8 15 13.9
ŧ	0 1 5.1	48	2 14 13.6	8	8 22 15.6
*	0 1 13.8	44	2 18 14.3	82	9 2 2.0
1	0 2 8.6	4	2 22 15.1	87	9 9 8.0
	0 3 4.9	5	2 27 0.0	9	9 16 14.7
عاد جانه مند بها عنه جده منه	0 4 3.2	51	3 3 3.2	91	9 24 7.1
1	0 5 2.7	51	3 7 8.1	94	10 4 1.0
ŧ	0 6 4.1	38	3 11 14.2	98	10 11 12.7
1	0 7 7.5	5 j	3 16 6.8	91	10 19 10.0
•	0 8 12.0	58	3 21 0.9	9	10 27 9.0
+	0 10 1.6	54	3 25 12.2	94	11 7 9.7
7	0 11 10.4	57	4 2 8.1	97	11 15 12.0
_	0 13 4.5	6	4 7 8.3	10	11 24 0.0
ŀ	0 14 15.4	61	4 12 8.8	101	12 4 5.6
t	0 16 12.9	61	4 17 11.0	101	12 12 12.9
H	0 18 11.0	68	4 22 14.8	10	12 21 5.8
H	0 20 12.0	61	5 0 4.3	101	13 2 0.4
	0 22 13.1	6	5 5 11.4	10	13 10 12.7
Ħ	0 25 1.7	64	5 11 4.2	104	13 19 10.6
F	0 27 6.4	6 %	5 16 14.7	10g	14 0 10.2
٠. ا	1 1 14.1	7	5 22 10.8	11	14 9 11.5
H	1 4 5.6	71	6 0 8.6	114	14 18 14.4
	1 6 15.6	74	6 6 8.1	111	15 0 3.0
	1 9 11.6	78	6 12 9.2	118	15 9 9.2
Ħ	1 12 9.1	71	6 18 12.0	114	15 19 1.1
Ħ	1 15 8.3	78	6 25 0.4	118	16 0 10.6
Ħ	1 18 9.1	74	7 3 6.5	114	16 10 5.8
H	1 21 12.6	73	7 9 14.2	117	16 20 2.7
_1	1 25 1.9	8	7 16 7.6	12	17 2 1.2

^{*} James Foden.

OBSERVATIONS ON TABLES III. AND IV.

The Tables of the weight of round and square bars of malleable iron have been obtained by the following approximate rules:

Rule 1.—For round bars. Multiply the square of the diameter in inches by the length in feet, and that product by 2.6. The product will be the weight in pounds avoirdupois, nearly.

Rule 2.—For square bars. Multiply the area of the end of the bar in inches by the length in feet, and that by 3.32. The product will be the weight in pounds avoirdupois, nearly.

Example 1.—What is the weight of a round bar of malleable iron 4½ feet long, and 2½ inches in diameter?

 $2 \cdot 25^2 \times 4 \cdot 5 = 22 \cdot 78125 \times 2 \cdot 6 = 59 \cdot 23125$ fbs. = 59 fbs. 3·7 oz.

Example 2.—Required the weight of a square bar of malleable iron whose length is 7½ feet, and 1½ inch square.

 $1.5^2 \times 7.25 = 16.3125 \times 3.32 = 54.1575$ fbs. = 54 fbs. 2.52 oz.

TABLE V.*

CONTAINING THE CIRCUMFERENCES FOR ANGLED IRON HOOPS,

From 6 Inches to 6 Feet Diameter, advancing by an Eighth of an Inch.

ANGLE OUTSIDE.

Diam.	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.	Circum.
In. 6	Ft. In. 1 5½ 1 5½ 1 6½ 1 6½ 1 7½ 1 7½ 1 8½	Ft. In. 10	Ft. In. 2 54 2 56 2 68 2 74 2 74 2 74	Ft. ln. 1 2 8 4 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Ft. In. 3 5 3 5 3 5 3 6 3 6 3 6 3 6 3 7 3 7 3 7 3 7	Ft. In. 1 6	Ft. In. 4 43 4 53 4 53 4 64 64 64 4 64 4 64 4 6
7 18 14 28 19 45 24 78	1 8½ 1 8½ 1 9½ 1 9½ 1 9½ 1 10½ 1 10½ 1 10½	11 	2 8 1 2 8 1 2 9 1 2 9 1 0 2 1 0 1 2 1 0 1 2 1 0 1 1 0 1 1 0 1 1 0 1 1 1 1	1 3	3 7 8 3 8 4 3 8 8 8 3 9 3 9 8 3 9 8 3 10 8 3 10 8 3 10 8 3 10 8 3 10 8 10 8	1 7	4 78 4 8 4 88 4 88 4 98 4 91 4 92 4 93 4 104
8 -10 -10 -10 -10 -10 -10 -10 -10 -10 -10	1 11# 1 11# 2 0# 2 0# 2 0# 2 1# 2 1# 2 2	1 0	2 11½ 2 11½ 2 11½ 3 0¼ 3 0¾ 3 1 3 1¾ 3 1¾	1 4	3 10 8 3 11 4 3 11 5 4 0 4 4 0 8 4 1 4 1 8	1 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4 108 4 11 4 118 4 115 5 0 5 08 5 04 5 11
9 18 14 25 18 8 24 18	2 2 5 2 2 5 2 3 5 2 3 5 2 4 5 2 4 5 2 4 5 2 4 5 2 4 5 2 4 5 2 4 5 2 4 5 2 4 5 5 5 5	1 1	3 2 2 8 3 2 4 5 3 3 3 4 4 5 8 3 3 4 5 8 3 3 4 5 8 3 3 4 5 8 3 3 4 5 8 3 3 4 5 8 3 4 5 8 3 4 5 8 3 4 5 8 3 4 5 8 3 4 5 8 3 4 5 8 5 8 5 8 5 8 5 8 5 8 5 8 5 8 5 8 5	1 5 to 14 con to 18 con	4 1‡ 4 2½ 4 2½ 4 2½ 4 3½ 4 3½ 4 3½ 4 3½	1 9	5 14 5 17 5 24 5 28 5 5 5 38 5 38 5 34 5 4

^{*} James Foden.

Die			Circum. Diam.			Circum.		Diam.		Ci-	eum.	Thi	am.	c
	In.	Ft. 5 5 5 5 5 5 5	In. 48 44 5 6 6 6 6 7	Ft. 2	In. 3	Ft. 6 6 6 6 6 6 6	In. 75 75 85 95 95	Ft. 2	In. 8 18 14 28 19 18 24 78	Ft. 7 7 7 7 7	In. 94 104 104 105 114 115 0	Ft. 3	In. 1 18 14 58 15 58 54 78	F
1 1	1 18 14 28 18 50 84 28	5 5 5 5 5 5 5 5	788 8 1 8 1 8 1 9 1 5 8	2	4 18 14 88 18 58 84 78	6 6 6 6 6 7 7	10 10 8 10 8 11 8 11 8 11 8 0 8	2	9	8 8 8 8 8 8 8	0 1 1 2 1 2 1 2 2 1 2 2 3 4 3 4	3	2 18 14 38 19 58 54 78	
2	0 18 14 58 12 55 54 78	5 5 5 5 6 6 6	101 105 11 113 114 01 01 07	2	5	7777777777	1 138 138 2 238 237 338 338	2	10	8 8 8 8 8 8 8	34 45 4 5 5 5 5 5 6 8	3	3	
2	1 18 14 38 12 58 34 78	6 6 6 6 6 6	11 15 2 25 27 3 38 34 34	2	6 18 14 28 12 58 24 78	777777777	3 8 4 4 5 5 8 5 8 5 8 6 1 8 6 1 8	2	11 \$ 4 \$ 5 5 5 5 4 7 8	8 8 8 8 8 8 8	61/2 67/2 71/2 8 8 8 8 8 9 1	3	4 18 14 28 1 1 5 24 78	
2	2 18 14 28 12 8 4 7	6 6 6 6 6 6	4 1 4 2 4 7 5 1 5 5 6 6 8 6 4 6 4 6 4 6 4 6 4 6 4 6 4 6 4 6	2	7 18 14 38 19 18 18 14 78	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	67 71 71 73 81 81 9	3	0 -18-14-000-19-190-19-	8 8 8 8 8 8	9½ 9¾ 10¼ 10å 11 11¼	3	5 -10-14-05-1-1-4-04	

iam.	Circu	m.	Di	am.	Circ	um.	Dia	am.	Circ	um.	Di	am.	Cir	cum.
In. 6	10 10 10 10 10 10	In. 3	Ft. 3	In. 11 10 14 25 15 24 15	Ft. 11 11 11 11 11 11	In. 54 61 61 61 71 71 81	Ft. 4	In. 4 18 14 50 15 50 54 75	12	In. 88 88 91 91 101 103	Ft. 4	In. 9 18 14 28 18 58 24 78	Ft. 13 13 14 14 14 14 14	In. 11 11\$ 11\$ 11\$ 0\$ 0\$ 1\$ 1\$ 1\$ 1\$
7 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	10 10 10 10 10	6 6 6 7 7 7 7 8 8	4		11 11 11 11 11 11	85 9 95 95 105 105 105 114	4	5	12 12 13 13 13 13 13 13	114 115 0 03 04 11 11	4	10 18 14 58 17 58 514 78	14 14 14 14 14 14 14	2 23 23 23 3 33 33 4 4 4
०० चेत्र स्थात चेत्र श्रीत श्रीत श्रीत श्रीत श्रीत	10 10 10 1 10 1 10 1	8	4	10 14 500 15 50 64 70	11 12 12 12 12 12 12 12	115 0 01 05 1 15 12 25	4	6 18 14 38 19 58 34 78	13 13 13 13 13 13 13	24 25 3 3 3 3 4 4 5 4 4 4 4 4 4	4	11 18 14 250 19 25 24 78	14 14 14 14 14 14 14	4音 5章 5章 6音 6章 7章
9 18 14 58 18 48 54 78	10 1 11 11 11 11 11 11	12 04 05 1 18 13 2 28	4	2 18 14 38 18 58 34 78	12 12 12 12 12 12 12 12	213 25 3 4 35 4 4 5 5 1 5 5	4	7 18 14 38 19 58 54 78	13 13 13 13 13 13 13 13	5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1	5	0 18 14 58 12 58 84 78	14 14 14 14 14 14 14	7
3 10	11 11 11 11 11 11 11	24 31 31 31 41 41 41 5	4	3 18 14 38 12 48 34 78	12 12 12 12 12 12 12 12	5 1 5 1 5 1 6 1 5 1 6 1 5 1 7 1 1 8	4	8	13 13 13 13 13 13 13	81 81 81 91 91 91 10	!	1 18 14 28 15	14 14 14 15	10\$\\ 11\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\

100 CIRCUMFERENCES FOR ANGLED IRON HOOPS.

Di	am.	Circ	um.	Di	am.	Cir	cum.	Di	am.	Cir	cum.	D	iam.	Cir
Ft. 5	In. 2	Ft. 15 15 15 15 15 15 15	In. 15 2 25 27 35 35 44	Ft. 5	In. 5 18 14 58 19 18 84 78	Ft. 15 15 15 16 16 16	In. 101 103 111 118 0 01 01 1	Ft. 5	In. 8	Ft. 16 16 16 16 16 16 16	In. 71 78 8 88 88 91 91 91	Ft. 5	In. 10 10 10 10 10 10 10 10 10 10 10 10 10	Ft. 17 17 17 17 17 17 17
5	3 10 14 20 17 20 24 70	15 15 15 15 15 15 15	48 5 58 58 61 61 61 71	5	6 10 14 20 14 15 24 28	16 16 16 16 16 16 16	15 15 25 25 21 27 31 35 4	5	9 18 14 28 18 28 24 78	16 16 16 16 16 17 17	101 101 101 111 111 0 01	5	11	17 17 17 17 17 17 17
5	4 18 14 58 17 50 24 78	15 15 15 15 15 15 15 15	71 78 84 88 9 98 98 101	5	7 18 14 38 19 50 54 78	16 16 16 16 16 16 16	4					6	0	17

OBSERVATIONS ON TABLE V.

As this Table, together with the following one, will be useful to those smiths who chiefly work angled iron, it will be necessary to remark, that the observation made on Table I., respecting adding the thickness of the iron to the diameter, must also be attended to in this, with this difference,—the breadth of the angle must be added to the diameter.

Example.—Suppose, as in the following sectional figure, a hoop is wanted to be made of $2\frac{1}{4}$ -inch angled iron, whose diameter inside must be 12 inches. Here the $2\frac{1}{4}$ inches must be added to the 12 inches, which raises the number to 1 foot $2\frac{1}{4}$ inches. Looking into the Table, I find the circumference, or length of iron requisite for the hoop, is 3 feet $6\frac{1}{4}$ inches.




TABLE VI.*

CONTAINING THE CIRCUMFERENCES FOR ANGLED HOOPS,

From 6 Inches to 6 Feet Diameter, advancing by an Eighth of ANGLE INSIDE.

Diam.	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.
In. 6	Ft. In. 1 8½ 1 8½ 1 9½ 1 9½ 1 10½ 1 10½ 1 10½ 1 11½	Ft. In. 10	Ft. In. 2 10½ 2 10½ 2 11½ 2 11½ 3 0% 3 0% 3 1½	Ft. In. 1 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Ft. In. 3 11 4 0 4 0 4 1 4 1 4 1 4 1 4 1 4 2 4 2 4 2 4 2 5 6 6 6 7 8 8 8 8 8 8 8 8 8	Ft. In. 1 6
7 18 14 58 12 58 84 78	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	11 \$ 14 550 1 5 50 5 4 7 5	3 15 3 2 3 2½ 3 2½ 3 35 3 35 3 44 3 45	1 3	4 38 4 34 4 48 4 48 4 5 4 5 4 5 4 6 4 6	1 7 ± 4 5 ± 5 ± 5 ± 5 ± 5 ± 5 ± 5 ± 5 ± 5 ±
8 14 38 19 50 44 75	2 38 2 34 2 44 2 48 2 5 2 5 2 56 2 68	1 0	3 5 3 5 3 5 3 6 3 6 3 6 3 7 3 7 8 8	1 4	4 63 4 78 4 78 4 8 4 8 4 8 4 9 4 9 3 4 9 3	1 8
9 14 20 17 19 24 18	2 6 3 4 2 7 4 5 2 8 2 8 5 2 9 3 8 2 9 3 4 2 9 3 4	1 1	3 8 4 3 8 5 3 9 8 5 3 9 8 5 3 10 1 3 11 1 3 11 1 1 1 1 1 1 1 1 1 1	1 5 ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ±	4 10 d 4 10 d 4 11 d 4 11 d 4 11 d 5 0 d 5 0 d 5 1 d 5	1 9 ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ± ±

^{*} James Foden.

iam.	Circum.	Diam.	Circum.	Diam.	Circum.	Diam.	Circum.
In. 10 R R R R R R R R R R R R R R R R R R	Ft. In. 6 34 6 4 6 6 4 6 6 5 6 6 6 6 6 6 6 6 6 6 6	Ft. In. 2 3 1 1 2 2 3 1 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	Ft. In. 7 88 7 88 7 94 7 94 7 106 7 101 7 11 7 118	Ft. In. 2 8	Ft. In. 9 1 1 9 2 9 2 2 5 9 3 5 9 4 1 9 4 1	Ft. In. 3 1 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	Ft. In. 10 68 10 71 10 71 10 8 10 88 10 88 10 91 10 94
11 8-4-56-18-50-54-78	6 6 6 7 8 6 8 8 6 8 6 8 6 9 4 6 9 3 4	2 4 18 14 25 18 25 24 75	7 11\$ 8 0\$ 8 0\$ 8 1\$ 8 1\$ 8 2 8 2\$ 8 2\$	2 9 18 14 48 19 50 54 7 18	9 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	3 2 \$ 14 and 19 19 19 19 19 19 19 19 19 19 19 19 19	10 101 10 101 10 11 10 11 10 11 10 11 11 0 11 0 11 0 11 1 11 0 11 1 11 0 11 1 11 0 11 1 11 0 11 1 11 0 11 1 11 0 11 0 1
0 18 14 28 19 50 24 75	6 10 1 6 10 1 6 11 6 11 6 11 6 11 7 0 1 7 0 1 7 1 1 1 1 1 1 1 1 1 1 1	2 5 18 14 28 19 19 19 19 19 19 19 19 19 19 19 19 19	8 3½ 8 3½ 8 4½ 8 4½ 8 5 8 5½ 8 5½ 8 6½	2 10 \$ 14 \$ 5 \$ 5 \$ 5 \$ 5 \$ 6 \$ 7 \$ 7	9 88 9 87 9 91 9 95 9 101 9 101 9 11	3 3 18 14 28 28 28 28 28 28 28 28 28 28 28 28 28	11 1½ 11 2 11 2 11 2 11 2 11 3 11 3 11 3 11 3
1 18 14 25 19 55 24 75	7 18 7 2 7 28 7 28 7 34 7 34 7 41 7 41	2 6 1 3 4 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	8 6 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	2 11 18 14 45 19 15 15 15 15 15 15 15 15 15 15 15 15 15	9 11	3 4 16 14 25 19 25 54 75	11 5 11 5 11 5 11 5 11 6 11 6 11 7 11 7 11 8
2 18 14 28 19 28 24 2	7 5 5 5 5 7 7 5 7 6 5 7 7 6 5 7 7 7 5 7 7 8	2 7 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	8 10½ 8 10½ 8 11 8 11¾ 8 11¾ 9 0½ 9 0¾ 9 1½	3 0	10 3½ 10 3½ 10 4½ 10 4½ 10 5 10 5¾ 10 5¾	3 5	11 8

104 CIRCUMFERENCES FOR ANGLED IRON HOC


Ī	Di	am.	Cir	cum.	D	iam.	Cir	cum.	Di	am.	Cir	cum.	D	ien
	Pt. 3	In. 6	Ft. 11 12 12 12 12 12 12 12	In. 114 04 05 11 11 12 28 28	Ft. 3	In. 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Ft. 13 13 13 13 13 13 13	In. 47 5 5 5 5 5 6 6 5 7 7 1 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	Ft. 4	In. 4 18 14 58 19 58 24 78	Ft. 14 14 14 14 15 15	In. 10 101 102 112 112 01 01 1	Pt.	. 1 ç
	3	7 18 14 28 18 24 28	12 12 12 12 12 12 12 12	34 44 44 55 64	4	0 नेक नोर कोळ नेम ब्लंब क्रेड कोड	13 13 13 13 13 13 13	88 84 91 98 10 101 107 118	4	5 -18 -14 -28 -23 -53 -54 -75	15 15 15 15 15 15 15	11 12 21 31 35 4 41 1	4	10
	3	8 14 38 18 48 34 75	12 12 12 12 12 12 12 12	6# 7 7# 7# 8# 8# 9#	4	1 18 14 28 13 48 84 78	13 14 14 14 14 14 14	114 04 08 1 12 23 24	4	6 15 14 25 1 1 1 5 5 4 7 5	15 15 15 15 15 15 15	43 54 54 65 7 74 78	4	11
	3,	9 -16 -14 -518 -18 -40 -516 -718	12 12 12 12 12 13 13	10 10 10 10 11 11 0 0 1	4	2 18 14 25 19 55 24 78	14 14 14 14 14 14 14	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4	7 15 14 38 19 15 84 78	15 15 15 15 15 15 15	81 82 91 91 10 101 101 111	5	(
	3	10	13 13 13 13 13 13 13 13	1 1 2 2 2 2 2 2 3 2 4 3 4 4 4 4 4 5	4	3 18 14 38 1 4 5 5 5 7 8	14 14 14 14 14 14 14	9 į	4	8 - 14 - 38 - 17 - 50 - 54 - 7 - 8	15 16 16 16 16 16 16	2∔	5	

ADVANCING BY AN RIGHTH.

Diam.	Circu	m.	Di	am.	Cir	cum.	Di	am.	Cir	cum.	E	iam.	Cir	cum.
In. 2	17 17 17 17 17 17 10 17 10	In. 81 82 91 91 0 8 0 11	Pt. 5	In. 5 18 14 28 19 19 19 19 19 19 19 19 19 19 19 19 19	Ft. 18 18 18 18 18 18 18	In. 61 7 78 78 84 91 91	Ft. 5	In. 8 18 14 280 18 48 44 78	Ft. 19 19 19 19 19 19	In. 42 54 54 54 64 7 72 72 72	Ft. 5	In. 10	Ft. 19 20 20 20 20 20 20 20	In. 118 01 118 118 121 125
3 18 4 28 19 40 24 18	18 18 18 18 18 18 18	14 01 01 13 13 21 24	5	6 -18-14-48-18-50-54-78	18 18 18 18 19 19	10 10 10 10 11 11 11 0 11	5	O -ta-te cha-in-in-sta-te-te	19 19 19 19 19 19	8½ 8½ 9½ 9½ 10 10½ 10½ 11½	5	11 ** ** ** ** ** ** ** ** ** ** ** ** *	20 20 20 20 20 20 20 20 20	3 1 3 4 4 4 4 4 4 4 5 4 5 4 5 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6
4 18 14 28 28 28 28 28 28 28 28 28 28 28 28 28	18 18 18 18 18 18 18	3 1 3 4 4 4 8 4 8 5 4 8 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6 1 6	5	7 18 14 28 13 58 24 75	19 19 19 19 19 19 19	18 17 24 24 38 31 4 48					6	0	20	61

OBSERVATIONS ON TABLE VI.

The observations respecting this Table are the reverse to those on the preceding one,—viz. the breadth of the angle must be taken from the diameter,—for this reason, that the diameter is taken from outside to outside of the ring, as in the following sectional figure:—



Suppose a ring is to be made of angled iron, whose diameter outside is to be 12 inches, the breadth of the angle $2\frac{1}{2}$ inches; then, by taking $2\frac{1}{2}$ inches from 12 inches, we have left $9\frac{1}{2}$ inches. Looking into the Table in the column of diameters, I find in the circumference column, opposite $9\frac{1}{2}$ inches, 2 feet $8\frac{1}{2}$ inches, which is the length of iron necessary for the ring.

It has been already observed, that between angled and plain iron a considerable difference exists with regard to the proportion of the circumference to the diameter: this is owing to the angle or flange on one side of the bar, and when the iron is formed into a hoop: it contracts more or less, as the angle or flange may be inside or outside of the hoop. From repeated experiments on this subject, I have ascertained that the proportions of the diameters to the circumferences are as follows:—For the angle inside

as 1:3.4248, and for the angle outside the hoop, as 1:2.9312:: Diam: Circumf.

The method used in obtaining the numbers in these Tables of Circumferences of angled iron is, for the angle inside by adding hath of 3.4248, or .4281 as a constant number; and for the angle outside, by constantly adding hath of 2.9312, or .3664.

Example 1.—For a hoop with the angle or flange inside, beginning with 2 feet diameter.

 $3.4248 \times 2 = 2.8496$ feet, and $.8496 \times 12 = 10.1952$ inches, and this decimal $.1952 \times \frac{1}{8}$,

Ex. 2.—For a hoop whose angle or flange is outside, commencing with a diameter of 3 feet.

Problem.—To find the circumference of an ellipse, or an oval hoop or ring.

Rule.—Add the length of the two axes together, and multiply the sum by 1.5708 for the circumference; or as it may be used in the Table of Circumferences, take half the sum of the axes as a diameter, with the breadth of the iron added, and enter the Table of Circumferences where it will be found.

Ex. Required the circumference of an elliptical hoop, whose axes are $18\frac{1}{2}$ and 13 inches, the thick-

ness of the iron being 21 inches.

18½
13

½)31½
15½
+ 2½ thickness.

181 inches the diameter.

Entering into the Table of Diameter with 184 inches, the circumference will be found to be 4 feet 94 inches.

In constructing elliptical hoops of angled iron, with the angle outside, reference must be made to the Tables for hoops of angled iron: the operation will be similar to the above example. But in hoops where the angle is inside, the thickness of the iron must be taken from half the sum of the axes.

Note.—It must be observed, that in the examples given in the Observations on Table I., and also on hoops formed of angled iron, that those circumferences are nothing more than the ends of the iron meeting together: therefore, every smith must allow for the thickening of the ends of the metal previous to scarving the same in order to weld it.

Proportional breadths for hexagonal or six-sided Nuts for wrought-iron Bolts.

Dia. of bolts.	Breadth of nuts.	Dia. of bolts.	Breadth of nuts.
ŧ	‡ inch.	11	l}∦inch.
1	<u> </u>	11	$2\frac{1}{16}$,,
ţ	18 "	18	2 8 "
. 1	118"	12	248 "
ı*	证"	ii	3

Ä	
OF PLATE OR SHEET IR	
9	NDS
LATE	POUNDS.
2	Z
FOOT 0	BRASS,
CIAL	AND
SUPERFICIAL FOOT	COPPER,
LOLY	
_	

	Iron.		No.	Iron.	Copper.	Brass.		No.	Iron.	Copper.	Brass.
-6	-		-		14.5	13-75		16	2.5	2.9	2.75
-	_	•	63	_	13-9	13-2	1	17	2.18	2.25	5.4
_	-	98	60	-	12-75	12.1	e B	18	1.86	2.15	2.04
÷	_	ne.	*	-	9.11	11	ne.	19	1.1	1.97	1.87
-	10	8 9	10	00	1.01	19-6	8 9	20	1.54	1.78	1.69
-	_	air	9	-	9-4	8-93	nir.	21	1.4	1.62	1.54
-	-	M S	7	-	8.7	8.25	N E	22	1.25	1.45	1.37
<u>.</u>	-	tp(00	9	6-2	7.54	q	23	1.12	1.3	1.23
-	_	À	6	9	7.2	98.9	λ	24	-	1.16	Ξ
-	_	l s	10	5	6.9	6.18	q s	25	6-	1.04	66.
-	-	S91	=	2	2.8	2.2	891	26	8	-92	.88
# TX	-	1 N	12	4	2.08	4.81	ıy.	27	.72	.83	.79
_	-	oid	13	÷	4.34	4.12	oįų	28	.64	.74	.7
_	_	T	14		3.6	3-43	T	29	.56	.64	.61
-	-		15	Ċ	3.27	3.1		30		.58	.55

110

COMPARATIVE WEIGHTS OF BODIES.

Note.—No. 1 wire gauge equal 5 ths of an inch.

,, <u>4</u>	"	#	,,
,, 7	,,	18 18	,,
,, 11	"		**
,, 16	**	7 8	,,
" 2 2	,,	प्रदेष	,,

The great variety of thicknesses into which copper is manufactured, causes intrade the weight to be named whereby to determine the thickness required, the unit being that of a common sheet, so designated, viz., 4 feet by 2 feet, in fbs.; thus,

A 70 tb. plate is 3 ths of an inch in thickness.

The thickness of lead is also in common determined or understood by the weight, the unit being that of a square or superficial foot; thus,

4-th. lead is 18th of an inch in thickness.

6	,,	10 10	91
71	"	18	91
11	"	3 16	91
15		1	

COMPARATIVE WEIGHTS OF DIFFERENT BODIES.

Bar iron being 1. Cast iron = '95 Steel = 1'02 Copper = 1'16 Brass = 1'09 Lead = 1'48	Bar iron = 1.07 Steel = 1.08 Brass = 1.16 Copper = 1.21	Dry deal being 1. Cast iron = 11.0 Cast tin = 11.2 Brass = 12.7 Copper = 13.3 Lead = 17.1
---	--	---

1. Suppose I have an article of plate iron, the weight of which is 728 tbs., but want the same of copper, and of similar dimensions, what will be its weight?

 $728 \times 1.16 = 844.48$ ths.

2. A model of dry pine weighing 32½ fbs., and in which the iron for its construction forms no material portion of the weight, what may I anticipate its weight to be in cast iron?

$32.5 \times 11 = 357.5 \text{ tbs.}$

Note.—It frequently occurs in the formation or construction of models, that neither the quality nor condition of the timber can be properly estimated, and in such cases it may be a near enough approximation to reckon 10 ibs. of cast iron to each ib. of model.

WEIGHTS OF 9-FEET LENGTHS OF CAST-IRON PIPES, OF VARIOUS DIAMETERS.

Diameter of bore.	Thickness of metal.	Diameter of flange.	Thickness of flange.	Diameter of circle through holes.	Diameter	holes.	We cwts.	ight in qrs. lbs
in. 2 3 4 5 6 7 8 9 10 11	मा होता होता नहीं नहीं कोन होने कोन कोन कोन कोन होता होता होता होता होता होता होता होता	in. 6½ 7½	in. 918	in. 43 6	मुक्त कांच कांच कांच प्रकार	4	0	3 0 0 3
4	1 2	94	4	74	8	4	1	3 5
5	5	10½ 12	8 2	83 10	3 4 7	4	3	1 12 2 1
7	5	14	18	113	7	6	4	3 17
8	4	15	1	123	1	6	5	2 9
9	3	161	116	141	1	6	-6	1 12
10	4	171	14	151	1	6	7	0 0
	7	19	1 3 1 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	164	1	6	8	3 24
12	7 8	20	11	174	11	6	9	3 5
13	3	21	11	184	11	6	10	2 0
14	7 8	22	14	19#	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	8	11	0 26
15	7 8	23	11	204	15	8	12	0 25
16	5	241/2	15	22	14	8	12	3 8
17	\$	251	$1\frac{5}{16}$ $1\frac{3}{8}$	23	14	8	13	2 17
18	1	261	13	24	11	8	16	1 15
19	1	28	13 13 13	25	18	8	17	2 13
20	1	29	13	26	18	8	18	0 26

Weights of Leaden Pipes.

	•	•		_	
4-inch	bore	weighs	10 fbs.	per	vard.

1	,,	"	12	99
1 1 1 1 1 1 1 1 1 1 1 2 1 2	"	,,	16	,,
11	,,	"	18	"
14			21	
3	"	"	24	"
-			24	••

TO ASCERTAIN THE WEIGHTS OF PIPES OF VARIOUS METALS, AND ANY DIAMETER REQUIRED.

Thickness in parts of an inch.	Wrought iron.		Copper			Lead	
10	•326	11½ fb	s. pla	te ·38	2 tbs	. lead	1 .483
32 16 32	.653	231	,,	.76	4	,,	-967
30	-976	35	**	1.14	51	**	1.45
	1.3	461	77	1.52	8	**	1.933
8 82 16 7 89	1.627	58	19	1.9	91	"	2.417
16	1.95	70	**	2.28	11	"	2.9
39	2.277	801	**	2.66	13	"	3.383
1	2.6	93	,,	3.04	15	**	3.867

Rule.—To the interior diameter of the pipe, in inches, add the thickness of the metal; multiply the sum by the decimal numbers opposite the required thickness and under the metal's name; also by the length of the pipe in feet, and the product is the weight of the pipe in fbs.

1. Required the weight of a copper pipe whose interior diameter is 7½ inches, its length 6¼ feet, and the metal ¼ of an inch in thickness.

 $7.5 + .125 = 7.625 \times 1.52 \times 6.25 = 72.4 \text{ tbs.}$

2. What is the weight of a leaden pipe 18½ feet in length, 3 inches interior diameter, and the metal ½ of an inch in thickness?

 $3 + .25 = 3.25 \times 3.867 \times 18.5 = 232.5$ ibs.

```
Note.-Weight of a cubic inch of
  Lead
             equal .4103
  Copper, sheet ,, 3225
                          ,,
  Brass, do.
                  .3037
                   ·279
  Iron, do.
                          ,,
               "·263
  Iron, cast
                          ,,
               " ·2636
  Tin, do.
                          ,,
                  .26
  Zinc. do.
                   .03617 ,,
  Water
```

WEIGHT OF CAST-IRON BALLS.

Dia- meter in inches.	Weight in ibs.	Dia, meter in inches.	Weight in ibe.	Dia- meter in inches.	Weight in the.
2	1.10	6	29.72	10	137·71 148·28
21 21	1·57 2·15	6 1	33·62 37·80	10 1 10 <u>1</u>	159.40
2 1	2·86	6 \$	42·35	10 2	171·05
3	3·72		47·21	11	183·29
3 1	4·71	7±	52·47	111	196·10
31	5·80	7±	58·06	111	209·43
3 4	7·26	7 1	64·09	11 4	223·40
4	8·81	8	70·49	12	237·94
44	10·57 12·55	8 1	77·32 84·56	12 1 12 1	253·13 268·97
4 4	14·76	8 1	92·24	12 4	285·37
5	17·12	9	100·39	13	302·41
5 1	19·93	9 1	108·98	13½	320·80
5 1	22·91		118·06	13½	338·81
54	26.18	94	127.63	134	357.93

1. What will be the weight of a hollow ball or shell cast iron, the external diameter being 9½ and inrnal diameter 8½ inches?

Opposite 9½ are 118.06, and Opposite 8½ are 92.24, subtract

25.82 tbs., weight required.

2. Requiring to remove a cast-iron ball 37.8 fbs. in

weight, and in diameter 6½ inches, and repla one of lead of an equal weight, what must be 4 meter of the leaden ball?

Weight of lead to that of cast iron = 1.56 (see Table, p Then $\frac{6.5^3}{1.56}$ = $\sqrt{176}$ = 5.6 inches, the diameter.

TABLES BY WHICH TO FACILITATE THE ME TION OF TIMBER.

1. Flat or Board Measure.

Breadth in inches.	Area of a lineal foot.	Breadth in inches.	Area of a lineal foot.	Breadth in inches.	1
1	.0208	4	·3334	8	Γ
i	.0417	41	•3542	81	١
<u> </u>	·0625	44	·375	8 1	l
1 .	·0834	42	•3958	8	l
11	.1042	5	.4167	9	١
1 <u>i</u>	·125	51/4	·4375	91	ı
14	·1459	5 1	·4583	91	l
2	-1667	5 2	·4792	9 2	
21	•1875	6	•5	10	l
2	.2084	61	-5208	101	
24	.2292	61	.5416	101	
3	.25	62	.5625	10	l
31	.2708	7	.5833	11	
3	•2916	71	.6042	111	ı
32	•3125	71	.625	111	l
	1	72	.6458	112	ı

Application and Use of the Table.

- 1. Required the number of square feet in : or plank 16½ feet in length and 9½ inches in b
 Opposite 9½ is .8125 × 16.5 = 13.4 square feet
- 2. A board 1 foot 23 inches in breadth and inlength; what is its superficial content in squa

Opposite $2\frac{\pi}{2}$ is $\cdot 2292$, to which add the 1 foot; t $1\cdot 2292 \times 21 = 25\cdot 8$ square feet.

3. In a board 15½ inches at one end, 9 inches at the other, and 14½ feet in length, how many square feet?

 $\frac{15\cdot 5+9}{2}$ = 12\frac{1}{4}, or 1.0208; and 1.0208 × 14.5 = 14.8 sq. ft.

2. Cubic or Solid Measure.

Mean d girt in inches.	Cubic feet in each lineal foot.	Mean d girt in inches.	Cubic feet in each lineal foot.	Mean # girt in inches.	Cubic feet in each lineal foot.
6	•25	14	1.361	22	3.362
61	.272	141	1.41	22 1	3.438
61	-294	141	1.46	221	3.516
64	-317	142	1.511	22	3.598
7	•340	15	1.562	23	3.673
7}	•364	15 1	1.615	23 1	3.754
7 1	•39	154	1.668	231	3.835
7₹	-417	154	1.722	234	3.917
8	•444	16	1.777	24	4
81	•472	164	1.833	241	4.084
81	-501	16 1	1.89	241	4.168
84	•531	164	1.948	244	4.254
9	•562	17	2.006	25	4.34
91	-594	17≹	2.066	251	4.428
9⅓	·626	17 }	2.126	25 1	4.516
97	·659	177	2.187	25 \$	4.605
10	•694	18	2.25	26	4.694
10 ↓	.73	18 1	2.313	264	4.785
101	·766	181	2.376	261	4.876
10 4	803	18‡	2.442	264	4.969
11	·84	19	2.506	27	5.062
111	-878	194	2.574	271	5.158
111	918	191	2.64	271	5.252
114	•959	194	2.709	274	5.348
12	1.	20	2.777	28	5.444
121	1.042	201	2.898	281	5.542
121	1.085	201	2.917	281	5.64
123	1.129	204	2.99	283	5.74
13	1.174	21	3.062	29	5.84
131	1.219	211	3.136	291	5.941
131	1.265	211	3.209	291	6·044 6·146
134	1.313	214	3.285	294	0.140

In the cubic estimation of timber, custom has established the rule of 1 the mean girt being the side of the square considered as the cross sectional dimensions; hence, multiply the number of cubic feet per lineal foot as in the Table of Cubic Measure opposite the 1 girt, and the product is the solidity of the given dimensions in cubic feet.

Suppose the mean 1 girt of a tree 211 inches, and its length 16 feet, what are its contents in cubic feet?

$3.136 \times 16 = 50.176$ cubic feet.

Battens, Deals, and Planks, as imported into this country, are each similar in their various lengths, but differing in their widths and thicknesses, and hence their principal distinction: thus, a batten is 7 inches by 2\frac{1}{2},—a deal 9 by 3,—and a plank 11 by 3,—thes being what are termed the standard dimensions, be which they are bought and sold, the length of each being taken at 12 feet; therefore, in estimating f the proper value of any quantity, nothing more is quired than their lineal dimensions, by which to asset tain the number of times 12 feet there are in the gi whole.

Suppose I wish to purchase the following:

```
7 of 6 feet 6 × 7 = 42 feet

5 ,, 14 ,, 14 × 5 = 70 ,,

11 ,, 19 ,, 19 × 11 = 209 ,,

and 6 ,, 21 ,, 21 × 6 = 126 ,,
```

12)447(37:25 standard

TABLE SHOWING THE NUMBER OF LINEAL FEET OF SCANTLING OF VARIOUS DIMENSIONS WHICH ARE EQUAL TO A CUBIC FOOT.

	In.		Ft.	In.		In.		Ft.	In.		In.		Ft. In
2 2½ 3 3½ 4 4½	2 36 2½ 28 3 24 3½ 20 4 18 4½ 16	36 28 24 20 18 16	36 0 28 9 24 0 20 7 18 0 16 0	4	4 4½ 5 5½ 6 6½		9 0 8 0 7 2 6 6 6 0 5 6		6 inches by	9½ 10 10½ 11 11½ 12		.2 6 2 5 2 3 2 2 2 1 2 0	
Z inches by	8 9 0 8½ 8 6 9 8 0 9½ 7 7 10 7 3	4 inches by	4 4 4 5 5 6 6 6 7 7 7 8 8 9 9 10 10 11 11 12			9 0 8 0 7 2 6 6 6 0 5 5 1 4 9 4 6 4 3 4 0 3 9 3 7 3 5 3 3 3 2 3 0	7 inches by	7 7½ 8 8 8½ 9 9½ 10 10½ 11 11½ 12	р	2 11 2 9 2 6 2 5 2 3 2 2 2 1 1 11 1 10 1 9 1 8			
	11 11 11 12	require in length	6 6	6 4 0		5 5½ 6	require in length	5 4	9 3 10	_	-	require in length	2 3 2 1 2 0 1 10
3 3 ½ 3 ½ 4 ½ 5 ½ 6 6 ½ 7 7 ½ 8 8 ½ 9 9 ½ 10 10 ½ 11 11 11 11 11 11 11 11 11 11 11 11 1	4 12 0 8 9 7 10 8 9 9 7 5 1 9 9 0 6 8 0 6 1 7 4 7 6 10 7 7 6 4	6 0 8 6 0 8 8 6 0 9 7 9 9 0 9 9 9 9 9 9 9 9 9 9 9 9 9 9	5 5 ½ 6 ½ 7 7 ½ 8 ½ 9 9 ½ 10 10 ½ 11 ½ 11 ½ 12	requin	5 5 4 4 4 3 3 3 3 3 2 2 2 2 2 2	9 - 3 10 5 1 10 5 5 2 0 10 - 5 1 2 10 - 5 1 2 10 - 5 1 2 10 - 5 1 2 10 - 5 1 2 10 - 5 1 2 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	8 inches by	8 8 ¹ / ₂ 9 9 ¹ / ₃ 10 10 ¹ / ₂ 11 11 ¹ / ₂ 12	requir	1 10 1 9 1 8 1 7 1 7 1 6			
			10½ 11 11½ 12		2 9 2 8 2 6 2 4		9 inches by	9 9½ 10 10½ 11 11½ 12		1 9 1 8 1 7 1 6 1 5			
	5 4 5 0 5 4 5 0 5 4 10 g		6 61			4 0 3 8		111 12		1 4			
,	10½ 11 11‡/	1	4 4 4	0 8 4 0 10 6 4 2	6 inches by	6 6½ 7 7½ 8 8½ 9		4 3 3 3 3 2 2	0 8 5 2 0 10 8	10 in. by	10 101 11 11	1	1 5

INSTRUMENTAL ARITHMETIC,

OR UTILITY OF THE SLIDE RULE.

THE slide rule is an instrument by which the greater portion of operations in arithmetic and mensuration may be advantageously performed, provided the lines of division and gauge-points be made properly correct, and their several values familiarly understood.

The lines of division are distinguished by the letters ABCD; AB and C being each divided alike, and containing what is termed a double radius, or double series of logarithmic numbers, each series being supposed to be divided into 1000 equal parts, and distributed along the radius in the following manner:

From 1	to 2	contains	301	of those parts, being the log.	of 2.
	9		477		3.
"	J	"	4//	"	J.
,,	4	"	602	,,,	4.
,,	5	,,	699	**	5.
"	6	,,	778		6.
,,	7	,,	845		7.
,,	8	"	903		8.
	9	"	954	••	9.
"	•			being the whole number.	•

The line n on the improved rules consists of only a single radius; and although of larger radius, the logarithmic series is the same, and disposed of along the line in a similar proportion, forming exactly a line of square roots to the numbers on the lines BC.

NUMERATION.

eration teaches us to estimate or properly value nbers and divisions on the rule in an arithmerm.

r values are all entirely governed by the value n the first figure, and being decimally reckoned, tenfold from the commencement to the term of each radius: thus, suppose 1 at the joint the 1 in the middle of the rule is ten, and 1 and, one hundred: again, suppose 1 at the joint n the middle is 100, and 1 or 10 at the end is &c., the intermediate divisions on which compae whole system of its notation.

) MULTIPLY NUMBERS BY THE RULE.

l on B opposite to the multiplier on A; and the number to be multiplied on B is the pro-

tiply 6 by 4.

on B to 4 on A; and against 6 on B is 24 on A. The is set, against 7 on B is 28 on A.

8 ,, 32 ,, 9 ,, 36 ,, 10 ,, 40 ,,

12 , 48 ,

15 ,, 60 ,, 25 ,, 100, &c., &c.

D DIVIDE NUMBERS UPON THE RULE.

the divisor on B to 1 on A; and against the r to be divided on B is the quotient on A. de 63 by 3.

on B to 1 on A; and against 63 on B is 21 on A.

PROPORTION, OR RULE OF THREE DIRECT.

Rule.—Set the first term on B to the second on A; and against the third upon B is the fourth upon A.

1. If 4 yards of cloth cost 38 shillings, what will 30 yards cost at the same rate?

Set 4 on B to 38 on A; and against 30 on B is 285 shillings on A.

2. Suppose I pay 31s. 6d. for 3 cwt. of iron, at what rate is that per ton? 1 ton = 20 cwt.

Set 3 upon B to 31.5 upon A; and against 20 upon B is 210 upon A.

RULE OF THREE INVERSE.

Rule.—Invert the slide, and the operation is the same as direct proportion.

1. I know that six men are capable of performing a certain given portion of work in eight days, but I want the same performed in three; how many men must there be employed?

Set 6 upon c to 8 upon A; and against 3 upon c is 16 upon A.

2. The lever of a safety-valve is 20 inches in length, and 5 inches between the fixed end and centre of the valve; what weight must there be placed on the end of the lever to equipoise a force or pressure of 40 lbs. tending to raise the valve?

Set 5 upon c to 40 upon A; and against 20 on c is 10 on A.

3. If $8\frac{3}{4}$ yards of cloth, $1\frac{1}{2}$ yard in width, be a sufficient quantity, how much will be required of that which is only $\frac{7}{6}$ ths in width, to effect the same purpose?

Set 1.5 on c to 8.75 on A; and against .875 upon c is 15 yards upon A.

SQUARE AND CUBE ROOTS OF NUMBERS.

On the engineer's rule, when the lines c and D are equal at both ends, c is a table of squares, and D a table of roots, as

Squares 1 4 9 16 25 36 49 64 81 on c.
Roots 1 2 3 4 5 6 7 8 9 on p.

To find the geometrical mean proportion between two numbers.

Set one of the numbers upon c to the same number upon c; and against the other number upon c is the mean number or side of an equal square upon c.

Required the mean proportion between 20 and 45. Set 20 upon c to 20 upon p; and against 45 upon c is 30 on p.

To cube any number, set the number upon c to 1 or 10 upon p; and against the same number upon p is the cube number upon c.

Required the cube of 4.

Set 4 upon c to 1 or 10 upon D; and against 4 upon D is 64 upon c.

To extract the cube root of any number, invert the slide, and set the number upon B to 1 or 10 upon D; and where two numbers of equal value coincide on the lines BD, is the root of the given number.

Required the cube root of 64.

Set 64 upon B to 1 or 10 upon D; and against 4 upon B is 4 upon D, or root of the given number.

On the common rule, when 1 in the middle of the line c is set opposite to 10 on p, then c is a table of squares, and p a table of roots.

To cube any number by this rule, set the number upon c to 10 upon p; and against the same number upon p is the cube upon c.

MENSURATION OF SURFACE.

1. Squares, Rectangles, &c.

Rule.—When the length is given in feet and the breadth in inches, set the breadth on B to 12 on A; and against the length on A is the contentin square feet on B.

If the dimensions are all inches, set the breadth on B to 144 upon A; and against the length upon A is the number of square feet on B.

Required the content of a board 15 inches broad and 14 feet long.

Set 15 upon B to 12 upon A; and against 14 upon A is 17.5 square feet on B.

2. Circles, Polygons, &c.

Rule.—Set .7854 upon c to 1 or 10 upon p; then will the lines c and p be a table of areas and diameters.

Areas 3.14 7.06 12.56 19.63 28.27 38.48 50.26 63.61 upon c.

Diam. 2 3 4 5 6 7 8 9 upon p.

In the common rule, set '7854 on c to 10 on p; then c is a line or table of areas, and p of diameters, as before.

Set 7 upon B to 22 upon A; then B and A form or become a table of diameters and circumferences of circles.

Cir. 3 14 6 28 9 42 12 56 15 7 18 85 22 25 13 28 27 upon A.

Dia. 1 2 3 4 5 6 7 8 9 upon B.

Polygons from 3 to 12 sides.—Set the gauge-point upon c to 1 or 10 upon D; and against the length of one side upon D is the area upon C.

Sides 3 5 6 7 8 9 10 11 12 Gauge-points 433 1.7 2.6 3.63 4.82 6.18 7.69 9.37 11.17

Required the area of an equilateral triangle, each side 12 inches in length.

Set 433 upon c to 1 upon p; and against 12 upon p are 62.5 square inches upon c.

Names.	f, p, f.	F, I, I.	I, I, I.	F, I.	I, I.	T.	I.
Cubic inches	578	83	1728	106	1273	105	121
Cubic feet	1	144	1	1833	22	121	33
Imp. gallons	163	231	277	294	353	306	529
Water in ibs.	16	23	276	293	352	305	528
Gold "	814	1175	141	149	178	155	269
Silver "	15	216	261	276	334	286	5
Mercury "	118	169	203	216	258	225	389
Brass "	193	177	333	354	424	369	637
Copper "	18	26	319	331	397	345	596
Lead ,,	141	203	243	258	31	27	465
Wrot.iron "	207	297	357	338	453	394	682
Cast iron "	222	32	384	407	489	424	733
Tin "	219	315	378	401	481	419	728
Steel "	202	292	352	372	448	385	671
Coal "	127	183	22	33	28	242	42
Marble "	591	85	102	116	13	113	195
Freestone ,,	632	915	11	1162	14	141	21

FOR THE COMMON SLIDE BULE.											
Names.	F, F, F.	F, I, I,	I, I, I.	F, I.	I, I.	F.	ı.				
Cubic inches	36	518	624	660	799	625	113				
Cubic feet	625	9	108	114	138	119	206				
Water in the.	10	144	174	184	22	191	329				
Gold "	507	735	88	96	118	939	180				
Silver "	938	136	157	173	208	173	354				
Mercury ,,	738	122	127	132	162	141	242				
Brass ,,	12	174	207	221	265	23	397				
Copper "	112	163	196	207	247	214	371				
Lead "	880	126	152	162	194	169	289				
Wrot.iron ,,	129	186	222	235	283	247	423				
Cast iron ,,	139	2	241	254	304	265	458				
Tin "	137	135	235	25	300	261	454				
Steel "	136	183	22	233	278	239	418				
Coal "	795	114	138	146	176	151	262				
Marble "	370	53	637	725	81	72	121				
Freestone "	394	57	69	728	873	755	135				

l.

MENSURATION OF SOLIDITY AND CA

General rule.—Set the length upon B to point upon A; and against the side of the diameter on D, are the cubic contents, o lbs. on C.

1. Required the cubic contents of a tre length, and 10 inches quarter girt.

Set 30 upon B to 144 (the gauge-point) upon A 10 upon D is 20.75 feet upon C.

2. In a cylinder 9 inches in length, a diameter, how many cubic inches?

Set 9 upon B to 1273 (the gauge-point) upon A 7 on p is 346 inches on c.

3. What is the weight of a bar of cast in square, and 6 feet long?

Set 6 upon B to 32 (the gauge-point) upon A; upon D is 168 ibs. upon C.

By the common rule.

4. Required the weight of a cylinder iron 10 inches long, and $5\frac{1}{2}$ diameter.

Set 10 upon B to 283 (G. Pt.) upon A; and ag p is 66.65 ths. on c.

5. What is the weight of a dry rope 25 and 4 inches circumference?

Set 25 upon B to 47 (G. Pt.) upon A; and aga 53.16 ibs. on c.

6. What is the weight of a short-link yards in length, and $\frac{6}{16}$ ths of an inch in

Set 30 upon B to 52 (G. Pt.) upon A; and age 129.5 ibs. on c.

LAND SURVEYING.

If the dimensions taken are in chains, the gaugeint is 1 or 10; if in perches, 160; and if in yards, 40.—Rule. Set the length upon B to the gaugeint on A; and against the breadth upon A is the atent in acres upon B.

1. Required the number of acres or contents of ield 20 chains 50 links in length, and 4 chains 40 ks in breadth.

Set 20.5 on B to 1 on A; and against 4.4 on A is 9 acres on B.

2. In a piece of ground 440 yards long, and 44 pad, how many acres?

Set 440 upon B to 4840 on A; and against 44 on A is cres on B.

POWER OF STEAM ENGINES.

Condensing Engines.—Rule. Set 3.5 on c to 10 on; then D is a line of diameters for cylinders, and C e corresponding number of horses' power; thus, Pr. 3\frac{1}{2} 4 5 6 8 1012 16 20 25 30 40 50 on c. D. 10 in. 10\frac{1}{2} 13\frac{1}{2} 15\frac{1}{2} 17 18\frac{1}{2} 21\frac{1}{2} 24 26\frac{1}{2} 29\frac{1}{2} 33\frac{1}{2} 37\frac{1}{2} on D. The same is effected on the common rule by setting on C to 12 on D.

Non-condensing Engines.—Rule. Set the pressure steam in its. per square inch on B to 4 upon A; d against the cylinder's diameter on D is the numr of horses' power upon c.

Required the power of an engine, when the cylinr is 20 inches diameter and steam 30 lbs. per uare inch.

Set 30 on B to 4 on A; and against 20 on D is 30 horses' wer on C.

The same is effected on the common rule b the force of the steam on B to 250 on A.

OF ENGINE BOILERS.

How many superficial feet are contained in 23 feet in length and $5\frac{1}{3}$ in width?

Set 1 upon B to 23 upon A; and against 5.5 126.5 square feet upon A.

If 5 square feet of boiler surface be suffi each horse-power, how many horses' power a is the boiler equal to?

Set 5 upon B to 126.5 upon A; and against 125.5 upon A.

TABLE BY WHICH TO FACILITATE THE CALCULATION OF BRITISH MONEY

	L.	S		D.	L.	S.	D.	L.	S.	D.	L.	8.	D.	L.	8.	D.	L.	S.	D.	L.	S.	D
No.		at :	d.		1	it d	d.	O	at P	d.	a	t 10	t.	a	t 1	d.	а	t 1	d.	B	t 1	d.
3 4 5 6	0 0 0 0	0000	1 1	1	0 0 0 0	0 0 0 0	1 12 2 2 2 3	0000	0 0 0	12 24 3 34 40	0 0 0 0	0 0 0	2 3 4 5 6	0 0 0	0 0 0	25 34 5 64 74	0 0 0 0	0000	3 44 6 74 9	0 0 0	0 0 0	3 5 7 8 10
7 8 9	0 0	0	2	1	0	0	31 4 41	0	0	54 6 64	0	0	7 8 9	0	0	10 11‡	0	1	104 0 14	0	1	9 3
10 11 12	0 0 0	0	3		0	0 0	54	0 0	0 0	7± 8± 9	0 0 0	0 0 1	10 11 0	0 0	1 1	04 14 3	0 0	1 1	3 41 6	0 0	1 1	5.79
13 14 15 16	000	0 0 0	3 3 4		0 0 0	0 0 0	7 74 8	0 0 0	0 0 1	93 104 114 0	0000	1 1	3 4	0 0 0	1 1	50 64 8	0 0 0	1 1 2	76 9 104 0	0 0	2 2 2	10
17 18 19	0	0	- 4	4-Dra4	0	0	9 1 8 1	0	1	02 11 24	0	1 1	6 7	0	1	9‡ 10± 11±	0	2 2	14 3 44	0	2 2	5 7 9
20 30	0	0	5		0	0	10	0	1	3 104	0	1 2	6	0	3	1	0	3	6	0	2 4	11
40 50	0	0	10	1	0	1 2	8	0	3	6	0	3	4 2	0	5	2 23	0	6	0	0	5	10
60	0	1	3		0	2	6	0	3	9	0	5	0	0	6	3	0	7	6	0	8	9
70 80	0	1	8	4	0	3	11	0	5	4±	0	6	10	0	7 8	34	0	8	9	0	10	2
90	0	î	10		o	3	9	0	5	74	o	7	6	0	9	45	ő	10	3	0	11 13	8
100 200	0	2	1 2		0	4 8	2	0	6	3	0	8 16	4 8	0	10	5	0	12	6	0	14	7 9
300	0	6	3	1	0	12	6	0	18	9	1	5	0	1	11	3	î	17	6	2	3	9
400	0	8	4		0	16	8	1	5	0	1	13	4	2	1	8	2	10	0	2	18	4
500	0	10	6		1	0	10	1	11	3	2	1	8	2	12	1	3	2	6	3	12	11
700	0	14	2		1	5	0 2	1 2	17	6	2 2	10	4	3	12	6	3	15	0	4	7	6
800	a	16	8		i	13	4	2	10	0	3	6	8	4	3	4	5	7	6	5	2	1
900	ō	18	9		î	17	6	2	16	3	3	15	0	4	13	9	5	12	6	6	16	3
2000	1 2	0	10		2	1 3	8	3 6	2 5	6	4	3	4	5	4	2	6	5	0	7	5	10
3000	3	2	6		6	5	0	9	7	6	12	10	8	10	12	6	12		0	14	11	8
1000	4	3	4		8	6	8	12	10	ő	16	13	4	15 20	16	8	18 25	15	0	21	17	6
5,000	5	4	2		10	8	4	15	12	6	20	16	8	26	0	10	31	5	0	36	9	2
Q000	6	5	0		12	10	0	18	15	0	25	0	0	31	5	0	37	10	0	43	15	0
7000		5	10		14	11	8	21	17	6	29	3	4	36	9	2	43	15	0	51	0	10
8000 9000	,-	6	8		16	13	4	25	0	0	33	6	8	41	13	4	50	0	0	58	6	8
- and	9	7	6		18	15	0	28	2	6	37	10	0	46	17	6	56	5	0	05	12	6

	L.	s.	D.	L.	s.	D.	L.	s.	D.	L.	s.	D.	L.	s.	D.	L.	s.	D.	L.
No.	-	t 20	ī.		t 2:	d.	<u> </u>	t 2			t 2		.—	t 3d			t 3	d.	-
2	0	0	4	0	0	44	0	0	5		0	54	0	0	6			61	<u> </u>
3	ŏ	ŏ	6	ŏ	ŏ	41 62	ŏ	ŏ	7 à	ŏ	ŏ	81	ŏ	ŏ	ğ	ŏ	ŏ	92	
4	0	0	8	0	0	9	0	0	10	0	0	11	0	1	0	0	1	1	1.9
5	0	. 0	10	0	0	114	0	1	0 ∮	0	1	12	0	1	3	0	1	4	
6	0	1	9	0	1	1 d 3 d	0	1	3 5}	0	1	44 74	0	1	6	0	1	74 101	
7 8	ŏ	i	4	ŏ	i	6	ŏ	i	8	٥	i	10	6	2	9	ŏ	ŝ	2	
ğ	ō	ī	6	ŏ	ì	8‡	ŏ	1	104	ŏ	2	07	ŏ	2	3	ŏ	3	5‡	1
10	0	1	8	0	1	10 1	0	2	1	0	2	34	0	2	6	0	2	84	1
11 12	0	1 2	10 0	0	2	0≵ 3	0	2	3 1	8	2	6₹ 9	0	2	9	0	3	112	
13	ŏ	2	2	ő	ŝ	51	ŏ	2	84	Ĭŏ	3	112	ŏ	3	8	0	3	61	П
14	ŏ	2	4	ŏ	2	74	ŏ	2	11	ŏ	3	24	ŏ	3	ŏ	ŏ	3	9	1
15	0	2	6	0	2	92	0	3	1ģ	0	3	5.	0	3	9	0	4		Ľ
16	0	3	8	0	8	0	0	3	4.	0	3	8	0	4	0	0	4	4,	H
17 18	0	2	10	0	8	24	0	3	ð Qf	0	3	102 14	0	4	8	0	4	7‡ 10‡	П
19	ŏ	3	2	ě	3	44 63	ŏ	8	114	ě	4	44	ŏ	4	9	ě	5	12	
20	0	3	4	0	3	9	0	4	2	0	4	7	0	5	0	0	5	5	١
30	0	5	0	0	5	74	0	6	3	0	6	104	0	.7	6	0	8	14	
40 50	0	6	8	0	7	6 43	0	8 10	4 5	0	11	2 51	9	10 12	6	0	10 13	10 61	
60	ő	10	i	8	9 11	3	ő	12	6	0	13	9	ö	15	Ö	0	16	3	П
70	ŏ	ii	8	ŏ	13	14	ŏ	14	7	١ŏ	16	04	ŏ	17	6	ŏ	18	114	Ŀ
80	Ô	13	4	0	15	0	0	16	8	0	18	4	1	Ö	0	1	1	8	ı
90	0	15	0	0	16	10 	0	18	9	1	0	7ŧ	1	2	6	1	4	4	l
100 200	0	16 13	8	0	18 17	9 6	1 2	0	10 8	1 2	2 5	11 10	1 2	5 10	0	1 2	7 14	1 2	١.
300	2	10	ō	2	16	3	3	2	6	3	8	9	3	15	ŏ	4	1	3	Г
400	3	6	8	3	15	Ō	4	3	4	4	11	8	5	0	ŏ	5	8	4	1
500	4	3	4	4	13	9	5	4	2	5	14	7	6	5	0	6	15	5	
600	5	16	0	5	12 11	6	6	5	.0	6	17	6	7	10	0	8	2	6	1
700 800	6	13	8	7	10	0	7 8	5 6	10 8	8 9	3	5 4	10	15	0	10	9 16	7	li
900	7	10	ō	8	8	ğ	9	7	6	10	6	3	11	5	ŏ	12	3	9	i
1000	8	6	8	9	7	6	10	8	4	11	9	2	12	10	0	13	10	10	1
2000	16	13	4	18	15	ò	20	16	8	22	18	4	25	.0	0	27	1	8	13
3000 4000	25 33	6	8	28 37	2 10	6	31 41	5 13	0	34 45	7 16	6	37 50	10 0	0	40 54	12	6	4
5000	41	13	4	46	17	6	52	13	4 8	57	5	10	62	10	Ö	67	14	2	1
6000	50	ő	ō	56	٠,	ŏ	62	10	ŏ	68	15	ő	75	ō	ŏ	81	• 5	õ	1 8
7000	58	6	8	65	12	6	72	18	4	80	4	2	87	10	ō	94	15	10	10
8000	66	13	4	75	0	0 '	83	6	8	91	13	4	100	0	0	108	.6	8	111
9000	75	0	0	84	7	6	93	15	0	103	2	6	112	10	0	121	17	6	18

		_				_				_						,					-
	L.	s.	D.	L.	s	D	L.	s.	D.	L.	s.	D.	L.	s.	Ď.	L.	s.	D.	L.	s.	I
No.	21	32	d.	at	4d.		al	4‡	đ.	at	4 <u>1</u>	d.	8.1	42	d.	8.1	5d	•	at	54	d.
2			7 è	0	-0	8	0	0	88	0	0	9	0	0	99	0	0	10	0	•	10
3		0	114	0	1	0	0	1	02	0	1	14	0	1	24	0	1	3	0	1	3
4	0	1	3	0	1	4	0	1	5	0	1	6	0	1	.7.	0	1	8	0	1	9
. 5		1	62	0	1 2	8	. 0	1 2	91	0	1	104	0	1	112	0	2	1	0	2	2
. 7		3	10 3	ŏ	2	4	8	2	14 52	0	2	3 74	ŏ	2	44 91	0	2 2	6 11	0	2	7
8	Ĭ	ŝ	6	ŏ	2	8	۱٥	2	10	ŏ	3	(a	ŏ	3	2	۱٥	8	4	ŏ	3	6
9	ě	2	92	Ŏ	8	ŏ	Ŏ	3	24	ō	3	44	Ŏ	8	63	, ŏ	3	9	ŏ	3	11
10		8	Ιģ	0	3	4	0	3	64	0	3	9	0	3	114	0	4	2	0	4	4
11		8	54	0	8	8	0	3	102	0	4	14	0	4	44	0	4	7	0	4	9
12 13		8	9 0 2	ő	1	4	0	4	3 7±	0	4	6 10±	0	5	9 1 2	0	5 5	0 5	0	5 5	8
14	ì	4	44	ŏ	4	8	ŏ	4	113	ŏ	5	3	ŏ	5	6	ŏ	5	10	ŏ	6	î
15	١ŏ	4	e <u>T</u>	ŏ	5	ŏ	ŏ	5	32	Ŏ	5	7 å	Ŏ	5	111	ŏ	ő	3	ŏ	6	ã
16		5	0	0	5	4	0	5	8	0	6	0	0	6	4	0	6	8	o	7	0
17	0	5	82	0	5	8	0	6	04	0	6	44	0	6	82	0	7	1	0	7	5
18	0	5	.74	0	6	0	0	6	44	0	6	9.	0	7	ᆙ	0	7	6	0	7	10
19	•	5	11‡	ľ	•	4	1	-	83	ľ	7	1ģ	1	٠	6‡	•	7	11	°	8	3
20	0	6	3		.6	8	0	7 10	1	8	7	6	8	7	11	0	8 12	4	0	.8	9
30 40	:	13	6	0	10 13	4	0	14	7ŧ	6	15	õ	0	15	10년 10	6	16	6	0	13 17	6
50		15	7å	Ĭŏ	16	8	ŏ	17	84	ľŏ	18	ğ	ŏ	19	94	۱ĭ	Ö	10	۱ĭ	'n	10
60	ě	18	9	ì	Ö	0	1	'n	3	1	2	6	li	3	9	ī	5	ō	l i	6	3
70] 1	1	104	1	3	4	1	4	94	1	6	3	1	7	8월	1	9	2	1	10	7
80	1 1	5	0	1	6	8	1	8	4.	1	10	0	1	11	8	1	13	4	1	15	0
90	1	8	19	1	10	0	1	11	10 ۇ	1	13	9	1	15	7ŧ	1	17	6	1	19	4
160 200	1 3	11	3 6	1 8	13	8		15 10	5 10		17 15	6	1 3	19 19	7	3	1	8	2 4	3 7	9
300	1 4	13	ğ	5	ŏ	ŏ	5	6	3	5	12	6	5	18	9	ō	5	ō	ō	ú	3
400	6	5	Ō	6	13	4	7	1	8	7	10	0	7	18	4	8	6	8	8	15	ō
500	7	16	3	8	6	8	8	17	1	9	7	б	9	17	11	10	8	4	10	18	9 6
600	9	.7	6	10	. 0	0	10	12	.6	111	5	0	11	17	6	12	10	0	13	2	
700 800	10	18 10	9	11 13	13 6	8	12	7	11	18 15	2	6	13 15	17 16	8	14 16	11 13	8	15 17	.6	3
900	14	1	8	15	Ö	ő		18	9	16	17	ő	17	16	3	18		ō	19	19	9
1000	15	12	6	16	13	4	17	14	2	18	15	0	19	15	10	20	16	8	21	17	6
2000	.31	5	0	33	6	8	95	8	4	37	10	0	39	11	8	41	13	4		15	0
3000		17	6	50		0	53	.2	6	56	5	0	59	7	6	62	10	0	65	12	6
4000	62	10	6	66 83	13 6	8	70	16	8 10	75	.0	0	79	.8	4	83	6	8	87	10	6
5000 6000	78	2 15	0	100	0	8	106	10 5	10	93 112	15 10	0	98 118	19 15	2	104 125	8	4	109 131	7	0
7000	100	7	ŏ	116	13	4	123	19	2	131	5	ŏ	138	10	10	145	16	8	153	2	6
8000	125	ó	ō	133	ĕ	8	141	13	4	150	ŏ	ŏ	158	ő	8	166	13	4	175	ō	0
	140	12	6	150	Ð	0	159	7	6		15	ŏ	178	2	6	187		0		17	6
l .							•	-		•						- 1				-	

	L.	8.	D.	L.	s	D.	L.	s.	D.	L.	s.	D.	L.	S	D.	L.	8.
No		t 5	d.	-	t 5	d.	a	t 6d			s 64	d.	-	t 6	d,	-	t 64
-			11	0			0		0			04	6			1	
1 5						5	0		6			63	9				
1 3				0		11 42	0		6	0			1 8			1 8	
1 6				۱ŏ			Ö		ŏ	ŏ		14	l à			1 6	
1 2	0			0		44	0		6			7₹	0			0	
5				0			0		6			2 81	0			0	
1		_	•	0		-		_		1	_	•	1			ł	_
11				0		94 31	0		6	0		24 82	1 8		5 113	9	
lis				0	5	a`	ŏ		ŏ	l ŏ		3	١٥			١٥	
18	0	5	114	0	6	22	0		6	O	- 6	94	Ó		양	Ó	
14				0			0		0	0		34	0		7.	0	
18			10å	8	7	- 8 3축	0	7	6	0		92	l°		1 <u>1</u>	0	
12			93	١٥	8	12	ŏ		6	0		102	lŏ		24	ŏ	
18	1 0	8		0	8		0	9	0	Ó	9	4	0	9	9	0	10
19	0	8	8 <u>\$</u>	0	9	14	0	9	6	0	9	102	0	10	3 §	0	10
20		9	2	0	9	7.	0		0	0	10	5	0		10	0	
30 40		13 18	9	0	14 19	44 2	0	15	0	0	15 0	7₹ 10	0 1	16 1	8	0	16
50		2	11	١ĭ	3	114	l i	5	ŏ	Ιi	ŏ	.04	Ιi	ż	ì	l i	8
60	1	7	6	1	8	9	1	10	Ō	1	11	3	ì	12	6	lī	13
70		12	1	1	13	64	1	15	0	1	16	5 ģ	1	17	11	1	19
80		16 1	8	1 2	18	4 14	2 2	0 5	0	2	6	8 10å	2 2	8	9	2	5 10
1	1	_	-	_	-	-4			-	-	-	•			Ξ.	i -	
100	2	5	10	2	.7	13	2	10	0		12	1	3	14	2	8	16
200 300	6	11	8	7	15 3	10 9	5 7	0 10	0	5 7	16	2	5 8	8	6	5 8	12
400	ۆا	'n	4	ۇ ا	11	8	10	ŏ	ö	16	8	4	10	16	8	ıñ	5
500	11	9	2	11	19	7	12	10	ŏ	18	ō	5	13	10	10	14	1
600	13	15	0	14	.7		15	0	0	15	12	6	16	. 5	0	16	17
700 800	16 18	6	10	16 19	15 3	4	17 20	10	0	18 20	16	7	18 21	19 13	2 4	19	13 10
900	20	12	6	21	11	3	22	10	Ö	25	10	ŷ	24	7	6	25	6
1000	22	18	4	23	19	2	25	0	0	26	0	10	27	1	8	28	2
2000	45	16	8	47	18	4	50	0	0	52	ì	8	54	3	4	56	5
3000			0	71	17	6	75	0	0	78	2	6	81	5	0	84	7
4000 5000	91	13 11	8	95 119	16 15	8 10	100 125	0	0	104	8	4	108 135	6	8	112 140	10
6000	137	10	ő	143	15	10	150	Ö	Ö	156	5	0	162	10	•	168	13 15
7000	160	8	4	167	14	2	175	ŏ	ŏ	182	5	10	189	ii	ě	196	17
8000	183	6	8	191	13	4	200	Ō	0	208	6	8	216	13	4	225	ő
9000	206	5	0	215	12	6	225	0	0	234	7	6	248	15	0	253	2

MOREY TABLE - CONTINUED.

D_{i}	L.	S.	D_{i}	L.	S.	D.	L.	s. I		L.	8.	D.	L.	S.	D.	L.	8.	D.
ı.	at	78	d.	a	79	d.	at	8d.		at	84	d.	at	8	d.	at	82	đ.
25 92 5 04 74 22 10	0 0 0 0 0	1 2 3 3 4 5	3 10½ 6 1½ 9 4½ 0	0 0 0 0 0	1 1 2 3 3 4 5	35 114 7 22 105 64	0 0 0	3 4 4 5	4 0 8 4 0 8 4	0 0 0 0 0	1 2 3 4 4 5	45 02 9 54 15 92 6	0 0 0 0 0 0 0	1 2 2 3 4 4 5	5 10 10 64 3 114	0 0 0 0	1 2 2 3 4 5 5	54 24 11 72 44 14 10
5± 0± 74	0 0	6	7± 3 10± 6	0	6 7	92 54 14	0 0	6 7	8 4	0	6 7	104 62	0	77	1 91	0 0	7 8	34
3 101 55 02 8 31 101 52	0000	7 8 9 10 10 11 11	1 de 10 de 1	0 0 0 0	7 8 9 10 10 11 12	9 42 04 84 4 112 75 34		9 10 10 11	0 8 4 0 8 4 0 8	0 0 0 0 0	8 9 10 11 11 12 13	3 114 70 33 0 84 40 02	0 0 0 0 0	9 9 10 11 12 12 13	6 2½ 11 7½ 4 0½ 9 5½	0 0 0 0 0	9 10 10 11 12 13 13	9 54 114 8 49 101
1 12 22 3 34 4 4	0 0 1 1 1 2 2	12 18 5 11 17 3 10 16	6 9 0 3 6 9 0 3	0 0 1 1 1 2 2 2	19 5 19 5 18 5 11 18	11 4½ 10 3½ 9 2½ 8 1½	0 1 1 1 2 2 2 3	6 13 0 6	4 0 8 4 0 8 4	0 1 1 1 2 2 2 3	13 0 7 14 1 8 15	9 72 6 42 3 12 0 102	0 1 1 1 2 2 2 3	14 1 8 15 2 9 16 3	2 3 4 5 6 7 8 9	0 1 1 1 2 2 2 3	14 9 16 3 11 18	7 10 2 5 9 0 4 7
5 10 3 8 1 6 11 4	3 6 9 12 15 18 21 25 28	5 7 10 12 15 17 0	6 0 6 0 6	3 6 9 12 16 19 22 25 29	9 13 18 2 7 12 16 1	7 9 4 11 6 1 8 3	3 6 10 13 16 20 23 26 30	6 13 0 6	4 0 8 4 0 8 4	3 6 10 13 17 20 24 27 30	8 17 6 15 3 12 1 10 18	9 5 3 0 9 6 3 0 9	3 7 10 14 17 21 24 28 31	10 12 3 14 5 15 6 17	10 8 6 4 2 0 10 8 6	3 7 10 14 18 21 25 29 32	19 5 18 11 4 17 10 3	11 10 9 8 7 6 5 4 3
2 4 6 8 10 0 2 4 6	31 62 93 125 156 187 218 250	5 10 15 0 5 10 15	0 0 0 0 0 0 0 0	32 64 96 129 161 193 226 259	5 11 17 3 9 15 0 6	10 8 6 4 2 0	33 66 100 133 166 200 233 266	0 6 13	4 0 8 4 0 8	34 68 103 137 171 206 240 275	7 15 2 10 17 5 12 0	6 0 6 0 6 0	35 70 106 141 177 219 247 283	8 16 5 13 1 10 18 6	4 8 0 4 8 0 4 8	36 72 109 145 182 218 255 291	5	2 4 6 8 10 0 2 4

	L.	s.	D.	L.	s,	D.	L.	s.	D.	L.	s.	D.	L.	s.	D.	L.	s.	D
No.	at	9ď.		at	940	i.	at	9}	i.	at	934	i.	at	104	i.	at	10	ď.
2	0	1	6	0	1	64	0	1	7	_	1	7 è	0	1	8	<u> </u>	1	8
3	0	2	3	0	2	35	0	2	44	0	2	54	0	3	6	0	3	6
4 5	0	3	9	0	3	1 10±	0	3	2 114	0	3	3 0\$	0	3	4	0	3	5 3
6	ŏ	4	6	ŏ	4	74	ŏ	4	9	ŏ	4	101	ŏ	5	ō	ě	5	ĭ
7	0	5	3	0	5	42	0	5	64	0	5	84	0	5	10	0		11
8	0	6	9	0	6	2 11±	0	6 7	14	0	6 7	6 3≩	0	6 7	8	0	7	10 8
	٠	v	,	·	٠	***	٠	•	-4	۳	•	24	ľ	•	٠	v	•	•
10	0	7	6	0	7	84	0	7	11	0	8	14	0	8	4	0	8	6
11	0	8	8	0	8	52	0	8	8 1	0	8	114	0	.9	3	0	9	4
12 13	0	9	9	0	9 10	3 01	0	9 10	33	0	9 10	9 64	0	10 10	0 10	0	10 11	8
14	ŏ	10	6	ŏ	10	94	ŏ	ii	ĭ	ŏ	ii	45	ŏ	ii	8	ŏ	ii	ıi
15	0	11	3	0	11	연활	0	11	10 4	0	12	24	0	12	6	0	12	9
16	0	12	0	0	12	4.	.0	12	8,	0	13	0	0	13	4	0	13	8
17	0	12	9	0 0	13 13	12 104	0	13 14	5 ۇ 3	0	18 14	9章 7章	0	14 15	2	0	14 15	6
19		14	3	ŏ	14	7	ŏ	15	9		15	51		15	10	ŏ	16	3
	١.		_									_	١.					
20 30	0	15 2	6	0	15 3	5 14	0	15 3	10 9	0	16 4	3 48	0	16 5	8	0	17	7
40	l i	10	Ö	i	10	10	i	11	8	l i	12	6	i	13	4	i	14	2
50	j	17	6	l ī	18	64	ì	19	7	2	ō	7 å	2	1	8	2	2	8
60	2	5	0	2	6	3	2	7	6	2	8	9	2	10	0	2	11	3
70 80	3	12	6	2	13	11 1	2 3	15 3	5 4	3	16 5	10å	2 3	18 6	8	2	19 8	9
90	3	7	6	3	ģ	44	3	11	3	3		14	3	15	Ö	3		10
1	[-	-	-	-	•	-		-	1		_	1					
100	3		0	3	17	1		19	2	4		3	4	3	4	4	5	5
200 300	7	10 5	0	11	14	2	7	18 17	6	12		6	12	6 10	8	8 12	10 16	10 9
400	15	ŏ	ŏ	15	8	4	15	îó	8	16		ŏ	16	13	4	17	'n	8
500	18	15	0	19	5	5	19	15	10	20	6	3	20	16	8	21	7	1
600	22	10	0	23	.2	6	23	15	0	24	7	6	25	0	0	25	12	6
700 800	26 30	5 0	0	26 30	19 16	7 8	27 31	14 13	24	28 32			29 33	3 6	8	29 34	17 3	11
900	33		ŏ	34	13	9		12	ò	36		3	37	10	ő	38	8	Ġ
						•						_	1					Ť
1000	37	10	0	38		10	39		8	40			41	13	4	42	14	2
2000 3000	75 112	0 10	0	115	1 12	8 6	79 118	3 15	4	81 121	5 17	6	83 125	6	8	85 128	8	4
4000	150	ő	ŏ	154	3	4	158	6		162		ŏ	166	13	4	170	16	ે
5000	187		0	192		2	197			203	2	6	208	6	8	213		
6000	225	.0	0	231	. 5	.0	237	10	0	243		0	250	.0	0	256	. 5	(
7000	262 300	10	0	269 308	15 6		277 316	1 13	8	284 325	7	6	291 333	13	8	298 341	19 18	5
	337		ŏ	346		6	356			365			375	ő		384	7	ાં
2300	1007			1040	٠,	-	500			1 500			/-			,		•

	L.	s.	D.	L.	S.	D.	L	8.	D.	L.	8.	D.	L.	s.	D.	L.	S.	D.
No.	at	10	d.	at	11	t.	at	11	d.	at	11,	d.	at	11	ld.	a	18	
2	0	1	91	0	1	10	0	1		0	1		0		114	0	2	0
3	0	2	84	0	2	9	.0	2	92	0	2	105	0	2	114	0	3	0
4	0	3	7.	0	3	8	0	3	9	0	3	10	0	3	11	0	5	0
6	0	5	52	0	5	6	0	5	84 74	0	5	94	0	5	103	0	6	0
7	0	6	44 31	0	6	5	0	6	64	0	6	84	0	6	104	0	7	0
8	0	7	2	0	7	4	0	7	6	0	7	8	0	7	10	0	8	ì
9	0	8	02	Õ	8	3	0	8	54	0	В	71	0	8	92	0	9	
10	0	8	114	0	9	2	0	9	44	0	9	7	0	9	94	0		•
11	0	9	104		10	1	0	10	32	0	10	6	0	10	94		11	
12		10 11	9 73	0	11	11	0	12	21	0	12	53	0	12	83		13	ì
14		12	64	0	12	10	0	13	13	0	13	5	0	13	87		14	i
15		13	54	0	13	9	0	14	02	0	14	43	0	14	81	0	15	
16		14	4	0	14	8	0	15	0	0	15	4	0	15	8	0	16	
17		15	23	0	15	7	0	15	114	0	16	35	0	16	72		17	
18		16	14		16	6	0	16	105		17	3	0	17	7± 7±		18	
19	0	17	0‡	0	17	5	0	17	94	0	18	25	0	18		0	19	(
20 30	0	17		0	18	6	0	18	9	0	19	9	0	19	7	1	10	-
40		15	10	i	16	8	1	17	6	1	18	4	1	19	2	2	0	(
50	2	4	94	2	5	10	2	6	104	2	7	11	2	8	114	2	10	
60	2	13	9	2	15	0	2	16	3	2	17	6	2	18	9	3	0	
70	3	2	84	3	4	2	3	.5	74	3	16	8	3	18	64	3	10	0
90	3	11	8 78	3	13	6	4	15	43	4	6	3	4	8	13	4	10	ì
1		13	11.03	1.5	í.		1	-3	. 0	11.5		270	113	43		1		
100	4	9	7	9	11	8	9	13	6	9	15	10		17	11	10	0	-
300	13	19	9	13	15	0	14	7	3	14	7	6	14	13	9	15	0	ì
400	17	18	4	18	6	8	18	15	0	19	3	4	19	11	8	20	0	1
500	22	7	11	22	18	4	23	8	9	23	19	2	24	9	7	25	0	(
600	26	17	6	27	10	0	28	2	6	28	15	0	29	7	6	30	0	-
700	31	7	1	32	1	8	32	16	3	33	10	10	34	5	5	35	0	
900	35	16	8	36	13	0	37 42	10	9	38 43	6	6	39	1	3	45	0	-
1000	44	15	10	45	16	В	46	17	6	47	18	4	48	19	2	50	0	(
2000	89	11	8	91	13	4	93	15	0		16	8	97	18	4	100	0	-
3000	134	7	6	137	10	0	140		6	143		0		17	6	150	0	
4000	179	3	4	183	6	8	187		0		13	4	195	16	8	200	0	(
5000	223		2	229	3	4	234		6	239		8	244	15	10	250 300	0	i
7000 7000	268	15	0	275 320	16	8	281 328	5 2	6	287 335	10	4	342	14	2	350	0	à
8000	313 358	10	10	366		4	375	0	0	383	6	8	391	13	4	400	0	ì
9000	403		6		10	0	421	17	6	431	5	ő	440		6	450	0	

NUMBERS.
AND
WEIGHTS
COMMON
5
PRICES
ALENT
EQUIV

00	D.	10	9	8	-	9	=	7	0	61	7	0	9	2	ø	8	-	9	=	4	0	œ	1	.0	2	10	ø	œ	-1	٥Ξ.
per 1000.	S.	0	=	-	2	C	120	80	133	4	=	2	2	10	91	9	17	-	17	•	18	6	19	10	0	10	-	=		
pe	L.	-	-	64	01	8	00	7	4	2	43	9	9	1	1	80	00	6	0	10	2	=	=	120	13 0	13	74	7	12	100
gross or 144,	D.	0	9	0	9	0	9	0	9	0	9	0	9	0	0		9	0	9	0	9	0	9	0	9	0	9	0	9	00
11.1	ò	8	7	9	4		0	6	13	15	9	8	61	-	æ	4	10	1	œ	0	=	3	*	9	1	6	0	CR	8	00
a. 5	L,	0	0	0	0	0	0	0	0	0	0	0	0	-	-	-	-	-	-	=	-	-	Ξ	=	=	Ξ	OR.	QQ.	o	01 01
50.	D.	9	0	0	60	9	0	. 0	07	9	6	0	60	9	6	0	60	9	6	0	8	9	6	0	8	9	0	0	60	00
per 120.	S	04	o	10	9	1	00	0	=	67	2	12	91	17	8	0	-	01	00	10	9	1	80	01	=	9	67	2	9	20
be	ï	•	0	0		•	0	•	•	0	0	0	•	0	•	-	-	-	+	-	-	-	-	-	-	-	7	-	-	
	D.	_	14		45	. 00	18		44		55	9	79	1	42	8	88	6	16	. 0	70	_	14		90		14		45	8 8
per 100.	S.	03	8	*	10	9	1	. 00	6	0	_	63	0		9				19					2	9		00	6		- 01
per	T.	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	-	-	-	-	-	_	-	-	-	=	
	D.		-60		-		-		+		+		-57		-0	3	:19		-60		+		-19		-10		+		-	0 4
score or 20.	17.4	9	-	10	-				10	-	00	9	8	Ξ	_	-		6	-	្ន	Ι	-	-	0	01		-	100		04
. 0	S.		_	_			_		_			_	_		_	_	_	_	_	_	_	_	_	_	_	-	_	_	_	_
. 6	D.	80	45	9	73		103	0	14	3	44	9	74	6	104	•	13	8	43	9	7	6	104	0	13	'n	49	9	74	001
doz. or 12.	S.	0	0	0	0	0	0	-	-	-	-	-	~	-	-	00	C4	C4	64	cl	¢4	C4	01	80	60	60	en	en	60	80 60
:						_								_		2							-	7					-	
ē 5	D.	-	***					17	=	-	1	1	1	1	-	20	04	GIÝ.	67	01	23	64	22	36	3	8	65	ñ	3	00 00
bs.	D.	38	54	1	83	90	10		33	55	74	6	50	60	お	+	53	74	16		200	77	갷	9	74	96	11		200	73
stone or 14 fbs.	s.	0	0		0	0	_	_	-	-	-	-	=	61	09	04	09	09	67	- C	60	8	89	8	8	00	8	4	4	++
-	D.		-6	2	+0		-		-h		-		-0		+		-17	-	7		-10		-19		4		49	-	+	00
qr. 28 lbs.	8. 1	-	10	-		-	~	-	-	1	-	_	5		_	_	Ξ		5	3 16	_	-			6	-	ĭ		8	**
or 2	L. 8	6								0		0	0	0		0							•							00
			=	2	-			-		-		_	-	-		Ē	-	-	_		_		3		Ē		Ē	Ť	÷	_
2 Ib	. D.	4	9	8	10	0	64	7	9	00	2	0	9	4		30	10	0	-	-	9	30	2	0	01	7	9		7	96
cwt. or 112 lbs.	L. S.	24	6	7	20	-	.00	0	10	Ξ	12	14	115	16	117	118	1 19		-	-	4	-0	9	8	9	10	=	12	13	11
_	-	9	-	9	-	-	-	-	9	9	9	-	9	-	-	-	_	_	_	-	_	_	_	_	_	_	_	_	_	
Per ton or 2240 lbs.	D.	8	0	4	8	0	4	œ	0	4	00	0	4	80	0	4	8	0	*	00	0	*	8	0	4	8	0	*	8	04
Per ton	Š	9	10	13	16	0	00	9	10		16																			98
P. P.	L.	ca	9	4	40	1	00	0	10	=	12	14	15	16	17	18	19	2	22	83	2	200	36	28	50	30	3	욁	8	38

										_	_		_						_					
9870		•• ••	6	• 01	• •	œ	9	4	7 C		60 •	0 4	•	0	2	*	*	•	•	2	9	9 4		۰
8747																								
2288																								
		~ ~			~		_		., .		-			<u>~</u>			_	_	_	_	_	_	_	-1
		•	•	•	•	•	•	•		•	•	•	•	•	•		•	•	•	•			•	•
0222																							-	٠l
9999																								
								_			_			_		_	_	_	_	_	_			- 1
8600	8	00	9	9	0 4	•	9	•	0 0	0	•	0	•	0	0	90	•	9	0	•	•	0	•	이
- 99 50 4	.00	82	2 :	2 :	0 0	1 10	~	2	2 5	1	•	7 49	~	2	!	22	.0	69	0	~	2 :	2 2	2	이
		or ós	64 0	• 64	00 0	9	9	9	~	9	4.	• •	•	•	4.	4 4							-	
																							_	-
\$ 2°	3 ~	₹.	95	=	• -	• 64	9	4	9	~	00 (25	=	0	- 0	N 07	4	•	•	-	30 0	20	=	이
1222	22	-	80 ×	~	22	7	9	8	9	4	•	» <u>e</u>	2	2	25	2-	9	•	^	9	= :	2 2	4	•
~~~		07 O7	<b>0</b> 1 0	9	<b>01</b> 0	9	64	•	20 00	10	<b>9</b> 3 (	n 01	•	9	00 0	9	4	•	•	4	4	• •	•	6
								-		_			_			-	_		_		_			-
ž~ <b>ã</b> °	*35"	7,	<b>a</b> ø	~	0 4	9	<b>03</b> (	<b>.</b>	- <b>1</b>	=	4 (	<b>3</b> 91	^	•	9	9 00	00	-	0	= '	•	<b>&gt;</b> e4	~	•
9~~~		<b>00</b> 00	•		9 9	2	=:	= 9	3 9	2	<u> </u>	3 4	Ī	20	9	9	9	2	_	_		9	9	2
													_				_	_			٠.			٦,
2,40	20	_ሚ					_			_													_	_
		==	<b>∞</b> €		-	•	9	91	u d	•	0 0	9 00	0	•	<b>10</b> (	9	0	9	0	0	9 6	90	0	91
4444	44	4 0 2 0																						
1111	44	7.0		100																				
1111	44	7 10	••		-		9	~1		~	œ ¢	0 00	80	6	0	<b>3</b> 0	10	2	2	<u>2</u> :	3 3	==	= 9	2
***	44	7 10	••		-		9	~1		~	œ ¢	0 00	80	6	0	<b>3</b> 0	10	2	2	<u>2</u> :	3 3	==	= 9	2
***	193	54.	20 20	101	94.	9	62	74.	74	inter it.	84.	98	80	94.	66	0	104.	104	104	104	114.	111	in gri	126. 11 12
1111	193	54.	20 20	101	94.	9	62	74.	74	inter it.	84.	98	80	94.	66	0	104.	104	104	104	114.	111	in gri	126. 11 12
***	193	54.	20 20	101	94.	9	62	7.4.	74 74	09 74 O	86.	11 84 8	25 SS	9 gd.	56	7	8 10d. 10	104 10	104	104	114.	5 114	in gri	0 126. 11 12
4400 2510 2510 2410 2410 4444	64 64 44	5 84 44 4 6 10 5d. 5	6 14 54 54 54 54 54 54 54 54 54 54 54 54 54	9 9 9	7 0 64.	7 7 64 6	7 104 65	74.	24 74 74 74 74 74 74 74 74	\$2 FO	84.8	98 11 0	10 24 SA	10 6 94.	10 95	11 46 93	11 8 104. 10	11 114 104 10	18 3 104 10	12 04 104	12 10 114. 11	13 6 114 11	118 84 112	14 0 12d. H 12
4400 2510 2510 2410 2410 4444	64 64 44	5 84 44 4 6 10 5d. 5	6 14 54 54 54 54 54 54 54 54 54 54 54 54 54	9 9 9	7 0 64.	7 7 64 6	7 104 65	74.	24 74 74 74 74 74 74 74 74	\$2 FO	84.8	98 11 0	10 24 SA	10 6 94.	10 95	11 46 93	11 8 104. 10	11 114 104 10	18 3 104 10	12 04 104	12 10 114. 11	13 6 114 11	118 84 112	14 0 12d. H 12
***	44	8 5 10 5d. 5	20 00 14 04 04 04 04 04 04 04 04 04 04 04 04 04	200	7000	9 7 7 64 6	9 7 104 64 6	74.	11 24 74 7 8 9 74 74 7	0 of 75	8 4 8d.	10 0 11 84 8	5 10 24 83 8	0 10 6 94.	7 10 95 94 9	0 11 45 95	4 11 8 104. 10	11 11 114 104 10	12 3 104 10	1 12 04 105 10	8 12 10 114. 11	10 13 5 115 11	11 84 112	0 14 0 13d.   13
2.1 %c	44	8 5 10 5d. 5	20 00 14 04 04 04 04 04 04 04 04 04 04 04 04 04	200	7000	9 7 7 64 6	9 7 104 64 6	74.	11 24 74 7 8 9 74 74 7	0 of 75	8 4 8d.	10 0 11 84 8	5 10 24 83 8	0 10 6 94.	7 10 95 94 9	0 11 45 95	4 11 8 104. 10	11 11 114 104 10	12 3 104 10	1 12 04 105 10	8 12 10 114. 11	10 13 5 115 11	11 84 112	0 14 0 13d.   13
0 0 74 4 99 4 6 10 0 0 0 10 0 0 0 10 0 0 0 10 0 0 0 10 0 0 0 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	010 1110 2011 100 100 100 100 100 100 10	011 44 5 84 44 4	0 19 30 60 14 54 54	0 13 5 6 84 55	0 14 0 7 0 64.	0 15 9 7 7 64 6	0 15 9 7 104 64 6	0 10 4 8 2 74. 7	0 17 6 8 9 74 7	7 5 50 0 1 81 0	0 18 8 4 84. 8	0 10 10 0 11 85 85	1 0 5 10 24 84 8	1 1 0 10 6 94. 9	1 1 7 10 95 94 9	2 0 11 46 95	1 3 4 11 8 104. 10	1 3 11 11 114 104 10	12 3 104 10	1 12 04 105 10	8 12 10 114. 11	10 13 5 115 11	11 84 112	0 14 0 13d.   13
6 0 0 74 4 99 4 4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	2 0 10 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6 0 11 44 5 84 47 4 8 0 11 8 6 10 5d. 5	4 0 19 10 0 14 54 54 5	8 0 13 5 6 84 55	4 0 14 7 7 84 64 6	8 0 15 9 7 7 64 6	0 0 15 9 7 104 64 6	74. 74. 74. 74. 74. 74. 74. 74. 74. 74.	0 0 17 6 8 9 74 7	4 0 18 1 9 04 75 7	8 0 18 8 4 84. 8	4 0 19 10 0 11 85 85	8 1 0 5 10 24 83 8	9 1 1 0 10 6 94. 9	4 1 1 7 10 94 94 9	1 2 2 1 4 9 9	4 1 3 4 11 8 10d. 10	8 1 3 11 11 114 104 10	0 1 4 0 12 3 10 10	4 1 5 1 12 04 104 10	8 1 5 6 12 10 114. 11	4 1 6 10 13 5 114 11	8 1 7 5 13 84 114 11	0 1 8 0 14 0 12d.   12
19 6 0 0 74 4 99 4 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	4 4 0 10 94 5 42 42 4	6 6 0 11 4 5 8 4 4 6 6 8 6 8 6 6 6 6 6 6 6 6 6 6 6 6	11 4 0 19 3 6 14 54 54 5	13 8 0 13 5 6 84 52	16 0 0 14 0 7 0 0d. 6	0 8 0 15 9 7 7 64 6	8 0 0 15 9 7 10t 6t 6	5 4 0 10 4 8 2 74 7	10 0 0 17 6 8 G 74 7	12 4 0 18 1 9 04 74 7	14 8 0 18 8 9 4 84. 8	10 4 0 10 10 0 11 85 8	1 8 1 0 5 10 24 83 8	4 0 1 1 0 10 6 94. 9	4 1 1 7 10 94 94 9	1 2 2 1 4 9 9	4 1 3 4 11 8 10d. 10	8 1 3 11 11 114 104 10	0 1 4 0 12 3 10 10	4 1 5 1 12 04 104 10	8 1 5 6 12 10 114. 11	4 1 6 10 13 5 114 11	8 1 7 5 13 84 114 11	0 1 8 0 14 0 12d.   12
19 6 0 0 74 4 99 4 4 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2 0 10 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	6 6 0 11 4 5 8 4 4 6 6 8 6 8 6 6 6 6 6 6 6 6 6 6 6 6	11 4 0 19 3 6 14 54 54 5	13 8 0 13 5 6 84 52	16 0 0 14 0 7 0 0d. 6	0 8 0 15 9 7 7 64 6	8 0 0 15 9 7 10t 6t 6	5 4 0 10 4 8 2 74 7	10 0 0 17 6 8 G 74 7	12 4 0 18 1 9 04 74 7	14 8 0 18 8 9 4 84. 8	10 4 0 10 10 0 11 85 8	1 8 1 0 5 10 24 83 8	4 0 1 1 0 10 6 94. 9	4 1 1 7 10 94 94 9	1 2 2 1 4 9 9	4 1 3 4 11 8 10d. 10	15 8 1 3 11 11 114 104 10	18 0 1 4 0 12 3 104 10	0 4 1 5 1 12 04 104 10	2 8 1 5 8 12 10 114. 11	7 4 1 6 10 13 5 114 11	8 1 7 5 13 84 114 11	12 0 1 8 0 14 0 12d.    12
1 198 6 0 0 74 4 99 4 4 4 119 4 4 4 4 4 4 4 4 4 4 4 4	2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	2 6 8 0 11 4 5 8 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	2 6 0 6 12 8 6 14 54 54 54 55 54 55 54 55 54 55 54 55 55	2 13 8 0 13 5 6 84 52	2 16 0 0 14 0 7 0 64 6	3 0 8 0 15 8 7 7 64 6	3 3 0 0 15 9 7 104 64 6	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3 10 0 0 17 6 8 9 74 7	S 12 4 0 18 1 0 04 75 7	3 14 8 0 18 8 4 84	3 19 4 0 19 10 6 11 85 8	4 1 8 1 0 5 10 24 82 8	4 0 1 1 0 10 6 94. 9	4 1 1 7 10 94 94 9	1 2 2 1 4 9 9	4 1 3 4 11 8 10d. 10	15 8 1 3 11 11 114 104 10	18 0 1 4 0 12 3 104 10	0 4 1 5 1 12 04 104 10	2 8 1 5 8 12 10 114. 11	7 4 1 6 10 13 5 114 11	9 8 11 7 8 18 84 113 11	12 0 1 8 0 14 0 12d.    12
1 138 d 0 D 74 4 99 4 4 99 4 4 4 4 4 4 4 4 4 4 4 4	2	4 2 6 8 0 11 8 6 10 54. 5	0 2 6 0 6 12 3 6 14 54 54 55	4 2 13 8 0 13 5 0 84 55	0 2 16 0 0 14 0 7 0 04 0	4 3 0 8 0 15 9 7 7 64 6	0 3 3 0 0 15 9 7 104 64 6	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	6 8 7 8 6 10 11 6 5 7 4 7 6 8 10 7 4 7	8 8 12 4 0 18 1 9 04 75 7	4 3 14 8 0 18 8 9 4 8d. 8	8 8 19 4 0 19 10 6 11 85 8	4 4 1 8 1 0 5 10 24 82 8	0 4 4 9 1 1 0 10 6 94. 9	8 4 0 4 1 1 7 10 94 94 9	0 411 0 1 2 0 11 48 93 9	8 4 13 4 1 8 4 . 11 8 104. 10	4 4 15 8 1 3 11 11 11 10 10 10	0 4 18 0 1 4 0 12 3 10	8 5 0 4 1 5 1 12 04 104 10	4 6 2 8 1 5 8 12 10 116. 11	6 5 7 4 1 6 10 13 5 114 11	4 5 9 8 1 7 5 13 84 114 11	0 5 12 0 1 8 0 14 0 13d.    12
130 0 110 0 0 0 74 4 95 4 10 110 0 0 11 110 0 110 110 0 110 110	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	10 0 2 5 6 0 11 4 5 8 4 4 6 4 13 4 8 6 10 5 6 6 6		13 4 2 13 8 0 13 5 6 8 5 5	6 0 2 16 0 0 14 0 7 0 04 64 64 64 64 64 64 64 64 64 64 64 64 64	18 4   3 0 8   0 15 9   7 7 64   6	0 0 8 8 0 0 15 9 7 104 64 6	7 7 7 8 8 8 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13 4 3 7 8 6 10 11 6 5 7 7 7	6 8 3 12 4 0 18 1 9 04 74 7	13 4 3 14 8 0 18 8 9 9 4 84.	6 8 3 19 4 0 19 10 19 11 85 8	13 4 4 1 8 1 0 5 10 24 84 8	0 0 4 4 0 1 1 0 10 6 94 9	0 8 4 0 4 1 1 7 10 95 95 9	0 4 11 0 1 2 0 11 4 93 9	6 8 4 13 4 1 8 4 . 11 8 104. 10	18 4 4 15 8 1 8 11 11 114 104 10	0 4 18 0 1 4 0 12 3 10	0 8 5 0 4 1 5 1 12 04 104 10	13 4 6 2 8 1 5 8 12 10 114, 11	6 6 5 7 4 1 6 10 13 5 115 11	13 4 5 9 8 1 7 5 13 84 112 11	0 5 12 0 1 6 0 14 0 12d.   12
1 138 d 0 D 74 4 99 4 4 99 4 4 4 4 4 4 4 4 4 4 4 4	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	10 0 2 5 6 0 11 4 5 8 4 4 6 4 13 4 8 6 10 5 6 6 6		13 4 2 13 8 0 13 5 6 8 5 5	6 0 2 16 0 0 14 0 7 0 04 64 64 64 64 64 64 64 64 64 64 64 64 64	18 4   3 0 8   0 15 9   7 7 64   6	0 0 8 8 0 0 15 9 7 104 64 6	7 7 7 8 8 8 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13 4 3 7 8 6 10 11 6 5 7 7 7	6 8 3 12 4 0 18 1 9 04 74 7	13 4 3 14 8 0 18 8 9 9 4 84.	6 8 3 19 4 0 19 10 19 11 85 8	13 4 4 1 8 1 0 5 10 24 84 8	0 0 4 4 0 1 1 0 10 6 94 9	0 8 4 0 4 1 1 7 10 95 95 9	0 4 11 0 1 2 0 11 4 93 9	6 8 4 13 4 1 8 4 . 11 8 104. 10	18 4 4 15 8 1 8 11 11 114 104 10	0 4 18 0 1 4 0 12 3 10	0 8 5 0 4 1 5 1 12 04 104 10	13 4 6 2 8 1 5 8 12 10 114, 11	6 6 5 7 4 1 6 10 13 5 115 11	13 4 5 9 8 1 7 5 13 84 112 11	0 5 12 0 1 6 0 14 0 12d.   12

# Practical Utility of the preceding Table

1. What will be the cost of 1 ton 2 cwts. 3 qr at 74 per ib.

```
1 ton = 2240 ibs.

2 cwts. = 224 ,...

3 qrs. = 84 ,...

4 ibs. = \frac{4}{2552} ,...

And 2000 at 7\frac{2}{3}d. (as per Table, p. 131) = £64 11

500 ,... = 16 2

50 ,... = 1 12

2 ,... = 0 1

£82 8
```

2. In the Table of Equivalent Prices, the flumn from the left hand is the price per single or 1; hence the other columns on the right and that give the price at an equal rate, according various denominations by which the columns are

Thus, suppose the price per fb.  $=3\frac{1}{4}d$ ., the properties  $\pounds 30$ . 6s. 8d. Again, suppose the price per  $\pounds 1.10s$ ., the price per dozen =2s. 6d., &c.

## STRENGTH OF MATERIALS.

MATERIALS of construction are liable to fo ferent kinds of strain; viz., stretching, cri transverse action, and torsion or twisting: tl of which depends upon the body's tenacity the second, on its resistance to compression; the on its tenacity and compression combined; a fourth, on that property by which it oppos acting force tending to change from a straigl to that of a spiral direction, the fibres of whi body is composed.

In bodies, the power of tenacity and resists

compression in the direction of their length, is as the cross section of their area multiplied by the results of experiments on similar bodies, as exhibited in the following Table.

Table showing the Tenacities, Resistances to Compression, and other Properties of the common Materials of Construction.

	Ah	olute	Compare	d with C	est Iron
			Compare	u with C	
Names of Bodies.		Resistance to compres- sion in lbs. per sq. in.		Its exten- sibility is	Its stiffness is
Ash	14130		0.23	2.6	0.089
Beech	12225	8548	0.15	2.1	0.073
Brass	17968	10304	0.435	0.9	0.49
Brick	275	562	l —		_
Cast iron	13434	86397	1.000	1.0	1.000
Copper (wrought) .	33000		<b> </b>		
Elm	9720	1033	0.21	2.9	0.073
Fir, or Pine, white .	12346	2028	0.23	2.4	0.1
,, ,, red .	11800	5375	0.3	2.4	0.1
" " yellow .	11835	5445	0.25	2.9	0.087
Granite, Aberdeen .	<b> </b>	10910	_	_	-
Gun-metal (copper 8,	1	1	ŀ		
and tin 1)	35838	I —	0.65	1.25	0.535
Malleable iron	56000	_	1.12	0.86	1.3
Larch	12240	5568	0.136	2.3	0.058
Lead	1824	_	0.096	2.5	0.0385
Mahogany, Honduras	11475	8000	0.24	2.9	0.487
Marble	551	6060	_	<b> </b>	l —
Oak	11880	9504	0.25	2.8	0.093
Rope (1 in. in circum.)	200		-		_
Steel	128000	<u> </u>	l —	l —	_
Stone, Bath	478			l —	_
" Craigleith .	772	5490	=	_	_
" Dundee	2661	6630			
, Portland .	857	3729	-	-	—
Tin (cast)	4736		0.182	0.75	0.25
Zinc (sheet)	9120	-	0.365	0.5	0.76

# Comparative Strength and Weight of Rope Chains.

Circum, of rope in inches.	Weight per fa- thom in ibs.	Diameter of chain in inches.	Weight per fathom in the.	stre	Proof ngth in & cwt.	Circum, of rope in inches.	Weight per fa- thom in lbs.	Diameter of chain in inches.	Weight per fa- thom in fls.	2 2
31	24	5 18 3 8	51	1	51	10	23	7 8 15 16	43	Ī
41	43	8	8	1	164	103	28	15	49	1
5	53	रेंड	101	3	10	111	301	1 in.		ŀ
5 54	7	1	14	3	51	121	36	116	63	Г
61	92	18	18	4	31	13	39	11	71	ı
7	111	7 16 10 9 16 5	22	5	2	133	45	13	79	Г
8	15	11	27	6	41	141	481	11	87	1
83	19	4	32	7	7	151	56	1.5	96	1
94	21	18	37	8	131	16	60	$\frac{1\frac{5}{16}}{1\frac{3}{8}}$	106	1

Note.—It must be understood and also borne in m in estimating the amount of tensile strain to which subjected, the weight of the body itself must also be to account; for according to its position so may it approits whole weight, in tending to produce tension with as in the almost constant application of ropes and a great depths, considerable heights, &c.

## Alloys that are of greater Tenacity than the their Constituents, as determined by the ments of Muschenbroek.

```
Swedish copper 6 parts, Malacca tin 1; tenacity per square inch
Chili copper 6 parts, Malacca tin 1;
Japan copper 5 parts, Banca tin 1;
                                                ,,
                                                                 ,,
Anglesea copper 6 parts, Cornish tin 1;
Common block tin 4, lead 1, zinc 1;
                                               ••
                                                                 ,,
                                                ,,
Malacca tin 4, regulus of antimony 1;
                                                ,,
                                                                 ,,
Block tin 3, lead 1;
                                                                 ,,
Block tin 8, zinc 1;
Lead 1, zinc 1;
```

#### RESISTANCE TO LATERAL PRESSURE, OR TRANS-VERSE ACTION.

The strength of a square or rectangular beam to resist lateral pressure acting in a perpendicular direction to its length, is as the breadth and square of the depth, and inversely as the length;—thus, a beam twice the breadth of another, all other circumstances being alike, equal twice the strength of the other; or twice the depth, equal four times the strength, and twice the length, equal only half the strength, &c., according to the rule.

Table of Data, containing the Results of Experiments on the Elasticity and Strength of various Species of Timber, by Mr. Barlow.

Species of Timber.	Value of E.	Value of S.	Species of Timber.	Value of E.	Value of S.
Teak Poona English oak . Canadian do. Dantzic do. Adriatic do. Ash Beech	122·26 105	2462 2221 1672 1766 1457 1383 2026 1556	Elm Pitch pine	158·5 90	1632 1341 1102 1100 1200 900

To find the dimensions of a beam capable of sustaining a given weight, with a given degree of defection, when supported at both ends.

Rule.—Multiply the weight to be supported in ibs. by the cube of the length in feet; divide the product by 32 times the tabular value of E, multiplied into the given deflection in inches, and the

quotient is the breadth multiplied by the cube of the depth in inches.

Note 1.—When the beam is intended to be square, then the fourth root of the quotient is the breadth and depth required.

Note 2.—If the beam is to be cylindrical, multiply the quotient by 1.7, and the fourth root of the product is the diameter.

Ex. The distance between the supports of a beam of Riga fir is 16 feet, and the weight it must be capable of sustaining in the middle of its length is 8000 lbs., with a deflection of not more than 3 of an inch: what must be the depth of the beam, supposing the breadth 8 inches?

 $\frac{10 \times 3000}{90 \times 32 \times 75} = 15175 + 8 = \sqrt[3]{1897} = 12.35$  inches the depth.  $16 \times 8000$ 

To determine the absolute strength of a rectangular beam of timber when supported at both ends, and loaded in the middle of its length, as beams in general ought to be calculated to, so that they may be rendered capable of withstanding all accidental cases of emergency.

Rule.—Multiply the tabular value of s by four times the depth of the beam in inches, and by the area of the cross section in inches; divide the product by the distance between the supports in inches, and the quotient will be the absolute strength of the

beam in ths.

Note 1.—If the beam be not laid horizontally, the distance between the supports, for calculation, must be the horizontal distance.

Note 2.—One-fourth of the weight obtained by the rule is the greatest weight that ought to be applied in practice as permanent load.

Note 3.—If the load is to be applied at any other point than the middle, then the strength will be, as the product of the two distances is to the square of half the length of the beam between the supports;—or, twice the distance from one end, multiplied by twice from the other, and divided by the whole length, equal the effective length of the beam.

Ex. In a building 18 feet in width, an engine boiler of  $5\frac{1}{4}$  tons is to be fixed, the centre of which to be 7 feet from the wall; and having two pieces of red pine 10 inches by 6, which I can lay across the two walls for the purpose of slinging it at each end,—may I with sufficient confidence apply them, so as to effect this object?

$$\frac{2240 \times 5.5}{2} = 6160 \text{ ibs. to carry at each end.}$$

And 18 feet -7 = 11, double each, or 14 and 22, then  $\frac{14 \times 22}{18} = 17$  feet, or 204 inches, effective length of beam.

Tabular value of s, red pine =  $\frac{1341 \times 4 \times 10 \times 60}{204}$  = 15776 ibs., the absolute strength of each piece of timber at that point.

To determine the dimensions of a rectangular beam capable of supporting a required weight, with a given degree of deflection, when fixed at one end.

Rule.—Divide the weight to be supported, in ibs., by the tabular value of E, multiplied by the breadth and deflection, both in inches; and the cube root of the quotient, multiplied by the length in feet, equal the depth required in inches.

Ex. A beam of ash is intended to bear a load of 700 lbs. at its extremity; its length being 5 feet, its breadth 4 inches, and the deflection not to exceed  $\frac{1}{2}$  an inch.

Tabular value of  $E = 119 \times 4 \times 5 = 238$ , the divisor; then  $700 + 238 = \sqrt[3]{2\cdot 94} \times 5 = 7\cdot 25$  inches, depth of the beam.

To find the absolute strength of a rectangular

beam, when fixed at one end, and loaded at the other.

Rule.—Multiply the value of s by the depth of the beam, and by the area of its section, both in inches; divide the product by the leverage in inches, and the quotient equal the absolute strength of the beam in ths.

Ex. A beam of Riga fir, 12 inches by  $4\frac{1}{2}$ , and projecting  $6\frac{1}{2}$  feet from the wall; what is the greatest weight it will support at the extremity of its length?

Tabular value of s = 1100  $12 \times 4.5 = 54$  sectional area, Then,  $\frac{1100 \times 12 \times 54}{78} = 9138.4$  ibs.

When fracture of a beam is produced by vertical pressure, the fibres of the lower section of fracture are separated by extension, whilst at the same time those of the upper portion are destroyed by compression; hence exists a point in section where neither the one nor the other takes place, and which is distinguished as the point of neutral axis. Therefore, by the law of fracture thus established, and proper data of tenacity and compression given, as in the Table (p. 137), we are enabled to form metal beams of strongest section with the least possible material: thus, in cast iron the resistance to compression is nearly as  $6\frac{1}{2}$  to 1 of tenacity; consequently a beam of cast iron to be of strongest section must be of the following form,

and a parabola in the direction of its length, the quantity of material in the bottom flange being about 6½ times that of the upper: but such is not the case with beams of timber; for although the tenacity of timber be on an average twice that of its resistance to compression, its flexibility is so great, that any con-

siderable length of beam, where columns cannot be situated to its support, requires to be strengthened or trussed by iron rods, as in the following manner:



And these applications of principle not only tend to diminish deflection, but the required purpose is also more effectively attained, and that by lighter pieces of timber.

To ascertain the absolute strength of a cast-iron beam of the preceding form, or that of strongest section.

Rule.—Multiply the sectional area of the bottom flange in inches by the depth of the beam in inches, and divide the product by the distance between the supports also in inches; and 514 times the quotient equal the absolute strength of the beam in cwts.

The strongest form in which any given quantity of matter can be disposed is that of a hollow cylinder; and it has been demonstrated that the maximum of strength is obtained in cast iron when the thickness of the annulus or ring amounts to ½th of the cylinder's external diameter; the relative strength of a solid to that of a hollow cylinder being as the diameters of their sections.

A Table showing the Weight or Pressure a Beam of 1 inch in breadth, will sustain without destroying force, when it is supported at each end, and loa middle of its length, and also the deflection in the muthat weight will produce. By Mr. Hodgkinson, M.

Length.	6 fee	rt.	7 feet.		8 feet.		9 feet.	
Depth in in.	Wt. in lbs.	Defl. in in.	Wt. in fbs.	Defl. in in.	Wt. in	Defl. in in.	Wt. in lbs.	Defl. in in.
3	1278	•24	1089	.33	954	.426	855	.54
31	1739	.205	1482	.28	1298	.365		.46
4	2272	·18	1936	245	1700	.32	1520	.405
41	2875	.16	2450	.217		.284	1924	•36
5	3560	·144	3050	196	2650	256	2375	•32
6	5112	·12	4356	.163	3816	.213	3420	.27
7	6958	·103	5929	·14	5194	.183	4655	•23
8	9088	.09	7744	·123	6784	.16	6080	.203
9	_	_	9801	·109	8586	.142	7695	•18
10		_	12100	.098	10600	·128	9500	·162
11		_		_	12826	·117	11495	·15
12		_	-	_	15264	·107	13680	·135
13		_		-	-	-	16100	·125
14	_	<b>—</b>	-	l —_	-		18600	·115
	12 feet. 14 fe		et. 16 fee		et. 18 feet.		et.	
6	2548	•48	2184	•65	1912	-85	1699	1.08
7	3471	.41	2975	.58	2603	•73	2314	-93
8	4532	.36	3884	.49	3396	•64	3020	.81
9	5733	.32	4914	•44	4302	.57	3825	.72
10	7083	.28	6071	.39	5312	•51	4722	·64
11	8570	.26	7346	∙36	6428	•47	5714	•59
12	10192	.24	8736	.33	7648	•43	6796	.54
13	11971	.22	10260	·31	8978	∙39	7980	•49
14	13883	.21	11900	.28	10412	.36	9255	•46
15	15937	·19	13660	•26	11952	•34	10624	•43
16	18128	•18	15536	•24	13584	•32	12080	•40
17	20500	.17	17500	.23	15353	•3	13647	.38
18	22932	.16	19656	•21	17208	28	15700	.36

Note.—This Table shows the greatest weight that ever oug upon a beam for permanent load, and if there be any liability! ample allowance must be made; also the weight of the bear be included.

To find the weight of a cast-iron beam of given dimensions.

Rule.—Multiply the sectional area in inches by the length in feet, and by 3.2, the product equal the weight in ths.

 $\vec{E}x$ . Required the weight of a uniform rectangular beam of cast iron, 16 feet in length, 11 inches in breadth, and 14 inch in thickness.

 $11 \times 1.5 \times 16 \times 3.2 = 844.8$  fbs.

# Resistance of Bodies to Flexure by vertical Pressure.

When a piece of timber is employed as a column or support, its tendency to yielding by compression is different according to the proportion between its length and area of its cross section; and supposing the form that of a cylinder whose length is less than seven or eight times its diameter, it is impossible to bend it by any force applied longitudinally, as it will be destroyed by splitting before that bending can take place; but when the length exceeds this, the column will bend under a certain load, and be ultimately destroyed by a similar kind of action to that which has place in the transverse strain.

Columns of cast iron and of other bodies are also similarly circumstanced, this law having been fully developed by the experiments of Mr. Hodgkinson on columns of different diameters, and of different lengths.

When the length of a cast-iron column with flat ends equals about thirty times its diameter, fracture will be produced wholly by bending of the material; —when of less length, fracture takes place partly by crushing and partly by bending: but, when the column is enlarged in the middle of its length from one and a half to twice its diameter at the ends, by being

cast hollow, the strength is greater by 1th than in a solid column containing the same quantity of material.

To determine the dimensions of a support or column to bear without sensible curvature a given pressure in the direction of its axis.

Rule.—Multiply the pressure to be supported in its. by the square of the column's length in feet, and divide the product by twenty times the tabular value of E; and the quotient will be equal to the breadth multiplied by the cube of the least thickness, both being expressed in inches.

Note 1.—When the pillar or support is a square, its side will be the fourth root of the quotient.

- 2. If the pillar or column be a cylinder, multiply the tabular value of E by 12, and the fourth root of the quotient equal the diameter.
- Ex. 1. What should be the least dimensions of an oak support, to bear a weight of 2240 lbs. without sensible flexure, its breadth being 3 inches, and its length 5 feet?

Tabular value of E = 105,

and 
$$\frac{2240 \times 5^2}{20 \times 105 \times 3} = \sqrt[3]{8.888} = 2.05$$
 inches.

Ex. 2. Required the side of a square piece of Riga fir, 9 feet in length, to bear a permanent weight of 6000 lbs.

Tabular value of E = 96,

and 
$$\frac{6000 \times 9^2}{20 \times 96} = 4\sqrt{253} = 4$$
 inches nearly.

Dimensions of Cylindrical Columns of Cast Iron to sustain a given load or

Practical Utility of the preceding Table.

Ex. Wanting to support the front of a building with cast-iron columns 18 ft. in length, 8 inches in diameter, and the metal 1 inch in thickness; what weight may

I confidently expect each column capable of supporting without tendency to deflection?

Opposite 8 inches diameter and under 18 feet = 1097 Also opposite 6 in. diameter and under 18 feet = 440

= 657 cwts.

**- ∙0785** 

Note.—The strength of cast iron as a column being 1.0000 steel wrought iron (oak) Dantzic red deal

Elasticity of torsion, or resistance of bodies to twisting.

The angle of flexure by torsion is as the length and extensibility of the body directly, and inversely as the diameter; hence, the length of a bar or shaft being given, the power, and the leverage the power acts with, being known, and also the number of degrees of torsion that will not affect the action of the machine, to determine the diameter in cast iron with a given angle of flexure.

Rule.—Multiply the power in its. by the length of the shaft in feet, and by the leverage in feet; divide the product by fifty-five times the number of degrees in the angle of torsion; and the fourth root of the quotient equal the shaft's diameter in inches.

Ex. Required the diameters for a series of shafts 35 feet in length, and to transmit a power equal to 1245 lbs., acting at the circumference of a wheel 24 feet radius, so that the twist of the shafts on the application of the power may not exceed one degree.

$$\frac{1245 \times 35 \times 2.5}{55 \times 1} = \sqrt{1981} = 6.67 \text{ inches in diameter.}$$

Relative strength of metals to resist torsion.

Cast iron	=1	Swedish bar iron.	= 1.05
Copper	= .48	English do	= 1.12
Yellow brass	= '511	Sheer steel	= 1.96
Gun-metal .	= .55	Cast do	=2·1

#### SMELTING.*

# GOLD AND SILVER ORES, &C.

In the assay by fusion the object is to produce a metal in its pure form, directly from the ore, and in some instances to produce all the metal of a certain kind which the ore may contain, with a view of comparing the result of the assay with the smelting process on the large scale. To succeed we must deoxidize the ore, and produce at the same time so much heat as to melt the metal; in addition, the foreign matter in the ore must be converted into a fusible scoria, which generally floats as a light glass on the top. Different ores require different modes of operation to produce the metal. Often a variety of the same ore must be subjected to different processes. For the latter reason we convert most ores. which are to be examined, into oxides by roasting. When a specimen is to be assayed we ought to know, at least approximately, its composition, in order to modify the manipulation accordingly. In most instances we recognize the quality by the appearance of the ore; in others, we apply the blow-pipe as an introductory examination. We shall, in order to facilitate the operation, describe the most prominent marks of the ores which may come under examina-

^{*} Overman's 'Treatise on Metallurgy,' 8vo.

tion, and the class to which they belong. If an assay is ineffectual at first, it is repeated with proper modifications until a satisfactory result is obtained. There is not much difficulty in this, as it chiefly requires the production of a suitable slag.

Gold.—An assay of gold ore is not difficult. we expect gold in a specimen, we pulverize it finely; then pass it through a fine sieve, and wash the powder in an iron pan, or a blackened pan of any kind

of material. The annexed figure represents the manner in which the operation is performed. pan is held in one hand firmly, and some water poured upon the ore; the other hand is now used for shaking the pan in a gentle but rapid manner. The powdered ore being thus gathered to one side, the heavy grains of gold

descend through the sand to the bottom of the pe and settle in the corner. After shaking the pan few minutes, it is to be moved so as to produce gentle current in casting off the water. carry with it some of the sand, and diminish quantity in the pan. In repeating this process v fresh water, another portion of sand is removed f the sample; and if the shaking and removal of is continued, the latter may be washed off ent or nearly so. The principle involved is, tha debris of rock is lighter than the gold; the will therefore sink to the bottom, and the f pass off, by moving the water gently on the of the pulverized ore, which is always retained same place, in a corner of the pan. When the is thus nearly washed away, a little water is

in the pan, moved around by inclining the pan, so that the water flows always into its corner or lowest part. This gentle current will move the debris of rock to another part of the pan and expose the metal to view. When this operation is performed on crushed rock, or on alluvial soil, it is in all cases necessary to pulverize the mineral that no particle of metal may escape detection. In this manner we cannot make a quantitative assay; for, with the greatest attention, we lose half of the metal. Gold is very fine when its ore has been crushed, and it is carried away by the water in washing off the rocky matter. In most cases we detect the gold in its metallic state. When an ore is thus treated, and we do not find it in the residue-which may happen in silver ores, in the tellurets, and sulphurets, and arseniurets—we crush the ore, as before, mix it with the fluxes, and smelt it.

Gold ores are not often so rich in metal that a small quantity smelted would furnish a safe estimate of the average contents of a mine. It is therefore necessary to assay at least 500 or 1000 grains at once, and repeat this operation on various parts of the vein. If the ore is a ferruginous slate, or quartz, it is intimately mixed with half its weight of pure litharge, half its weight of borax-glass, and one part of carbonate of potash: these ingredients must be well dried and the whole then finely pulverized. This mixture receives an addition of sufficient carbon to precipitate a certain quantity of lead in the metallic state; and as one part of charcoal produces 30 parts of metal, we add accordingly. From 1000 grains of ore, 100 grains of lead may be produced, which will contain all the gold present; and in order to obtain these, we add 4 grains of fine charcoal and

mix it intimately with the ore and flux. Here is more carbon than is required, but we must consider that a little carbon is always lost in the operation. This mixture is put into a Hessian crucible, which should not be more than half filled; for the mass, when heated, will boil and overflow the brim of the pot. Instead of carbon, black flux might be used; but as we do not know the amount of carbon in that flux exactly, we are exposed, in using it, to the producing of too much or too little lead. Over the test in the crucible a little common salt. a stratum of about a quarter or half of an inch thick, is laid. which will prevent the evaporation of carbon and accelerate the solution of metallic substances in the ore. The use of a graphite, or black-lead crucible, is inadmissible in this case: for its carbon would precipitate more lead than is needed, and cause it to be impure. The crucible and contents are now placed in the furnace, covered by a slab to prevent the falling in of coal, and surrounded with coal so as to cover the crucible; fire is then applied at the top by adding hot charcoal. The fire thus kindled will heat the crucible from the top downwards, which protects the pot and prevents its fracture. In half an hour the fire should be drawn to the grate-bars, and fresh coal added, sufficient for at least three-quarters of an hour; the furnace is then covered, the grate cleaned, and a vigorous heat applied. In half an hour the furnace-cover is partly removed, the cover of the crucible lifted, and the contents examined. mass is fluid but still boiling, that is, throwing up gas-bubbles, the pot is covered again; and when there is a deficiency of coal to last the heat out. fresh supply is added to complete the assay. When coke or anthracite is used, we need not add fresh

fuel to a once charged furnace; the use of charcoal, however, makes this invariably necessary. As the addition of fresh fuel delays the operation, and is in some cases injurious to the assay, we see the importance of using hard coal, either coke or anthracite, in crucible smeltings. A strong heat, and one of short duration, is all-important in this assay; for lead is volatile, and the flux will at last eat through the crucible.

After the lapse of about ten minutes, the contents of the crucible are again examined; and if the mass is now found to be perfectly fluid and quiet on its surface, the covers of the furnace and pot are removed, the fuel rammed down by means of an iron rod, and the crucible withdrawn from the fire and set in a dry or warm place on the brick floor. The crucible may be withdrawn by a pair of blacksmith's tongs, the fire-lips of which are nearly as long as the shanks, thus causing very little pressure upon the sides of the pot. Basket tongs may also be used, similar to those of the brass-founders; but they are generally too heavy and clumsy for assaying operations. On putting the crucible down on the floor some few gentle taps are given to it, to gather in the bottom those globules of metal which are suspended in the slag. When the crucible is perfectly cool, it is broken over a basin with water, that its contents may be examined when wet. In the bottom of the pot, a button of lead is found; and on breaking the scoria, we may examine it for grains of metal. If no metal is visible with the aid of a lens, all the parts of the pot and the slags are thrown away; if metal is visible, the pot and slag is to be pulverized, and washed, so as to recover it. This operation is performed in a wash-pan, like that with the crude ore

above described. All the metal must be free adhering slags by means of the hammer and it is then weighed and a cupel selected of weight, or heavier, for refining it.

Use of Salt.—In this assay we recommer use of salt in the form above mentioned, an mixed with the ore and other fluxes. good flux, because it does not aid in the solu silex directly; it merely dissolves the metallic and prepares them to combine with silex. the metals combined with chlorine are very ve and in assays, other than those of the pr metals, salt is inadmissible. Saltpetre is pref to salt; but as the oxygen of the saltpetre i absorbed by the carbon present in the mixtr lead will be precipitated; or else all the saltpet be converted into alkaline flux, which is not a flux for gold or silver ores; it causes the lead so impure as to cupel with difficulty. Some co salt, or fluor-spar, is requisite to free the leas iron, copper, and such metals, which delay and spoil the cupelling of it. In these assays it m the aim of the assaver to obtain pure lead in th smelting; if it is not obtained, it must be rewith a little saltpetre, or a mixture of saltpet common salt.

Sulphurets and Tellurets.—When gold or not perfectly oxidized, which frequently happ when pyrites are present, or the gold is con with tellurium or galena,—the operation is son difficult if we expect a correct quantitative In this case, as well as in the foregoing, we assay by means of litharge, using four or five to one part of ore, or, in fact, any quantity m less than that specified, and precipitate as muc

as we want by means of a specified quantity of coal or black flux. Such an assay is never correct; the slag is decidedly alkaline, and it retains a portion of the precious metal which may amount to 10, or 20, or even a greater per-centage of that contained in the specimen. In all cases when precious metals are to be assayed, and the object is to obtain the whole amount, the slag which is formed ought to be of an acid nature: if not acid, it should be, at least, a neutral salt. Gold is soluble in an alkaline slag, particularly in an alkaline sulphuret; and it cannot be expected to follow the metallic lead when so dissolved, or suspended in the slag. The means commonly employed for the purpose have proved insufficient, and the author has been induced to perform a series of experiments which resulted in a more perfect mode of assay, and in a smelting operation, the benefits of which he has secured to himself by a patent right. This operation is as follows. When the ore contains sufficient galena, no lead is added; but when it does not contain lead in some form or other, some finely-powdered litharge is added to the pulverized ore, and the whole intimately mixed. From ten to fifteen per cent. of oxide of lead is in all cases sufficient to procure all the gold. pounded ore and litharge is mixed with about one half of its weight of common salt; the whole mass is moistened with water so as to dissolve the salt, and then exposed to evaporation under constant stirring. When dry, the contents are gently heated in an iron pot with a concave bottom, and as soon as any signs of melting are perceptible, the mass is diligently stirred by a bent iron rod. It soon becomes semifluid, and the heat should be modified so as not to make the slag perfectly fluid and evaporate the

chlorine, for the latter must be retained. Wh slag has been well stirred for a short time, small pieces of burning charcoal are added stirred with the cinder. The charcoal reduc oxide of lead, and the heat must be so regulate no lead can sink to the bottom of the pot. suspended in the semi-fluid slag. By constar ring, the particles of metallic lead absorb the cles of gold which may be suspended or dissol the semi-fluid sulphuret, and an alloy is ob disseminated in small globules through the About half an hour is sufficient time to finis smelting operation; the iron pot is removed the fire, and the mass quickly thrown int water. Then the slag dissolves, the salt is ext and there remains in the vessel a black, fine p which feels like plumbago; it consists of th phurets of various metals, and metallic lead in grains and spangles. The sulphurets are ext fine, and are held in suspension in the strong fresh water should be added at discretion. t phurets gently washed away, and the remaining gathered for cupellation.

By this mode of assaying all the gold is obtained, but it requires a low heat and a work to make the operation successful. If su iron pyrites is present, the addition of a litt serves to secure the precious metal; if there a little iron in the ore, a small quantity of o iron should be added to decompose the sulp A gentle heat, the presence of salt, and the scause the evaporation of some sulphur, also and tellurium, and the sulphurets are thus do of the power to dissolve gold. The gold suspended in the pasty mass, and obtained b

bining it with metallic lead. If the combination is produced when the mass is in a state of rest, many particles of gold may be lost, because they are fine, and washed away with the water and the fine sulphurets; diligence is therefore necessary to make the operation succeed well. The presence of any alkali will injure this operation, and if some of the lead remains in the form of a sulphuret in the slags, the assay is doubtful. There is no danger of reducing the ores of iron, copper, or other metals by carbon; gold, silver, the platinum metals, and lead are the only ones which can be obtained. tion of an excess of carbon under the influence of a limited heat has therefore no other effect than to increase the mass and the labour in washing. The lead obtained in this operation may be re-melted in a crucible along with a little saltpetre to form it into a button and to free it from impurities.

In ancient times, assayers melted pyrites in potash and soda, and dissolved the slag in warm water, supposing that all the gold was contained in the alkaline sulphuretted solution. But this was a mistake : gold is soluble only in alkalies which contain a large quantity of sulphur. Sulphur must, therefore, either be added to such an assay, or the gold will adhere to the metallic sulphurets and be precipitated with It is very doubtful if with the addition of sulphur the whole amount of gold is obtained in the solution, because it is not very soluble in that menstruum. Other metallurgists recommend to melt the pyrites with saltpetre and litharge, then to evaporate all the sulphur and produce metallic lead. This is a safe way of assaying, but as saltpetre is easily decomposed and forms an alkaline slag, it requires either a very large quantity of the flux, or the assay

is incorrect. It needs at least an amount of salt petre equal to that of the ore when clean, and if the slag is not very liquid, a part of the gold will remain in it. The method of roasting or oxidizing the pyrites, and removing the oxide by washing, is at

imperfect that it deserves no further notice.

If gold is contained in metals, such as refuse iron tin, zinc, brass, or copper, under the form of works of art, it is scraped off with a scraper or file. labour may be accelerated by oxidizing the metals at a low heat. The gold thus obtained, as well as jewellers' sweepings, are either melted with saltpetre or with saltpetre and lead; in the latter case, some lead is obtained which contains all the gold, and may be cupelled in the usual manner. In this case tin or zinc is frequently present in the refuse, and as the oxides of these metals do not melt in saltpetre, it is advisable to add some common salt to the assav. to remove them from the lead, for these render the operation of cupelling slow and tedious; and if zinc or antimony is present, some of the gold is carried off by the evaporation of these metals. If sufficient saltpetre is used, and a little common salt, there will not be any other metals than lead and gold or silver in the button. It has been proposed to free gold from other metals by means of sulphuret of antimony; but this operation, which is generally practised by jewellers for refining their gold, is not applicable to an assay, because it is never correct. It has been also proposed to oxidize artificially all the metals which may be combined with gold, by using black manganese or oxide of iron. This method is not sufficiently correct to deserve any notice; for in all instances the oxides which are formed contain gold in small particles which never can be recovered.

The true principle of an assay for gold, in all cases, is to form a very fusible slag which absorbs all the metals; and as the gold will adhere readily to melted lead, it should be brought in contact with that metal in a state of fusion, and all the particles will be obtained. Common salt, or borax, remarkably promotes the solubility of metallic oxides, and in fact dissolves them very readily. In all cases, therefore, where we have to deal with metals or metallic oxides, either one or the other should be present; but, as borax causes other metals than lead to be formed, and salt produces only the precious metals and a limited quantity of lead, the presence of the latter is, in all cases, preferable to borax, when the precious metals are the object of the assay. There is no substance which dissolves metals more readily and converts them into oxides than chlorine. and when this is present in a sufficient quantity, the precious metals are not excepted; but when metallic lead is once produced in a crucible, it is only necessary to bring the dissolved gold in contact with the lead, and it is absorbed by it.

Metals and Gold.—When other metals are alloyed with gold, we separate the first either by cupellation, or if the kind and quantity is not suitable, we convert the first into oxide and divide the latter. The alloy of lead and gold is the most suitable for cupellation, and it is in all cases advisable to remove all other metals and convert the alloys into this combination. As gold is very volatile, these conversions must be performed by as low a degree of heat as possible. The cupellation of lead and gold is perfectly safe and easy: this is not the case with other metals and gold. Copper and gold combine very readily, and in fact more so than lead and gold, but

this alloy cannot be cupelled; it is therefore melted with lead, and the latter causes the oxide of copper to be absorbed by the cupel. The operation is uncertain, for the oxide of copper will absorb gold and carry it off. Such an assay is never correct, the refined gold containing copper, and the oxide of copper, gold. The same is the case with all other metals, and it is an object of peculiar importance not to cupel a test wherein other metals or substances than lead are contained. Other alloys than those of lead should be dissolved in muriatic acid, and precipitated by carbonate of soda, and the precipitate smelted like a mineral. In smelting, an excess of litharge is used; the quantity of lead is determined by the carbon which is added. An alloy of copper and gold requires a large quantity of lead for cupellation. We may assume that 100 parts of lead to one of copper is not too much, considering their relation, and the uncertainty of success in such an assay. It is easily understood that the solution of the alloy, and its precipitation with an alkali, is the only safe way of proceeding. As an alloy of gold always contains some silver, and as gold is not soluble in muriatic acid, the remaining parts which do not dissolve in the acid must be smelted with the precipitate. There would be no necessity of precipitating the solution, and merely smelting the residue would answer the purpose, but for the circumstance that chloride of silver is soluble to a certain extent in other or soluble chlorides; and as in most cases the amount of foreign metals is small, this method does not increase the labours of the assayer.

If the quantity of a metal in a test specimen is large, it is advisable to make a sulphuret of the alloy. This is accomplished in melting the speci-

men by adding gradually sulphuret of iron, coarsely pounded; the native pyrites contain sufficient to produce this effect on a large quantity of other metals. Galena may be used also, but it is not so effectual as iron pyrites. If neither iron nor lead pyrites can be obtained, pure sulphur is used, which is added to the melted or heated metal in small quantities and in the form of a coarse powder. The resulting sulphuret is then treated as native sul-

phurets, as has been stated in former pages.

Platinum, Silver, and Gold.—The presence of the first of these metals causes the cupellation to work slowly, and in some cases, particularly when copper is present, the gold does not form a globule at all, but is carried with the oxide of copper and the platinum metal over the cupel. In such cases we melt the test with some silver, of which at least twice the amount of the gold alloy must be added, and also some lead to make the mass fusible; it is then cupelled in a strong heat to obtain the metal in a perfect globule. The quantity of lead is variable; if the heat in the cupel is strong, which is the most advantageous, the quantity of lead may be 12 or 14 times that of the alloy. If the heat is low, but sufficient to melt the alloy, the quantity of lead must be at least 20 times that of the alloy. In all cases the resulting refined metal is adulterated by copper if that metal is present, which is more likely to be the case if the heat has been low in the cupellation. If no copper is present, less lead may be used in refining the metal. The presence of platinum in a test is recognized by the globule, which assumes a flattened instead of a round form, - this is pre-eminently marked in pure gold; silver, or an alloy with much silver, is also liable to form a flat globule in the shape of a hemisphere, while that of platinum is distinctly flattened. One per cent. of platinum will cause the globule to be rough and rugged on the surface, while pure gold and silver is perfectly smooth and shows a mirror-like lustre. In all cases the presence of platinum causes the globule to be dull and instraion, often showing crystals on the surface. When the alloy contains more than ten per cent. of platinum, the cupel is covered with a silver coating, under the influence of a strong heat, which is often yellowish or gravish, and consists of platinum metal.

Moist analysis. - When a globule of gold is abtained in the process of capellation, it is never were. particularly when derived from a mineral of The globule, for the purpose of testing it, is flattened on a steel anvil with a hammer; at first it is place directly on the naked steel, and afterwards between strong and thin paper. It is next exposed to the influence of pure nitric acid, which must be free from muriatic acid, which will not cause a precipitate with nitrate of silver. If the gold is nearly pure it is not attacked by the acid; we melt it then with some pure lead, about equal to twice its weight, and dissolve this alloy. The nitric acid, gently heated, will now hold in solution the lead and silver. and leave gold, platinum, and the platinum metals at the bottom of the vessel. If pure silver is at hand it may be melted with the globule, of which an equal weight is sufficient. The result is more certain the by allowing it with lead. The residue of the solution is treated with agua regia, which dissolves the The solution thus obtained is evaporated in a flat porcelain dish, over a basin of boiling water, which causes the evaporation of all the acid. The dried chloride of gold is now dissolved in water, and to this is added a fresh solution of proto-sulphate of iron, which in a short time precipitates the gold is

the form of a yellowish brown powder. This is dull and lustreless, but assumes brightness when filtrated, dried, and burnished by a hard and polished substance. The proto-sulphate of iron is prepared by dissolving copperas, and adding to the solution pure metallic iron. This solution must be prepared some days previous to its use, for the iron does not dissolve very readily in the copperas. A surplus of metallic iron should always be in the solution. It is advisable to use both gold and iron solutions in a somewhat diluted state; it does not then form a precipitate at once, but requires some time. The mixed solution appears at first to be light blue, and in reflected light reddish yellow; the gold gradually subsides in the form of a yellow powder. This powder is pure gold; it is filtrated on clean paper, and may be weighed in this state, or it may be gathered into a globule with some borax and saltpetre in a crucible.

Remarks.—In all the assays of gold, we must be extremely cautious to avoid the presence of an alkaline slag; for in most cases some oxide or sulphuret of gold is always present in a mineral which contains gold. Both are soluble in alkalies, and if the slag we melt with is alkaline, we are uncertain of the results of the assay. Borax, potash, and soda are to be avoided, if possible; and the use of salt requires caution, for all these fluxes dissolve gold. Saltpetre is the most suitable flux, but in the presence of sulphur, carbon, and some of the metals, it is decomposed and ceases to be good. Chlorides are the most practicable fluxes; but as these cannot bear a high heat, nor one of long duration, the operation must be so arranged as to perform the assay in the shortest time which is possible. For these reasons the fluxes and mineral are mixed in a wet condition to bring the particles in close contact before heat is applied—this facilitates the smelting considerable The moistened mass must be dried before items packed into an earthen crucible, because it will break the crucible when it is deposited in a moist states Gold is not often found in large quantities in minerals; and as a minute quantity is sufficient toom for its extraction, the assay of gold ore claims at attention which is not required in assaying the arm of other metals. Chlorides dissolve the exide of gold, but not metallic gold; and when fluid lead is brought in contact with the dissolved oxide or sulphuret, it will absorb them; but as lead is heavy, it is inclined to subside, and thus deprives the particles of gold, which still may be present in the slag, of sa epportunity to combine with it: for these reasons we prefer the assay in an iron pot, with a constant stirring of the mass. The melted lead performs here the office of mercury in an amalgamation.

Platinum and Platinum Metals; Palladium, Rhodium, Iridium, Osmium. The latter metals are generally alloyed with platinum. Platinum is exceedingly refractory; it can be melted only when alloyed with another metal. When a grain of metal of a leaden appearance resists all degrees of heat; and neither melts nor oxidizes, we may conclude that it is platinum. If the grains of the metal are fance, and imbedded in rocky matter, it is treated as gold ore, melted with suitable fluxes, and cupelled. In this case silver must be present to cause the platinum and addition of pure metal must be made to the assets. In a strong heat, platinum combined with two parts of silver may be cupelled. But as a strong heat is

not generally at the command of the assayer, it is advisable to make use of more than two parts of silver to one of platinum. In most cases it is the best plan to arrange the assay so that one part of platinum in the ore is melted with 6 parts of silver and 50 parts of lead. If less lead and silver is in the alloy, the metals palladium and rhodium do not remain in the globule, but are spread over the cupel. If the amount of platinum in the test is not more than five per cent., or  $\frac{1}{20}$  of the silver, the appearance of the globule in the heat of the cupel is similar to that of pure silver. If  $\frac{1}{10}$  of platinum is in the silver, the globule does not show the bright glistening surface of silver or gold, but is dull and gray. With 1 of platinum it requires a strong heat, and the cupelling is extremely slow; the grain is flattened, dull, and obstinately retains the last portions of lead. The globule thus obtained in cupelling contains silver and platinum, and it may also contain gold and other metals; if thrown into concentrated boiling sulphuric acid, all the silver is dissolved, but not the platinum. The residue is platinum, and if gold has been in the alloy, it contains gold. It is then dissolved in aqua regia, some ammonia is added, and the solution evaporated over boiling water. The dry residue is triturated with alcohol of 84 specific gravity, and dissolved in water after the alcohol has extracted the yellow liquid. The gold only is dissolved; the platinum remains as a platinum chloride combined with chloride of ammonia. This is calcined in a red heat over the spirit-lamp, and the remaining powder, which is platinum, weighed. The gold may be obtained by means of proto-sulphate of Too much silver in the alloy is not good for solution, because some little platinum appears to be

soluble in sulphuric acid when the amount of silver is more than 2 to 1 of platinum; but as this loss is very small, the assay indicates too little metal. When iridium is present the precipitate of platinumammonium chloride is reddish or brick-red, instead The precipitate is then calcined in a porcelain crucible and dissolved in aquafortis, which alone dissolves platinum; this, when precipitated by ammonia, forms a yellow precipitate. The separation of the other platinum metals from the solution. is. if not difficult, at least of such a nature as to

belong more to chemistry than to metallurgy.

Silver.—The assay of silver ore is, in itself, extremely simple. Most of the silver ores contain lead, others copper, which metals in many instances so far predominate as to make their extraction pro-We make the assay in this case with a view to procure the accompanying metal. In all cases it is necessary to combine the silver with some lead in smelting, and separate the silver by cupellation. If there is not sufficient lead in the ore, litharge must be added to increase it. The test can be melted with metallic lead, also, in case litharge cannot be obtained sufficiently pure. Metallic lead should be It may be tried by cupelling a part of that which is designed to form the matrix for the silver. If it proves to be pure in the cupel—that is, shows no other colours, but converts that of the cupel into a uniform whitish-yellow and no metallic globule remains—we may conclude the metal to be sufficiently pure for the purpose. The assays with metallic lead, and those with the oxide of lead, have their peculiar advantages: the first is for quantitative assays in the smelt-works; the second is the most convenient for qualitative assays.

Assay by Metallic Lead.— We thus assay all the ores in which we expect to find silver or other precious metals. The lead used in this assay, the purity of which has been tested, is granulated in the following manner. The metal is melted in a clean iron ladle, the dross or sullage on its surface is removed, and the liquid poured into a wooden trough, which is previously rubbed over with reddle, in order to prevent the burning of the wood. The trough is



represented in the annexed figure. It is taken up with both hands, and the lead kept constantly in motion until it is near congelation; at this point the lead is thrown up, and in falling back into the trough again it is broken into small fragments, which are often very minute, and the mass appears in the form of fine sand if the operation has been well performed. When all the lead is thus divided, and cold, it is thrown on a sieve, of about twenty meshes to the inch; the fine part is removed for use. and the coarse grains which remain are reserved for remelting. This lead, in quantities of two ounces for one test, is placed upon a flat dish, and mixed with the ore for smelting. The dishes used for this purpose are manufactured of good fire-clay, similar to that of which crucibles or fire-bricks are made; a mixture of three parts of pure clay and four parts of refractory sand is considered a good composition.

Dishes of three inches diameter are made by hand of this siliceous clay, but where many are required, it is necessary to manufacture them by such a machine as is used for making cupels. The capacity of the dish must be abundantly sufficient to melt four ounces of lead and half an ounce of ore. These dishes, when first made, are too soft and porous for use: they are dried in the air and then baked in a furnace. notter can manufacture and bake them with his ordinary ware. With a cupel furnace, having a large muffle, a number of tests may be assayed at once; and in all cases, two tests should be assayed from every species of ore. Whenever meltings, smelting, and cupelling are done at the same time, the dishes, pots, or cupels, are marked with reddle, and numbered in such a manner that each test may be recognized: this reddle mark is not obliterated by fire. Two ounces of granulated lead are laid around the edge of the dish, so that the concavity in the centre In the middle,  $\frac{1}{8}$  of an ounce, or 60 grains, of ore finely pulverized, is placed, and some of the granulated lead mixed with it, in such a manner that the ore does not reach to the edge of the dish. dishes thus prepared with ore and lead are pushed slowly into the heated muffle of the furnace; the most refractory specimens foremost, and those afterwards which melt easily. The ores which contain much siliceous matter or iron are refractory; those which contain pyrites chiefly, are very fusible. short time, say five or eight minutes after exposure to the heat of the muffle, the ore begins to roast, that is, exhale sulphur, arsenic, and other volatile substances, and the lead begins to melt. and metal are thus heating, the mouth of the muffle is shut by a piece of hard charcoal, and the dishes radually exposed to a stronger heat by stirring the ire: this must not be done too fast, because some res foam in melting and flow over the lead, thus poiling the assay. The principal object of this meration is to form a slag of the ore, and bring at the same time melted lead in contact with it in its molten state, which may absorb the precious metal. In case the ore does not contain sufficient flux for melting, some of the lead is oxidized by the heat, and forms a flux for it. It is therefore evident that too much heat is disadvantageous to the ore, because some of it may boil over the edge of the vessel and The heat must not be too slow to act, because in that case the oxide of lead, which is generated abundantly, will eat through the dish. heat in the muffle is easily regulated by putting more or less coal at the mouth. It is therefore advisable to have the fire rather too strong than too weak. After the lapse of fifteen or twenty minutes we observe a bright metallic spot in the middle of the dish. It is the melted lead surrounded by the fluid ore, which is now in the form of a slag. lead is all the time burning and evaporating; and if these vapours of it draw over the dishes, it is an indication that the heat is too low; on the other hand. if these vapours rise high on the roof of the muffle. the fire is too hot. The vapours of lead ought to form a cloud, which is suspended half-way between the roof and the bottom of the muffle. drawal of coal at the mouth of the muffle will cool it. and the addition of coal heat it. When the bright spot in the middle of the dish disappears, the mouth of the muffle should be entirely shut, and a strong heat applied about ten minutes longer. This is the finishing heat; the ore becomes now perfectly fluid,

and separates entirely from the button of lead below This heat is sufficient to finish the operation. The time consumed in the assay is between one hour and one and a quarter. The dish is now withdraws from the hot muffle, and its contents cast into sipte viously heated iron mould which has been rabbed over with some fat or tallow. After the contents of the mould are cooled sufficiently to adhere together, they are put into cold water, and the slag carefully separated from the lead by striking it with a hour mer. This lead is ready for refining, and may be placed in the cupel. In case the cres contain very refractory matter, such as particles of clay, slate; heavy spar and quarts, about ten grains of beensglass may be mixed with the ore; but if the test will work without, it is better. If a series of tests are to be assayed, it is the best plan to melt the whole of them before refining the lead.

Smelting with Oxide of Lead.—All ores may be smelted with the oxide of lead instead of metallic lead, which is preferable when much lead is in the ore. Some ores must be roasted before melting: these do not often present themselves, and generally we may smelt without previous roasting. under examination is finely pounded, and mixed with. double its weight of a mixture consisting of one part of saltpetre and two parts of crude cream of tartar. This is the composition of black flux, which may be used here to advantage in its crude form, particularly when sulphur is in the ore. The use of this mixture presupposes the presence of lead in the ore and one ounce is smelted at a time; this brings th quantity of ore assayed to near five hundred grain If no lead is in the ore, or very little, an equal weigh of pure litharge is mixed with it, and the other pr

portions are the same as mentioned before. In most cases it is the best plan to take 100 grains of this kind of ore, and mix with the required flux for smelting. If we want a correct assay of lead, the test is not smelted in an earthen or clay crucible, but in a copper pot, so that all siliceous matter is ex-

cluded. In the figure annexed, a pot of this kind is represented. It is about 1 of an inch thick in metal, and as the flux is exceedingly alkaline, very little lead can remain in an oxidized state in the slag. Over the mixture of ore and flux a stratum of salt is laid. This is necessary to prevent the flying of the ore. The crude flux, in detonating with the saltpetre. would throw out the ore unless it was covered with salt. especially if the narrow mouth



of the copper pot was open. A short time, 35 or 40 minutes, is sufficient to smelt the test, for which of course the heat must not be made so high as to melt the copper. This test may be smelted in an iron pot if the ore contains no sulphur. When the smelting is finished, the contents are poured into the iron mould, and the quantity of lead which is obtained shows the exact quantity of that metal in the ore.

When oxide of lead is added to the assay, no test can be made for determining the quantity of lead. The operation is essentially the same as that above mentioned, and may be performed in a clay or Hes-

sian crucible, in a black lead pot, or an iron pot. The lead thus obtained is cupelled. In all cases where crude tartar is used as a flux, the fire must be kindled above the pots, for if it comes from below. the detonating saltpetre is apt to throw most of the ore out, in spite of all precautions. The fire must be low so long as a noise is perceived in the pot; when that ceases, the draught-holes may be opened and more fire applied.

In this assay we may use litharge, as in the gold assay; that is, take an excess of litharge and precipitate lead by mixing with it a definite quantity of carbon. But in this case, as in the previous one, a large quantity of silver may remain in the slags. This is of less importance than in the case of the gold assay; still it is sufficient to cause an assay made in a clay crucible to be incorrect. In all these instances we recommend smelting in an iron pot, with salt and a constant stirring of the mass, and the extraction of the granules of lead by dissolving the cinder. This assay furnishes a more correct result than any other.

When sulphurets are extensively present in an ore, the operation is in all cases performed with greater facility if the test is smelted with saltpetre only, or a mixture of saltpetre and litharge, to which carbonate of soda is added. Galena may thus be conveniently assayed for silver, if we pound it with three or four times its weight of saltpetre, and dry carbonate of soda of a weight equal to its own, or the same quantity of oxide of lead. Thus a small quantity of lead is produced which contains all the silver, but not all the gold if any is present. phurets may be also smelted in a clay pot, with just sufficient saltpetre to oxidize all the sulphur and

produce no metallic lead. The slag thus formed is covered by a sheet of metallic lead, which in melting down carries all the silver with it. This operation may be correct when executed properly, but it is one of those difficult assays in which the result depends on the skill of the operator. When an assay is performed in an iron pot under constant stirring, all the sulphurets of an ore may be decomposed by litharge; when to this, metallic lead is added and the assay in its fluid state is poured into a hot clay crucible and rapidly melted, so as to accumulate all the metal at the bottom, we may obtain all the silver in the ore, but not all the gold. If a mixture of ore and flux of litharge is so regulated as to form an oxide, the ore never boils on melting; we may therefore in such a case fill the crucible, and cover the top of the ore with pure litharge. As much metallic lead will be produced as is indicated by the amount of sulphur in the ore, which in iron and copper pyrites is considerable. An assay of this kind must be made in the shortest possible time, for the litharge soon eats through a Hessian crucible. Thus we obtain all the silver, and the process is simple and easily performed; the heat necessary is too great for an iron or copper pot, and if the assay is well regulated, the amount of metal produced may by proper attention be considerably diminished.

The first method, that is, the assay with metallic lead in the muffle of the cupel furnace, is the most correct, and whenever any doubt exists, it may be resorted to as a final proof of a good assay. It can be applied in all cases where the presence of the precious metals is expected; it is a quick operation, causing but little labour to perform it on an extensive scale. It is the best method of assaying. The

use of borax facilitates the operation in some measure, but when more than  $\frac{1}{16}$  or  $\frac{3}{38}$  of the ore is employed, the assay works slower and is not quite correct.

When metallic ores are exposed to heat and such re-agents as develope the metal, it is commonly called smelting, in contradistinction from the mere application of heat, which causes ore to become fluid, and is called melting. Smelting is a chemical operation, conducted on the same principles as a moist assay in the laboratory; excepting that we produce in this case but one valuable substance, the metal, and consider the slags as accidental results. slags require the closest attention of the metallurgist, because if they are of the right composition, the metal will invariably appear in the proper form. In all cases of smelting, it is an essential condition that the degree of heat should be so high as to cause all substances to become perfectly fluid. In principle there is no difference—if we mix two fluids, or a fluid and a solid, which show different affinities for the matter in solution—if the fluidity is produced by matter which is fluid at common temperatures, or only at a high heat. If oxide of iron is put into a watery solution of the sulphuret of potassium, the result is sulphuret of iron and potash; if the sulphuret of potassium is melted by heat, and we put into the fluid the oxide of iron, we have the same result; sulphuret of iron and potash are in the hot, melted mass. If some potash or soda is put into a red-hot solution of silicate of lead, metallic lead is precipitated, because the potash has more affinity for silex than oxide of lead. When into a fluid silicate of iron, carbon, lime, or other bases, or an oxide of metal is brought, such as manganese, which has more

affinity for silex than iron—it will deprive the silex of its iron, and precipitate the latter in its metallic state. The manipulation in the laboratory differs from the manner of operation in metallurgy, but we

recognize in both the same laws of affinity.

In almost all smelting operations the object is to produce a certain metal, and to form of all the other metals oxides and slags. This operation is greatly facilitated by the fact that most of the metals are specifically heavier than their melted oxides, or than these oxides in combination with silex or other acids; and if slags and metal are actually rendered perfectly fluid, they will separate in consequence of their want of affinity and their difference in specific gravity. This case is like that of common fluids. Water and oil may be mixed, but they soon separate, the oil floating in a distinct stratum on the surface of the water. Metallic lead and oxide of lead, or a silicate of the oxide of lead, or any other silicate, may be mixed when in a rigid state, and they do not separate; but when both are fluid or melted, metal and slag soon separate, the former being found below the latter. When lead, iron, and slag are melted together, we obtain lead for the lowest stratum, iron on that, and the slag above the iron. The specific gravity of each indicates their relative positions. all smelting operations we obtain at least two separate strata, often three, and in some instances four. of different substances.

Metals.—These are contained in the ores, in most cases, as compounds; and if it is the object to separate them, we are to put such matter in contact with them as will deprive the metal of its compound. If a silicate of iron is melted, we do not precipitate iron by adding carbonate of soda or caustic lime to the

fluid mass: this addition merely increases the fluidity of the slag without producing any metal. But if we add sodium, the oxide of iron will be deprived of its oxygen and form metal. Carbon has more affinity for oxygen than metal in the high heat of a melted silicate: if therefore we add carbon to the melted silicate of iron, some iron is produced in all cases. When in this instance sufficient iron is precipitated to deprive the slag of its fluidity, no metal is formed, however much carbon we may add; for the metal requires a slimy, glassy coating to protect it against the influence of oxygen. When exposed in small particles to the influence of oxygen, almost all metals burn more readily than carbon,—gold, the platinum metals, and silver, in some measure excepted. therefore we desire to obtain metal, we must produce a slag which protects it and at the same time admits of its coagulation. If to fluid silicate of iron, potash or soda is added, and at the same time carbon, metallic iron will be produced, because the slag retains its fusibility by this addition; but when so much iron is precipitated as to render the slag not sufficiently fusible to cover the metal with a slimy coating, the presence of potash even will not prevent the iron from burning. Carbon in any form has a strong affinity for oxygen, and precipitates all the metals from oxidized compounds; but it must never be forgotten that metal in fine particles has more affinity for oxygen than carbon, no matter how high or low the temperature may be. It is evident from this that no metallurgical operation can be perfect until the heat is sufficient to melt both metal and Some metals are extremely refractory, and do not melt in any heat we can produce by means of carbon; such are platinum, chromium, iron, and

others. In these cases we combine the metal with other substances which cause it to be fusible. Platinum is fusible in combination with lead; chromium in combination with arsenic; and iron in connection with carbon, phosphorus, arsenic, sulphur, and a number of alloys, is fusible, while by itself it cannot be melted. By these means we may precipitate and melt a metal which without such an addition would Silver and gold, if pure, do not melt very not melt. readily, and they evaporate at a heat only little higher than their melting point; it is therefore necessary to combine these metals with one that is more fluid, in order not to lose much of them. These considerations will lead the metallurgist to employ the proper means for obtaining the metal in a finid state.

Slage.—As was remarked above, the composition of the slags determines the quality and quantity of the metal produced; and if considerations of economy did not interfere with the application of fluxes, other than natural ones, there would be no limit to the production of metals in quality and quantity. Slags are glasses compounded of substances which melt at a particular degree of heat for each definite composi-The study of the nature of slags forms the science of smelting; the metals follow of course when the fluxes are correctly compounded. not always the case that metals are obtained at first melting; some ores are first converted into matt, such as copper, then roasted, and the metal extracted by a series of roastings and smeltings. These operations, all made with a view of compounding a proper slag, complicate the smelting process so far that we distinguish in them oxidizing, melting, reducing or smelting, and refining. Each

of these operations involves different principles we shall for these reasons speak of them l

treating of the composition of slags.

Oxidation.—When sulphurets which cannot be desulphuretted by roasting, such as copper py are to be smelted, we either melt and roast by spheric air, or by the addition of oxides t melted mass. When iron pyrites is melted tog with the oxide of iron, a large portion of sulph evaporated in the form of sulphurous acid, an remaining sulphuret of iron when exposed to atmosphere is easily decomposed; part of it is verted into green vitriol, and the rest forms per of iron.

The oxidizing operation is facilitated either w without the assistance of atmospheric air, by a highest oxides of metals, such as oxide of lead oxide of iron, black manganese, saltpetre, cor salt, silex, water, and in fact any substance gives off oxygen, or facilitates an absorption of spheric oxygen. Oxidizing smeltings are ofte cheaper than roasting, and this is an object v well deserves the attention of metallurgists, especially as it requires less labour and fuel to o sulphurets in this manner, than by roasting, p ing, and washing. In the large operation we c employ litharge or saltpetre as a means of oxid because they are too expensive; but instead of we use coarse silex, gypsum, salt, oxide of ire black manganese. In this case it is all-sufficion mix the mineral with such substances as cause divide and offer more surface to the atmospheri The substances used for oxidation are depe entirely on the quality of ore, and the mo operation in the subsequent reducing process

roast galena with fine silex, which of course will n liberate the lead from sulphur, not much metal be obtained, because the slag formed by the le of lead and silex is so far infusible as to admit no separation of the lead from it. But if the x is used in large grains, which leaves sufficient ces for the globule of melted metal, we may obas much metal in the presence of an excess of zeous matter as in a perfectly fluid and alkaline This of course excludes the possibility of a ble slag, but it serves as an illustration of the sciples involved in smelting. Any other subice than silex may serve the same purpose, proed it has no affinity for that which is to be loved by evaporation, and is sufficiently refracr to resist melting with the oxide produced by metal which is to be oxidized. The most exrive application of oxidizing melting is made in lting sulphurets of copper in reverberatory fures. In this case iron must be always present; this al combines with sulphur more readily than per, but it also parts with it more readily, when osed to the effect of the oxygen of the atmoere: the oxides of iron thus formed absorb sulr from copper as long as any is present; and n all the sulphur is expended the iron forces the per from its combinations with silex. Common is profitably employed for oxidation; all chlorare volatile, and so is common salt; but if the ntity used is small, and it serves as a mere stant in the operation, it will long resist the innce of heat, particularly in alkaline slags. presence of clay or lime, common salt will bear gh heat for many hours without scarcely evapong. Salt to the amount of one or two per cent.

in the slag will resist the heat of a puddling-furnace for 24 hours, without being expelled. Sulphates act like chlorides, but it is necessary that no carbon should be present; the latter will decompose any sulphate in a melted condition, and it ceases then to act as an oxidizing agent. The presence of carbon facilitates the evaporation of chlorides also, but that which remains is still a powerful means of oxidation.

The oxidizing operation by smelting is always imperfect, that is, all the volatile substances, such as sulphur, arsenic, antimony, and phosphorus, are never removed entirely, and the metal is obtained gradually. The presence of the volatile matter serves in part to liquefy the slags. By these means, copper, lead, antimony and a few other metals may be obtained; but when it is an object to produce all the gold and silver contained in an ore, every particle of sulphur, &c. should be removed, and the mineral brought to the highest state of oxidation, before subjecting it to the reducing operation with carbon.

Reducing.—The means employed for obtaining metals from oxides, and other compounds, are so extensive and varied, and the apparatus so well adapted for accomplishing the object in view, that speculations on this subject are the most interesting of all branches of industry to which intellect may be applied. Conducted on the principles developed by chemistry, the mineral may require water for solution or heat; but as the composition of minerals is extremely variable, the means employed are of course equally so. The heat ranges from the boiling point of water to the highest attainable. The means of reduction are, metals, and to some extent

the oxides of the heavy metals, alkalies and alkaline earths, carbon, hydrogen, carburetted hydrogen, and a variety of other matter.

By Metals.—If we put into a fluid solution of sulphurets, arseniurets, or oxides, a metal which has more affinity for sulphur, oxygen, arsenic, &c., than one of the metals in solution, the latter is precipitated, and the first assumes its position in the fluid mass, provided it is soluble. If it is not soluble it will still absorb the substance for which it has most affinity from the metal, and float upon the reduced metal, provided the latter is heavier and both have little affinity for each other. This operation must be conducted with all the niceties of a chemical experiment. When sulphuret of lead or antimony is melted, and pure metallic iron is placed in contact with it, the iron will absorb the sulphur from these metals and produce them in their pure condition. Lead has little or no affinity for iron, the metal produced is therefore pure. Antimony combines readily with iron, and if the quantity of the latter is larger than merely to absorb the sulphur, it will combine with iron and form an alloy. In the first case it does no harm if more iron is used than is required, but in the latter it is injurious to the metal which is to be reduced. The quantity of the substance used for liberating metal from its combinations is here of equal importance as in chemistry, and the same laws are applied; the quantity increases the affinity. When a large quantity of iron is present in copper ores, we may succeed in obtaining almost all the copper; but when little iron is in the slag, the copper has such affinity for either volatile matter or silex, that a large per-centage remains in the slags, which can be recovered only by heavy expense. In

all operations of this kind we are therefore to consider the affinities and also the amount of the mass.

By Oxides.-When a mixture of potash and soda is melted, and we add to it a sulphuret of a metal whose basis melts below the heat of the alkaline sulphuret, and whose sulphuret is not soluble in the alkali, we obtain a certain portion of the metal, and often the whole of it. Zinc blende, galena, and the sulphurets of the fusible metals, form pure metals which separate; but iron or copper pyrites form no metal, because they do not melt in that heat, and remain either as oxides or sulphurets in the solution. Sulphurets of gold, platinum, or silver, do not produce metals, but when lead is present a part of these metals may be obtained. The sulphurets of arsenic and tin do not form metals, because these combinations as well as their oxides are soluble in alkalies. The same law which is here applied to potash and soda is applicable to the alkaline earths, and metallic oxides when these form fluid slags. Lime will effectually reduce the sulphuret of any metal, but as the heat by which it melts is very high, we can produce only those metals which do not evaporate at that heat. If the vapours of the metal are equally valuable with the melted metal, such as quicksilver and zinc, we reduce sulphurets by the use of lime successfully. When lime is used to excess in reducing sulphuret of iron, the latter may be freed from sulphur almost entirely. In the same manner. protoxide or magnetic oxide of iron acts upon galena; if the iron predominates and becomes fluid at so low a heat as not to evaporate the lead, all the lead may be obtained. The application of these principles is extremely important in metallurgy, and it deserves more attention than is commonly paid to it. Oxides

of metals cannot be reduced by other oxides, unless the higher oxidization of a newly formed oxide is more soluble than the previous one. When oxide of lead or of tin is cast into an alkaline silicate of iron, some metal is produced; this is not because the higher oxidization of iron causes the slag to be more fluid, but because some of the iron may be more highly oxidized without interfering with the fluidity of the cinder; the addition of some oxide of lead which remains, causes it to be more fluid, or at least

retain its fluidity.

Carbon.—Of all the means at the disposal of the metallurgist, carbon is the most available for reduction. It is of little use in reducing chlorides, sulphurets, and arseniurets—for these metals are necessary: but as most minerals are in the form of oxides. and carbon is, in the high heat required, a strong agent in removing oxygen, it is generally applied. Hydrogen is also an effective means of reduction; but as its compound, water, oxidizes hot metal readily, and as the heat by which it operates is generally too low to melt the metal, its application is extremely limited. Hydrogen is employed in some cases, in its combinations with carbon, to reduce oxides, such as oxide of tin, or zinc; but it is then used to a very limited extent, such as the small quantity which is present in the coal employed, whether bituminous mineral coal or soft charcoal. This gas has in many cases a decided influence on the smelting operation, as we shall see; and it is mostly removed by charring that fuel which contains hydrogen to an injurious extent. Carbon is particularly suitable for the reduction of oxides in consequence of its volatile compounds with oxygen, and its harmless combinations with the metal produced.

The results of the deoxidizing operation, that is, carbonic acid and carbonic oxide, are extremely volatile, and escape without any injury to the slags, or the metal produced. When carbon is brought in contact with oxidized ore, and there is no other oxygen present but that in the ore, it will be forced to combine with that. When a mixture of carbon and ore is exposed to fire, no combination between the ore and carbon can ensue, because both are rigid and the particles cannot move; and as motion is indispensable in any chemical operation, no combination between carbon and the oxygen of the ore could happen, unless one or the other was made fluid by heat. In the first place, there is always some air, particularly oxygen, in the pores of charred coalalso in the pores of ore; this oxygen is at liberty to move and will combine with carbon, and as carbon is sufficiently abundant the combination formed is carbonic oxide. This gas will combine with another portion of oxygen where it finds such at a sufficiently high heat; and inasmuch as the ore nearest to it is hot, the gas will absorb oxygen from the ore and escape in the form of carbonic acid. The ore thus deprived of oxygen produces metal. This explanation may serve in all those cases where the metals readily part with their oxygen, but it is not sufficient to explain the reduction of metals which have a strong affinity for oxygen and even melt with their oxides. For these reasons the refractory metals are smelted with fluxes, which cause the ores to become fluid, and in this manner they are brought in close contact with the coal. The use of fluxes is. therefore, not confined to the absorption of foreign matter: it is highly valuable in accelerating the smelting operation. For this reason we see the

oxides of lead, bismuth, antimony, nickel, and cobalt, reduced very readily; because the oxides themselves, or mixed with fluxes, form fusible slags which readily flow over the carbon and cause a close contact between it and the oxygen. Tin, zinc, iron, chromium, and manganese, are not easily reduced, because their oxides are very refractory, and the first two metals evaporate in that heat at which carbonic acid is formed from their oxides: for these reasons it is necessary that soft charcoal or bituminous coal be used in their reduction. Neither the oxides of the other metals, nor the metals themselves, melt readily; but if we cause the oxides to become more fusible by adding fluxes, and the metals by alloying them with a substance which makes them fusible, we may produce either of these metals very readily. The reduction in most cases takes place previous to melting—and it is in fact not necessary that the ore should be melted before reduction ensues: but if it should be, it facilitates the formation of metal.

The doctrine that carbonic oxide is the agent in the process of reduction is not objectionable, so far as those metals are concerned which are not oxidized by carbonic acid, and which do not absorb carbon. This theory does not, therefore, apply generally. Some metals decompose carbonic acid—they cannot be reduced by it or in its presence; others again absorb carbon, which neither carbonic acid nor the carbonic oxide can afford; and it is necessary to adopt a hypothetical compound of carbon and oxygen in order to explain the carbonized state of some metals, such as iron, lead, manganese, and others. The combination of carbon and metals appears to be in most cases a mere mechanical mixture, and it can-

not be assumed that the affinity of metals for carbon is so strong as to decompose carbonic oxide. We shall illustrate this subject by referring to a particular case in which carbon is of peculiar effect, namely, that of iron. When iron ore is smelted in a blast-furnace, it is found not only difficult, but almost impossible to manufacture gray iron from magnetic ore, when not roasted or oxidized previous to smelting. It is impossible to make gray iron by smelting silicates of any kind, such as forge cinders or puddling-furnace slag. If only the presence of carbonic oxide was required, these forms of iron ore ought to furnish gray iron as well as any other ore, for the ore is constantly in contact with that gas and with pure carbon also. We explain this by referring to the compact form of the ore. All the ores which are compact are reduced by the carbon acting on the exterior particles of the lumps. The metal formed being fluid, runs off by accumulating into a body, which is in that form not accessible to carbon, or capable of forming any compound with other matter. because the points of attraction and contact are wanting. No matter, however, what the rationale of this phenomenon may be, the fact is generally known. Porous iron ores—spongy hydrates—are the most suitable to produce gray iron; in fact, they produce it as a necessary consequence of their form. latter was not the cause, this ore would be as little suited to form gray iron as any other, for it is of the same composition as specular ore, containing generally, however, more impurities than the latter; still it is very difficult to make gray iron of specular ore, and in fact of every kind of compact ore, no matter what may be its composition. Compact ore may be either perfectly pure or very impure; neither

condition renders it suitable to form gray iron. If iron, or its compounds, are in a porous condition, there is not the slightest difficulty in combining them with carbon. We conclude therefore that carbon penetrates into the pores of ore and metal in a solid form; for it is evident that spaces are required to bring particles of carbon in contact with particles of ore, or the compact ores would form gray iron quite as well as porous ones.

If porosity of the ore or metal is an essential condition of carbonizing it, then it is evident that carbonic oxide gas cannot have the power of conveying solid carbon to the metal, for that gas will penetrate less porous bodies than iron ores of a compact form. When carbonic oxide gas is the agent, it will carbonize iron wherever it finds it in a proper condition: for if it is fluid, all the requisites of combination are presented. Still, we know by experience that pure carbonic oxide will not carbonize iron in the converting box of the steel manufacturer; it requires the immediate contact of solid carbon and solid iron to form a carburet. Iron may be carbonized and decarbonized when in a fluid state, but the operation is extremely slow, and cannot be supposed to happen in a blast-furnace where the melted metal sinks down into the hearth rapidly. We assume, therefore, which assumption is supported by experiment, that carbon in a solid form is deposited in the pores of the ore before it is melted, and that in melting, the cohesion of the metal brings the carbon into so close contact with the metal as to force it into its pores and effect a union. The carbonizing of iron in the converting box presents no objection to this theory, as we shall see hereafter.

When carbon is present in the ore before it is

melted, how does it get there? how is it deposited in that form? Carbonic oxide cannot deposit carbon. for it finds abundance of oxygen in the ore to combine with, and will naturally form carbonic acid. But supposing carbonic oxide was decomposed in the pores of the ore, the result must be carbonic acid in all cases, which is evidently not the fact in the blastfurnace, for we find the latter filled with carbonic oxide nearly to its top; at least so far down as any carbonic acid is formed, no perceptible alteration is observed in the ore. From the lowest point where carbonic acid ceases, downwards, the effect of carbon commences, the cementation of ore goes on, and still there is little or no carbonic acid gas in the furnace. A cold plate is blackened when held over the flame of a clear-burning candle; solid carbon is deposited from the gaseous solution of the flame. It may be objected to this parallel example, that in the flame of oil and of fat there is an abundance of hydrogen, which holds carbon in solution. May not carbonic oxide have a similar effect on carbon as hydrogen when at a high heat? The solvent power of this gas for carbon may be very faint, existing only at a high heat, and being destroyed at a diminution of that heat. The operations of the blast-furnace, the mode in which the blast is introduced, and the appearance of the ore and gas in the furnace, confirm this theory of carbonizing iron.

Alloys.—If we adopt the foregoing theory for combining carbon with metals, we obtain at once a clear, comprehensive view of the conditions under which alloys, and the various combinations of metals and other substances, may be formed; and as these combinations are of the utmost importance to the metallurgist, they are well worth the trouble of a

examination. It is not only the combination. lso the separation of such combinations, which f interest. The above demonstration shows at under what conditions alloys may be formed, if the affinities and other relations are averse y combination. We may melt pure iron and ic metal together as long as we please, no union e two can be effected; the arsenic evaporates e the iron is sufficiently hot for its combination. f we heat fine iron filings and arsenious acid carbon, at first gently, we may melt both togevery readily and obtain an extremely fusible inret of iron. This operation is still more performed if we heat borings of gray cast iron reenious acid together. And this alloy may be seed in any form or compound which we choose, mix arsenious acid, oxide of iron, and carbon in s together, and bring the various particles in contact before heating, by moistening the mixwith a weak solution of potash or soda, and g the whole before smelting. A very slight will melt this alloy, and all the iron in the mixis readily obtained under a cover of carbon. most refractory metals may thus be made le, and obtained from their ores, and the facility which they are produced depends on the gement which we have made before smelting is Chromium is very refractory, but if ix its oxide with carbon and a little phosphoric and moisten the mixture with an alkaline soluso as to bring all the ingredients into close ct before smelting, we obtain chromium at a neat in a perfect button, which is of course erated by phosphorus. It is extremely tedious luce potash so as to obtain potassium in a pure be enected. If we had it in our power t perfectly pure oxide of iron, and mix it wi fectly pure carbon, and exclude any other such as silex, from coming in contact w mixture, steel might thus be formed to per But as one of the first conditions in thus pre steel is the absence of all other matter excel carbon and pure oxide of iron, we may real doubt the possibility of producing good s these means, because on a large scale neither of iron nor carbon can be obtained sufficiently It is therefore necessary to produce metallic that form in which it has the least impurities, is, pure wrought iron,—and cement it in manner that other substances than those wh volatile cannot come in contact so as to penet mass. When iron melts by excess of heat converting box, it is changed into impure car of which steel cannot be made; in this flui it absorbs so much silex from the charcoal 

When melted galena is passed over red-hot pure iron, metallic lead and sulphuret of iron is produced; and when fluid carburet of iron (gray cast iron) is poured into fluid litharge, iron and metallic lead are produced. When an alloy of lead and tin is mixed with melted iron, the latter will combine with the tin and separate the lead. Gray cast iron, mixed with a silicate of iron, will reduce so much of the oxide of iron as its carbon indicates; this operation is often accidentally performed in the puddling-furnace of the iron-works.

From these speculations it is easy to infer the great importance of the composition of the slags for the purity of the metals produced. In all smelting operations, slags must be formed in order to remove the impurities of the ore; and when carbon or any other substance is combined with the metal produced, and that may be retained in the cinder when the metal passes through it, in most cases the carbon, &c. will change places with some substance in the slag. The metal is thus adulterated with the substance taken from the slag. This subject is of

extreme importance.

Separation by Weight.—In reducing metals from their ores, it must be the aim of the operator to form globules, and at the same time form such spaces through which they may descend. In a mixture of ore and carbon, if the latter is so fine as to prevent the descent of the metal, this may be perfectly reduced, and still no accumulation ensues: this happens particularly when an excess of carbon is used, and as this is inevitable in large operations, it is advantageous to select the coals in coarse parts. The larger these globules, the size of which is facilitated by coarse carbon, the faster their descent will

be. When small globules reach a mass of fluid slag, and are too small to penetrate it, they will remain on its surface, and even may be suspended within the body of it. This phenomenon happens frequently at blast-furnaces; -it may be, at those for smelting lead, copper or iron; a stiff slag will always retain metal in round grains, which is often found to amount to a considerable portion of all which is produced. If the slags are thrown away, this metal is entirely lost; but it may be recovered by pounding and washing the slags. At iron furnaces this loss amounts on an average to five per cent., often more: it is considerable at copper and lead furnaces, and in fact cannot be avoided in any smelting operation. The larger the globules of metal, the less are they liable to be retained by the slag. It is therefore disadvantageous to use too small coal, or form a stiff, tenacious slag.

Slags.—The form of slags, their fluidity and composition, is of so much importance to the metallurgist, that too much attention cannot be paid to this We shall here confine our remarks to operations on a large scale. The substances of which slags are formed are chiefly silex, as the acid, and the metallic oxides, as bases or alkalies. Besides silex, we find, however, carbonic acid, chlorine, sulphuric acid, fluorine, phosphoric acid, and others in the slags; also sulphur and phosphorus. The alkalies are chiefly, oxide of iron, the oxides of manganese, lead, and copper; the alkaline earths are clay, and such fixed alkalies as are brought into the mixture accidentally, either by the ore or by the fuel. The substances which are added to an ore, in order to separate the metal, are fluxes, of which the number is very limited, because considerations of

economy compel the smelter to confine his selections to a small number of minerals and artificial ingredients. The most common fluxes in use are limestone, oxides of iron, and iron pyrites; siliceous or ferruginous slates and shales; clay; fluor-spar; black manganese; common salt; and a few other aubstances.

Fusibility of Slags.—The degree of heat at which slags melt is very different for different compositions, and ranges, as remarked before, between the boiling point of water and the highest attainable heat.

When it is the object to liquefy silex, the only agents by which to do it effectually are potash, soda, lime, oxide of lead, oxide of iron, and manganese. The presence of phosphoric acid or chlorine will not add to the capacity of these substances for dissolving silex, but as their combinations with metals are very fusible, they increase the fluidity of the slag: this alludes particularly to those slags which contain an abundance of metallic oxides. It cannot therefore be the object to dissolve silex by any such acid, but to cause the bases to be more fluid, and by that means compel the imperfectly dissolved silex to float more freely in the slags. The application of other acids than silex is limited to low heats only, because they generally evaporate before certain combinations or reductions can be effected. Protoxide of iron is the substance most generally used for dissolving silex, not because of its fusibility, but because it can be obtained abundantly in every place, its cheapness being the cause of its general use. Lime is next in importance to oxide of iron as a flux, but it does not form quite as fusible a slag with silex as iron or manganese; and metals which cannot bear a high heat cannot be fluxed means of lime, magnesia, clay, and similar s The fusibility of sulphurets is in m stances. instances resorted to as a means to form slags, these cannot dissolve silex, and so far as the la substance is removed by sulphurets, it is only by being suspended in the fluid mass and rende more fluid. Yet all these heterogeneous substan may be united in a slag and form a perfectly f mass; and it is an important fact to be known metallurgical operations, that all compounds more fusible than single elements, and all slags crease in fusibility as their number of eleme This relates to metals and allovs as as to slags; and on this principle all operat must be conducted.

Lime and silex are not very easily melted: and silex show hardly any signs of melting; lime, clay, and silex melt very readily toget Protoxide of iron and silex form a fusible slag, when manganese, or lime, or soda, or potasl added, the fusibility of the slag is remarkably a In all cases the fusibility of a compo of various slags is greater than the mean fusibilit the whole, when considered as melted by th selves. If a compound of lime and silex melt 3000°, that of protoxide of iron and silex at 20 and that of a silicate of oxide of lead at 1000°, mean heat of the three, by which they will a when mixed together, is not  $\frac{3000+2000+1000}{2}=20$ as their various degrees indicate, but it may be 1500°, and in this case even lower than that. greater the number of elements in a slag, the n fusible it becomes; it is therefore of the utr importance in all smelting operations to mult

the kind of ores: this produces fusible slags and fusible metals. In smelting iron, copper, lead, and all other metals, these rules are very well known by experienced smelters, and attended to; still they are not so much observed at the furnaces as they should As foreign matter has a decided influence upon some metals, it requires extreme caution in the selection of fluxes for certain kinds of metal. flux which contains phosphorus will not in the least interfere with the quality of lead, but does great harm to iron, less to copper, and none at all to silver or gold. The presence of arsenic in an iron ore causes cast iron to be very short and hard, but it has a beneficial influence in making wrought iron: this substance cannot be removed from silver but by a tedious refining process: it acts in the same manner with lead. Sulphur is very injurious to iron and copper, but has no effect whatever on lead; silver and gold are more or less affected by its presence. The selection of fluxes must be therefore made with some discrimination and judgment in these respects.

Slags should be as fusible as the metal which is to be smelted with their assistance. If they are more refractory than the metal, the slag causes it to assume a heat by which more or less of it is evaporated. The slags must be so compounded that the flux which is added to the ore has more affinity for the foreign matter than for the oxide of the metal, or the metal itself which is to be produced. In the mean time the new compound formed by the flux and the foreign matter ought to be more fusible than the metal, so as to float down before the metal is perfectly melted. In some instances, namely, in those where the metal is to be carbonized, this rule

is not applicable, for it invariably removes the carbon from the metal. By means of such a fluid slag any kind of impurities may be removed from the metal when properly attended to. Another advantage of a fusible slag is the saving of fuel, for in this instance there is no need of raising the heat beyond the melting point of the metal.

Learned men have demonstrated that certain quantities of particular matter are required to form the most fusible compound. There is no doubt that certain laws regulate the formation of slags, which have evidently a strong bearing upon the results of metallurgical operations, but in smelting we cannot pretend to the niceties of the laboratory, and it is quite sufficient if we approach the laws strictly regulating this subject. When a slag is tough and tenacious it requires an alkali to make it more fluid; and if it is hard and brittle, inclined to chill, it requires an acid to flux it. In many cases the addition of other slags, so as to increase the quantity, causes the slag to be more fusible, and affords at the same time a protection to the metal. here allude to a few facts which indicate the importance of composition.

A slag taken from a blast-furnace for smelting iron, and which was composed of 50 silex, 17 alumina, 30 lime, and 3 protoxide of iron, melted by 2576°; but when the ingredients forming this slag were put together, finely powdered and mixed, and then exposed to heat, it required 3400° to form a slag of them. This shows how much more heat is required to melt a crude mixture than to melt a compound in which the particles are already arranged. It shows at the same time, that when the flux or a part of the flux is soluble in water, it ought

to be dissolved so as to bring it and the ore in close contact before exposing them to the influence of heat. Another composition of iron slags, which consisted of 58 silex, 6 clay, 2 protoxide of iron, 2 protoxide of manganese, 10 magnesia, and 22 lime, required the same heat as above for softening it, namely, 3400°. The heat by which it was kept in fusion was also similar to the above, namely, 2600°. Slag from a lead furnace, which was held in a fluid condition by a heat of 2400°, required 2650° for softening the ingredients of its composition. That slag was composed of 36.5 silex, 40.5 protoxide of iron, 8.5 alumina, 4. lime, 3. magnesia, 7.5 oxide of lead. A slag from a copper smelting furnace, for crude copper, contained 32.7 silex, 60.3 protoxide of iron, 7 alumina: this was held in a fluid state by 2400°, and required 2700° for melting the ingredients of which it was composed. We see here that the smaller the number of elements, the less readily a mixture melts.

In order to compare the above degrees of heat by which the slags are melted and kept in solution, with the degrees of heat by which metals melt, we annex the following: gold melts by 2000°, silver by 1870°, lead 630°, cast iron 2500° to 3000°, and platina 4580°.

General Reflections on Smelting.—In order to obtain a clear insight into smelting operations, it is necessary to analyze each process, and each part of that process, and observe what influence certain causes produce upon the metal. Here, as everywhere, it is difficult to reason from effect to cause, and therefore we follow the other way of arriving at conclusions. And if we apply the well-known laws of chemistry, with due regard to temperature, we

shall hardly ever fail of coming to correct conclusions in our experiments. Of the metals, copper has the strongest affinity for sulphur; then follow iron, tin, zinc, lead, silver, antimony, arsenic. here, copper has a stronger affinity for sulphur than iron, and still copper is desulphuretted by iron, simply because of the mass of iron present: if the latter does not predominate, sulphur cannot be removed from copper by iron. This is no exception to the law for disengaging sulphur, for it is very well known that affinity is increased by mass. The alkaline earths and fixed alkalies have still more affinity for sulphur than these metals; and still they cannot remove the sulphur from most of these metals. Sulphurets of zinc, copper, or iron, cannot be decomposed by melted potash, at least no metal is produced to any extent: galena may be reduced entirely by it. reason is, that metallic lead is more fusible than its sulphuret, and will separate at a lower heat than will melt the latter in potash. Sulphuret of copper, or iron, does not dissolve in potash. The latter absorbs some of the sulphur, but still leaves the metals with so much remaining as not to form pure metal. If the copper or iron were more fusible than the sulphuret suspended in the potash, it would coagulate, form globules, and separate in the metallic Some metals are not formed of sulphurets, even if an abundance of alkali is present, until carbon is brought in contact with them. Of this kind are lead, copper, and some others. forms sulphates of lead, and lime of galena, and only a small portion of metal is separated; but if carbon is added sufficient to decompose these sulphates, nearly all the metal may be obtained from its sulphuret. In some instances the fusibility of

two united substances is resorted to in order to dissolve the one only. Sulphurets are not soluble in chlorides, neither are silicates, phosphates, or borates, and still a silicate with some chlorides is extremely fluid: a sulphuret may be perfectly mixed with chloride in the heat of a grate-fire; but as soon as the mass is cooled and water poured on, both separate. The cause is here obvious: sulphurets and chlorides are both soluble in heat, but not in water, in which only the latter is dissolved: and as no affinity exists between the two, both separate very readily. Still this compound performs in its smelted condition all the services of a slag. Carbonate of soda is no solvent for any sulphuret; it will melt, and the sulphuret will melt; both may be mixed together, but no decomposition ensues; but if carbon is introduced, so as to decompose the carbonic acid and liberate the caustic soda, it will absorb sulphur and produce metal in many cases, provided the metal is fusible in the heat which is applied. Copper may be reduced by these means. Iron cannot be melted, at least but very imperfectly, under a cover of potash or soda, because these substances will evaporate before the metal is melted. If carbon or sulphur is present in the iron, we may succeed somewhat better, but still imperfectly. however, a phosphate is present, either in the iron or in the flux, and also carbon sufficient to reduce the phosphate, iron may be melted easily under a cover of potash or soda. The metal, of course, which is the result of this operation, is very brittle, and a phosphuret, but it is chiefly iron. There is not the slightest difficulty in removing any quantity of impurities from a metal by means of matter which has more affinity for these substances than the

metal itself. This implies always the condition that the metal should be fusible at the same degree of heat, or nearly, at which the slag is fusible; also

that it should not evaporate by that heat.

Sublimation. — Metals which are very volatile cannot be advantageously smelted; they are distilled, and in some cases sublimation is resorted to. is not the slightest difficulty in smelting zinc, under a cover of carbonate of soda and potash, with carbon. But such a flux is expensive; and when not closely attended to while fluid, the loss is greater than the value of the metal obtained. It is for these reasons found to be cheaper to mix the oxide or carbonate of zinc with carbon, and distil it; or to mix the zinc blende with iron, and perform the same operation. The heat applied in these processes is by far higher than it is in smelting, and may cause the use of ten times as much fuel; still it is asserted that distillation is cheaper than smelting. Mercury is frequently produced by simple sublimation, without the addition of flux or coal; so also is arsenic. in most instances, carbon and such substances as decompose the ore are added to it.

Refining.—Refining gold and silver is done in large or small reverberatory furnaces, of which the bottom forms a cupel. Copper or lead is refined in reverberatories by melting, and the addition of fluxes. Tin is purified in reverberatory furnaces, and also in iron pots, being stirred by wood so as to oxidize its impurities. Zinc is refined in the same manner and by the same means. Iron is refined in charcoal forges, in run-out fires, in reverberatories, and in puddling and reheating furnaces.

Liquefaction.—This is a delicate operation, but it is of great utility. Bismuth is obtained by liquefac-

If the ore of this metal is heated with proper fluxes and in a proper apparatus, to a degree of heat which will melt the bismuth only, it will flow out from the ore, and form metal without the rocky and foreign matter being converted into a fusible slag. Antimony may be obtained by the same means, and in fact every kind of metal, provided the remains of the ore do not melt partially, so as to enclose grains of metal in a refractory, pasty cinder. As a mode of refining, it is chiefly used in separating silver from copper. When 11 parts of lead are melted with 3 parts of argentiferous copper, and this alloy is cooled slowly, the lead and silver may be made to flow out from the copper and lead; and the fluid lead thus obtained contains all the silver. The mode of operation in this case is generally to melt lead and copper perfectly, then cool it slowly. The copper and lead alloy, being the most refractory of the compound, will crystallize first, and the silver and lead last. When this combination of lead and silver. and the combination of lead and copper, is heated in a proper apparatus, the first will flow out at a certain heat and leave the other, which remains as a skeleton of the form of the whole body of alloy. Impure tin is refined on the same principle: when a pig of tin is laid on the highest part of the sloping hearth of a reverberatory furnace, and gently heated, the pure tin flows out first, and leaves behind a skeleton of iron, copper, and other metals, which do not melt at a low heat, and which are removed. This principle may be applied for the separation of metals by filtration: when, for instance, alloy is brought upon a body of sand, bone-ashes, lime, or similar matter, and melted, the moist fluid of the metals in the alloy will flow out first, pass through

the sand, and a skeleton of the refractory metals will remain.

Crystallization.—Most of the metals crystallize readily; all of them crystallize by proper treatment. Antimony and iron are particularly distinguished for their power of crystallization. The alloys of metals are not so much inclined to form regular bodies, at least not at the same degree of heat: for these reasons alloys may be separated from the pure metal. The fluid metals act here on the same principle as a salt dissolved in water. This property of metals and alloys has led to a valuable refining process for silver. When argentiferous lead is melted and then slowly cooled, the pure lead will sooner crystallize than the alloy of silver and lead, and a part of the pure lead may be gradually removed by a skimmer, or drainer. No perfect separation ensues here, for the coagulated lead still contains silver, and the richer the alloy the more silver is contained in the crystallized lead. which contains but 10 ounces of silver in a ton of lead may be concentrated with little expense, to lead of 30 ounces of silver per ton. When these principles are intelligently applied, much may be expected of them in the way of refining metals.

Table of Squares, Cubes, and Fourth Power of Numbers.

	c cy ~q	<del></del>	Caoce, a	7000 1	Dai the A	. ower oj	ivumoers.
Root.	Square.	Cube.	ith Power.	Root.	Square.	Cube.	4th Power.
1	1	1	1 1	7	49	343	2401
1.1	1.51	1.831	1.4641	1.1	50.41	357-911	2541:1681
.3	1.44	1.728	2.0736	.3	51.84	373.348	2687:3856
.3	1.69	2.197	2.8561	.8	\$3.70	899.017	2839.8241
1 .4	1.06	2.744	8.8416	'4	84.76	405.234	2998-6576
.2	2.25	8.875	5.0025	•5	56.52	421.878	3163.8632
.6	2.20	4.000	6.5536	.6	87.76	438-976	3346.3176
7.8	2·89 3·24	4.013	8.3521	.7	59.29	456.533	3515-3041
.9	3.61	5.833 6.850	10.2876	.8	60 84	474.552	3701-4756
2	1 200	8	18.0321	9.9	62.41	493.039	3895.0081
2.1	4.41	0.361	19:4481	°.,	68-61	512 531:441	4096
1 .	4.84	10.048	23.4256	9	67:24	551.368	4904-6721
-3	5.80	12-107	27:8841	.3	68.89	871.787	4521:2176 4745:8221
1 .4	5.76	13.834	88-1776	1.4	70.86	503.204	4979-5836
.5	0.25	18-628	39.0625	1.5	72.25	614-135	8220.0632
1 .6	6.76	17.576	45.6976		73.96	636.056	8470.0816
•7	7.29	10 683	59'1441	.7	78.00	658.203	5728-9761
·8	7.84	21.025	61:4656	·š	77.44	681:472	5996-9536
.0	8'41	24.880	70.7281	9	79.31	704.969	6274.2141
3	9	27	81	9	81	729	6561
1.1	9.61	29.791	92.8521	1 '1	82.81	753-571	6857:4961
.3	10.34	83.768	104.8576	.3	84.64	778.688	7173-9296
.8	10.80	85.037	118.5921	•3	86.49	804.357	7479.5201
1.4	11.90	89.304	133.6336	14	88.30	830.284	7807:4896
*5	12.50 13.50	42'875	150.0625	.8	90.35	857:375	8075.0525
:6	18.60	40.050 50.053	167·9616	.6	92.16	884.736	8493.6656
1.7	14.44	54.872	208-5136	.7 .8	94.00	912-678	8751-9981
9	15-21	59.319	281:3441	٠,	96·04 98·01	941·192 970·299	9231:0816
149	16	64	256	10	100	1000	9308·9601
1 .	16.81	68-921	282-5761	.,	102.01	1030-301	10406-0401
9.	17.64	74.088	311 1696		104.04	1001.308	10624-3216
.3	18-49	79.507	841.8801	•8	106.00	1092.727	11255-0881
14	19.36	85 184	874.8096	•4	108-16	1124.864	11698-5856
1 .2	20.32	91.132	410.0625	•5	110.25	1157-625	12155-0625
-6	21.16	97.336	447.7456	.6	112.36	1191.016	12624.7696
1 .7	23.00	103.873	487.9681	.7	114.49	1225.043	13107-9601
.8	23.04	110.203	530.8416	.8	116.64	1259.712	13604.8896
.0	24.01	117.619	576-4801	.0	118.81	1295.029	14115'8161
5	25 26·01	125	625	11	121	1331	14641
1:1	27:04	132.651	676-5201	.1	123.31	1367-631	15180-7041
.3	28.00	140·608 148·877	731·1616 780·0481	.3	125.44	1404.928	15735-1936
1.4	20.16	157.464	850.3056	-4	127.69	1442'597	16314-7361
1 .5	30.25	166-375	915.0622	.5	132·25	1520.878	16899·6016
-6	31.36	175.616	989.4496	.6	134.20	1560-896	18106-3036
	32.40	185-193	1055-6001	1.7	136.80	1601-613	18749 9721
1.7	33.64	195-112	1181-6496	1 -6	130.54	1643.032	19387-7776
j ·ŏ	34.81	205.879	1311.7361	·ŏ	141.61	1685-159	20158-3021
16	36	216	1296	12	144	1728	20736
-1	37.21	226.081	1384.2841	•1	146-41	1771-561	21345-8881
.2	38.44	238.378	1477-6336	.3	148'84	1815-848	22253-4556
.8	30.60	250.047	1575 2961	•3	151.29	1860.867	22898-6641
1 4	40.96	263-144	1677.7316	•4	153.76	1906-624	23642-1376
.2	42.25	274.025	1785.0625	•5	156.25	1953-125	24414 0625
6:	43.86	287.496	1897:4796	.6	158.76	/ 3000.31g	/ 32304.1310 /
) <del>,</del>	44·89     46·24	300.763	2015-1121	7	101.50	2048.383	
/ % /		314.432	2138-1376	.8	163.84		
<u> </u>	-/·UI /	828.809	2266-7121	11 .0	166.4	1 / 3146.6	80 / 31,003.38

# PRINCIPLES & PRACTICAL APPLICATIONS OF MECHANIC POWERS.


MECHANIC Powers, or the Elements of Machinery, are certain simple mechanical arrangements whereby weights may be raised or resistances overcome with the exertion of less power or strength than is neces-

sary without them.

They are usually accounted six in number, viz. the lever, the wheel and axle, the pulley, the inclined plane, the wedge, and the screw; but properly two of these comprise the whole, namely, the lever and inclined plane,—the wheel and axle being only a lever of the first kind, and the pulley a lever of the second,—the wedge and the screw being also similarly allied to that of the inclined plane: however, although such seems to be the case in these respects, yet they each require, on account of their various modifications, a peculiar rule of estimation adapted expressly to the different circumstances in which they are individually required to act.

# l. THE LEVER.

Levers, according to mode of application, as the following,



are distinguished as being of the first, second, or third kind; and although levers of equal lengths produce different effects, the general principles of estimation in all are the same; namely, the power is to the weight or resistance, as the distance of the one end of the fulcrum is to the distance of the other end to the same point.

In the first kind, the power is to the resistance, as

the distance AB is to the distance BC.

In the second, the power is to the resistance, as the distance AB is to that of AC; and,

In the third, the resistance is to the power, as the

distance AB is to that of AC.

Rule, first kind.—Divide the longer by the shorter end of the lever from the fulcrum, and the quotient is the effective force that the power supplied is equal to.

Ex. 1. Let the handle of a pump equal 65 inches in length, and 10 inches from the shortest end to centre of motion; what is the amount of effective leverage thereby obtained?

$$65-10=55$$
, and  $\frac{55}{10}=5\frac{1}{2}$  to 1.

Ex. 2. Required the situation of the fulcrum on which to rest a lever of 15 feet, so that  $2\frac{1}{2}$  cwt. placed at one end may equipoise 30 cwt. at the other, the weight of the lever not being taken into account.

 $\frac{15 \times 2.5}{2.5 + 30} = 1.154 \text{ feet from the end on which the 30 cwt.}$  is to be placed.

The common steelyard, or Roman balance, as represented in fig. 1, Plate D, is a lever of the first kind, and so divided that one weight w, moved to or from the axis of motion, will equipoise and there indicate the weight of any article required to be known.

It is by the second kind of lever that the greatest effect is obtained from any given amount of power; hence the propriety of the application of this principle to the working of force-pumps, and shearing of iron, as by the lever of a punching-press, &c.


Rule, second kind.—Divide the whole length of lever, or distance from power to fulcrum, by the distance from fulcrum to weight, and the quotient is the proportion of effect that the power is to the weight or resistance to be overcome.


Ex. Required the amount of effect or force produced by a power of 50 fbs. on the ram of a Bramah's pump, the length of the lever being 3 feet, and distance from ram to fulcrum 41 inches.

3 feet=36 inches, and  $\frac{36}{4\cdot 5}$ =8, or the power and resistance are to each other as 8 to 1; hence  $50 \times 8 = 400$  ibs. force upon the ram.


The lever on the safety-valve of a steam boiler is of the third kind, the action of the steam being the power, and the weight or spring-balance attached the resistance; but in such application the action of the lever's weight must also be taken into account, and may be simply ascertained by such means as represented in fig. 2, Plate D, where A is a Salter's balance attached to the lever by a light line, immediately at the point of pressure on the valve, and which, raised by hand or otherwise, will indicate the lever's action at that point.

This is perhaps the most frequent application of the third kind of lever to mechanical advantage, and that in which great nicety is required in estimation of effect: hence observe, as in other levers, there are three distinct points that require to be particularly attended to; namely, the weight, fulcrum, and re-





sistance, as shown in the annexed diagram to illustrate this particular case.



Thus, suppose the weight to be placed on any one of the divisions, it is still the same weight, or 1; but because of the principle of the lever, the resistance is increased equal to the number of times the weight is distant from the fulcrum; consequently the action of the lever tends to press down the valve equal the sum of the weight and resistance, or the number of times the weight is distant from the resistance.

#### 2. THE WHEEL AND PINION, OR CRANE.

The mechanical advantage of the wheel and axle, or crane, is as the velocity of the weight to the velocity of the power; and being only a modification of the first kind of lever, it of course partakes of the same principles.

1. To determine the amount of effective power produced from a given power by means of a crane with known peculiarities.

Rule.—Multiply together the diameter of the circle described by the winch, or handle, and the number of revolutions of the pinion to 1 of the wheel; divide the product by the barrel's diameter in equal terms

of dimensions, and the quotient is the effective power to 1 of exertive force.

Ex. Let there be a crane the winch of which describes a circle of 30 inches in diameter; the pinion makes 8 revolutions for 1 of the wheel, and the barrel is 11 inches in diameter; required the effective power in principle, also the weight that 36 ibs. would raise, friction not being taken into account.

 $\frac{30 \times 8}{11}$  = 21.8 to 1 of exertive force; and 21.8 × 36 = 784.8 ibs.

2. Given any two parts of a crane, to find the third, that shall produce any required proportion of mechanical effect.

Rule.—Multiply the two given parts together, and divide the product by the required proportion of effect; the quotient is the dimensions of the other parts in equal terms of unity.

Ex. Suppose that a crane is required, the ratio of power to effect being as 40 to 1, and that a wheel and pinion 11 to 1 is unavoidably compelled to be employed, also the throw of each handle to be 16 inches; what must be the barrel's diameter on which the rope or chain must coil?

 $16 \times 2 = 32$  inches diameter described by the handle.

And  $\frac{32 \times 11}{40}$  = 8.8 inches, the barrel's diameter.

#### 3. THE PULLEY.

The principle of the pulley, or more practic the block and tackle, is the distribution of weigh various points of support; the mechanical advar derived depending entirely upon the flexibility tension of the rope, and the number of pulle sheives in the lower or rising block: hence, by I and tackle of the usual kind, as shown in fig. 3, the power is to the weight as the number of cords attached to the lower block; whence the following rules.

- 1. Divide the weight to be raised by the number of cords leading to, from, or attached to the lower block; and the quotient is the power required to produce an equilibrium, provided friction did not exist.
- 2. Divide the weight to be raised by the power to be applied; the quotient is the number of sheives in, or cords attached to the rising block.

Ex. Required the power necessary to raise a weight of 3000 lbs. by a four and five-sheived block and tackle, the four being the moveable or rising block.

Necessarily there are nine cords leading to and from the rising block.

Consequently  $\frac{3000}{9} = 333$  ibs., the power required.

Ex. 2. I require to raise a weight of 1 ton 18 cwt., or 4256 lbs.; the amount of my power to effect this object being 500 lbs., what kind of block and tackle must I of necessity employ?

 $\frac{4256}{500} = 8.51 \text{ cords}; \text{ of necessity there must be 4 sheaves}$ or 9 cords in the rising block.

As the effective power of the crane may, by additional wheels and pinions, be increased to any required extent, so may the pulley and tackle be similarly augmented by purchase upon purchase; two of the most useful of such applications being represented in figs. 3 and 4, Plate D, the first of which is known by the term runner and tackle, and the second by that of Spanish burton.

#### 4. THE INCLINED PLANE.

The inclined plane is properly the second elementary power, and may be defined the lifting of a load by regular instalments. In principle it consists of any right line not coinciding with, but laying in a sloping direction to, that of the horizon; the standard of comparison of which commonly consists in referring the rise to so many parts in a certain length or distance, as 1 in 100, 1 in 200, &c.,—the first number representing the perpendicular height, and the latter the horizontal length in attaining such height, both numbers being of the same denomination, unless otherwise expressed; but it may be necessary to remark, that the inclination of a plane, the sine of inclination, the height per mile, or the height for any length, the ratio, &c., are all synonymous terms.

The advantage gained by the inclined plane, when the power acts in a parallel direction to the plane, is as the length to the height or angle of inclination: hence the rule. Divide the weight by the ratio of inclination, and the quotient equal the power that will just support that weight upon the plane. Or, multiply the weight by the height of the plane, and divide by the length,—the quotient is the power.

Ex. Required the power or equivalent weight capable of supporting a load of 350 fbs. upon a plane of 1 in 12, or 3 feet in height and 36 feet in length.

$$\frac{350}{12}$$
 = 29.16 lbs., or  $\frac{350 \times 3}{36}$  = 29.16 lbs. power, as before.

Note.—The weight multiplied by the length of the base, and the product divided by the length of the incline, the quotient equal the pressure or downward weight upon the incline.

Table showing the Resistance opposed to the Motion of Carriages on different Inclinations of Ascending or Descending Planes, whatever part of the insistent weight they are drawn by.

				ĺ	Han	Hundreds.				
Tens		100	200	300	400	200	009	200	800	900
		10-	-005	-00333	-0025	.002	-00167	-00143	-00125	-00111
10	·	60600-	-00476	-00322	-00244	96100-	.00164	00141	.00123	-0011
20	.05	.00833	.00454	-00312	.00238	-00192	-00161	-00139	.00122	-00109
30	.0333	69200-	-00435	-00303	-00232	-00189	-00159	-00137	-0012	-00107
40	.025	.00714	-00417	-00594	.00227	-00185	-00156	-00135	-00119	-00106
20	-05		-004	-00286	-00222	-00182	-00154	-00133	81100-	-00105
09	9910-	.00625	-00385	.00278	-00217	-00178	-00151	-00131	-00116	-00104
20	.0143	·00588	.0037	-0027	-00213	-00175	-00149	.0013	00115	00103
80	.0125	-00555	-00357	.00263	.00208	.00172	-00147	-00128	-00114	-00102
06	-0111	.00526	.00345	-00256	-00204	9100-	.00145	-00126	-00112	.00100

Vote.—Although this Table has been calculated particularly carriages on railway inclines, it may with equal propriety be lied to any other incline, the amount of traction on a level 1g known.

# Application of the preceding Table.

1. What weight will a tractive power of 150 ibs. draw up an incline of 1 in 340, the resistance on the level being estimated at \$\frac{1}{2\cdot 0}\$th part of the insistent weight?

Added together=-00711

Then  $\frac{150}{00711}$  = 21097 ibs. weight drawn up the plane.

2. What weight would a force of 150 fbs. draw down the same plane, the friction on the level being the same as before?

Friction on the level = 00417
Gravity of the plane = 00294 subtract

=:00123

And  $\frac{150}{.00123}$  = 121915 fbs. weight drawn down the plane.

Example of incline when velocity is taken into account.

A power of 230 fbs., at a velocity of 75 feet per minute, is to be employed for moving weights up an inclined plane 12 feet in height and 163 feet in length, the least velocity of the weight to be 8 feet per minute; required the greatest weight that the power is equal to.

$$\frac{230 \times 75 \times 163}{12 \times 8} = \frac{2811750}{96} = 29288 \text{ ibs., or } 13.25 \text{ tons.}$$

Showing the ascent or descent per yard, and the corresponding ascent or descent per chain, per mile; and also the ratio. TABLE OF INCLINED PLANES,

Per	Per yard.	Per chain.	Per mile.	Ratio.	Per	Per yard.	Per chain.	Per mile.	Ratio.
In parts of an in.	In decls. of an inch.	Inches.	Feet.	One in	In parts of an in.	In decls. of an inch.	Inches.	Feet.	One in
-12	-0156	-344	2-29	2304	4	-4375	9.625	64.17	82
4	-0208	-458	3.06	1728		.2	11	73-33	72
- 6	.0312	189-	4.58	1152	9	-5625	12.375	82.5	64
-6	-0417	-917	6-11	864	7	-5833	12.833	85.56	62
-	-0625	1.375	9-17	929	a cope	9.	13.2	88	09
4	-0833	1.833	12-22	432	o-de	.625	13.75	91.67	28
-		2.5	14.67	360	cele	1999-	14.667	97-78	54
	.125	2.75	18-33	288	1	-6875	15-125	100-83	52
- 10	1991.	3.667	24.44	216	24	.7	15-4	102-67	51
0	.1875	4.125	27.50	192	- min	.75	16.5	110	48
- No	.5	4.4	29-33	180	- 4k	æ	17.6	117-33	45
-4+	.25	2.2	36.67	144	1 2	-8125	17-875	119.17	44
-	÷	9.9	44	120	de	-8333	18.333	122-22	43
9	-3125	6.875	45.83	115	e Hz	.875	19-25	128-33	41
-la	.3333	7.333	48.89	108	ol;	6.	19.8	132	40
rojuo	.375	8-25	55	96	7	-9167	20-167	134-44	39
000	7.	8.8	28.67	20	100	-9375	20-625	137.5	38
9	-4167	6.167	11.19	98			22	146.67	36

#### THE WEDGE.

The wedge is a double inclined plane, consequently its principles are the same: Hence when two bodies are forced asunder by means of the wedge in a direction parallel to its head,—Multiply the resisting power by half the thickness of the head or back of the wedge, and divide the product by the length of one of its inclined sides; the quotient is the force equal to the resistance.

Ex. The breadth of the back or head of a wedge being 3 inches, and its inclined sides each 10 inches, required the power necessary to act upon the wedge so as to separate two substances whose resisting force is equal to 150 lbs.

$$\frac{150 \times 1.5}{10} = 22.5$$
 fbs.

Note.—When only one of the bodies is moveable, the whole breadth of the wedge is taken for the multiplier.

#### THE SCREW.

The screw, in principle, is that of an inclined plane wound around a cylinder which generates a spiral of uniform inclination, each revolution producing a rise or traverse motion equal to the pitch of the screw, or distance between two consecutive threads,—the pitch being the height or angle of inclination, and the circumference the length of the plane when a lever is not applied; but the lever being a necessary qualification of the screw, the circle which it describes is taken, instead of the screw's circumference, as the length of the plane: hence the mechanical advantage is, as the circumference of the circle described by

the lever where the power acts, is to the pitch of the screw, so is the force to the resistance in principle.

Ex. 1. Required the effective power obtained by a screw of  $\frac{7}{4}$  inch pitch, and moved by a force equal to 50 fbs. at the extremity of a lever 30 inches in length.

$$\frac{30 \times 2 \times 3.1416 \times 50}{.875} = 10760 \text{ fbs.}$$

Ex. 2. Required the power necessary to overcome a resistance equal to 7000 fbs. by a screw of  $1\frac{1}{4}$  inch pitch, and moved by a lever 25 inches in length.

$$\frac{7000 \times 1.25}{25 \times 2 \times 3.1416} = 55.73$$
 ibs. power.

In the case of a screw acting on the periphery of a toothed wheel, the power is to the resistance, as the product of the circle's circumference described by the winch or lever, and radius of the wheel, to the product of the screw's pitch, and radius of the axle, or point whence the power is transmitted; but observe, that if the screw consist of more than one helix or thread, the apparent pitch must be increased so many times as there are threads in the screw. Hence, to find what weight a given power will equipoise:

Rule.—Multiply together the radius of the wheel, the length of the lever at which the power acts, the magnitude of the power, and the constant number 6.2832; divide the product by the radius of the axle into the pitch of the screw, and the quotient is the weight that the power is equal to.

Ex. What weight will be sustained in equilibrio by a power of 100 fbs. acting at the end of a lever 24 inches in length, the radius of the axle, or point whence the power is transmitted, being 8 inches, the

radius of the wheel 14 inches, the screw consisting of a double thread, and the apparent pitch equal # of an inch?

 $\frac{14 \times 24 \times 100 \times 6 \cdot 2832}{\cdot 625 \times 2 \times 8} = 21111 \cdot 55 \text{ ibs., or } 9.4 \text{ tons, the power}$ 

Note.—It is estimated that about one-third more power must be added to overcome the friction of the screw when loaded, than is necessary to constitute a balance between power and weight.

#### OF CONTINUOUS CIRCULAR MOTION.

In mechanics, circular motion is transmitted by means of wheels, drums, or pulleys; and accordingly as the driving and driven are of equal or unequal diameters, so are equal or unequal velocities produced: hence the principle on which the following rules are founded.

# 1. WHEN TIME IS NOT TAKEN INTO ACCOUNT.

Rule.—Divide the greater diameter, or number of teeth, by the lesser diameter, or number of teeth, and the quotient is the number of revolutions the lesser will make for 1 of the greater.

Ex. How many revolutions will a pinion of 20 teeth make for 1 of a wheel with 125?

125 + 20 = 6.25, or 61 revolutions.

Note.—Intermediate wheels of whatever diameters, so as to connect communication at any required distance apart, cause no variation of velocity more than otherwise would result were the first and last in immediate contact.

To find the number of revolutions of the last, to 1 of the first, in a train of wheels and pinions.

Rule.—Divide the product of all the teeth in the driving, by the product of all the teeth in the driven, and the quotient equal the ratio of velocity required.

- Ex. 1. Required the ratio of velocity of the last, to 1 of the first, in the following train of wheels and pinions; viz., pinions driving,—the first of which contains 10 teeth, the second 15, and third 18; -wheels driven, —first 15 teeth, second 25, and third 32.
  - $\frac{10 \times 15 \times 18}{15 \times 25 \times 32} = 225 \text{ of a revolution the wheel will make to 1}$ of the pinion.
- Ex. 2. A wheel of 42 teeth giving motion to one of 12, on which shaft is a pulley of 21 inches diameter, driving one of 6; required the number of revolutions of the last pulley to I of the first wheel.

 $\frac{12 \times 6}{12 \times 6} = 12.25$ , or  $12\frac{1}{4}$  revolutions.

Note.—Where increase or decrease of velocity is required to be communicated by wheel-work, it has been demonstrated that the number of teeth on each pinion should not be less than 1 to 6 of its wheel, unless there be some other important reason for a higher ratio.

#### 2. WHEN TIME MUST BE REGARDED.

Rule.—Multiply the diameter, or number of teeth in the driver, by its velocity in any given time, and divide the product by the required velocity of the driven; the quotient equal the number of teeth, or diameter of the driven, to produce the velocity reauired.

Ex. 1. If a wheel containing 84 teeth makes 20 revolutions per minute, how many must another contain to work in contact, and make 60 revolutions in

the same time?

$$\frac{84 \times 20}{60}$$
 = 28 teeth.

Ex. 2. From a shaft making 45 revolutions per minute, and with a pinion 9 inches diameter at the pitch line, I wish to transmit motion at 15 revolutions per minute; what at the pitch line must be the diameter of the wheel?

$$\frac{45\times9}{15} = 27 \text{ inches.}$$

Ex. 3. Required the diameter of a pulley to make 16 revolutions in the same time as one of 24 inches making 36.

$$\frac{24 \times 36}{16} = 54 \text{ inches.}$$

The distance between the centres and velocities of two wheels being given, to find their proper diameters.

Rule.—Divide the greatest velocity by the least; the quotient is the ratio of diameter the wheels must bear to each other. Hence, divide the distance between the centres by the ratio plus 1; the quotient equal the radius of the smaller wheel; and subtract the radius thus obtained from the distance between the centres; the remainder equal the radius of the other.

Ex. The distance of two shafts from centre to centre is 50 inches, and the velocity of the one 25 revolutions per minute, the other is to make 80 in the same time; the proper diameters of the wheels at the pitch lines are required.

 $80+25=3\cdot2$ , ratio of velocity, and  $\frac{50}{3\cdot2+1}=11\cdot9$ , the radius of the smaller wheel; then  $50-11\cdot9=38\cdot1$ , radius of larger; their diameters are  $11\cdot9\times2=23\cdot8$ , and  $38\cdot1\times2=76\cdot2$  inches.

To obtain or diminish an accumulated velocity by means of wheels and pinions, or wheels, pinions, and pulleys, it is necessary that a proportional ratio of velocity should exist, and which is simply thus at

tained:—Multiply the given and required velocities together, and the square root of the product is the mean or proportionate velocity.

Ex. Let the given velocity of a wheel containing 54 teeth equal 16 revolutions per minute, and the given diameter of an intermediate pulley equal 25 inches, to obtain a velocity of 81 revolutions in a machine; required the number of teeth in the intermediate wheel, and diameter of the last pulley.

$$\sqrt{81 \times 16} = 36$$
 mean velocity.  
 $\frac{54 \times 16}{36} = 24$  teeth, and  $\frac{25 \times 36}{81} = 11.1$  inches, diameter of pulley.

To determine the proportion of wheels for screw cutting by a Lathe.

In a lathe properly adapted, screws to any degree of pitch, or number of threads in a given length, may be cut by means of a leading screw of any given pitch, accompanied with change wheels and pinions; course pitches being effected generally by means of one wheel and one pinion with a carrier, or intermediate wheel, which cause no variation or change of motion to take place: hence the following

Rule.—Divide the number of threads in a given length of the screw which is to be cut, by the number of threads in the same length of the leading screw attached to the lathe; and the quotient is the ratio that the wheel on the end of the screw must bear to that on the end of the lathe spindle.

Ex. Let it be required to cut a screw with 5 threads in an inch, the leading screw being of  $\frac{1}{2}$  inch pitch, or containing 2 threads in an inch; what must be the ratio of wheels applied?

5+2=2.5, the ratio they must bear to each other.

Then suppose a pinion of 40 teeth be fixed upon for the spindle,—

 $40 \times 2.5 = 100$  teeth for the wheel on the end of the screw.

But screws of a greater degree of fineness than about 8 threads in an inch are more conveniently cut by an additional wheel and pinion, because of the proper degree of velocity being more effectively attained; and these, on account of revolving upon a stud, are commonly designated the stud-wheels, or stud-wheel and pinion; but the mode of calculation and ratio of screw are the same as in the preceding rule;—hence, all that is further necessary is to fix upon any 3 wheels at pleasure, as those for the spindle and stud-wheels.—then multiply the number of teeth in the spindle-wheel by the ratio of the screw, and by the number of teeth in that wheel or pinion which is in contact with the wheel on the end of the screw; divide the product by the stud-wheel in contact with the spindle-wheel, and the quotient is the number of teeth required in the wheel on the end of the leading screw.

Ex. Suppose a screw is required to be cut containing 25 threads in an inch, the leading screw as before having 2 threads in an inch, and that a wheel of 60 teeth is fixed upon for the end of the spindle, 20 for the pinion in contact with the screwwheel, and 100 for that in contact with the wheel on the end of the spindle;—required the number of teeth in the wheel for the end of the leading screw.

$$25 \div 2 = 12.5$$
, and  $\frac{60 \times 12.5 \times 20}{100} = 150$  teeth.

Or suppose the spindle and screw-wheels to be those fixed upon, also any one of the stud-wheels, to find the number of teeth in the other.

$$\frac{60 \times 12.5}{150 \times 100} = 20 \text{ teeth, or } \frac{60 \times 12.5 \times 20}{150} = 100 \text{ teeth.}$$

'able of Change Wheels for Screw Cutting, the leading screw being of \( \frac{1}{2} \) inch pitch, or containing 2 threads in an inch.

	Num	b. of h in	in	Nu	mber o	of teet	h în	io	Nu	mber o	f teetl	in
inch of screw.	Lathe spindle- wheel.	Leading screw- wheel.	Number of threads inch of screw.	Lathe spindle- wheel.	Wheel in contact with spindle-wheel.	Pinion in contact with screw-wheel.	Lending screw- wheel.	Number of threads inch of screw.	Lathe spindle- wheel.	When in contact with spindle-wheel.	Pinion in contact with screw-wheel.	Leading screw-
	80	40	81	40	55	20	60	19	50	95	20	100
1	80	50	81	90	85	20	90	191	80	120	20	130
1	80	60	83	60	70	20	75	20	60	100	20	120
4	80	70	91	90	90	20	95	$20\frac{1}{4}$	40	90	20	90
3	80	90	93	40	60	20	65	21	80	120	20	140
1	80	90	10	60	75	20	80	22	60	110	20	120
21	80	100	101	50	70	20	75	$22\frac{1}{2}$	80	120	20	150
23	80	110	11	60	55	20	120	224	80	130	20	140
3	80	120	12	90	90	20	120	234	40	95	20	100
34	80	130	124	60	85	20	90	24	65	120	20	130
31	80	140	13	90	90	20	130	25	60	100	20	150
34	80	150	131	60	90	20	90	$25\frac{1}{2}$	30	85	20	90
1	40	80	134	80	100	20	110	26	70	130	20	140
14	40	85	14	90	90	20	140	27	40	90	20	120
44	40	90	144	60	90	20	95	271	40	100	20	110
44	40	95	15	90	90	20	150	28	75	140	20	150
5	40	100	16	60	80	20	120	281	30	90	20	95
51	40	110	161	80	100	20	130	30	70	140	20	150
6	40	120	164	80	110	20	120	32	30	80	20	120
61	40	130	17	45	85	20	90	33	40	110	20	120
7	40	140	171	80	100	20	140	34	30	85	20	120
74	40	150	18	40	60	20	120	35	60	140	20	150
8	30	120	184	80	100	20	150	36	30	90	20	120

Table by which to determine the Number of Teeth, or Pitch of Small Wheels, by what is commonly called the Manchester principle.

Diametral pitch.	Circular pitch.	Diametral pitch.	Circular pitch.
3	1.047	9	•349
4	·785	10	.314
5	·628	12	.262
6	.524	14	.224
7	•449	16	.196
8	∙393	20	.157

Ex. 1. Required the number of teeth that a wheel of 16 inches diameter will contain of a 10 pitch.

 $16 \times 10 = 160$  teeth, and the circular pitch = 314 inch.

Ex. 2. What must be the diameter of a wheel for a 9 pitch of 126 teeth?

 $\frac{126}{9}$  = 14 inches diameter, circular pitch ·349 inch.

Note.—The pitch is reckoned on the diameter of the wheel instead of the circumference, and designated wheels of 8 pitch, 12 pitch, &c.

Strength of the Teeth of Cast-Iron Wheels at a given velocity.

Pitch	Thickness	Breadth	Strengt	h of teeth	in horse-po	wer, at
of teeth in inches.	of teeth	of teeth in inches.	3 ft. per second.	4 ft. per second.	6 ft. per second.	8 ft. per second.
3.99	1.9	7.6	20.57	27.43	41.14	54.85
3.78	1.8	7.2	17.49	23.32	34.98	46.64
3.57	1.7	6.8	14.73	19.65	29.46	39.28
3.36	1.6	6.4	12.28	16.38	24.56	32.74
3.15	1.5	6	10.12	13.50	20.24	26.98
2.94	1.4	5.6	8.22	10.97	16.44	21.92
2.73	1.3	5.2	6.58	8.78	13.16	17.54
2.52	1.2	4.8	5.18	6.91	10.36	13.81
2.31	1.1	4.4	3.99	5.32	7.98	10.64
2.1	1.0	4	3.00	4.00	6.00	8.00
1.89	-9	3.6	2.18	2.91	4.36	5.81
1.68	-8	3.2	1.53	2.04	3.06	3.08
1.47	.7	2.8	1.027	1.37	2.04	2.72
1.26	•6	2.4	\ •64	/ •86 '	\ 1.38 (	1.84
1.05	•5	2	/ .375	03.	1.75	, J.00

# teeth at a green pitch.

	inch		9	103	113	0	1	20	50	4	54	64	74	8	6	10	104	113	70	- C	23	50
	3 i	117	0	0	0	-	-	-	-	-	-	-	-	_	-	-	-	-	2	2	27	2
	24		18	9	10%	114	0.50	17	2	27	200	4	27	68	7	8	6	97	104	114	0.4	7
	24				0				-	-	-	-	-	-	-	-	-	-	-	_	2	C
	-			00/4	98	roles	-44		10/4	-	rola	-te	_	-	-100	ec)ar	-la	~	814	10	7	-10
	20					_	5		_	7	CV	4.3	4	4		~	•	~	~	٠.	=	=
	_		_	-	0	-	-	-	-	-	-	-	-	-	-	_	_	_	_	=	_	_
	24		74	77	00	98	10	103	113	6	0,5	1.00	22	3	C.)	44	54	9	6.5	7	80	89
			0	0	0	0	0	0	0	-	-	-	-	-	-	-	-	-	-	-	-	-
	24	ches.	63	74	8	180	9	104	102	111	0.4	08	-10	2	24	331	4	43	25	61	64	L'
	24	Ē.	0	0	0	0	0	0	0	0	-	-	_	-	-	-	-	-	-	-	-	-
es.	2 inch	Diameter at the pitch circle in feet and inches	64	7	NAME OF	00	6	98	104	103	113	03	040	13	01	28	6.5 Sp	33	44	54	54	64
nch de	2	lee	0	0	0	0	0	0	0	0	0	-	-	-	-	-	-	-	-	-	-	-
Pitch of the teeth in inches	14	e in	9	9	120	140	80	6	98	104	10%	II a	0	0.3	18	1	200	22	50	44	48	5,0
eth		2	0	0	0	0	0	0	0	0	0	0	-	-	-	-	-	-	-	-	-	-
he te	00 4	tch c	10	3	649	ooko L'	74	200	6	98	01	108	114	113	03	03	14	2	23	60	500	4
5		'E	0	0	0	0	0	0	0	0	0	0	0	0	-	-	-	-	-	-	-	-
tch o	union	the	5	54	68	63	rolz L	77	1000	18	98	92	103	11	113	0	0	-	-	2	23	m
Pit		4	0	0	0	0	0	0	0	0	0	0	0	0	0	-	-	-	-	-	-	-
	101	mete	4	S S	52	64	63	7	1	18	00 00	16	98	10	108	11	111	0	0	-	14	17
	FI	Dia	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	-	-	-	-	-
	mion		44		SIS.	C)	64	68	1	100	00	000	83	94	95	10	104	11	113	117	0	80
	П		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	-	-
	-44		4	4	4	54	20	9	68	64	7.	-100	00	00 00	80	8	91	10	103	10%	114	115
			0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	-izo		100	4	4	4	2	Sign Sign	500	64	19	62	7	1	77	8	30	6	16	98	10	103
	-		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	inch		34	33	37	7	44	44	25	23	53	9	68	63	-	roix.	Name of	00	84	200	6	16
	1 ir	ŲΙ,	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Table of the Diameters of Wheels—continued.

					_																
		3 inch		44	7	3	7	8	6	101	114	3	14	2	3	4	2	9	-	7.5	,
		ಣ		0	8	8	0	<b>~</b>	0	8	01	က	က	က	က	က	60	67	က	m	•
		24		24	3	4	44	3	9	7	8	6	ğ	3	7	*	=	2	3	4	
		"		63	8	67	8	~	8	8	~	~	~	~	~	m	62	60	62	60	
				_	*	-	7	_	*	-	-	-4	_	-	-44	rolu	-	•	ale	-	_
		2		_											œ	6	2	=	Ξ	0	٠
I				-2	_		8	~	~	63	~	8	~	27	67	64	67	~	2	<b>m</b>	-
		77		6	ਟੁ	=	H	Ö	_	C4	2	Š	4	4	2	9	3	7	*	6	;
Ì				_	_	_	_	~	8	01	8	07	03	~	<b>C</b> 4	2	8	~	~	01	
Ì		_	3	<b>8</b>	6	₹6	7	_	12	-	_	14	23	62	33	-	2	200	*	-	•
		<b>2</b>	inc	_	_	_	_	7	_	~	~3	~1	~	~							•
		ا ۾	ם	-	1004	roles	,	-	-4	7	-	-		_	=		2	-	64		-
	þe	2 inch	# H	7	-	00	6	9	2	2	Ξ	0	9	_	2	22	8	4	4	3	•
	Ĭ.	2	, <u>s</u>	_	_	_	_	_	~	_	_	0	0	01	N	8	63	8	0	03	
	Pitch of the teeth in inches.	1,5	Diameter at the pitch circle in feet and inches.	9	<del>5</del> 9	7	7	8	6	6	0	8	=	7	7	_	-	7	2,	3	ï
	et.	-	ırcı	_	_	_	_	_	_	_	Ξ	$\Box$	Ξ	Ξ	~	2	~	~	~	~	
	e t	-	РС	-	-200	7	19		-	80	<b>₹8</b>	-4	4	*0 0	700		-		<del>,                                    </del>	-	
	ftb	*	itc	٠.			_	•		<b>&amp;</b>	œ	5	53	=	=	=	0	0	_		
ı	0 0	-	e l	Ξ	_	_	=	_	_	_	_	_	_	_	_	_	27	2	01	8	
	itel	18	#	8	4	4	Ş	Ç	9	3	7	7	8	8	6	8	Ѯ*	<u>*</u>	=	7	ı
ı	Ы		8	_	_	_	-	_	-	_	_	_	_	_	_	_	_	_	$\Box$	Ξ	
ı		_	et	25	75	Sept.	35	44	40	2	2	3	*	2	-400	20	400	6	~		
l		14	ig	_	_	_	_	_	_	_	_	_	_	_		٠.	٠.	٠.	٥.	=	
I		-	-	-		_	-40	_	-ola	-	_		_	Ξ	_	_	=	_	_	=	
		₩		_	_	61	8	က	က်	. 35.	4	4	ů	ÿ	9	9	9	77	-	80	
				_	_	_	_	=	_	_	_	_	_	_	_	_	_	-	-	_	
		14		0	0	*	#	#	<b>~</b>	233	2	3	3	4	4	4	2	5	9	39	
		-		_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	
		_		*	-40	-	-	-	-90	,	-44	-	·	rojec	mie		-40	-	_	=	
		*		2	=	=	=	0	0	_	_	_	8	~	~	က	3	3	4	4	
		-			-	•		_		_	_	_	=	_	_		_	_	_	_	
		inch		6	6	10.	10,	107	<u>∓</u>	] ]	11.3	6	0	0	_	-	4	<b>~</b>	2	2	
l.		_	_	0	0	0	0	0	0	0	0	_	_	-	_	_	_	_	_	_	
	or of h.	dm 1901		30	3	6	9 60	3 6	, e	3 4	9,	200	200	6		6	14	**	52	4.	

10-12234505C8860010123554505586 **3000000000000000000000000000** _____ .______ 44557846568666667465746

Table of the Diameters of Wheels—continued.

	3 inch		4	NO.	63	7	8	94	104	=	0	-	64	23	34	43	5.4	6.5
	က		9	9	9	9	9	9	9	9	-		-	-	-	-	1	-
	75		10	103	113	0.50	13	22	31	4	2	54	63	7	8	6	104	115
			73	10	10	9	9	9	9	9	9	9	9	9	9	9	9	9
	\$ <del>7</del>		35	44	5	9	63	7	8	94	10	103	114	08	-	2	23	3
		1113	~	•	2	53	*	*3	2	2	*0	2	~	9	-	-	9	_
	24		94	10	103	111	0	0,4	7	2	63	34	4	5	5,4	6	7	80
		25	4	4	4	4	2	10	5	2	0	10	0	b	10	5	20	10
	24	ches	63	64	7	8	00	9	104	104	111	6	20	-	24	27	34	44
		d ii	*	4	4	4	4	4	4	4	4	5	10	5	10	'n	10	20
neo.	2 inch	t an	8	34	44	14	53	6	63	7	8	8	94	16	103	113	113	0
Ting ting	62	fee	4	*	*	4	4	4	4	4	4	4	4	4	4	4	4	10
rich of the techn in inches	18	Diameter at the pitch circle in feet and inches	111	0 %	3	75	24	233	3	37	4	10	10 20	64	1	74	8	8
200		irc	3	4	4	4	4	*	4	4	4	4	4	4	4	4	*	4
200	mier	tch	83	91	6	10	103	#	111	0	-	19	23	23	3	33	4	44
5		d p	3	es	3	3	63	3	3	*	4	4	4	4	4	4	*	4
INCH	inian	at the	NO.	52	68	64	4	7	8	6	9	10	103	Ξ	113	70	90	7
4		ra .	3	8	3	က	က	3	က	e	3	3	က	3	3	4	4	4
	-67	amet	24	22	34	3	4	44	5	25	9	63	-	73		00	8	98
		Ä	8	3	က	3	8	3	3	3	3	3	3	3	3	3	3	3
	voice F		=	111	111	08	000	77	-	2	23	22	37	32	44	44	54	54
	1		CI	04	CI	3	3	3	3	3	3	3	3	3	3	3	3	3
	+1		2	8	88	6	98	94	104	104	=	113	113	10	80	7	7	14
			63	C)	21	21	N	01	23	C	01	63	2	43	3	3	3	3
	-400		140	2	10	Spiral spiral	9	63	63	7	70	1	84	89	87	16	6	10
			23	2	27	21	27	21	21	23	_	_	_			_		_
	inch		12	42/4	21	22	23	60	33	35	4	4	A.	4.2	5	5.5	54	<b>#9</b>
	-		2	2	27	2	27	2	21	C)	C1	CI	C)	63	23	C)	63	01
	eeth mpe		80	81	82	83	84	85	98	18	88	68	06	91	92	93	94	95

# FRICTION.

FRICTION is an effect produced by bodies rubbing one upon another, which acts as a retarding influence in the motion of all mechanical contrivances, but might not unfrequently be considerably diminished by a due regard to its laws, and a proper attention to the selection of those materials on which a uniform smooth surface may be attained, and which, according to experiments, are least liable to tear or become hot, and cause a roughness to arise when in working contact.

Several doubts existed a few years since respecting the laws of friction; but those doubts were entirely removed through the experiments of Mr. G. Rennie, on his own account, and those of M. Morin, acting for and under the sanction of the French Government, from or by which the following laws have been fully

established.

1. That when no unguent is interposed, the friction of any two surfaces (whether of quiescence or of motion) is directly proportional to the force with which they are pressed perpendicularly together; so that for my two given surfaces of contact, there is a constant atio of the friction to the perpendicular pressure; nat is, a double pressure will produce a double amount friction, a triple pressure a triple amount, &c., of y other proportionate increase of the load.

2. That when no unguent is interposed, the amount the friction is in every case wholly independent of extent of the surfaces in contact; so that the force with which two surfaces are pressed together being the same, their friction is the same, whatever may be the extent of their surfaces of contact.

- 3. That the friction of motion is wholly independent of the velocity of the motion; that is, supposing two shafts or axles of equal bearings and of equal weights or pressures, but the one making 100 revolutions while the other makes but 50, the amount of friction in each is alike.
- 4. That when unguents are interposed, the amount of friction depends more upon the nature of the unguent than upon that of the surfaces of contact; and hence, that the nature of the unguent to be applied must be governed by the pressure or insistent weight. Mr. Rennie found, that with the unguents tallow and anti-attrition, on axles under a pressure of from 1 to 5 cwt., the friction did not exceed \(\frac{1}{36}\)th of the whole pressure; but when softer unguents were applied, as oil, hog's-lard, &c., the ratio of the friction to the pressure considerably increased; from which it is naturally inferred that the consistence of an unguenought just to prevent the bodies coming into contac with each other.

5. That the friction of metals, without a stratum unguent interposed, varies as their hardness, the ha metals producing less friction than the soft ones.

6. That without unguents, and within the limits 32½ lbs. pressure per square inch, the friction of h metals upon hard metals may very generally be  $\epsilon$  mated at about  $\frac{1}{2}$ th of the whole pressure.

7. That within the limits of their abrasion, the tion of metals is nearly alike; but from 1.66 cwt square inch to 6 cwt. per square inch, the resis increases in a very considerable ratio, being greatest with steel on cast iron, and the least brass on wrought iron.

# PRACTICAL PROPERTIES OF WATER AND AIR:

#### OR OF LIQUIDS AND FLUIDS IN GENERAL.

WATER is the most abundant liquid we possess, and air is the most abundant fluid,—their properties contributing largely to the subserviency of man, not only as the support of his existence, and the comforts of his domestic enjoyments, but because of inherent energies which render them exceedingly advantageous, both as an efficient and disposable source of motive

power.

By analysis it is ascertained that water is composed of the gases oxygen and hydrogen in a state of chemical union; its distinguishing properties, like that of other liquids, being incompressibility,* gravity, capability of flowing, and constant tendency to press outwards in every direction; also that of being easily changed by the absorption of caloric to an aëriform state of any required density or degree of elastic force: hence the principle of the hydraulic press, the waterwheel, the steam engine, &c.

Atmospheric air, like water, is also a gaseous compound: of 100 parts of air, reckoning by weight, 75.55 parts are nitrogen, 23.32 oxygen, and 1.13 carbonic acid and watery vapour; and in such proportions

* Exact experiments have determined that water is not entirely incompressible, but the degree of compressibility is so small, being only about 464 millionth parts per atmosphere, that the terms incompressible and non-elastic fluid are not at all in practice inappropriate.

it is most conducive to animal existence. It also in this state possesses many important mechanical properties, a few of which are the following; viz., gravity, fluidity, compressibility, force or pressure, and elasticity; also expansibility by rarefaction or heat; and it is because of the oxygen it contains that combustion By change of temperature in the atis supported. mosphere, currents and winds are created; hence the means by which vessels are enabled to make distant voyages; also the cause which produces circular motion through the medium of the sails of a wind-mill: and it may likewise be observed, that without the pressure of the atmosphere the common pump would be with-Such preliminaries, being properly conout effect. sidered, tend much to pave the way to an efficient knowledge of those elements, water and air, either as regards the production of or retarding mechanical effects in their application as motive power.

# 1. Effects produced by water in its natural state.

Because of liquids possessing the properties of gravity and capability of flowing freely in every direction, sides of vessels, flood-gates, sluices, &c., sustain a pressure equal to the product of the area multiplied by half the depth of the fluid, and by its gravity, in equal terms of unity.

But when a sluice or opening through which a liquid may issue is under any given continued head, the pressure is equal the product of the area multiplied into the height from the centre of the opening to the surface of the fluid.

Ex. 1. Required the pressure of water on the sides of a rectangular cistern 18 feet in length, 13 in width, and 9 in depth.

The terms of measurement or unity are in feet: I cubic foot of water = 62.5 fbs.: hence  $18 \times 9 \times 2 + 13 \times 9 \times 2 = 558 \times 4.5$  $\times$  62.5 = 156937.5 tbs.

Weight of water on bottom =  $18 \times 13 \times 9 \times 62.5 = 131625$  fbs.

Ex. 2. Required the pressure on a sluice 3 feet square, and its centre 30 feet from the surface of the water.

 $3 \times 3 \times 30 \times 62.5 \Rightarrow 16875$  ths. pressure.

The weight of water or other fluid is as the quantity, but the pressure exerted is as the vertical height; hence, as fluids press equally in every direction, any vessel containing a fluid sustains a pressure equal to as many times the weight of the column of greatest height of that fluid, as the area of the vessel is to the sectional area of the column.

Ex. Let a cubical vessel whose sides are each 4 square feet have a tube inserted 1 inch in diameter and 6 feet in height, and let both vessel and tube be filled with water; required the whole weight of the water therein contained, and also the whole pressure exerted in tending to burst the vessel.

Cubic contents of the vessel = 8 feet, and each foot = 62.5 hs.

(see page 55).

Then,  $62.5 \times 8 = 500$ . Area of pipe's section = .7854 inches and height 72 in., also a cubic inch of water = 03617 fbs.; hence  $.7854 \times 72 \times .03617 = 2$  ths. +500 = 502 ths. total weight of the water.

Again, the whole height of the column = 96 inches; then  $\cdot 7854 \times 96 \times \cdot 03617 = 2.33 \text{ fbs. pressure of column on}$ an equal area. 144 square inches = 1 square foot, and  $144 \times 4 \times 6$  sides = 4400.4 times the area of the pipe's .7854

diameter in the whole surface; therefore 4400.4 x 2.33 = 10253 ibs., or total amount of pressure exerted.

Upon the preceding principles of water rests utility of the hydraulic press. Thus, into a uniforcylinder of suitable strength is fitted a piston or a moveable in a parallel direction, around which are a perly fitted leather collars, to prevent any possible of the water's escape; the water being injected means of a force-pump, and, by its non-compression property, repelling the ram with a force equal to number of times the end of the ram exceeds the softhe pump.

Ex. Required the repulsive force of a 6-inch r when a power of 50 lbs. is applied to the end of lever, which is as 12 to 1 in effect, and the diam of the pump or plunger 4ths of an inch.

Area of ram  $=\frac{28\cdot2744}{\cdot6013}=47$ ; and  $50 \times 12 \times 47 = 28200$  ibs., or 12 tons nearly.

When a body is partly or wholly immersed in we or other fluid, the vertical pressure of the fluid te to raise the body with a force equal to the weight the fluid displaced; hence the weight of any placed quantity of a fluid by a buoyant body equation that body.

Ex. 1. Suppose a vessel with all its masts, storand general equipments is found to displace 35, cubic feet of sea water, what is the whole weight the vessel?

Sea water average 64 hs. per cubic foot.  $\frac{35000 \times 64}{2240} = 1000 \text{ tons},$ 

Ex. 2. What must be the thickness of sheet i whereby to form a rectangular vessel 5 feet in leng 2 in width, and 1½ in depth, that will just sin

iches in common water; laps, seams, and rivets not eing taken into account?

5 ft. or 60 in. 
$$\times$$
 15 = 900  $\times$  2 = 1800 in. or sum of the sides.  
, 60 ,  $\times$  15 = 1440 , bottom.  
2 , 24 ,  $\times$  15 = 360  $\times$  2 = 720 , ends.

And 3960 x 281 (see page 30) = 1112.7, the divisor.

Then 60 in. x 15 x 3 x 03617 = 156.254 ibs. of water to displace.

Hence  $\frac{156\cdot254}{1112\cdot7}$  = 14 in., the thickness of iron required.

The resistance by which a moving body is opposed 1 passing through water is as the square of the body's elocity; hence, if a body be propelled at a certain elocity by a known power, to double that velocity rill require four times the power; to triple it, nine imes the power, &c.

Water in flowing through an orifice or aperture der any given head, is governed by the same law gravity as that of a solid body in vacuo descending ough the same space, or falling from an equal ght; but as friction is created by the motion of hard bodies in contact, so is friction also created the action of the water in passing through the ce or aperture: hence an aperture twice the width nother will discharge more than a double quantity, use of the area advancing in a much greater ratio at of the resistance. Thus, suppose an opening square feet be required: in a circular form its eter would be about 2 feet 3 inches, and its cirrence, or cause of friction, 7 feet; in a square 2 feet by 2 feet, and the amount of its sides : but in a rectangular form, 4 feet in length in breadth, the cause of resistance is increased to 10 feet; thus showing that the circular form is that which ought to be adopted in preference to any other for the conduction of water where practicability will admit.

When water issues out of a circular orifice in a thin plate at the bottom or side of a reservoir, the issuing stream tends to converge to a point at the distance of about half its diameter outside the orifice. and this contraction of the stream reduces the area of its section from 1 to 619, or nearly \$ths. short parallel tube be attached, the vein of the stream is less contracted, and the area will equal '762. if the tube attached be the frustum of a cone whose greater end is the aperture, the length equal half the diameter of the aperture, and the area of the small end to the area of the larger as 1 to 1.6, there will be no contraction of the vein: hence the propriety of making the pipe in this form from a reservoir or other head of water through which the greatest quantity, according to its area, is required to pass.

To find the velocity of water issuing through a circular orifice at any given depth from the surface.

Rule.—Multiply the square root of the height or depth to the centre of the orifice by 8.1, and the product is the velocity of the issuing fluid in feet per second.

Ex. Required the velocity of water issuing through an orifice under a head of 11 feet from the surface.

 $\sqrt{11} = 3.3166 \times 8.1 = 26.864$  feet, velocity per second.

In the discharge of water by a rectangular aperture in the side of a reservoir, and extending to the surface, the velocity varies nearly as the square root of the height, and the quantity discharged per second equal ards of the velocity due to the mean height, allowing for the contraction of the fluid according to the form of the opening, which renders the co-efficient in this case equal to 5:1; whence the following general rules.

- 1. When the aperture extends to the surface of the fluid. Multiply the area of the opening in feet by the square root of its depth also in feet, and that product by 5·1; then will ‡rds of the last product equal the quantity discharged in cubic feet per second.
- 2. When the aperture is under a given head. Multiply the area of the aperture in feet by the square root of the depth also in feet, and by 5·1; the product is the quantity discharged in cubic feet per second.
- Ex. 1. Required the quantity of water in cubic feet per second discharged through an opening in the side of a dam or weir, the width or length of the opening being  $6\frac{1}{2}$  feet, and depth 9 inches, or .75 of a foot.

Square root of .75 = .866. Then  $\frac{6.5 \times .75 \times .866 \times 5.1 \times 2}{3} = 14.3839$  cubic feet.

Ex. 2. What would be the quantity discharged through the above opening if under a head of water 4 feet in height?

Square root of 4=2, and  $2 \times 5 \cdot 1 = 10 \cdot 2$  feet velocity of the water per second.

And  $6.5 \times .75 \times 2 \times 5.1 = 49.725$  cubic feet discharged in the same time.

PRACTICAL RULES BY WHICH TO DETERMINE THI NECESSARY HEAD, AND QUANTITY OF WATER DISCHARGED THROUGH CIRCULAR PIPES IN A GIVEN TIME.

Rule 1.—To the product of the pipe's length in feet, multiplied by the square of the quantity requires in cubic feet per second, add the product of 50 time the pipe's diameter in feet, multiplied into the squar of the required quantity per second; divide the sun by the product of 1542 133 into the fifth power of the diameter, and the quotient equal the head in feet to produce the velocity required.

Rule 2.—Multiply 1542·133 times the fifth power of the pipe's diameter in feet by the head of water in feet, and divide the product by the sum of the pipe's length and 50 times its diameter; the square root of the quotient equal the quantity discharged in

cubic feet per second.

Ex. 1. Required the head of water necessary to produce a velocity of 2.988 feet, or 9.387 cubic fee per second, by a pipe of 2 feet in diameter and 180 feet in length.

$$\frac{\overline{9\cdot387^2\times180} + \overline{50\times2\times9\cdot387^2}}{1542\cdot133\times2^5} = \frac{15860\cdot8}{49348} = \cdot 5 \text{ of a foot head.}$$

Ex. 2. What quantity of water per second will be discharged through a pipe of 2 feet diameter and 180 feet in length, when pressed by a head of water 5 of a foot in height.

$$\frac{1542\cdot133\times2^{6}\times\cdot5}{180+50\times2} = \sqrt{88\cdot1219} = 9\cdot387 \text{ feet per second.}$$

And the area of the end of the pipe in feet, multiplied into the velocity, equal the quantity in cubic feet.

Note.—The above rules apply strictly only to straight pipes bends in a pipe diminish the velocity of a fluid equal to 003

times the sum of the sines of the several angles of inflection; hence, a bend in a pipe should not be sudden, and on no account should an angle be admitted.

Table of the Diameters of Pipes through which a required quantity of water may be discharged in a given time.

Cubic feet Diameter per minute. Diameter in inches.		Cubic feet per minute.		Cubic feet per minute.	Diameter in inches.
1	1	25	43	160	121
2	13	30	51	170	124
3	14	35	55	180	124
4	17	40	6	190	131
5	21/8	45	61	200	135
6	23	50	63	225	148
7	25	55	71	250	151
8	23	60	71	275	16
9	21	65	73	300	165
10	3	70	8	350	18
11	31	80	85	400	191
12	31	90	91	441	201
13	31	100	94	529	22
14	34	110	10	625	24
15	33	120	101	729	26
16	37	130	11	841	28
18	4	140	112	900	29
20	41	150	113	1000	30

The combined properties of gravity and fluidity which water possesses render it so available as a source of motive power; gravity being the property by which the power is produced, and fluidity that by which it is so commodiously qualified to the various modifications in which it is employed.

Water, it is ascertained, is subject to the same laws of gravity as those of solid bodies, and thereby accumulates velocity or effect in an equal ratio when falling through an equal space, or descending from an equal height: hence the velocity attained is as the

square root of the height of its fall; and is quite satisfactorily decided, that because of a clastic property of water, its greatest effect is when acting by gravity throughout its whole whether it be applied on a water-wheel, tu other machine, through which circular motion the immediate result.

In regard to Water-Wheels and other I through which motion is produced by the water, considerable discrepancy of opinion existed, both as to form and velocity, besid essential points requisite in gaining a max effect with the least possible strain; but there are now in a great measure removed throperiments by the Franklin Institute in added to those in France by Morin, and the of a patented machine by Whitelaw and Stirrland, combined with pertinent observations marks by interested parties in this as well as countries: hence have been deduced the ademonstrative conclusions.

- 1. That to gain a maximum of effect be zontal water-wheel, the water must be laid wheel on the stream side, and the diamet wheel so proportioned to the height of the the water may be laid on about  $52\frac{3}{4}$  degree from the summit of the wheel; or the height fall being 1, the height or diameter of the equal 1·108.
- 2. That the periphery of a water-wheel move at a velocity equal to about twice th root of the fall of the water in feet per sec the number of buckets equal 2.1 times the diameter in feet; also, that precautionary adopted for the escape of the air out of the

either by making the stream of water a few inches narrower than the wheel, or otherwise.

3. That because of water producing a less efficient power by impulse than gravity, turbines, or machines through which the motion is obtained by reaction, are greatly preferable to undershot, or low breast wheels.

4. That a head* of water is required sufficient to cause the velocity of its flowing to be as 3 to 2 of the wheel; ith of the wheel's diameter being an approximate height, near enough for practical purposes.

5. That the effective power of a wheel constructed according to these restrictions is equal to the product of the number of cubic feet, and velocity in feet per minute, multiplied into '001325.

#### Example for general illustration.

Suppose a fall of water 25 feet in height, over which is delivered 112 cubic feet per minute; required the various peculiar requisites for a wheel to be in accordance with the preceding rules.

1st.  $25 \times 1.08 = 27$  feet, the wheel's diameter.

2nd.  $\sqrt{25} \times 2 = 10$  feet, velocity of the wheelin feet per second. Also  $27 \times 2 \cdot 1 = 56 \cdot 7$ , say 57 buckets.

3rd. 27+9=3 feet, head of water required.

4th.  $112 \times 10 \times 60 \times 001325 = 89$  horses' power.

The turbine of Fourneyron, in France, and the patented Water-Mill of Whitelaw and Stirrat, Scotland, have of late years attracted a considerable share of public attention, their simplicity of construction and asserted effects in like situations being equal to those of the best applied water-wheels. In their manner of construction they differ, but in principle they are the same; the action of each being created by a centrifugal and tangential force, caused by the weight or impulsion of a column

* By head is meant the distance from the surface of the water to that point at which it strikes upon the wheel.


of water whose height or altitude is equal to twi the height of the fall due to the water's velocity and in order to produce a maximum of effect either the one or the other by the pressure as centrifugal force of the effluent water, it is nece sary that the emitting tubes, or helical channels the machine, be so curved that the apertures shall in a right line with the radius of the wheel.


In 1838 a number of experiments were made France by Morin, with a view to the more gener introduction of turbines, and a positive proof of the merited qualities in preference to wheels of impuls which terminated considerably in favour of turbine and from which the following deductions were made


- 1. That turbines are equally adapted to great as small falls of water.
- 2. That they are capable of transmitting a usef effect to from 70 to 78 per cent. of the absolute power
- 3. That their velocities may vary very considerable from the maximum effect, without differing very set sibly from it.
- 4. That they will work nearly as effectually who drowned to the depth of 5 or 6 feet as when free, at consequently, they will make use of the whole of the fall when placed below the level of extreme low water.
- 5. That they may receive variable quantities water without altering the ratio of the power to the effect. Corresponding results have also been realize by Whitelaw and Stirrat's machine: hence what said of the one is equally applicable to the other.


General Rule by Mr. Whitelaw, whereby to computhe power of their Turbine, or Water-Mill.


Rule.—Multiply the effective quantity of wat flowing in cubic feet per minute by the height of the fall of the water in feet, and divide the product by 700











John Weale 39 High Helborn 1858 .

e quotient equal the effect produced in horses' )wer.

Ex. Required the power produced by 1400 cubic et per minute over a fall of 30 feet.

$$\frac{1400 \times 30}{700} = 60 \text{ horses' power.}$$

Plates G and H exhibit miniature views of a ponrous overshot water-wheel, chiefly of wrought iron, id in which novelty of construction, immense diaeter, and great efficiency, have rendered it an object 'universal interest throughout the district in which is situated: its nominal power is that of 30 horses, at upwards of 40 of indicated resistance seems not aterially to diminish its velocity; and no doubt, on count of the improved form of the buckets, the eatest amount of the water's effect is obtained.

### Effects produced by water in an aëriform state.

When water in a vessel is subjected to the action fire, it readily imbibes the heat or fluid principle of hich the fire is the immediate cause, and sooner or ter, according to the intensity of the heat, attains a mperature of 212° Fahrenheit. If at this point of mperature the water be not enclosed, but exposed atmospheric pressure, ebullition will take place, ad steam or vapour will ascend through the water. arrying with it the superabundant heat, or that hich the water cannot under such circumstances of ressure absorb, to be retained and to indicate a higher mperature.

Water, in attaining the aëriform state, is thus uniormly confined to the same laws under every degree f pressure; but as the pressure is augmented, so is he indicated temperature proportionately elevated: ence the various densities of steam, and correspond-

ng degrees of elastic force.

Table of the Elastic Force of Steam, and corresponding Temperature of the Water with which it is in contact.

	ure per e inch,	Elastic	Force in	Tempera	ture in De	egrees of	Volume of Steam
atmospheric pressure included.		Inches of Mercury.	Metres of Mercury.	Fahr.	Reaum.	Cent.	with vol. of Water
lbs. 14.7	kilog. 6.668	30.00	-762	212.0	80.0	100.0	1711
15	6.80	30.60	-778	212-8	80.4	100.4	1670
16		32.64	-829	216.3	81.9	102.4	1573
17	7.26	34.68	-880	219.6	83.3	104.2	1488
18	7.71	36.72	-932	222.7	84.7	105.9	1411
19	8-16	38.76	984	225.6	86.0	107.6	1343
20	8.62		1.037	228.5	87.3	109.2	1281
21	9.07	40·80 42·84	1.089	231.2	88.5	110.7	1225
	9.52			233.8	89.7		
22	9.98	44.88	1.140	236.3	90.8	112·1 113·5	1174
23	10.43	46.92	1.244	238.7	91.9	114.8	1127
24	10.88	48.96	1.244	241.0	93.0	116.1	1084
25 26	11.34	51.00	1.348	243.3	93.9	117.4	1044
	11.79	53.04		245.5	94-9		1007
27	12.25	55.08	1.400			118.6	973
28	12.70	57.12	1.452	247·6 249·6	95·8 96·7	119.8	941
29	13.15	59.16	1.503			120.9	911
30	13.61	61.21	1.555	251·6 253·6	97·6 98·5	123.1	883
31	14.06	63.24	1.607		99.3	124.2	857 833
32	14.51	65.28	1.659	255.5			
33	14.97	67.32	1.711	257.3	100.1	125.2	810
34	15.42	69.36	1.763	259·1 260·9	101.7	126.2	788
35	15.87	71.40	1.814			127.2	767
36	16.33	73.44	1.866	262-6	102.5	128-1	748
37	16.78	75.48	1.918	264.3	103·2 104·0	129-1	729
38	17.23	77.52	1.970	265.9	7.5.	129.9	712
39	17.69	79.56	2.022	267.5	104.7	130.8	695
40	18.14	81.60	2.074	269.1	105.4	131.7	679
41	18.59	83.64	2.126	270.6	106.0	132.6	664
42	19.05	85.68	2.178	272.1	106.7	133.4	649
43	19.50	87.72	2.229	273.6	107.4	134.2	635
44	19.96	89.76	2.281	275.0	108.0	135.0	622
45	20.41	91.80	2.333	276.4	108-6	135.8	610
46	20.86	93.84	2.385	277.8	109-2	136.6	598
47	21.32	95.88	2.437	279.2	109-9	137.3	586
48	21.77	97.92	2.489	580.2	110.4	138.1	575
49	22·22 22·68	99.96	2.541		$\frac{5}{9}/111.1$	138.8	564

The preceding Table is peculiarly adapted for estimating the power of steam engines on the condensing principle, because in such the effective force of the steam is the difference between the total force and the resisting vapour retained in the condenser. The following Table is more adapted for estimating the effects of non-condensing engines, as, in such, the atmospheric pressure is not generally taken into account, engines of this principle being supposed to work in a medium; or, the atmospheric pressure on the boiler, to cause a greater density of steam, is equal to the resisting atmosphere which the effluent steam has to contend with on leaving the cylinder.

Table of the Elastic Force of Steam, the Pressure of the Atmosphere not being included.

1	lastic Force i	Tempera- ture in	of Steam	Cubic in. of Water in	
Atmosphere.	ths. speq. in.	in. of Merc.	degrees of Fahr.	Water being 1.	a cubic foot of Steam.
1.19	2.5	5.15	220	1496	1.14
1.22	3	6.18	222	1453	1.18
1.29	4	8.24	225	1366	1.25
1.36	5	10.3	228	1282	1.33
1.70	10	20.6	240	1044	1.64
2.04	15	30.9	251	883	1.93
2.38	20	41.2	260	767	2.23
2.72	25	51.5	268	678	2.52
3.06	30	61.8	275	609	2.81
3.40	35	72·1	282	553	3.09
3.74	40	82.4	288	506	3.38
4.08	45	92.7	294	468	3.66
4.42	50	103.0	299	435	3.93
4.76	55	113.3	304	407	4.20
5.10	60	123.6	309	382	4.48

Steam, independent of the heat indicated by an mmersed thermometer, also contains heat that cannot

be measured by any instrument at present known, and, in consequence of which, is termed latent or concealed heat; the only positive proof we have of its existence being that of incontestable results or effects produced on various bodies. Thus, if one part by weight of steam at 212°, be mixed with nine parts of water at 62°, the result is water at 178.6°; therefore, each of the nine parts of water has received from the steam 116.6° of heat, and consequently the steam has diffused or given out  $116.6 \times 9 = 1049.4 - 33.4 =$ 1016° of heat which it must have contained. Again, it is ascertained by experiment, that if one gallon of water be transformed into steam at 212°, and that steam allowed to mix with water at 52°, the whole will be raised to the boiling point, or 212°. From these and other experiments, it is ascertained that the latent heat in steam varies from 940° to 1044°, the ratio of accumulation advancing from 212°, as the steam becomes more dense and of greater elastic force: hence the severity of a scald by steam to that by boiling water.

It is because of the latent heat in steam, or water in an aëriform state, that it becomes of such essential service in heating, boiling, drying, &c. In the heating of buildings, its economy, efficiency, and simplicity of application, are alike acknowledged;—the steam being simply conducted through all the departments by pipes, by extent of circulation condenses, the latent heat being thus given to the pipes and diffused by radiation. In boiling, its efficiency is considerably increased if advantage be taken of sufficiently enclosing the fluid and reducing the pressure on its surface by means of an air-pump; thus, water in a vacuum boils at about a temperature of 98°, and in sugar-refining, where such means are employed,

the syrup is boiled at 150°.

Steam is also of great utility as a productive source of motive power; and in this respect its properties are, elastic force, expansive force, and reduction by condensation. Elastic force signifies the whole urgency or power the steam is capable of exerting with undiminished effect. By expansive force is generally understood the amount of diminishing effect of the steam on the piston of a steam engine, reckoning from that point of the stroke where the steam of uniform elastic force is cut off; but it is more properly the force which steam is capable of exerting when expanded to a known number of times its original bulk. And

Condensation, here understood, is the abstraction or reduction of heat by another body, and consequently not properly a contained property of the steam, but an effect produced by combined agency, in which steam is the principal; because any colder body will extract the heat and produce condensation, but steam cannot be so beneficially replaced by any other

fluid capable of maintaining equal results.

The rules formed by experimenters as corresponding with the results of their experiments on the elastic force of steam at given temperatures vary, but approximate so closely that the following rule, because of being simple, may in practice be taken in preference to any other.

Rule.—To the temperature of the steam in degrees of Fahrenheit, add 100, divide the sum by 177, and the 6th power of the quotient equal the force in inches of mercury.

Ex. Required the force of steam corresponding to a temperature of 312°.

$$\frac{312+100}{177} = 2.3277^6 = 159 \text{ inches of mercury.}$$

But the Table, page 242, is much better adapted to practical purposes, as the various results or effects are obtained simply by inspection.

To estimate the amount of advantage gained by using steam expansively in a steam engine.

When steam of a uniform elastic force is employed throughout the whole ascent or descent of the piston, the amount of effect produced is as the quantity of steam expended. But let the steam be shut off at any portion of the stroke, say, for instance, at one-half, it expands by degrees until the termination of the stroke, and then exerts half its original force; hence an accumulation of effect in proportion to the quantity of steam.

Rule.—Divide the length of the stroke by the distance or space into which the dense steam is admitted, and find the hyperbolic logarithm of the quotient, to which add 1, and the sum is the ratio of the gain.

Ex. Suppose an engine with a stroke of 6 feet, and the steam cut off when the piston has moved through 2; required the ratio of gain by uniform and expansive force.

6+2=3; hyperbolic logarithm of 3=1.0986+1=2.0986 ratio of effect; that is, supposing the whole effect of the steam to be 3, the effect by the steam being cut off at  $\frac{1}{3}=2.0986$ .

Again, let the greatest elastic force of steam in the cylinder of an engine equal 48 fbs. per square inch, and let it be cut off from entering the cylinder when the piston has moved  $4\frac{1}{2}$  inches, the whole stroke being 18; required an equivalent force of the steam throughout the whole stroke.

 $18+4\cdot5=4$ , and 48+4=12. Logarithm of  $4+1=2\cdot38629$ . Then  $2\cdot38629\times12=28\cdot635$  ths. per square inch.

2.30258

2.48490

2.63905

2.77258

2.89037

No. Logarithm. No. Logarithm. No. Logarithm. No. Logarithm. ·22314 31 1.25276 5<del>1</del> 1.74919 8 2.07944 81 2.14006 ·40546 34 1.32175 6 1.79175 61 ·55961 1.38629 1.83258 2.19722 91 .69314 41 1.44691 6<del>1</del> 1.87180 2.25129

67

71

72

7<u>1</u> -

1.90954

1.94591

1.98100

2.01490

2.04769

10

12

14

16

18

Table of Hyperbolic Logarithms.

11

14

14

21

21

21

3<del>1</del>

·81093

·91629

1.01160

1.09861

1.17865

44

44

5

5<del>1</del>

5<del>1</del>

1.50507

1.55814

1.60943

1.65822

1.70474

.2

In regard to the other case of expansion: When the temperature is constant the bulk is inversely as the pressure: thus, Suppose steam at 30 lbs. per square inch, required its bulk to that of original bulk, when expanded so as to retain a pressure equal to that of the atmosphere, or 15 lbs.

$$\frac{15+30}{15} = 3 \text{ times its original bulk.}$$

Condensation of steam for motive purposes, generally, is effected by cold water, the quantity of which may be estimated by the following rule. From 1000 plus the temperature of the steam, subtract the required temperature of the condensed water, divide the remainder by the temperature of the condensed water minus the temperature of the cold or condensing water, and the quotient equal the number of times that the quantity, for condensation, must exceed that by which the steam is formed.

Ex. Required the ratio or quantity of water for condensation to 1 of water for the formation of steam, the temperature of the steam being 220°, and the required temperature of condensed water 180°.

$$\frac{1000 + 220 - 180}{180 - 52} = 8 \text{ times the quantity.}$$

Water holding impurities in solution tends to retard its attaining the aëriform state, and so impairs the amount of its elastic force at an equal temperature, as exhibited in the following Tables. Thus, common water boils at 212° Fahrenheit.

Name of Substance.		ortionate quantity in 100 parts veight of water.	Boiling points. 213·2° F.	
Salts in sea water.		3.03.		
Sulphate of soda	$\overline{\cdot}$	31.5	213	
Sulphate of iron	water	64	216	
Alum	B A	<b>52</b>	220	
Sulphate of lime		45	220	
Sulphate of magnesia	сошшоп	57.5	222	
Muriate of soda	ā	30	224	
Nitrate of soda	8	60	246	
Acetate of soda	므	60	256	

Elastic Force of Steam in Inches of Mercury.

Common water boiling point, 212° F. elastic force 30 in Sea water . . . } boiling point, 212° F. elastic force 30 in 212° M. . . . . 23.05° M. Common water boiling point, 216° F. elastic force 32.5° in 24.6° M. Common water boiling point, 220° F. elastic force 35.1° in Sea water . . . } boiling point, 220° F. elastic force 35.1° in Sea water . . . }

Hence the propriety of procuring, for steam, water in its purest state.

## 3. Effects produced by air in its natural and also in a rarefied state.

The weight or pressure of the atmosphere is equal to the weight of a column of water 34 feet in height, or to a column of mercury 30 inches in height, or to 14.7 lbs. av. per square inch at a mean temperature. But air, like all other gases, is rendered lighter by

the application of heat, for then the particles of the mass are repelled from each other, or rarefied, and occupy a greater space. Rarefied air being specifically lightest, mounts above that of common density; hence change of temperature, and the principal cause of winds.

Table of the Expansion of Atmospheric Air by Heat.

Deg. of Fahr.	Bulk.	Deg. of Fahr.	Bulk.	Deg. of Fahr.	Bulk.
32°	1000	65°	1077	100°	1152
35	1007	70	1089	120	1194
40	1021	75	1099	140	1235
45	1032	80	1110	160	1275
50	1043	85	1121	180	1315
55	1055	90	1132	200	1364
60	1066	95	1142	212	1376

The pressure or gravity of the atmosphere being equal to a column of water 34 feet in height, is the means or principle on which rests the utility of the common pump, also of the syphon and all other such hydraulic applications. In a pump the internal pressure on the surface of the liquid is removed by the action of the bucket, and as by degrees the density becomes lessened, so the water rises by the external pressure to the above-named height; and at such height it will remain, unless by some derangement of construction taking place, the atmospheric fluid is allowed to enter and displace the liquid column. But observe, if the temperature of the water or other liquid be so elevated that steam or vapour arise through it, then, according to the vapour's accumulation of density, may the action of the pump be partially or wholly destroyed; and the only means of evasion in such cases is to place the working bucket beneath the surface of the liquid which is required to be raised.

250 PUMPS.

Table showing the quantity of Water per lineal foot in Pumps or Vertical Pipes of different diameters.

Diameter of pump in inches.	Number of gallons per lineal ft.	Number of cubic feet per lineal ft.	Diameter of pump in inches.	Number of gallons per lineal ft.	eubie feet
2	·136	-0218	8	2.176	•3490
21	·172	·0276	81	2.314	-3712
2 j	·212	.0340	81	2.456	3940
23	.257	.0412	84	2.603	4175
3	•306	.0490	9	2.754	•4417
31	.359	·0576	91	2.909	·4666
3 i	.416	.0668	91	3.068	·4923
34	·478	•0766	92	3.232	-5184
4	.544	•0872	10	3.400	*5454
44	·614	·0985	101	3.572	-5730
41	•688	·1104	101	3.748	-6013
44	.767	·1230	102	3.929	·6302
5	·850	·1363	11	4.114	•6599
54	.937	·1503	111	4.303	-6902
51	1.028	·1649	111	4.496	.7212
5%	1.124	·1803	112	4.694	·7529
6	1.224	·1963	12	4.896	·7853
61	1.328	.2130	121	5.312	·8521
61/2	1.436	•2304	13	5.746	·9217
64	1.549	•2489	13 <del>1</del>	6.196	·9939
7	1.666	.2672	14	6.664	1.0689
74	1.787	·2866	15	7.650	1.2271
71/2	1.912	•3067	16	8.704	1.3962
7 3 4	2.042	•3275	18	11.016	1.7670

### Examples illustrative of the Utility of the Table.

1. Required the quantity of water lifted by each stroke of the bucket of a  $9\frac{1}{2}$ -inch pump, the length of the stroke being  $2\frac{1}{4}$  feet.

 $3.068 \times 2.25 = 6.903$  gallons each stroke.

2. What length of stroke with a 6-inch pump will be necessary to discharge 44 gallons of water per

minute, the number of strokes being 18 in the given time?

$$\frac{44}{1\cdot224\times18} = 2 \text{ fest, the length of stroke.}$$

3. What must be the diameter capable of raising 25 cubic feet of water per minute, the length of the stroke being 2½ feet, and making 16 effective strokes per minute?

$$\frac{25}{2.5 \times 16} = .625$$
, or  $10\frac{3}{4}$  inches nearly.

It is by the oxygen of the atmosphere that combustion is supported. The common combustibles of nature are chiefly compounds of carbon and hydrogen, which, during combustion, combine with the oxygen of the atmosphere, and are converted into carbonic acid and watery vapour, different species of fuel requiring different quantities of oxygen. The quantity required for the combustion of a pound of coal varies from 2 to 3 lbs., according to the quality of the coal: 60 cubic feet of atmospheric air is necessary to produce 1 lb. of oxygen.

The pressure or fluid properties of the atmosphere oppose bodies in passing through it, the opposing resistance increasing as the square of the velocity of the body, and the resistance per square foot in its. as its velocity in feet per second, multiplied into 002288. Thus, suppose a locomotive engine in a still atmosphere, at a velocity of 25 miles per hour, presents a resisting frontage of 20 feet; required the amount of opposing resistance at that velocity.

25 miles per hour equal 36.67 feet per second.

Then 36.67² × .092288 × 20 = 61.5 tbs. constant opposing force.

Table of the Force and common Appellations given to Winds at different velocities.

Velocity of	Velocity of the Wind in		Force in ids.				
Miles per hour,	Feet per second.	avoirdupois per square foot.	Common Appellations given to the Wind.				
1	1.47	•005	Hardly perceptible.				
2 3	2·93 4·40	·020 ·044	} Just perceptible.				
4	5.87	•079	Gentle pleasant wind.				
5 10	7·33 14·67	·123 ·492	Genere bicasane wind.				
15	22.00	1.107	Pleasant brisk gale.				
20 25	29·34 36·67	1.968 3.075	Very brisk.				
30 ·	44.01	4.429	High winds.				
35 40	51·34 58·68	6·027 7·873	Linkii Minus.				
40 45	66.01	9.963	Very high.				
50	73.35	12.300	A storm or tempest.				
60	88.02	17.715	A great storm.				
80	117.36	31.490	A hurricane.				

In order to gain the greatest amount of the wind's impulsive effect to produce rotary or circular motion by the sails of a wind-mill, the total surface of the sails presented to the wind ought to be about \( \frac{7}{4} \)ths of the circle's surface which is formed by their motion, and each sail angled to the plane of motion as follows, the whip or back being divided into six equal parts.

Distance from centre of motion 1 2 3 4 5 6 Smeaton's Angle with plane of motion ... 18° 19 18 16 12½ 7 rule.

By G. Forrester, Liverpool ... 24° 21 18 14 9 3

# RULES, TABLES, &c., RELATIVE TO BOILERS AND THE STEAM ENGINE.

THE Boiler of a Steam Engine may be explained as that portion of the structure in which the vital principle of the engine is generated; consequently its construction is of the utmost importance, for upon the proper efficiency of the boiler depends in a great measure the efficiency of the engine.

Boilers not unfrequently, because of unavoidable peculiarities, are necessarily constructed of various forms; but for land or stationary engine boilers, if no thwarting circumstances intervene, either the waggon or cylindrical forms are commonly resorted to; the former for those of condensing engines, and the latter

for those of the high-pressure principle.

In the construction of boilers, much attention ought to be paid in avoiding thin films of water where the action of the fire is great, because it is neither consistent with safety, nor can there be the proper quantities of steam generated according to the surface exposed, unless under some extraordinary degree of pressure. Also convex surfaces, exposed to the action of the steam, unless properly supported, ought strenuously to be avoided. Large water spaces, concave surfaces, or straight plates securely stayed, with ample steam room, are the chief requisites to be attended to.

1. To determine the proper quantity of heating surface in a boiler for an engine with a cylinder of a given capacity, and steam at any density required.

Rule.—Multiply 375 times the area of the cylinder in feet by the velocity of the piston in feet per minute, and divide the product by the volume of steam to 1

of water at the density required (see Table, page 242), and the quotient is the amount of effective heating surface in square feet.

Ex. Required the amount of effective heating surface in a boiler for an engine whose cylinder is  $4\frac{1}{2}$  square feet in area, and the piston's velocity 224 feet per minute, the pressure of the steam to equal 5 lbs. per square inch above the pressure of the atmosphere.

 $\frac{375 \times 4.5 \times 224}{1282} = 295 \text{ square feet nearly; the fire-grate being}$ 

in accordance with the following rule.

Multiply the number of square feet of heating surface by 12, the product equal the area of fire-grate in square feet, thus:

 $295 \times 12 = 35.4$  square feet of furnace-bar.

Note.—By effective heating surface is meant horizontal surfaces over fire, flame, or heated air; vertical or side surfaces requiring about 1½ ft. to equal in effect 1 of horizontal surface.

- 2. To determine the proper dimensions for a waggonshaped boiler, when the amount of effective heating surface in square feet is obtained by the preceding rule.
  - 1. The bottom surface equal half the whole surface.
- 2. The length of the boiler equal twice the square root of bottom surface.
  - 3. The width equal one-fourth the length; and

4. The height equal one-third the length.

Ex. Required the dimensions for a boiler of the waggon form that may present an effective heating surface of 295 square feet.


Bottom surface = 295 + 2, or 147.5 square feet.

Length . . .=  $\sqrt{147.5} \times 2$ , or 24.26 feet. Width . . .= 24.26+4, or 6.06 feet.

Height . .  $= 24 \cdot 26 + 3$ , or 8.08 feet.

Note.—The amount of side or vertical surface equal twice





Lordon J. Weale 2853

ne length of the boiler, added to the width, and multiplied by '75 to obtain that of effective surface; hence,

 $\frac{147.5 \times 1.75}{24.26 \times 2 + 6.06} = 4.7$  feet, depth of side flue.

3. To determine the dimensions for a cylindrical oiler.

Rule.—Extract the square root of 1.34 times the ffective heating surface in square feet, and twice the oot equal the boiler's circumference in feet; also, he circumference equal the length.

Ex. Let a cylindrical boiler be required with an ffective heating surface of 86 square feet; what must e its length and diameter in feet?

 $\sqrt{86 \times 1.34} = 10.74 \times 2 = 21.48$  feet circumference, or 6 feet 10 inches diameter, and 21.48 feet in length.

Note.—When an internal flue is to be inserted in a boiler, he external surface of the boiler may be diminished in length, qual to half the exposed surface of the flue. Observe, also, hat the height of the contained water in boilers generally ught to be about §rds the whole height of the boiler.

Marine Engine Boilers have become so varied in heir designs, that any attempt at enumerating—by ver so slight a description—those that may be considered worthy of record, would much exceed the limits of my present purpose; but having been favoured by Messrs. Bury, Curtis, and Kennedy, with particulars of the boilers constructed by them for the 'Braganza' team vessel, and which have given the highest legree of satisfaction in every respect, I annex lesigns and data, in preference to those of any other lescription. (See Plate K.)

These boilers are constructed so as to work at 0 lbs. per square inch if required; they are four n number; the diameter of each cylinder is 62½ nches, length of stroke 5½ feet, or calculated velocity bout 231 feet per minute: the nominal power of each

engine is 140 horses, and the heating surface per horse-power is 14.1 square feet.

Now  $14.1 \times 140 = 1974$  square feet to each engine.


Then as per rule (page 253), 375 multiplied by the area of cylinder or 21 feet, and by the velocity per minute or 231 feet, and divided by 1044 (see Table, page 243) or volume of steam to 1 of water, at 10 ibs. per square inch, equal 1742 a square feet; to which add about 1th of the quotient, or 217.8, for side or vertical surface, equal 1960.2 square feet to each engine,—thus nearly corresponding with their given quantity of heating surface.

Note.—In the four boilers there are 608 brass tubes, 6½ feet in length, and 3 inches in diameter. The length of each fire-place is 5 feet 10 inches, and breadth 2 feet 10; there are '56 of a square foot of fire-bar to each cubic foot of cylinder capacity, and '16 of a square foot of tube aperture to each square foot of fire-bar, the openings of the tubes being reduced by the thickness of the tube hoops. The diameter of each chimney, of which there are two, is 3 feet 5 inches.


Locomotive Boilers, in the manner of their construction, are a class which, of necessity, demand the utmost degree of qualified attention, because of the great pressures they are required to sustain, and the unavoidably narrow limits in which such vast volumes of steam are required to be generated.

In boilers of this description, it is of the most essential consequence that the water spaces in the fire-box be of a sufficient width, say, on the back and sides, not less than  $2\frac{3}{4}$  to 3 inches, and in the front, where the tendency of the fire is urged by the action of the blast-pipe, at least  $3\frac{1}{4}$  inches.

The boiler which I have selected for illustration (see Plate L) is of the most modern description; and from an intimate knowledge of its performances, I am enabled to assert, with full confidence, that it possesses efficient and economical properties to the production of steam.



London: J. Weale, 1853.



pecified particulars relative to the Boiler and Engine	
Diameter of cylinders 14 inches.	
Length of stroke	
Lap of the valve	
Diameter of driving wheels 5 feet.	
Length of internal fire-box 2 feet 11 inches.	
Width of ditto 3 ,, 5 ,,	
Length of cylindrical part of boiler . 8 ,, 8 ,,	
Diameter of do 3 ,, 41 ,,	
Length of tubes 8 , 11 ,	
Number of tubes 133, of brass.	
Interior diameter of do 12 inches.	
Diameter of blast-pipe 4 ,,	
About 112 lbs. of coke consumed in this boiler	r
raporate 84 gallons of water; and from 20 to 25 lbs	
coke are consumed per mile.	

Heating Powers of Combustible Substances.

Species of combustible.	ibs. of water heated from 32° to 212°.	ibs. of boil- ing water evaporated by 1 lb. of fuel.	ibs. of atmospheric air to each ib. of fuel.
Wood in its ordinary state.	26	4.72	4.47
Wood charcoal	73	13.37	11.46
Coal	60	10.90	9.26
Coke	65	11.81	11.46
Turf	30	5.45	4.60
Turf charcoal	64	11.63	9-86

In regard to the giving of an order for a steam agine of any required number of horses' power, it as been argued and ultimately decided, that in a ammercial point of view the order is not sufficiently ampleted by the dimensions of cylinder, boiler, &c. eing of ample magnitude to produce the specified ynamical effect in horses' power; and not unless corsponding with the established custom by Boulton and Watt, or that of other manufacturers of equally ell known respectability: hence, generally, the fol-

lowing Tables may be better adapted to practice than even the most simple rule.

Table of Dimensions for Steam Engine Cylinders by celebrated makers.

Stationary Con- densing Engines, by Boulton & Watt.			Marine Engines, by Maudslay, Na- pier, &c.			High-Pressure, or Non-Condensing Engines, by various makers.				
Nominal horses' power.	Diameter of cylinders in Inches. Lengths of strokes in feet. Nominal horses' power. Of cylinders in inches.		Lengths of strokes in feet.	Nominal horses' power.	the for	meters of the per square 30 lbs.	e steam	being,		
6	141	3	10	20	2	1	34	31	3	25
8	161	3	15	24	21	3	51	48	41	33
10	18	31	20	27	24	3	61	6	5	41
12	191	4	25	291	23	4	71	63	6	51
14	21	41	30	32	3 34	5	81	71	61	5 7 6 1 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
16	221	44	40	36	34	6	9	81	71	61
18	231	5	50	40	4	7	94	9	73	64
20	241	5	60	43	4	8	104	93	81	7 1
22	26		70	461	41	9	111	101	83	77
24	27	51	80	471	41	10	113	11	91	81
25	271	51	90	50	43	11	124	113	93	83
26	28	53	100	53	5	12	13	12	101	91
28	29	6	110	551	$5\frac{1}{2}$	14	14	124	111	10
30	30	6	120	57	$5\frac{1}{2}$	16	15	134	12	104
35	321	61	130	603	53	18	153	141	123	111
40	341	61	150	65	6	20	163	151	131	113
50	381	7	200	741	6	25	181	171	15	13
60	421	7	250	84	6	30	201	193	161	141

The *unit* of nominal power for steam engines, or the usual estimate of dynamical effect per minute of a horse, called by engineers a horse-power, is 33,000 lbs. at a velocity of 1 foot per minute; or, the effect of a load of 200 lbs. raised by a horse for 8 hours a day, at the rate of  $2\frac{1}{2}$  miles per hour, or 150 lbs. at the rate of 220 feet per minute.

To estimate by means of an indicator the amount of effective power produced by a steam engine.

Rule.—Multiply the area of the piston in square inches by the average force of the steam in fits. and by the velocity of the piston in feet per minute; divide the product by 33,000, and \(\frac{1}{10}\)ths of the quotient equal the effective power.

Ex. Suppose an engine with a cylinder of 371 inches diameter, a stroke of 7 feet, and making 17 revolutions per minute, or 238 feet velocity, and the average indicated pressure of the steam 16.73 lbs. per square inch; required the effective power.

Area = 
$$1104.4687$$
 inches × 16.73 fbs. × 238 feet
$$= \frac{33000}{10} = 93.282$$
 horses' power.

To determine the proper velocity for the piston of a steam engine.

Rule.—Multiply the logarithm of the nth part of the stroke at which the steam is cut off by 2.3, and to the product of which add .7. Multiply the sum by the distance in feet the piston has travelled when the steam is cut off, and 120 times the square root of the product equal the proper velocity for the piston in feet per minute.

Ex. Let the steam be cut off in an 8-feet stroke when the piston has travelled 1th of the length; required its proper velocity.

Logarithm of 4=0.60206
Multiplied by 2.3
1.384738
70 which add 7
2.084738
2
4.169476 = 2.04 × 120 = 245 fee

 $\sqrt{4.169476} = 2.04 \times 120 = 245$  feet, velocity per minute.

Table of Approximate Velocities for the Pistons of Steam Engines.


Con	densing E	ngines.	Non-Condensing Engines.					
Length of stroke in feet.	in feet	Number of revolutions per minute.	of stroke	in feet	Number of revolutions per minute.			
2	160	40	11	186	62			
21	1774	354	2	200	50			
3	192	32	21	2121	421			
31	203	29	24	217 <del>1</del>	394			
4	214	262	3	222	37			
41	220 <del>1</del>	24	31	231	33			
5	230	23	4	236	291			
51	2361	211	41	243	27			
6	240	20	5	2471	242			
7	245	171	51	253	23			
8	256	16	6	264	22			

Of the Parallel Motion in a Steam Engine.


When the power from the piston is communicated by means of a beam or lever moving upon an axis, the parallel motion becomes a very important portion of the machine, for then it forms the link of connection, and by its properties renders the action of alternate circular motion and reciprocating vertical motion mutually agreeable, thereby properly insuring to the piston-rod a truly direct line to that of the cylinder: but to effect this, the greatest degree of exactitude of the various parts is required, otherwise extra friction is created, and the effective power of the engine proportionately diminished. (See Plates E and F.)

Fig. 1, Plate E, is a motion for a double-cylinder engine.


- ,, 2, ,, a motion for a pumping engine.
- " 3, " the common condensing engine.
- Fig. 1, Plate F, is for a marine engine.
  - " 2, " also for a marine engine.
- ,, 3, ,, for a non-condensing or high-pressure engine.



John Weale, 59, High Holborn 1863.



## PARALLEL MOTIONS.



John Weale, 50, High Holborn, 1853.

3.W.Lowry



ble by which to determine the various Distances of the Moveable Points in a Parallel Motion.

bars in ft.	Len of ra rod ft. 8	s in	Radius of beams in ft.	Parallel bars in ft.	ro	ngth adius ds in & in.	Radius of beams in ft.	Parallel bars in ft.	Le of ro	ength radius ds in & in.	Radius of beams in ft.	Parallel bars in ft.	Le of 1	ngth radius ds in & in.
14 15 54	2 1 0 1 0 0	0 48 103 67 4	64 feet	3 3 3 3 3 3 4 4 4	4 3 2 2 1 1	1 1 3 6 7 6 8 6 4 6 4 6 4 2 4	8½ feet	34 4 44 44 44 45 5	6 5 4 3 2 2	01 62 3 68 111 52	104 feet	5 5 5 5 5 6 6 6	6 5 4 3 3 2	0½ 3 6½ 11 3¼ 10¾
14	3 2 1	11/2	_	41 41	0	101		51 51	1	01 78		6± 6±	2 2	5 8 1
100	1 0 0	71 18 9 54	feet	3 3 3 3 3 3 4	5 4 3 3	4 6 23		4 44 44	6 5 4	3 34 6	feet	54 54 54	6 5 4	3½ 6 9½
14-19-24 14-19	4 3 2 1	6 43 6 101	7 fe	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1 1 0	278 3 9 458 978 988	9 feet	44 5 54 54 54 54	3 2 2 1	95 21 85 24 10	11 6	6 64 64 64	3 3 2	2 75 13 81 81
141	1	4 111 73		31 32 34	4	67		6	1	6		5½ 5¾	6 5	61 9
	4 3 2 2 1	8# 7# 9 1	74 feet	34 44 44 44 5 54	3 2 2 1 1 0	9 04 6 0 . 7 3	94 feet	4½ 4¾ 5 5¼ 5½ 5¾ 6	5 4 4 3 2 2 2	65 9 05 55 10 54 05	111 feet	6 64 64 7 74	5 4 3 2 2	0½ 5 10½ 4 10½ 6
-	0	13 97 10	_	3½ 3¾	5 4	9½ 9¾		44 5	5	91		54 6 61	6 6 5	81 0
34 - H - 10 m/4	3 2 1 1 1 1	0 37 91 41 0	8 feet	4 4 4 4 4 4 4 5	4 3 2 2 1	0 34 85 24	10 feet	5 1 5 1 5 1 6 6 1 6 1 6 1	3 3 2 2	0 3½ 8¼ 1¾ 8	12 feet	64 64 7 74	4 4 3 3 2	315 745 1 645 184 84
1	0	81		51	1	9 <del>§</del> 5‡		67 04	i	101		13		. 4

#### LOGARITHMS.

LOGARITHMS literally signify ratios of numbers; hence Logarithmic Tables may be various, but those in common use for the facilitating of arithmetical operations generally are of the following corresponding progressions, viz.

Arithmetical, 0, 1, 2, 3, &c., or series of logarithms. Geometrical, 1, 10, 100, 1000, &c., or ratio of numbers.

And thus it may be perceived, that if the log. of 10 be 1, the log. of any number less than 10 must consist wholly of decimals, because increasing by a decimal ratio. Again, if the log. of 100 be 2, the log. of any intermediate number between 10 and 100 must be 1, with so many decimals annexed; and in like manner, the log. of any intermediate number between 100 and 1000 must be 2, with decimals annexed proportionally, as before.

## APPLICATION AND UTILITY OF COMMON LOGARITHMIC TABLES.

The whole numbers of the series of logarithms, as 1, 2, 3, &c., are called the indices, or characteristics of the logarithm, and which must be added to the logarithm obtained by the Table, in proportion to the number of figures contained in the given sum. Thus, suppose the logarithm be required for a sum of only two figures, the index is 1; if of three figures, the index is 2; and if of four figures, the index is 3, &c., being always a number less by unity than the number of figures the given sum contains.

Ex. The index of 8 is 0, because it is less than 10. The index of 80 is 1, because it is less than 100.

The index of 800 is 2, because it is less than 1000.

The index of 8000 is 3, because it is less than 10,000, &c.

The index of a decimal is always the number which denotes the significant figure from the decimal point, and is marked with the sign thus —, to distinguish it from a whole number.

Ex. The index of 32549 is -1, because the first significant figure is the first decimal.

The index of 032549 is -2, because the first

significant figure is the second decimal.

The index of .0032549 is —3, because the first significant figure is the third decimal, and so on, of any other sum.

If the given sum for which the logarithm is required contains or consists of both integers and decimals, the index is determined by the integer part, without having any regard to the other.

1. To find the logarithm of any whole number under 100.

Look for the number under N in the first page of any Logarithmic Table; then immediately on the right of it is the logarithm required, with its proper index. Thus, the log. of 64 is 1.806180, and the log. of 72 is 1.857332.

2. To find the logarithm of any number between 100 and 1000, or any sum not exceeding 4 figures.

Find the first three figures in the left-hand column of the page under N, in which the number is situated, and the fourth figure, at the top or bottom of the page; then the logarithm directly under the fourth figure, and in a line with the three figures in the column on the left, with its proper index, is the logarithm required. Thus, the log. of 450 is 2.653213, and the log. of 7464 is 3.872972. Or, the log. of 378.5 is 2.578066, and that of .7854 is -1.895091.

## 3. To find the number indicated by a given logarithm.

Look for the decimal part of the given logarithm in the different columns, and if it cannot be found exactly, take the next less. Then under N in the left-hand column, and in a line with the logarithm found, are three figures of the number required, and on the top of the column in which the found logarithm stands is one figure more; place the decimal point as indicated by the logarithmic index, which determines the sum, properly valued, as required.

If the logarithm cannot be found exactly in the Tables, subtract from it the next less that can be found, and divide the remainder by the tabular difference; the quotient will be the rest of the figures of the given number, which, being annexed to the tabular number already found, is the proper number

required.

Ex. Required the number answering to the logarithm 3.233568.

> Given logarithm . . . .=3.233568 Next less is the log. of 1712 = 3.233504

> > Remainder 64

Tab., Diff. = 253, and  $\frac{64}{253}$  = 25

Hence the number required = 1712.25.

For practical purposes in mechanics, logarithms are seldom resorted to, unless for the raising of the powers of numbers or extraction of their roots: these operations, when Tables are at hand, they very much facilitate; involution, or the raising of powers, being performed simply by multiplication; and evolution, or the extraction of roots, by division, as in simple arithmetic.

Ex. 1. Required the square or second power of 25.791.

Log. of 25.791 = 1.411468
Multiplied by 2, the power required.

Logarithm 2:822936, indicated number or square required=665:175.

Ex. 2. What is the cube of 30.7146?

Logarithm = 1.487345 Multiplied by 3, the

3, the power required.

Logarithm 4.462035, indicated number or cube required = 28975.7.

Ex. 3. Required the square root of 365.

Log. =  $\frac{2.562293}{2}$  = 1.281146, indicated number or root = 19.105.

Ex. 4. Find the cube root of 12345.

Log. =  $\frac{4.091491}{3}$  = 1.363830, indicated number or root = 23.1116.

Table of Logarithms from 1 to 100.

N.	Log.	N.	Log.	N.	Log.	N.	Log.
1	0.000000	26	1.414973	51	1.707570	76	1.880814
2	0.301030	27	1.431364	52	1.716003	77	1.886491
3	0.477121	28	1.447158	53	1.724276	78	1.892095
4	0.602060	29	1.462398	54	1.732394	79	1-897627
5	0.698970	30	1.477121	55	1.740363	80	1.903090
6	0.778151	31	1.491362	56	1.748188	81	1.908485
7	0.845098	32	1.505150	57	1.755875	82	1.913814
8	0.903090	33	1.518514	58	1.763428	83	1-919078
9	0.954243	34	1.531479	59	1.770852	84	1.924279
10	1.000000	35	1.544068	60	1.778151	85	1.929419
11	1.041393	36	1.556303	61	1.785330	86	1.934498
12	1.079181	37	1.568202	62	1.792392	87	1-939519
13	1.113943	38	1.579784	63	1.799341	88	1.944483
14	1.146128	39	1.591065	64	1.806180	89	1.949390
15	1.176091	40	1.602060	65	1.812913	90	1.954243
16	1.204120	41	1.612784	66	1.819544	91	1.959041
17	1.230449	42	1.623249	67	1.826075	92	1.963788
18	1.255273	43	1.633468	68	1.832509	93	1.968483
19	1.278754	44	1.643453	69	1.838849	94	1.973128
20	1.301030	45	1.653213	70	1.845098	95	1-977724
21	1.322219	46	1.662758	71	1.851258	96	1.982271
22	1.342423	47	1.672098	72	1.857332	97	1.986772
23	1.361728	48	1.681241	73	1.863323	98	1.991226
24	1.380211	49	1.690196	74	1.869232	99	1.995635
25	1.397940	50	1.698970	75	1.875061	100	2.000000

Note.—The best Tables of Logarithms are those by Taylor, Gardiner, Hutton, Babbage, and Caillet. The smaller works are those by Lalande, Hassler, Renaud, Christison, and Wallace, and those published in the 'Library of Useful Knowledge.'

## CIRCUMFERENCES AND AREAS OF CIRCLES. 267

Tables of the Circumferences of Circles to the nearest fraction of practical measurement; also the Areas of Circles in inches and decimal parts, likewise of feet and decimal parts, as may be required.

by 6.232, the product is the number of imperial gallons at 1 foot in depth.

2. Any of the areas in feet multiplied by .03704, the product equal the number of cubic yards at 1 foot in depth. 3. The area of a circle in inches multiplied by the length or thickness in inches, and Rules that mny render the following Tables more generally useful. by '263, the product equal the weight in ibs. of cast iron.

Note.—The French cubic metre, or unit of solid measure, equal 35-31716 English cubic feet. Also the litre, or unit for measures of capacity, equal 61-028 English cubic inches, or about 453 of an imperial gallon.

Dia. in inch.	Circum. in inch.	Area in sq. inch.	Side of = squ.
18	196	-0030	.0554
10	.392	.0122	-1107
3	-589	.0276	.1661
1	.785	.0490	2115
5	-981	.0767	.2669
3	1.178	.1104	.3223
7 16	1.374	.1503	.3771
1	1.570	.1963	4331
16	1.767	.2485	4995
\$	1.963	.3068	.5438
11	2.159	.3712	-6093
4	2.356	4417	.6646
18	2.552	.5185	.7200
7	2.748	.6013	.7754
15	2.945	.6903	.8308
l in.	34	.7854	7
11	31	.9940	7 & 3 2
11	37	1.227	I in.
18	44	1.484	13
14	44	1.767	15
15	51	2.074	178
14	51	2.405	1.0
17	57	2.761	111
2 in.	64	3.141	13
21/8	64	3.546	12
24	7	3.976	2 in.
24	78	4.430	21
$2\frac{1}{2}$	74	4.908	2 1 8
28	81	5.412	25
24	85	5.939	270
27	9	6.491	2.9
3 in.	9 3	7.068	24
31	93	7.669	23
31	101	8.295	27
3	105	8.946	3 in.
31	11	9.621	3 in.
34	113	10.350	1 34
34 37	15#	11.044	1 3

	_				
Dia. in inch.	Circ ft.	um.in in.	Area in sq. inch.	Area in sq. feet.	Dia. in inch.
4 in.	1	40	12.566	·0879	9 in.
44	1	07	13.364	∙0935	91
44	1	lå	14.186	.0993	91
48	1	14	15.033	1052	98
44	] ]	2	15.904	1113	91
4	1	21	16.800	1176	98
44	1	27	17.720	1240	94
44	1	34	18.665	·1306	97
5 in.	1	34	19.635	·1374	10 in.
54	1	44	20.629	1444	10 <del>1</del>
5₹	1	4	21.647	·1515	10}
54	1	47	22.690	·1588	10≹
51	1	54	23.758	·1663	10 <del>1</del>
5	1	54	24.850	·1739	10∯
54	1	6	25.967	·1817	103
57	1	6 <del>8</del>	27.108	1897	10 <del>2</del>
6 in.	1	64	28.274	·1979	11 in.
64	lī	71	29.464	2062	114
1 6 <del>1</del>	Ĭ	7	30.679	2147	114
63	1	8	31.919	.2234	118
6 €	1	83	33.183	.2322	114
6	1	8 <u>3</u>	34.471	.2412	115
64	1	9 <u>ř</u>	35.784	.2504	113
$6\frac{7}{8}$	1	9¥	37.122	.2598	117
7 in.	ī	10	38.484	·2693	12 in.
71	li	10 ₈	39.871	2791	121
71	ī	103	41.282	2889	121
78	ī	114	42.718	2990	123
7	1	114	44.178	.3092	121
78	1	117	45.663	·3196	12≸
74	2	0흡	47.173	∙3299	123
7 7	2	$0\frac{3}{4}$	48.707	·3409	$12\frac{7}{8}$
8 in.	2	11	50.265	·3518	13 in.
81	2	14	51.848	.3629	13 III.
81	2	17	53.456	.3741	134
84	2	$2\frac{1}{2}$	55.088	3856	133
81	2	2	56.745	3972	13 1
84	2	3	58.426	1.4089	<i>∥ 13₫</i>
83	2	38	60.132		133
8 <b>?</b>	2	37	61.86	2   •4339	$0 \parallel 13 \frac{1}{2}$

•	
<del></del>	
:	
•	
-	
••	
*2	
,••	
•	
••	
::	
••	
3*.	
:::	
	,
<b>:</b> :	
·	"0
*:	ys.
:	
;; ·	9.0
*** *	evia
<b>;</b> :	¹ of
•	r an
::	
• ;	
	gardin
1.	line. 1
r L	ling, n
	"Inous"
1••	ment)
;• ·	· oneir
<u>:</u>	
15 15 16	da.
12 .	···.
<u>.                                      </u>	
•	· per foo
<b>;</b>	ustants c
•	
	oors, batter
•	
- ·	oors, frame whee and wham
	ashes and
	· sham

				1	<del></del>		Т	
Dia. in inch.	Circ ft.	um.in in.	Area in sq. inch.	Area in sq. feet.	Dia. in inch.	Circum.in	Area in eq. inch.	Area in sq. feet.
4 in.	1	01	12.566	.0879	9 in.	2 41	63-617	-4453
41	1	07	13.364	∙0935	91	2 4	65.396	4577
41	1	12	14.186	.0993	91	2 5	67.200	4704
43	1	lå	15.033	.1052	9≹	2 54	69.029	4832
41	1	$2\frac{1}{4}$	15.904	·1113	91	2 5	70.882	4961
44	1	2	16.800	·1176	9#	2 61	72.759	-5093
42	1	$2\frac{7}{4}$	17.720	1240	94	2 6	74.662	.5226
47	1	3 <del>1</del>	18.665	·1306	9 <del>7</del>	2 7	76.588	•5361
5 in.	1	3 8	19.635	·1374	10 in.	2 78	78-540	-5497
5 <del>}</del>	1	41	20.629	·1444	10 <del>1</del>	2 7	80.515	•5636
51	1	41	21.647	·1515	10 <del>1</del>	2 8	82.516	-5776
58	1	47	22.690	1588	10≩	2 8	84.540	-5917
5 <u>i</u>	1	5 <u>1</u>	23.758	·1663	10 l	2 87	86.590	-6061
5 -	1	5∦	24.850	1739	10	2 91	88.664	-6206
54	1	6	25.967	1817	104	2 9	90.762	•6353
5 <del>7</del>	1	6 <del>g</del>	27.108	·1897	10 <del>ž</del>	2 10	92.855	•6499
6 in.	1	6 <del>2</del>	28.274	·1979	11 in.	2 101	95.033	·6652
6 <del>1</del>	1	71	29.464	.2062	114	2 107	97.205	·6804
6 <u>₹</u>	1	7 <u>k</u>	30.679	.2147	111	2 111	99.402	-6958
$6\frac{3}{8}$	1	8	31.919	.2234	11#	2 114	101.623	.7143
6 j	1	8유	33.183	.2322	114	3 0	103.869	.7270
68	1	8 <u>3</u>	34.471	2412	115	3 01	106.139	•7429
$6\frac{3}{4}$	1	9 į	35.784	2504	114	3 07	108.434	·7590
$6\frac{7}{8}$	1	9 <u>1</u>	37.122	.2598	117	3 1 <del>1</del>	110.753	-7752
7 in.	1	10	38.484	·2693	12 in.		113.097	·7916
7 <del> </del> 7 <del> </del> 7	1	10 <del>8</del>	39.871	.2791	12 <del>1</del>	3 2	115.466	·8082
74	1	$10\frac{3}{4}$	41.282	2889	121	3 2 <del>1</del>	117.859	·8250
7 3 7 3 7 3 7 3 7 3 7 3 7 3 7 3 7 3 7 3	1	]]	42.718	·2990	128	3 27	120.276	*8419
71/2	1	11 <u>¥</u>	44.178	3092	12	3 34	122.718	·8590
7∄	1	114	45.663	·3196	12	3 3	125.185	·8762
74	2	0용	47.173	·3299	$12\frac{3}{4}$	3 4	127.676	·8937
7	2	08	48.707	*3409	$12\frac{7}{8}$	3 43	130-192	·9113
8 in.	2	11	50.265	·3518	13 in.		132.732	·9291
81	2	11/2	51.848	.3629	13 <del>1</del>	3 51	135-297	·9470 '
8 <del>1</del>	2	17	53.456	.3741	134	3 5	137.886	.9642
8 <del>3</del>	2	2 <del>1</del>	55.088	∙3856	134	3 6	140.500	•9835
81	2	25	56.745	3972	∥ 13⅓	3 64	143.139	
RE I	2	3	58.426	1.4089	<i>∦ 13</i> ₽	13 63		
83 84 84	2	34	60.132		// 13#	/3 7	148.48	9,1.0501
8ž	2	3 <del>7</del>	61.862	2   •4339	)    13 <del>1</del>	$\frac{6}{3}$	1 /121.5	01,1.028

n	Circum.in ft. in.	Area in sq. inch.	Area in sq. feet.	Dia. in inch.	Circum.in ft. in.	Area in sq. inch.	Area in sq. feet.
	3 7%	153-938	1.0775	19	4 115	283-529	1.9847
	3 83	156-699	1.0968	191	5 0	287-272	1.9941
	3 84	159.485	1.1193	191	5 01	291.039	2.0371
١	3 91	162-295	1.1360	193	5 04	294.831	2.0637
	3 91	165.130	1.1569	194	5 11	298.648	2.0904
	3 97	167-989	1.1749	195	5 14	302-489	2.1172
	3 101	170.873	1.1961	193	5 2	306.355	2.1443
	3 104	173.782	1.2164	197	5 28	310.245	2.1716
	3 111	176-715	1.2370	20	5 21	314-160	2-1990
1	3 111	179.672	1.2577	201	5 31	318-099	2.2265
1	3 117	182.654	1.2785	201	5 35	322.063	2.2543
J	4 01	185-661	1.2996	203	5 4	326.051	2.2822
1	4 04	188-692	1.3208	201	5 48	330.064	2.3103
	4 1	191.748	1.3422	204	5 43	334.101	2.3386
ı	4 11	194.828	1.3637	203	5 54	338-163	2.3670
	4 17	197-933	1.3855	202	5 51	342.250	2.3956
	4 21	201.062	1.4074	21	5 54	346-361	2.4244
1	4 25	204.216	1.4295	211	5 6	350.497	2.4533
	4 3	207:394	1.4517	211	5 63	354.657	2.4824
1	4 34	210-597	1.4741	213	5 71	358-841	2.5117
1	4 33	213.825	1.4967	211	5 71	363.051	2.5412
	4 41	217.077	1.5195	215	5 77	367-284	2.5708
1	4 45	220.353	1.5424	213	5 84	371-543	2.6007
	4 5	223.654	1.5655	2178	5 84	375.826	2.6306
	4 54	226-980	1.5888	22	5 91	380-133	2.6608
	4 54	230.330	1.6123	221	5 91	384-465	2.6691
	4 61	233.705	1.6359	221	5 9%	388-822	2.7016
1	4 61	237.104	1.6597	228	5 101	393-203	2.7224
	4 67	240.528	1.6836	221	5 105	397-608	2.7632
	4 78	243-977	1.7078	225	5 11	402.038	2.7980
	4 74	247.450	1.7321	223	5 114	406.493	2.8054
	4 81	250.947	1.7566	227	5 117	410-972	2.8658
	4 81	254-469	1.7812	23	6 01	415-476	2.8903
	4 87	258.016	1.8061	231	6 05	420.004	2.9100
	4 91	261.587	1.8311	231	6 1	424.557	2.9518
	4 94	265.182	1.8562	238	6 13	429-135	2.9937
	4 10	268-803	1.8816	234	6 13	433-737	3.015
	4 104	272-447	1.9071	235	6 24	438.36	3 /3.03
1	4 104	276-117	1.9328	233	16 5	£ \443.0	14 3.0
1	4 114	279-811	1.9586			447	690 /3

Dia ft.	. in in.	Cire ft.	um. io , <b>i</b> n.	Area in sq. inch.	Area in sq. feet.	D ft.		Circ ft.	um.in in.	Area in sq. inch.	Area in sq. feet.
2	0	6	33	452-390	3.1418	2	10	8	104	907-922	6.3051
2	01	6	4 %	461.864	3.2075	2	10 <del>1</del>	8	111	921.328	6.3981
2	0	6	47	471.436	3.2731	2	101	9	0	934-822	6.4911
2	0	6	54	481.106	3.3410	2	104	9	ıį	948-419	6.5863
2	ì	6	61	490.875	3.4081	2	11	9	14	962-115	6-6815
2	Ĩ.	6	71	500.741	3.4775	2	111	9	21	975-908	6.7772
2	11	6	81	510.706	3.5468	2	114	9	31	989-800	6.8738
2	14	6	87	520.769	3.6101	2	11#	9	41	1003.79	6-9701
2	2	6	94	530-930	3.6870	3	0	9	5	1017:87	7.0688
2	21	6	10å	541.189	3.7583	3	01	9	57	1032.06	7.1671
2	21	6	114	551.547	3.8302	3	0į	9	6 <del>1</del>	1046-35	7.2664
2	2	7	0	562.002	3.9042	3	0	9	71	1060-73	7.3662
2	3	7	03	572.556	3.9761	3	1	9	8 <u>1</u>	1075-21	7.4661
2	31	7	1 🙀	583-208	4.0500	3	11	9	9	1089.79	7.5671
2	3 į	7	24	593.958	4.1241	3	1 j	9	9 <del>7</del>	1104.46	7.6691
2	34	7	3 🖁	604.807	4.2000	3	17	9	10 <u>1</u>	1119-24	7.7791
2	4	7	37	615.753	4.2760	3	2	9	11#	1134-12	7.8681
2	41	7	4 <del>3</del>	626.798	4.3521	3	21	10	0 <u>¥</u>	1149.09	7-9791
2	41	7	5 i	637.941	4.4302	∥3	21	10	07	1164.16	8.0846
2	44	7	$6\frac{1}{4}$	649.182	4.5083	3	2	10	14	1179.32	8.1891
2	5	7	7	660.521	4.5861	3	3	10	21	1194.59	8.2951
2	5 <del>1</del>	7	77	671.958	4.6665	3	31	10	31	1209.95	8.4026
2	5 j	7	84	683.494	4.7467	∥3	3 <u>i</u>	10	4	1225.42	8.5091
2	5 <del>3</del>	7	91	695.128	4.8274	3	34	10	47	1240-98	8.6171
2	6	7	10 <del>1</del>	706.860	4.9081	3		10	5 <del>§</del>	1256-64	8-7269
2	6 <del>1</del>	7	11	718-690	4.9901	3	44	10	6 <del>8</del>	1272-39	8-8361
2	6 <u>}</u>	7	114	730.618	5.0731	3	41	10	74	1288-25	8.9462
2	64	8	0套	742.644	5.1573	3	44	10	8	1304.20	9.0561
2	7	8	18	754.769	5.2278	3	5	10	8 <del>\$</del>	1320-25	9.1686
2	7 <del>1</del>	8	2	766.992	5.3264	3	54	10	91	1336.40	9.2112
2	71	8	$2\frac{7}{8}$	779.313	5.4112	3	5 }	10	10홍	1352.65	<b>9</b> ·3936
2	74	8	34	791.732	5.4982	3	54	10	111	1369.00	9.5061
2	8	8	41	804-249	5.5850	3	6	10	117	1385-44	9.6212
2	81	8	5 <del>8</del>	816.865	5.6729	3	64	11	02	1401.98	9.7364
2	81	8	6 <del>1</del>	829.578	5.7601	3	61	11	11	1418-62	9.8518
2	83	8	$6\frac{7}{8}$	842.390	5.8491	∦3			21	1435.36	9.9671
	9	8	7 <u>š</u>	855.300	5.9398	// 3		/11	7 3	/1425.50	10.084
•	9# [	8	8 <u>1</u>	868.308	6.0291	.	-		1 3	£ /1469·14	
9	<b>i</b> / ∎	8	91	881.415	6.120	r //			11 4	14   1486-) 54   1503:	
9		8 1	0	894.619	6.212	9 /	3	74	11	54 / 1503	20 /10.

_						_					T
)is t.	in.	Circ ft.	um.in in.	Area in sq. inch.	Area in sq. feet.	Di ft.	a. in in.	Circ ft.	um.in in.	Area in sq. inch.	Area in sq. feet.
_	8	11	61	1520.53	10.559	4	6	14	14	2290.22	15.904
	81	ii	7	1537.86	10.679	4	6 <del>1</del>	14	2書	2311.48	16.051
•	81	ii		1555.28	10.800	4	6 <del>1</del>	14	31	2332.83	16.209
•	8 <u>\$</u>	11	7 <del>2</del> 81	1572.81	10.922	4	64			2354.28	16.349
								14	4	2375.83	16.498
•	9	11	98	1590.43	11.044	4	7	14	43		
•	9‡	11	101	1608-15	11.167	4	71	14	51	2397.48	16.649
,	91	11	104	1625.97	11.291	4	71	14	68	2419.22	16.800
<b>5</b>	94	11	114	1643.89	11.415	4	72	14	7 <del>}</del>	2441.07	16.951
,	10	12	01	1661-90	11.534	4	8	14	77	2463.01	17.104
3	10±	12	11	1680.02	11.666	4	81	14	8	2485.05	17.257
	10 i	12	2	1698-23	11.793	4	8 i	14	9 <del>1</del>	2507.19	17.411
į.	10	12	27	1716.54	11.920	4	8	14	10 <del>1</del>	2529.42	17.565
į.	īi"	12	3	1734.94	12.048	4	9	14	11	2551.76	17.720
ĺ	111	12	48	1753.45	12.176	4	91	14	114	2574.19	17.876
i	111	12	5 <del>1</del>	1772.05	12.305	4	91	15	0	2596.72	18.033
Š	112	12	6	1790.76	12.435	4	9	15	12	2619.35	18.189
_					12 100	<u> </u>				2010 00	10 100
Ŀ	0	12	62	1809.56	12.566	4	10	15	21	2642.08	18.347
Ŀ	01	12	7	1828-46	12.697	4	10 <del>1</del>	15	27	2664.91	18.506
Ŀ	0į	12	8	1847.45	12.829	4	10i	15	3	2687.83	18.665
Ļ	02	12	9¥	1866.55	12.962	4	102	15	4	2710.85	18.825
Ĺ	ı	12	97	1885.74	13.095	4	11	15	5 <u>1</u>	2733.97	18.985
Ĺ	11	12	10%	1905.03	13.229	4	111	15	6 i	2757.19	19.147
Ĺ	14	12	111	1924.42	13.364	4	111	15	6 <del>7</del>	2780.51	19.309
Ŀ	14	13	01	1943-91	13.499	4	114	15	74	2803.92	19.471
_	2	13	1	1963.50	13.635	5	0	15	81	2827:44	19.635
i	2 <del>1</del>	13	14	1983.18	13.772	5	01	15	91	2851.05	19.798
_	21	13		2002.96	13.772	5	01	15	10	2874.76	19.963
•			25					_			20.128
1	24	13	38	2022.84	14.047	5	0#	15	104	2898.56	
•	3	13	44	2042.82	14.186	5	1	15	114	2922.47	20.294
•	31	13	5	2062.90	14.325	5	14	16	08	2946.47	20.461
4	31	13	57	2083.07	14.465	5	11	16	11	2970.57	20.629
4	34	13	61	2103.35	14.606	5	14	16	17	2994.77	20.797
4	4	13	7 <u>2</u>	2123.72	14.748	5	2	16	23	3019-07	20.965
4	41	13	8	2144-19	14.890	5	21	16	31	3043.47	21.135
4	41	13	87	2164.75	15.033	5	2	16	41	3067.96	21.305
4	4	13	94	2185.42	15.176	5	24	16	5	3092-56	21.476
ā	5	13	104	2206.18	15.320	5	3	116		3772.52	127.647
ã	5}	13	114	2227.05	15.465	š	34			\	1 51.81
ī	54	14	0	2248.01	15.611	15				7/3166.	35 /51.0
		14	- 1	2269.06		1 5				81/3191	
_	-41		<u> </u>	2203.00	15.757	11 5	, 0	41	7.0	04/0-0-	

Di ft.	a. in in.	Circ ft,	um.in in.	Area in sq. inch.	Area in sq. feet.		in.	Circ ft.	um. in	Area in sq. inch.	Area in sq. feet
5	4	16	9	3216-99	22:333	6	2	19	41	4300.85	29.867
5	41	16	94	3242-17	22.515	6	21	19	51	4329-95	30-069
5	41	16	105	3267-46	22.621	6	21	19	6	4359-16	30-271
5	43	16	11	3292.83	22.866	6	24	19	63	4388-47	30.47
5	5	17	01	3318-31	23.043	6	3	19	74	4417-87	30.679
5	51	17	07	3343.88	23.221	6	31	19	88	4447-37	30.884
5	51	17	14	3369-56	23.330	6	31	19	91	4476-97	31.090
5	53	17	21	3395-33	23.578	6	34	19	97	4506-67	31.296
5	6	17	33	3421-20	23.758	6	4	19	103	4536.47	31.503
5	61	17	41	3447.16	23.938	6	41	19	111	4566.36	31.710
5	61	17	47	3473-23	24.119	6	41	20	01	4596.35	31.919
5	63	17	54	3499-39	24.301	6	48	20	11	4626.44	32.114
5	7	17	61	3525-66	24.483	6	5	20	14	4656.63	32.337
5	71	17	71	3552-01	24.666	6	51	20	24	4686-92	32.548
5	74	17	8	3578.47	24.850	6	51	20	31	4717:30	32.759
5	74	17	88	3605.03	25.034	6	54	20	41	4747.79	32.970
5	8	17	95	3631-68	25-220	6	6	20	5	4778-37	33.183
5	81	17	108	3658.44	25.405	6	61	20	53	4809.05	33.396
5	81	17	111	3685.29	25.592	6	61	20	61	4839.83	33.619
5	84	17	117	3712-24	25.779	6	63	20	78	4870-70	33.824
5	9	18	03	3739-28	25.964	6	7	20	81	4901.68	34.039
5	91	18	11	3766.43	26.155	6	71	20	87	4932-75	34.25
5	91	18	21	3793-67	26.344	6	74	20	93	4963.92	34.47
5	94	18	31	3821.02	26.534	6	74	20	101	4995.19	34.68
5	10	18	37	3848-46	26.725	6	8	20	111	5026-26	34.900
5	101	18	45	3875.99	26.916	6	81	21	01	5058.02	35.12
5	$10\frac{1}{2}$	18	51	3903.63	27.108	6	81	21	07	5089.58	35.344
5	103	18	64	3931.36	27.301	6	83	21	14	5121.24	35.564
5	11	18	7	3959-20	27.494	6	9	21	23	5153.00	35.784
5	111	18	73	3987-13	27.688	6	91	21	31	5184.86	36.000
5	$11\frac{1}{2}$	18	8	4015-16	27.883	6	91	21	4	5216.82	36-227
5	114	18	98	4043.28	28.078	6	98	21	44	5248.87	36.45
6	0	18	$10\frac{1}{8}$	4071.51	28-274		10	21	51	5281-02	36.67
6	01	18	107	4099.83	28.471		104	21	63	5313.27	36.89
6	$0\frac{1}{2}$	18	113	4128-25	28.668		$10\frac{1}{2}$	21	71	5345.62	37-122
;	03	19	01	4156.77	28.866	16	104		78	5378.07	37.347
	1 /	19	11	4185.39	29.065	16		15.			137.57
		19	21	4214.11	29.264	- 11		- /	6 12	- 1	
		19	27	4242.92	29.46	- 11		-21	21 1		
1	2/1	9	34	4271.83	29.66	5 1	6	13	21 1	1 1 0000	24 19

Dia. in ft. & in.	Circum. in ft. and in.	Area in feet.	Dia. in ft. & in.	Circum. in ft. and in.	Area in feet.
7 0	21 117	38.4846	10 0	31 5	78.5400
1	22 3	39.4060	1	31 8 <del>1</del>	79.8540
2	22 6	40.3388	2	31 111	81.1795
3	22 91	41.2825	3	32 2 <del>8</del>	82.5160
4	23 08	42.2367	4	32 5 <del>1</del>	83.8627
5	23 21	43.2022	5	32 8 <del>§</del>	85.2211
6	23 63	44.1787	6	32 114	86.5903
7	23 11	45.1656	7	33 27	87.9697
8	24 11	46.1638	8	33 6 <del>1</del>	89.3608
9	24 4	47.1730	9	33 9 <del>1</del>	90.7627
10	24 71	48.1926	10	34 0	92.1749
11	24 10 ⁸	49.2236	11	34 31	93.5986
8 0	25 11	50.2656	11 0	34 6 <del>§</del>	95.0334
1	25 48	51.3178	1	34 94	96.4783
2	25 77	52.3816	2	35 0 <del>ž</del>	97.9347
3	25 11	53.4562	3	35 4 g	99.4021
4	26 2 <del>1</del>	54.5412	4	35 7₺	100.8797
5	26 51	55.6377	5	35 10 <del>§</del>	102.3689
6	26 8	56.7451	6	36 1	103.8691
7	26 111	57.8628	7	36 4 <del>1</del>	105.3794
8	27 24	58.9920	8	36 7 <del>3</del>	106.9013
. 9	27 54	60.1321	9	36 10 <del>8</del>	108.4342
10	27 9	61.2826	10	37 24	109-9772
11	28 01	62.4445	11	37 5}	111.5319
9 0	28 31	63.6174	12 0	37 8 <del>8</del>	113.0976
1	28 6	64.8006	1	37 11 <del>1</del>	114.6732
2	28 9 <del>1</del>	65.9951	2	38 2 <del>§</del>	116.2607
3	29 0∯	67.2007	3	38 5 <del>4</del>	117.8590
4	29 34	68.4166	4	38 8 <del>ž</del>	119.4674
5	29 7	69.6440	5	39 0	121.0876
6	29 101	70.8823	6	39 3 <del>1</del>	122.7187
7	30 11	72.1309	7	39 68	124.3598
8	30 48	73.3910	8	39 91	126.0127
9	30 71	74.6620	9	40 0 <del>8</del>	127.6765
10	30 114	75.9433	10	40 34	129.3504
11	31 14	77.2362	11	40 6 <del>7</del>	131.0360

## 274 CIRCUMFERENCES AND AREAS OF CI

			<del></del>			
	a. in & in.	Circum. in ft. and in.	Area in feet.	Dia. in ft. & in.	Circum. in ft. and in.	
13	0	40 10	132-7326	16 0	50 31	
	ī	41 11	134.4391	1	50 6 <del>1</del>	
1	2	41 4	136-1574	2	50 9¥	
1	3	41 7	137.8867	3	51 04	
	4	41 10	139.6260	4	51 34	
	5	42 1	141-3771	5	51 6 <del>1</del>	
1	6	42 47	143-1391	6	51 10	
1	7	42 8	144-9111	7	52 11	
1	8	42 11 <del>1</del>	146-6949	8	52 4 <del>1</del>	
1	9	43 2	148-4896	9	52 7	
1	10	43 5	150-2943	10	52 104	
	11	43 8	152-1109	11	53 1 <del>§</del>	
14	0	43 113	153-9384	17 0	53 4 <del>7</del>	
į	1	44 27	155.7758	1	53 8	
Ì	2	44 6	157.6250	2	53 11 <del>1</del>	
Ì	3	44 9 <del>}</del>	159.4852	3	54 2 <del>1</del>	
1	4	45 0 <del>1</del>	161.3553	4	54 5	
1	5	45 31	163.2373	5	54 8 ₃	
-	6	45 6	165.1303	6	54 118	
1	7	45 93	167.0331	7	55 2 <del>8</del>	
1.	8	46 0 <del>7</del>	168 9479	8	55 6	
	9	46 4	170.8735	9	55 9 <del>1</del>	
1	10	46 71	172.8091	10	56 0 <del>1</del>	
	11	46 111	174.7565	11	56 3½	
15		47 11	176.7150	18 0	56 6 <del>1</del>	
	1	47 48	178.6832	1	56 9 <del>§</del>	
	2	47 74	180.6634	2	57 0 <del>8</del>	
1	3	47 107	182.6545	3	57 4	
	4	48 2	184.6555	4	57 7 <del>1</del>	
	5	48 5	186.6684	5	57 10 <del>1</del>	
1	6	48 81	188-6923	6	58 18	
1	7	48 113	190.7260	7	58 41	
1	8	49 25	192.7716	8	58 7	
1	9	49 5	194.8282	9	58 104	
1	10	49 87	196.8946	10	59 2	
1	11	50 0	198-9730	11	59 5 ₈	

No.	S. R.	C. R.	No.	8. R.	C. R.	No.	9.70				T
1	1.0000	1.0000	55	7:4161	3.8020	_	S. R.	C. R.	No.	S. R.	C. R.
1 2	1.4142	1.52599	56	7.4833	3.8029	109	10.4403	4.7768	163	12.7671	5.4625
3	1.7320	1.4422	57	7.5498	3.8482	iii	10.4880 10.2320	4.7914	164	12.8062	5.4737
4	2.0000	1.5874	58	7.6157	3.8708	112	10.2830	4.8202	165 166	12.8452	5.4848
5	2.2360	1.7099	59	7.6811	3.8929	113	10.6301	4.8345	167	12.8840 12.9228	5.4958
6	2.4494	1 8171	60	7.7459		114	10.6770	4.8488	168	12.0614	5.5068
7	2.6457	1.9129	61	7.8102	9.9364	115	10.7238	4.8620	169	13.0000	5·5178 5·5287
8	2.8284	2.0000	62	7.8740	3.9578	116	10.7703	4.8769	170	13.0384	5.5396
9	3.0000	2.0800	63	7.9372	3.9790	117	10.8166	4.8000	171	13.0766	5.5504
10	3.1623	2.1244	64	8.0000	4.0000	118	10.8627	4.0048	172	13-1148	5.5612
11	3.3166	2.2239	65	8.0623	4.0207	119	10.9087	4.9186	173	13.1520	5.5720
12	3.4641	2.5884	66	8.1240		120	10.9544	4.0324	174	18.1000	5.5827
13	3.6055	2.3513	67	8.1823	4.0612	121	11.0000	4.0460	175	13.2287	5.5934
14	3.7416	2'4101	68	8.2462	4.0816	122	11.0423	4.9596	176	13.2664	5.6040
15	3.8729	2.4662	69	8.3066	4.1012	123	11.0002	4.9731	177	13.3041	5.6146
16	4.0000	2.5198	70	8.3666	4.1213	124	11.1355	4.0866	178	13.3416	5.6252
17	4.1231	2.5712	71	8.4261	4.1408	125	11.1803	5.0000	179	13.3790	5.6857
18	4.3588	2·6207 2·6684	72	8.4852	4.1601	126	11.2249	5.0133	180	13.4164	5.6462
19	4.4721	2.7144	73	8.5440 8.6023	4.1793	127	11.2694	5.0262	181	13.4536	5.6566
21	4.5825	2.7589	74 75	8.6602	4.1983	128	11.3137	5.0396	182	13.4907	5.6670
22	4.6904		76	8.7177	4.2358	129 130	11.3578	5.0527	183	13.5277	5.6774
23		2.8438	77	8.7749		131	11:4017	5 0657	184	13.5646	5.6877
24	4.8989	2.8844	78	8.8317		132	11.4455		185	13.6014	5.6980
25		2.9240	79	8.8881		133	11.5325	5.0916 5.1044	186	13.6381	5.7082
26	5.0990	2.0624	80	8.0442		134	11.5758		187 188	13.6747 13.7113	5.7184
27	5.1961	3.0000	81	0.0000		135	11.0189	5.1500	189	13.7477	5.7286
28	5.2015		82	0.0583		136	11.6619	5.1422	190	13.7840	5·7387 5·7488
29	5.3851	3.0723	83	9.1104	4.3620	137	11.7046	5.1551	191	13.8303	5.7589
30	5.4772	3.1072	84	9.1651	4.3795	138	11.7473	5.1676	192	13.8564	5.7689
31	5.2677	3.1413	85	9.2195	4.3968	139	11.7898		193	13.8924	5.7789
32		3.1748	96	9.2736	4.4140	140	11.8321	5.1924	194	13.9283	5.7889
33		3.5022	87	9.3278		141	11.8748	5.2048	195	13.9642	5.7988
34	9.8300	3.5300	88	9.3808	4.4479	142	11.0168	5.3171	196	14.0000	5.8087
35	5.9160		89	9.4339		143	11.0288	5.3393	197	14.0356	5.8186
36	6.0000	3.3010	90	9.4868		144	12.0000	5.3414	198	14.0713	5.8284
37	6.0827	3.3322	91	9.5393	4.4979	145	12.0412	5.3585	199	14.1067	5.8382
38	6.2449	3.3019	92	9.5916		146	12.0830	5.5020	200	14.1421	5.8480
40	6.3245	3.4199	93 94	9·6436 9·6953	4.5306	147	12.1248		201	14.1774	5.8577
41	6.4031		95	9.7467	4.5620	148 149	12.1655	5.2895	202	14.3130	5.8674
42	6.4807	3.4760	96	9.7979	4.5788	150	12.2062	5.3014	203	14.2478	5.8771
43	6.5574		97	9.8488	4.5947	151	12:2474 12:2882	5.3132 5.3250	204	14.2828	5.8867
44	6.6332	3.2303	98	9.8994	4.6104	152	12.3288	5.3368	205 206	14·3178 14·35 <b>27</b>	5.8968
45	6.7082	3.5568	99	9.9498	4.6260	153	12.3693	5.3484	207	14.3874	5.0050 5.0124
46	6.7828	3.5830	100	10 0000	4.6415	154	12.4096	5.3601	208	14.4223	5.9249
47	6.8556	3.6088	101	10.0408	4.6570	155	12.4498	5.8716	200	14.4568	5.0344
48		3.6342	102	10.0992	4.6723	156	12.4809	5.3832	210	14.4013	5.0430
49	7.0000		103	10.1488	4.6875	157	12.5299	5.3946	211	14.5258	5.0533
50	7.0710		104	10.1080	4.7026	158	12.5698	5.4061	212	14.5602	5.9627
51	7.1414		105	10.3460	4.7176	159	12.6005	5.4175	213	14.5945	5.9720
52	7.2111		106	10.5026	4.7326	160	12.0491	5'4288	214	14.6287	5.9814
53	7.2801		107	10.3440	4.7474	161	12.0882			14.6628	5.9907
54	7'3484	3'7797	108	10.3923	4.7023	102	12.7279	5.4513	216	14.6969	6.0000

To find the square or cube root of a number consisting of integers and decimals.—Rule. Multiply the difference between the root of the integer part of the given number, and the root of the next higher number, by the decimal part of the given number, and add the product to the root of the given integer number; the sum is the root required.

Ex. Required the square root of 20.321.

Square root of 21=4.5825

Do. 20=4.4721 Diff. = 1104

 $= 1104 \times 321 + 4.4721 = 4.507$ , &c., the root required.

Contract Contract

#### PER-CENTAGE AND DISCOUNT TABLE.

Rate per cent.	Rate per £. in shillings.	Rate per s. in pence.	Rate per cent.	Rate per £. in shillings.	Rate per s. in pence.			
1	∙025	·015	5 <del>1</del>	1.1	•66			
ì	∙05	•03	6	1.2	•72			
ī	•1	•06	61	1.25	•75			
8 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	·15	•09	71	1.5	.9			
1	•2	•12	82	1.75	1.05			
2	•4	•24	10	2	1.2			
21	•5	•3	121	2.5	1.5			
3	·5 ·6	•36	15	3	1.8			
31	.7	.42	20	4 .	2.4			
4	-8	•48	25	5	3			
41	.9	•54	30	6	3.6			
5	1	•6	40	8	4.8			
To cover a	Mult. the	Divide the	To cover a		Divide the			
	net price by		discount of		product by			
5 p. ct.	20	19	27½ p.ct.	40	29			
7 3	40	37	30	10	7			
10	10	9	$32\frac{1}{2}$	40	27			
121	8	7	35	20	13			
15	20	17	371	8	5			
171	40	33	40	5	5 3			
20	5	4	421	40	23			
221	40	31	45	20	11			
25	4	3	471	40	21			
For 50 per cent., double the sum.								

- Ex. 1. Required the per-centage on £ 127 at  $3\frac{1}{2}$  per cent.  $127 \times 7 = 88.9$  shillings, or £ 4. 8s.  $10\frac{3}{2}d$ .
- Ex. 2. What is the per-centage on 36 shillings at 2½ per cent.?  $36 \times 3 = 10.8$  pence, or 10 pence and 3 farthings nearly.

#### JUST PUBLISHED

## BY JOHN WEALE, 59, HIGH HOLBORN.

## TREDGOLD ON THE STEAM ENGINE.

- Published in 74 Parts, price 2s. 6d. each, in 4to, illustrated by very numerous engravings and wood-cuts, a new and much extended edition now complete in 3 vols. bound in 4, in elegant half-morocco, price Nine Guineas and a Half.
- THE STEAM ENGINE, in its progressive and present state of improvement: practically and amply elucidating, in every detail, it modifications and applications, its duties and consumption of fuel, with an investigation of its principles and the proportions of its parts for efficiency and strength; including examples of British and American recently constructed engines, with details, drawn to a large scale.
  - Division A. Locomotive Engines for Railways, practically drawn and explained
    - being Vol. I.

      B. Marine Engines for Sea and River Service, with the Construction of Steam Vessels, British and American; being Vol. II. (bound in Two Vols.)
    - C to G. Comprising Stationary Engines, Pumping Engines for raising Water, or for supplying Towns with Water; Engines for Mills Examples of Marine Boilers, &c.; being Vol. III.

The well-known and highly appreciated Treatise, Mr. Tredgold's national Work on the Steam Engine, founded on scientific principle and compiled from the practice of the best makers—showing also easy rules for construction, and for the calculation of its power in all cases—has commanded a most extensive sale in the several English editions and in Translations on the Continent. These editions being now out of print, the proprietor has been induced to enlarge and extend the present edition by practical examples of all kinds, with the most recent improvements in the construction and practical operations of the steam engine both at home and abroad.

The work is divided into the sections named below, either of which may be purchased separately: working engineers will be thus enabled to select those portions which more especially apply to the objects upon which they may be respectively employed.

Several scientific men, extensively and practically employed, have contributed original and really practical papers of the utmost utility by which the value of this extended edition is much increased. Jopping INDEX for reference is added.

- DIVISION A. Locomotive Engines, 41 plates and 55 wood-cuts, complete, making Vol. I. In half-morocco binding, price £2. 12s. 6d.
- DIVISION B. Marine Engines, British and American, numerous plate and wood-cuts, making Vol. II.; bound in 2 vols. half-morocea, yeir £3. 13s. 6d.
- Division C. to G. making Vol. III., and completing the work, prising Stationary Engines, Pumping Engines, and several ex-

of Boilers employed in the British Steam Navy, in half-morocco, price £3.13s.6d.

#### SUMMARY OF THE ILLUSTRATIONS.

	Locomotive Engines Marine Engines .					Plates. 41 85	Wood-cuts 55 51
III.	Stationary Engines, I Engines for Flour-M						
	Boilers, &c., &c.	•	•	•	•	100	58
	Total	al				226	164

In One Volume, 8vo, extra cloth, bound, price 9s.,

# THE STUDENT'S GUIDE TO THE PRACTICE OF DESIGNING, MEASURING, AND VALUING

## ARTIFICERS' WORKS;

Containing Directions for taking Dimensions, abstracting the same, and bringing the Quantities into Bill; with Tables of Constants, and copious memoranda for the Valuation of Labour and Materials in the respective trades of Bricklayer and Slater, Carpenter and Joiner, Sawyer, Stonemason, Plasterer, Smith and Ironmonger, Plumber, Painter and Glazier Paper-hanger. Thirty-eight Plates and Wood-cuts.

The measuring, &c., edited by Edward Dobson, Architect and Surveyor Second Edition, with the additions on Design by E. Lacy Garbett Architect.

#### CONTENTS.

Preliminary Observations on Designing Artificers' Works.

Preliminary Observations on Measurement, Valuation, &c. — On measuring—On rotation therein—On abstracting quantities—On valuation—On the use of constants of labour.

#### BRICKLAYER AND SLATER.

DESIGN OF BRICKWORK — technical terms, &c.

Foundations—Arches, inverted and erect—Window and other aperture heads—Window jambs—Plates and internal cornices—String courses—External cornices—Chimney shafts—On general improvement of brick architecture, especially fenestration.

MEASUREMENT.

Of diggers' work — Of brickwork, of facings, &c.

DESIGN OF TILING, and technical terms.

Measurement of tiling—Example of the mode of keeping the measuring book for brickwork.

ABSTRACTING Bricklayers' and Tilers' Work.

Example of bill of Bricklayers' and Tilers' work.

VALUATION of Bricklayers' work, Earthwork, Concrete, &c.

Table of sizes and weights of various articles — Tables of the new

of bricks or tiles in various works—Valuation of Diggers' and Brick- 'layers' labour—Table of Constants for said labour.

XAMPLES OF VALUING.

A yard of concrete. — 2. A rod of brickwork. — 3. A foot of facing.
 — 4. A yard of paving — 5. A square of tiling.

ESIGN AND MEASUREMENT OF SLATING.

Valuation of slating.

#### CARPENTER AND JOINER.

ESIGN OF CARPENTRY — technical terms, &c.

Breast-summers, an abuse: substitutes for them — Joists, trimmers, trimming-joists — Girders, their abuse and right use — Substitutes for girders and quarter-partitions — Quarter-partitions — Roof-framing— Great waste in present common modes of roof-framing—To determine the right mode of subdividing the weight, and the right numbers of bearers for leaded roofs — The same for other roofs — Principle of the truss — Considerations that determine its right pitch—Internal filling or tracery of trusses — Collar-beam trusses — Connection of the parts of trusses —Variations on the truss; right limits thereto — To avoid fallacious trussing and roof-framing—Delorme's roofing; its economy on circular plans—Useful property of regular polygonal plans — On combinations of roofing, hips, and valleys — On gutters, their use and abuse—Mansarde or curb roofs.

ESIGN OF JOINERY - technical terms, &c.

Modes of finishing and decorating panel-work—Design of doors.

[EASUREMENT of Carpenters' and Joiners' work-Abbreviations.

Modes of measuring Carpenters' work — Classification of labour when measured with the timber — Classification of labour and nails when measured separately from the timber.

XAMPLES OF MEASUREMENT, arch centerings.

Bracketing to sham entablatures, gutters—Sound-boarding, chimney-grounds, sham plinths—Sham pilasters, floor-boarding, mouldings—Doorcases, doors, doorway linings—Dado or surbase, its best construction—Sashes and sash-frames (examples of measurement)—Shutters, boxings, and other window fittings—Staircases and their fittings.

BSTRACTING Carpenters' and Joiners' work.

Example of Bill of Carpenters' and Joiners' work.

ALUATION of Carpenters' and Joiners' work, Memoranda.

Tables of numbers and weights.

ABLES OF CONSTANTS OF LABOUR.

Roofs, naked floors—Quarter-partitions, Labour on fir, per foot cube— Example of the valuation of deals or battens—Constants of labour on deals, per foot superficial.

ONSTANTS OF LABOUR, and of nails, separately.

Battening, weather boarding -- Rough boarding, deal floors, batten floors.

ABOUR AND NAILS together.

On grounds, skirtings, gutters, doorway-linings—Doors, framed partitions, mouldings—Window-fittings—Shutters, seales and frames, staircases—Staircase fittings, wall-strings—Dados, sham columns and pilasters.

ILUATION OF SAWYERS' WORK.

DESIGN OF STONEMASONS' WORK.

I)r. Robison on Greek and Gothic Architecture—Great fallacy in the Gothic ornamentation, which led also to the modern 'monkey styles'—'Restoration' and Preservation.

MEASUREMENT of Stonemasons' work.

Example of measuring a spandril step, three methods—Allowance for labour not seen in finished stone—Abbreviations, Specimen of the measuring-book—Stairs, Landings, Steps, Coping—String-courses, Plinths, Window-sills, Curbs—Columns, Entablatures, Blockings—Cornices, Renaissance Niches.

ABSTRACTING AND VALUATION.

Table of weight of stone—Table of Constants of Labour—Example of Bill of Masons' work.

#### PLASTERER.

DESIGN OF PLASTER-WORK in real and mock Architecture.

Ceilings and their uses—Unnecessary disease and death traced to their misconstruction—Sanitary requirements for a right ceiling—Conditions to be observed to render domestic ceilings innoxious—Ditto, for ceilings of public buildings—Barbarous shifts necessitated by wrong ceilings—Technical terms in Plasterers' work.

MEASUREMENT of Plaster-work.

Abbreviations—Abstracting of Plasterers' work—Example of Bill of Plasterers' work.

VALUATION.

Memoranda of quantities of materials—Constants of Labour.

#### SMITH AND FOUNDER.

On the Use of Metal-work in Architecture.

Iron not rightly to be used much more now than in the middle ages—Substitutes for the present extravagant use of iron—Fireproof (and sanitary) ceiling and flooring—Fireproof roof-framing in brick and iron—Another method, applicable to hipped roofs—A mode of untrussed roof-framing in iron only—A principle for iron trussed roofing on any plan or scale—Another variation thereof—On the decoration of metallic architecture.

MEASUREMENT of Smiths' and Founders' work.

## PLUMBER, PAINTER, GLAZIER, &c.

DESIGN, &c. OF LEAD-WORK.

MEASUREMENT OF PAINT-WORK-Abbreviations.


Specimen of the measuring-book—Abstract of Paint-work—Example of Bill of Paint-work.

VALUATION of Paint-work.


Constants of Labour—Measurement and Valuation of GLAZING—Measurement and Valuation of PAPER-HANGING.

#### APPENDIX ON WARMING.

Modifications of sanitary construction to suit the English open fire— More economic modes of warming in public buildings—Ditto, to private ones—Warming by gas.



•





•

